


Radiated Measurement Setup below 18 GHz.

Note that for ANSI C63.10 setup requirements above 1 GHz the wireless device is located in the handle area placing it ~1.5 m above the ground plane.



**Conducted Measurement Setup** 



Radiated Spurious 18-25 GHz Setup