

 **Manufacturer:**
Siterwell Electronics Co., Limited
No.666 Qingfeng Road, Jiangbei District,
Ningbo, Zhejiang Province, China 315034



Smoke alarm device item number | GS511-B-H61

WARNING

- Battery not replaceable
- See instruction manual
- This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions:
(1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

Date for replacement:
XX-XXXX



FCC ID : 2ASY-GS511-B-H61
EN 14604:2005 + AC:2008
Intended use: Fire Safety