

INTERNAL PHOTOS

**Reference Test Report No:
ULR-TC56882230000096F**


Seite 1 von 8
Page 1 of 8




Internal Construction –Top view




Internal Construction – Bottom view




Internal Construction - Side view




Internal Construction - Side view




Internal Construction – Side view




Main Board and Interface Board - Top view




Main Board and Interface Board - Bottom view




LCD Board - Top view




LCD Board - Bottom view




Dual feeder Control Board - Top view



Dual feeder Control Board - Bottom view



Magnetic Encoder Board - Top view



Magnetic Encoder Board - Bottom view




HID_PCB_TOP View


INTERNAL PHOTOS

**Reference Test Report No:
ULR-TC56882230000096F**

Seite 7 von 8
Page 7 of 8



HID_PCB_Rear View




HID_PCB_Dimensional View

INTERNAL PHOTOS

**Reference Test Report No:
ULR-TC56882230000096F**

**Seite 8 von 8
Page 8 of 8**



HID_PCB_Dimensional View



HID PCB with Encloser