



11A_Ant1_5180




Date: 12.OCT.2019 14:33:45

11A_Ant1_5200




Date: 12.OCT.2019 14:50:51

11A_Ant1_5240




Date: 12.OCT.2019 14:55:37

11A_Ant1_5745




Date: 12.OCT.2019 15:01:48

11A_Ant1_5785




Date: 12.OCT.2019 15:06:50

11A_Ant1_5825




Date: 12.OCT.2019 15:11:48

11N20SISO_Ant1_5180




Date: 14.OCT.2019 09:52:47

11N20SISO_Ant1_5200




Date: 14.OCT.2019 09:58:19

11N20SISO_Ant1_5240




Date: 14.OCT.2019 10:03:41

11N20SISO_Ant1_5745




Date: 14.OCT.2019 10:09:39

11N20SISO_Ant1_5785




Date: 14.OCT.2019 10:14:35

11N20SISO_Ant1_5825




Date: 14.OCT.2019 10:20:47

11N40SISO_Ant1_5190




Date: 14.OCT.2019 10:26:43

11N40SISO_Ant1_5230




Date: 14.OCT.2019 10:31:20

11N40SISO_Ant1_5755




Date: 14.OCT.2019 10:36:10

11N40SISO_Ant1_5795




Date: 14.OCT.2019 10:45:17

11AC20SISO_Ant1_5180




Date: 14.OCT.2019 10:50:08

11AC20SISO_Ant1_5200




Date: 14.OCT.2019 10:56:35

11AC20SISO_Ant1_5240




Date: 14.OCT.2019 11:01:34

11AC20SISO_Ant1_5745




Date: 14.OCT.2019 11:06:36

11AC20SISO_Ant1_5785




Date: 14.OCT.2019 11:11:53

11AC20SISO_Ant1_5825




Date: 14.OCT.2019 11:20:05

11AC40SISO_Ant1_5190




Date: 14.OCT.2019 11:26:50

11AC40SISO_Ant1_5230




Date: 14.OCT.2019 11:31:32

11AC40SISO_Ant1_5755




Date: 14.OCT.2019 11:36:41

11AC40SISO_Ant1_5795




Date: 14.OCT.2019 11:48:27

11AC80SISO_Ant1_5210



Date: 14.OCT.2019 12:00:05

11AC80SISO_Ant1_5775



Date: 15.OCT.2019 09:55:10