



**CENTEGIX™**

EVERY.SECOND. MATTERS.

## **Badge**

1. Centegix Badge packaging removal
  - a. Take the badge out of box
2. Assigning the Centegix Badge
  - a. Use a barcode scanner and scan the QR code into the Centegix system
    - i. The badge is now assigned to that user
3. How to use the badge
  - a. Press the button on the badge 3 times for a staff alert
  - b. Press the button on the badge 8 times for a lockdown event

## **Strobe**

1. Centegix Strobe packaging removal
  - a. Remove the Strobe from the box
2. Assigning the Strobe
  - a. Walk to where you want to install the Centegix Strobe
  - b. Press and hold the button on the back of the Strobe for 3 Seconds
  - c. In the Centegix installer application use your phone to scan the QR code on the back of the Centegix Strobe
  - d. Assign the strobe to the location at which you are located
3. Install Strobe
  - a. Put the wire leader over the ceiling tile and attach the connector to the wire so the strobe does not fall
  - b. With the magnet place the strobe on the ceiling tile

## **Beacon**

1. Centegix Beacon packaging removal
  - a. Remove the Beacon from the box
2. Assigning the Beacon
  - a. Walk to where you want to install the Centegix Beacon
  - b. Press and hold the button on the back of the Beacon for 3 Seconds
  - c. In the Centegix installer application use your phone to scan the QR code on the back of the Centegix Beacon
  - d. Assign the Beacon to the location at which you are located
3. Install Beacon
  - a. Put the wire leader over the ceiling tile and attach the connector to the wire so the beacon does not fall
  - b. With the magnet place the beacon on the ceiling tile

## FCC Statement

This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.

Caution: Any changes or modifications to this device not explicitly approved by manufacturer could void your authority to operate this equipment.

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

Specific Absorption Rate (SAR) information:

This Badge meets the government's requirements for exposure to radio waves. The guidelines are based on standards that were developed by independent scientific organizations through periodic and thorough evaluation of scientific studies. The standards include a substantial safety margin designed to assure the safety of all persons regardless of age or health. FCC RF Exposure Information and Statement the SAR limit of USA (FCC) is 1.6 W/kg averaged over one gram of tissue. Device types: Badge has also been tested against this SAR limit. This device was tested for typical body-worn operations with the back of the device kept 0mm from the body. The use of belt clips, holsters and similar accessories should not contain metallic components in its assembly. The use of accessories that do not satisfy these requirements may not comply with FCC RF exposure requirements, and should be avoided.

FCC ID: 2ATQ2-CEBDG02