


Appendix A


Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0




Date: 20.SEP.2022 19:34:14

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 20.SEP.2022 19:34:27

Band 2_1.4 MHz_Middle_QPSK_RB6#0




Date: 20.SEP.2022 19:34:44

Band 2_1.4 MHz_Middle_16QAM_RB6#0




Date: 20.SEP.2022 19:35:01

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 20.SEP.2022 19:35:18

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 20.SEP.2022 19:35:34

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 20.SEP.2022 19:37:08

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 20.SEP.2022 19:37:21

Band 2_3 MHz_Middle_QPSK_RB15#0




Date: 20.SEP.2022 19:37:35

Band 2_3 MHz_Middle_16QAM_RB15#0




Date: 20.SEP.2022 19:37:48

Band 2_3 MHz_High_QPSK_RB15#0




Date: 20.SEP.2022 19:38:02

Band 2_3 MHz_High_16QAM_RB15#0




Date: 20.SEP.2022 19:38:19

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 20.SEP.2022 19:39:12

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 20.SEP.2022 19:39:26

Band 2_5 MHz_Middle_QPSK_RB25#0




Date: 20.SEP.2022 19:39:40

Band 2_5 MHz_Middle_16QAM_RB25#0




Date: 20.SEP.2022 19:39:54

Band 2_5 MHz_High_QPSK_RB25#0




Date: 20.SEP.2022 19:40:14

Band 2_5 MHz_High_16QAM_RB25#0




Date: 20.SEP.2022 19:40:31

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 20.SEP.2022 19:41:25

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 20.SEP.2022 19:41:42

Band 2_10 MHz_Middle_QPSK_RB50#0




Date: 20.SEP.2022 19:41:56

Band 2_10 MHz_Middle_16QAM_RB50#0




Date: 20.SEP.2022 19:42:13

Band 2_10 MHz_High_QPSK_RB50#0




Date: 20.SEP.2022 19:42:30

Band 2_10 MHz_High_16QAM_RB50#0




Date: 20.SEP.2022 19:42:47

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 20.SEP.2022 19:52:20

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 20.SEP.2022 19:52:38

Band 2_15 MHz_Middle_QPSK_RB75#0




Date: 20.SEP.2022 19:52:53

Band 2_15 MHz_Middle_16QAM_RB75#0




Date: 20.SEP.2022 19:53:08

Band 2_15 MHz_High_QPSK_RB75#0




Date: 20.SEP.2022 19:53:26

Band 2_15 MHz_High_16QAM_RB75#0




Date: 20.SEP.2022 19:53:41

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 20.SEP.2022 19:54:39

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 20.SEP.2022 19:54:57

Band 2_20 MHz_Middle_QPSK_RB100#0




Date: 20.SEP.2022 19:55:15

Band 2_20 MHz_Middle_16QAM_RB100#0




Date: 20.SEP.2022 19:55:33

Band 2_20 MHz_High_QPSK_RB100#0




Date: 20.SEP.2022 19:55:48

Band 2_20 MHz_High_16QAM_RB100#0




Date: 20.SEP.2022 19:56:03

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 20.SEP.2022 21:24:06

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 20.SEP.2022 21:24:32

Band 5_1.4 MHz_Middle_QPSK_RB6#0




Date: 20.SEP.2022 21:24:46

Band 5_1.4 MHz_Middle_16QAM_RB6#0




Date: 20.SEP.2022 21:25:03

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 20.SEP.2022 21:25:29

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 20.SEP.2022 21:25:46

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 20.SEP.2022 21:26:27

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 20.SEP.2022 21:26:53

Band 5_3 MHz_Middle_QPSK_RB15#0




Date: 20.SEP.2022 21:27:10

Band 5_3 MHz_Middle_16QAM_RB15#0




Date: 20.SEP.2022 21:27:26

Band 5_3 MHz_High_QPSK_RB15#0




Date: 20.SEP.2022 21:27:44

Band 5_3 MHz_High_16QAM_RB15#0




Date: 20.SEP.2022 21:28:00

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 20.SEP.2022 21:28:46

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 20.SEP.2022 21:28:59

Band 5_5 MHz_Middle_QPSK_RB25#0




Date: 20.SEP.2022 21:29:17

Band 5_5 MHz_Middle_16QAM_RB25#0




Date: 20.SEP.2022 21:29:37

Band 5_5 MHz_High_QPSK_RB25#0




Date: 20.SEP.2022 21:29:54

Band 5_5 MHz_High_16QAM_RB25#0




Date: 20.SEP.2022 21:30:11

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 20.SEP.2022 21:31:00

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 20.SEP.2022 21:31:17

Band 5_10 MHz_Middle_QPSK_RB50#0




Date: 20.SEP.2022 21:31:34

Band 5_10 MHz_Middle_16QAM_RB50#0




Date: 20.SEP.2022 21:31:51

Band 5_10 MHz_High_QPSK_RB50#0




Date: 20.SEP.2022 21:32:09

Band 5_10 MHz_High_16QAM_RB50#0




Date: 20.SEP.2022 21:32:22

Band 12_1.4 MHz_Low_QPSK_RB6#0




Date: 20.SEP.2022 21:32:42

Band 12_1.4 MHz_Low_16QAM_RB6#0




Date: 20.SEP.2022 21:32:58

Band 12_1.4 MHz_Middle_QPSK_RB6#0




Date: 20.SEP.2022 21:33:12

Band 12_1.4 MHz_Middle_16QAM_RB6#0




Date: 20.SEP.2022 21:33:29

Band 12_1.4 MHz_High_QPSK_RB6#0




Date: 20.SEP.2022 21:33:46

Band 12_1.4 MHz_High_16QAM_RB6#0




Date: 20.SEP.2022 21:34:05

Band 12_3 MHz_Low_QPSK_RB15#0




Date: 20.SEP.2022 21:34:47

Band 12_3 MHz_Low_16QAM_RB15#0




Date: 20.SEP.2022 21:35:03

Band 12_3 MHz_Middle_QPSK_RB15#0




Date: 20.SEP.2022 21:35:21

Band 12_3 MHz_Middle_16QAM_RB15#0




Date: 20.SEP.2022 21:35:37

Band 12_3 MHz_High_QPSK_RB15#0




Date: 20.SEP.2022 21:35:51

Band 12_3 MHz_High_16QAM_RB15#0




Date: 20.SEP.2022 21:36:07

Band 12_5 MHz_Low_QPSK_RB25#0




Date: 20.SEP.2022 21:36:49

Band 12_5 MHz_Low_16QAM_RB25#0




Date: 20.SEP.2022 21:37:09

Band 12_5 MHz_Middle_QPSK_RB25#0




Date: 20.SEP.2022 21:37:30

Band 12_5 MHz_Middle_16QAM_RB25#0




Date: 20.SEP.2022 21:37:46

Band 12_5 MHz_High_QPSK_RB25#0




Date: 20.SEP.2022 21:38:10

Band 12_5 MHz_High_16QAM_RB25#0




Date: 20.SEP.2022 21:38:30

Band 12_10 MHz_Low_QPSK_RB50#0




Date: 20.SEP.2022 21:39:12

Band 12_10 MHz_Low_16QAM_RB50#0




Date: 20.SEP.2022 21:39:29

Band 12_10 MHz_Middle_QPSK_RB50#0




Date: 20.SEP.2022 21:39:49

Band 12_10 MHz_Middle_16QAM_RB50#0




Date: 20.SEP.2022 21:40:06

Band 12_10 MHz_High_QPSK_RB50#0




Date: 20.SEP.2022 21:40:23

Band 12_10 MHz_High_16QAM_RB50#0




Date: 20.SEP.2022 21:40:40

Band 13_5 MHz_Low_QPSK_RB25#0




Date: 20.SEP.2022 21:41:00

Band 13_5 MHz_Low_16QAM_RB25#0




Date: 20.SEP.2022 21:41:17

Band 13_5 MHz_Middle_QPSK_RB25#0




Date: 20.SEP.2022 21:41:31

Band 13_5 MHz_Middle_16QAM_RB25#0




Date: 20.SEP.2022 21:41:48

Band 13_5 MHz_High_QPSK_RB25#0




Date: 20.SEP.2022 21:42:05

Band 13_5 MHz_High_16QAM_RB25#0




Date: 20.SEP.2022 21:42:22

Band 13_10 MHz_Middle_QPSK_RB50#0




Date: 20.SEP.2022 21:43:11

Band 13_10 MHz_Middle_16QAM_RB50#0




Date: 20.SEP.2022 21:43:28

Band 41_5 MHz_Low_QPSK_RB25#0




Date: 28.SEP.2022 15:13:58

Band 41_5 MHz_Low_16QAM_RB25#0




Date: 28.SEP.2022 15:14:23

Band 41_5 MHz_Middle_QPSK_RB25#0




Date: 28.SEP.2022 15:14:57

Band 41_5 MHz_Middle_16QAM_RB25#0




Date: 28.SEP.2022 15:15:14

Band 41_5 MHz_High_QPSK_RB25#0




Date: 28.SEP.2022 15:15:43

Band 41_5 MHz_High_16QAM_RB25#0




Date: 28.SEP.2022 15:16:07

Band 41_10 MHz_Low_QPSK_RB50#0




Date: 28.SEP.2022 15:16:34

Band 41_10 MHz_Low_16QAM_RB50#0




Date: 28.SEP.2022 15:16:53

Band 41_10 MHz_Middle_QPSK_RB50#0




Date: 28.SEP.2022 15:17:15

Band 41_10 MHz_Middle_16QAM_RB50#0




Date: 28.SEP.2022 15:17:40

Band 41_10 MHz_High_QPSK_RB50#0




Date: 28.SEP.2022 15:18:05

Band 41_10 MHz_High_16QAM_RB50#0




Date: 28.SEP.2022 15:18:33

Band 41_15 MHz_Low_QPSK_RB75#0




Date: 28.SEP.2022 15:19:09

Band 41_15 MHz_Low_16QAM_RB75#0




Date: 28.SEP.2022 15:19:36

Band 41_15 MHz_Middle_QPSK_RB75#0




Date: 28.SEP.2022 15:20:04

Band 41_15 MHz_Middle_16QAM_RB75#0




Date: 28.SEP.2022 15:20:41

Band 41_15 MHz_High_QPSK_RB75#0




Date: 28.SEP.2022 15:21:28

Band 41_15 MHz_High_16QAM_RB75#0




Date: 28.SEP.2022 15:21:59

Band 41_20 MHz_Low_QPSK_RB100#0




Date: 28.SEP.2022 15:22:27

Band 41_20 MHz_Low_16QAM_RB100#0




Date: 28.SEP.2022 15:22:55

Band 41_20 MHz_Middle_QPSK_RB100#0




Date: 28.SEP.2022 15:23:23

Band 41_20 MHz_Middle_16QAM_RB100#0




Date: 28.SEP.2022 15:23:48

Band 41_20 MHz_High_QPSK_RB100#0



Date: 28.SEP.2022 15:24:16

Band 41_20 MHz_High_16QAM_RB100#0



Date: 28.SEP.2022 15:24:37