


Appendix B


Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 20.SEP.2022 20:16:39

Band 2_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 20.SEP.2022 20:16:50

Band 2_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 20.SEP.2022 20:17:05

Band 2_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 20.SEP.2022 20:17:16

Band 2_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 20.SEP.2022 20:17:28

Band 2_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 20.SEP.2022 20:17:38

Band 2_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 20.SEP.2022 20:18:15

Band 2_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 20.SEP.2022 20:18:25

Band 2_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 20.SEP.2022 20:18:41

Band 2_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 20.SEP.2022 20:18:51

Band 2_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 20.SEP.2022 20:19:04

Band 2_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 20.SEP.2022 20:19:14

Band 2_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 20.SEP.2022 20:20:02

Band 2_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 20.SEP.2022 20:20:12

Band 2_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 20.SEP.2022 20:20:28

Band 2_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 20.SEP.2022 20:20:38

Band 2_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 20.SEP.2022 20:20:54

Band 2_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 20.SEP.2022 20:21:04

Band 2_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 20.SEP.2022 20:21:57

Band 2_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 20.SEP.2022 20:22:07

Band 2_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 20.SEP.2022 20:22:23

Band 2_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 20.SEP.2022 20:22:33

Band 2_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 20.SEP.2022 20:22:46

Band 2_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 20.SEP.2022 20:22:56

Band 2_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 20.SEP.2022 20:23:53

Band 2_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 20.SEP.2022 20:24:03

Band 2_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 20.SEP.2022 20:24:16

Band 2_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 20.SEP.2022 20:24:27

Band 2_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 20.SEP.2022 20:24:40

Band 2_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 20.SEP.2022 20:24:50

Band 2_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 20.SEP.2022 20:25:36

Band 2_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 20.SEP.2022 20:25:46

Band 2_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 20.SEP.2022 20:26:00

Band 2_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 20.SEP.2022 20:26:10

Band 2_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 20.SEP.2022 20:26:24

Band 2_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 20.SEP.2022 20:26:34

Band 5_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 20.SEP.2022 22:07:01

Band 5_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 20.SEP.2022 22:07:11

Band 5_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 20.SEP.2022 22:07:27

Band 5_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 20.SEP.2022 22:07:37

Band 5_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 20.SEP.2022 22:07:49

Band 5_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 20.SEP.2022 22:08:00

Band 5_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 20.SEP.2022 22:08:39

Band 5_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 20.SEP.2022 22:08:53

Band 5_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 20.SEP.2022 22:09:05

Band 5_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 20.SEP.2022 22:09:15

Band 5_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 20.SEP.2022 22:09:28

Band 5_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 20.SEP.2022 22:09:38

Band 5_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 20.SEP.2022 22:10:33

Band 5_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 20.SEP.2022 22:10:44

Band 5_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 20.SEP.2022 22:10:56

Band 5_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 20.SEP.2022 22:11:07

Band 5_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 20.SEP.2022 22:11:22

Band 5_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 20.SEP.2022 22:11:33

Band 5_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 20.SEP.2022 22:12:25

Band 5_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 20.SEP.2022 22:12:35

Band 5_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 20.SEP.2022 22:12:48

Band 5_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 20.SEP.2022 22:12:59

Band 5_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 20.SEP.2022 22:13:15

Band 5_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 20.SEP.2022 22:13:25

Band 12_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 20.SEP.2022 22:13:43

Band 12_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 20.SEP.2022 22:13:53

Band 12_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 20.SEP.2022 22:14:05

Band 12_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 20.SEP.2022 22:14:16

Band 12_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 20.SEP.2022 22:14:28

Band 12_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 20.SEP.2022 22:14:38

Band 12_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 20.SEP.2022 22:15:15

Band 12_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 20.SEP.2022 22:15:26

Band 12_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 20.SEP.2022 22:15:38

Band 12_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 20.SEP.2022 22:15:48

Band 12_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 20.SEP.2022 22:16:01

Band 12_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 20.SEP.2022 22:16:11

Band 12_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 20.SEP.2022 22:16:48

Band 12_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 20.SEP.2022 22:16:58

Band 12_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 20.SEP.2022 22:17:11

Band 12_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 20.SEP.2022 22:17:21

Band 12_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 20.SEP.2022 22:17:37

Band 12_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 20.SEP.2022 22:17:47

Band 12_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 20.SEP.2022 22:18:31

Band 12_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 20.SEP.2022 22:18:42

Band 12_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 20.SEP.2022 22:18:58

Band 12_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 20.SEP.2022 22:19:08

Band 12_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 20.SEP.2022 22:19:21

Band 12_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 20.SEP.2022 22:19:31

Band 13_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 20.SEP.2022 22:19:49

Band 13_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 20.SEP.2022 22:20:00

Band 13_5 MHz_Low_QPSK_RB25#0_3(763MHz-775MHz)




Date: 20.SEP.2022 22:20:13

Band 13_5 MHz_Low_QPSK_RB25#0_4(793MHz-806MHz)




Date: 20.SEP.2022 22:20:26

Band 13_5 MHz_Low_QPSK_RB25#0_5(1.559GHz-1.61GHz)




Date: 20.SEP.2022 22:20:36

Band 13_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 20.SEP.2022 22:20:49

Band 13_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 20.SEP.2022 22:21:02

Band 13_5 MHz_Middle_QPSK_RB25#0_3(763MHz-775MHz)




Date: 20.SEP.2022 22:21:15

Band 13_5 MHz_Middle_QPSK_RB25#0_4(793MHz-806MHz)




Date: 20.SEP.2022 22:21:28

Band 13_5 MHz_Middle_QPSK_RB25#0_5(1.5590GHz-1.61GHz)




Date: 20.SEP.2022 22:21:38

Band 13_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 20.SEP.2022 22:21:54

Band 13_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 20.SEP.2022 22:22:04

Band 13_5 MHz_High_QPSK_RB25#0_3(763MHz-775MHz)




Date: 20.SEP.2022 22:22:18

Band 13_5 MHz_High_QPSK_RB25#0_4(793MHz-806MHz)




Date: 20.SEP.2022 22:22:31

Band 13_5 MHz_High_QPSK_RB25#0_5(1.5590GHz-1.61GHz)




Date: 20.SEP.2022 22:22:41

Band 13_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 20.SEP.2022 22:23:26

Band 13_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 20.SEP.2022 22:23:36

Band 13_10 MHz_Middle_QPSK_RB50#0_3(763MHz-775MHz)




Date: 20.SEP.2022 22:23:49

Band 13_10 MHz_Middle_QPSK_RB50#0_4(793MHz-806MHz)




Date: 20.SEP.2022 22:23:59

Band 13_10 MHz_Middle_QPSK_RB50#0_5(1.5590GHz-1.61GHz)




Date: 20.SEP.2022 22:24:12

Band 41_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 20.SEP.2022 23:01:53

Band 41_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 20.SEP.2022 23:02:03

Band 41_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 20.SEP.2022 23:02:16

Band 41_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 20.SEP.2022 23:02:26

Band 41_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 20.SEP.2022 23:02:42

Band 41_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 20.SEP.2022 23:02:52

Band 41_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 20.SEP.2022 23:03:10

Band 41_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 20.SEP.2022 23:03:20

Band 41_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 20.SEP.2022 23:03:36

Band 41_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 20.SEP.2022 23:03:46

Band 41_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 20.SEP.2022 23:03:59

Band 41_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 20.SEP.2022 23:04:09

Band 41_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 20.SEP.2022 23:04:24

Band 41_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 20.SEP.2022 23:04:35

Band 41_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 20.SEP.2022 23:04:48

Band 41_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 20.SEP.2022 23:04:58

Band 41_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 20.SEP.2022 23:05:15

Band 41_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 20.SEP.2022 23:05:25

Band 41_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 20.SEP.2022 23:05:43

Band 41_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 20.SEP.2022 23:05:54

Band 41_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 20.SEP.2022 23:06:07

Band 41_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 20.SEP.2022 23:06:18

Band 41_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)



Date: 20.SEP.2022 23:06:34

Band 41_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)



Date: 20.SEP.2022 23:06:45