



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0




Date: 28.MAY.2023 17:57:05

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 28.MAY.2023 17:57:11

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 28.MAY.2023 17:57:19

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 28.MAY.2023 17:57:26

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 28.MAY.2023 17:57:36

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 28.MAY.2023 17:57:42

Band 2_3 MHz_High_QPSK_RB15#0




Date: 28.MAY.2023 17:57:50

Band 2_3 MHz_High_16QAM_RB15#0




Date: 28.MAY.2023 17:57:57

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 28.MAY.2023 17:58:08

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 28.MAY.2023 17:58:14

Band 2_5 MHz_High_QPSK_RB25#0




Date: 28.MAY.2023 17:58:23

Band 2_5 MHz_High_16QAM_RB25#0




Date: 28.MAY.2023 17:58:30

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 28.MAY.2023 17:58:42

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 28.MAY.2023 17:58:50

Band 2_10 MHz_High_QPSK_RB50#0




Date: 28.MAY.2023 17:58:59

Band 2_10 MHz_High_16QAM_RB50#0




Date: 28.MAY.2023 17:59:07

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 28.MAY.2023 17:59:18

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 28.MAY.2023 17:59:25

Band 2_15 MHz_High_QPSK_RB75#0




Date: 28.MAY.2023 17:59:33

Band 2_15 MHz_High_16QAM_RB75#0




Date: 28.MAY.2023 17:59:40

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 28.MAY.2023 17:59:52

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 28.MAY.2023 17:59:59

Band 2_20 MHz_High_QPSK_RB100#0




Date: 28.MAY.2023 18:00:07

Band 2_20 MHz_High_16QAM_RB100#0




Date: 28.MAY.2023 18:00:14

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 28.MAY.2023 19:39:55

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 28.MAY.2023 19:40:01

Band 5_3 MHz_High_QPSK_RB15#0




Date: 28.MAY.2023 19:40:09

Band 5_3 MHz_High_16QAM_RB15#0




Date: 28.MAY.2023 19:40:15

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 28.MAY.2023 19:40:24

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 28.MAY.2023 19:40:31

Band 5_5 MHz_High_QPSK_RB25#0




Date: 28.MAY.2023 19:40:38

Band 5_5 MHz_High_16QAM_RB25#0




Date: 28.MAY.2023 19:40:45

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 28.MAY.2023 19:40:57

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 28.MAY.2023 19:41:05

Band 5_10 MHz_High_QPSK_RB50#0




Date: 28.MAY.2023 19:41:14

Band 5_10 MHz_High_16QAM_RB50#0




Date: 28.MAY.2023 19:41:23

Band 12_1.4 MHz_Low_QPSK_RB6#0




Date: 28.MAY.2023 19:41:39

Band 12_1.4 MHz_Low_16QAM_RB6#0




Date: 28.MAY.2023 19:41:45

Band 12_1.4 MHz_High_QPSK_RB6#0




Date: 28.MAY.2023 19:41:52

Band 12_1.4 MHz_High_16QAM_RB6#0




Date: 28.MAY.2023 19:41:58

Band 12_3 MHz_Low_QPSK_RB15#0




Date: 28.MAY.2023 19:42:08

Band 12_3 MHz_Low_16QAM_RB15#0




Date: 28.MAY.2023 19:42:16

Band 12_3 MHz_High_QPSK_RB15#0




Date: 28.MAY.2023 19:42:23

Band 12_3 MHz_High_16QAM_RB15#0




Date: 28.MAY.2023 19:42:29

Band 12_5 MHz_Low_QPSK_RB25#0




Date: 28.MAY.2023 19:42:40

Band 12_5 MHz_Low_16QAM_RB25#0




Date: 28.MAY.2023 19:42:47

Band 12_5 MHz_High_QPSK_RB25#0




Date: 28.MAY.2023 19:42:55

Band 12_5 MHz_High_16QAM_RB25#0




Date: 28.MAY.2023 19:43:01

Band 12_10 MHz_Low_QPSK_RB50#0




Date: 28.MAY.2023 19:43:13

Band 12_10 MHz_Low_16QAM_RB50#0




Date: 28.MAY.2023 19:43:22

Band 12_10 MHz_High_QPSK_RB50#0




Date: 28.MAY.2023 19:43:30

Band 12_10 MHz_High_16QAM_RB50#0




Date: 28.MAY.2023 19:43:37

Band 13_5 MHz_Low_QPSK_RB6#0




Date: 27.MAY.2023 00:41:39

Band 13_5 MHz_Low_16QAM_RB6#0




Date: 27.MAY.2023 00:40:28

Band 13_10 MHz_Middle_QPSK_RB15#0




Date: 27.MAY.2023 00:36:32

Band 13_10 MHz_Middle_16QAM_RB15#0




Date: 27.MAY.2023 00:35:37

Band 13_5 MHz_High_QPSK_RB6#0




Date: 27.MAY.2023 00:43:03

Band 13_5 MHz_High_16QAM_RB6#0




Date: 27.MAY.2023 00:43:48

Band 41_5 MHz_Low_QPSK_RB6#0




Date: 29.MAY.2023 20:25:11

Band 41_5 MHz_Low_16QAM_RB6#0




Date: 29.MAY.2023 20:26:46

Band 41_5 MHz_High_QPSK_RB6#0




Date: 29.MAY.2023 20:23:23

Band 41_5 MHz_High_16QAM_RB6#0




Date: 29.MAY.2023 20:20:30

Band 41_10 MHz_Low_QPSK_RB15#0




Date: 29.MAY.2023 20:30:28

Band 41_10 MHz_Low_16QAM_RB15#0




Date: 29.MAY.2023 20:29:30

Band 41_10 MHz_High_QPSK_RB15#0




Date: 29.MAY.2023 20:31:26

Band 41_10 MHz_High_16QAM_RB15#0




Date: 29.MAY.2023 20:32:04

Band 41_15 MHz_Low_QPSK_RB25#0




Date: 29.MAY.2023 20:39:56

Band 41_15 MHz_Low_16QAM_RB25#0




Date: 29.MAY.2023 20:40:43

Band 41_15 MHz_High_QPSK_RB25#0




Date: 29.MAY.2023 20:38:42

Band 41_15 MHz_High_16QAM_RB25#0




Date: 29.MAY.2023 20:38:00

Band 41_20 MHz_Low_QPSK_RB50#0




Date: 29.MAY.2023 20:45:23

Band 41_20 MHz_Low_16QAM_RB50#0




Date: 29.MAY.2023 20:43:45

Band 41_20 MHz_High_QPSK_RB50#0



Date: 29.MAY.2023 20:46:55

Band 41_20 MHz_High_16QAM_RB50#0



Date: 29.MAY.2023 20:47:33