



**Cellular Band**

**GSM  
Low Channel**




Date: 2.DEC.2023 00:09:41




Date: 2.DEC.2023 00:10:08

### Middle Channel




Date: 2.DEC.2023 00:12:41




Date: 2.DEC.2023 00:13:02

### High Channel




Date: 2.DEC.2023 00:17:57




Date: 2.DEC.2023 00:18:18

### RMC Low Channel




Date: 1.DEC.2023 23:52:58




Date: 1.DEC.2023 23:53:19

### Middle Channel




Date: 1.DEC.2023 23:50:12




Date: 1.DEC.2023 23:50:21

### High Channel




Date: 1.DEC.2023 22:46:40




Date: 1.DEC.2023 22:46:50

PCS Band

GSM  
Low Channel




Date: 2.DEC.2023 10:55:31




Date: 2.DEC.2023 10:57:44

### Middle Channel




Date: 2.DEC.2023 11:00:11




Date: 2.DEC.2023 11:01:03



### High Channel




Date: 2.DEC.2023 11:05:19




Date: 2.DEC.2023 11:07:25

### RMC Low Channel




Date: 1.DEC.2023 21:57:41




Date: 1.DEC.2023 21:58:41

### Middle Channel




Date: 1.DEC.2023 22:01:19




Date: 1.DEC.2023 22:01:47

### High Channel




Date: 1.DEC.2023 22:04:22



Date: 1.DEC.2023 22:05:14


**LTE Band**

Band-2\_1.4-MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 1.DEC.2023 00:33:35

Band-2\_1.4-MHz\_Low\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 1.DEC.2023 00:33:59

Band-2\_1.4-MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 1.DEC.2023 00:34:27

Band-2\_1.4-MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 1.DEC.2023 00:34:57

Band-2\_1.4-MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 1.DEC.2023 00:35:28

Band-2\_1.4-MHz\_High\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 1.DEC.2023 00:35:58

Band-2\_3-MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)



Date: 1.DEC.2023 00:36:56


Band-2\_3-MHz\_Low\_QPSK\_RB15#0\_2(1GHz-20GHz)



Date: 1.DEC.2023 00:37:22




Band-2\_3-MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 1.DEC.2023 00:37:51

Band-2\_3-MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 1.DEC.2023 00:38:11

Band-2\_3-MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 1.DEC.2023 00:38:39

Band-2\_3-MHz\_High\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 1.DEC.2023 00:39:09

Band-2\_5-MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 1.DEC.2023 00:40:38

Band-2\_5-MHz\_Low\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 1.DEC.2023 00:40:58

Band-2\_5-MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 1.DEC.2023 00:41:29

Band-2\_5-MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 1.DEC.2023 00:41:59

Band-2\_5-MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 1.DEC.2023 00:42:27

Band-2\_5-MHz\_High\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 1.DEC.2023 00:42:51

Band-2\_10-MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 1.DEC.2023 00:43:57

Band-2\_10-MHz\_Low\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 1.DEC.2023 00:44:33

Band-2\_10-MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 1.DEC.2023 00:45:01

Band-2\_10-MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 1.DEC.2023 00:45:31

Band-2\_10-MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)



Date: 1.DEC.2023 00:46:00


Band-2\_10-MHz\_High\_QPSK\_RB50#0\_2(1GHz-20GHz)



Date: 1.DEC.2023 00:46:23




Band-2\_15-MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 1.DEC.2023 00:48:06

Band-2\_15-MHz\_Low\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 1.DEC.2023 00:49:08

Band-2\_15-MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 1.DEC.2023 00:49:33

Band-2\_15-MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 1.DEC.2023 00:50:00

Band-2\_15-MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 1.DEC.2023 00:50:28

Band-2\_15-MHz\_High\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 1.DEC.2023 00:50:55

Band-2\_20-MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 1.DEC.2023 00:54:57

Band-2\_20-MHz\_Low\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 1.DEC.2023 00:55:27

Band-2\_20-MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 1.DEC.2023 00:55:56

Band-2\_20-MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 1.DEC.2023 00:56:22

Band-2\_20-MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 1.DEC.2023 00:56:44

Band-2\_20-MHz\_High\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 1.DEC.2023 00:57:07

Band-5\_1.4-MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 30.NOV.2023 22:35:13

Band-5\_1.4-MHz\_Low\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 30.NOV.2023 22:35:43

Band-5\_1.4-MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)



Date: 30.NOV.2023 22:36:12


Band-5\_1.4-MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-10GHz)



Date: 30.NOV.2023 22:36:38




Band-5\_1.4-MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 30.NOV.2023 22:37:07

Band-5\_1.4-MHz\_High\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 30.NOV.2023 22:37:33

Band-5\_3-MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 30.NOV.2023 22:38:28

Band-5\_3-MHz\_Low\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 30.NOV.2023 22:38:54

Band-5\_3-MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 30.NOV.2023 22:39:23

Band-5\_3-MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 30.NOV.2023 22:39:49

Band-5\_3-MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 30.NOV.2023 22:40:25

Band-5\_3-MHz\_High\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 30.NOV.2023 22:40:48

Band-5\_5-MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 30.NOV.2023 22:42:12

Band-5\_5-MHz\_Low\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 30.NOV.2023 22:42:38

Band-5\_5-MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 30.NOV.2023 22:43:13

Band-5\_5-MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 30.NOV.2023 22:43:39

Band-5\_5-MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 30.NOV.2023 22:43:59

Band-5\_5-MHz\_High\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 30.NOV.2023 22:44:25

Band-5\_10-MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)



Date: 30.NOV.2023 22:45:21


Band-5\_10-MHz\_Low\_QPSK\_RB50#0\_2(1GHz-10GHz)



Date: 30.NOV.2023 22:45:47




Band-5\_10-MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 30.NOV.2023 22:46:35

Band-5\_10-MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 30.NOV.2023 22:47:01

Band-5\_10-MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 30.NOV.2023 22:47:30

Band-5\_10-MHz\_High\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 30.NOV.2023 22:47:50

Band-12\_1.4-MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 30.NOV.2023 22:49:09

Band-12\_1.4-MHz\_Low\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 30.NOV.2023 22:49:41

Band-12\_1.4-MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 30.NOV.2023 22:50:13

Band-12\_1.4-MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 30.NOV.2023 22:50:36

Band-12\_1.4-MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 30.NOV.2023 22:51:02

Band-12\_1.4-MHz\_High\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 30.NOV.2023 22:51:25

Band-12\_3-MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 30.NOV.2023 22:52:20

Band-12\_3-MHz\_Low\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 30.NOV.2023 22:52:49

Band-12\_3-MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 30.NOV.2023 22:53:18

Band-12\_3-MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 30.NOV.2023 22:53:38

Band-12\_3-MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)



Date: 30.NOV.2023 22:54:10


Band-12\_3-MHz\_High\_QPSK\_RB15#0\_2(1GHz-10GHz)



Date: 30.NOV.2023 22:54:36




Band-12\_5-MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 30.NOV.2023 22:55:43

Band-12\_5-MHz\_Low\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 30.NOV.2023 22:56:06

Band-12\_5-MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 30.NOV.2023 22:56:38

Band-12\_5-MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 30.NOV.2023 22:57:01

Band-12\_5-MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 30.NOV.2023 22:57:33

Band-12\_5-MHz\_High\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 30.NOV.2023 22:57:53

Band-12\_10-MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 30.NOV.2023 22:58:50

Band-12\_10-MHz\_Low\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 30.NOV.2023 22:59:41

Band-12\_10-MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 30.NOV.2023 23:00:10

Band-12\_10-MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 30.NOV.2023 23:00:39

Band-12\_10-MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 30.NOV.2023 23:01:05

Band-12\_10-MHz\_High\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 30.NOV.2023 23:01:25

Band-7\_5-MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 30.NOV.2023 23:49:58

Band-7\_5-MHz\_Low\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 30.NOV.2023 23:51:28

Band-7\_5-MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)



Date: 30.NOV.2023 23:51:58


Band-7\_5-MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-26.5GHz)



Date: 30.NOV.2023 23:52:18




Band-7\_5-MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 30.NOV.2023 23:52:47

Band-7\_5-MHz\_High\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 30.NOV.2023 23:53:17

Band-7\_10-MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 30.NOV.2023 23:54:24

Band-7\_10-MHz\_Low\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 30.NOV.2023 23:54:51

Band-7\_10-MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 30.NOV.2023 23:55:23

Band-7\_10-MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 30.NOV.2023 23:55:47

Band-7\_10-MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 30.NOV.2023 23:56:16

Band-7\_10-MHz\_High\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 30.NOV.2023 23:56:45

Band-7\_15-MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 30.NOV.2023 23:57:48

Band-7\_15-MHz\_Low\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 30.NOV.2023 23:58:20

Band-7\_15-MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 30.NOV.2023 23:58:51

Band-7\_15-MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 30.NOV.2023 23:59:18

Band-7\_15-MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 30.NOV.2023 23:59:52

Band-7\_15-MHz\_High\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 1.DEC.2023 00:00:18

Band-7\_20-MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)



Date: 1.DEC.2023 00:01:15


Band-7\_20-MHz\_Low\_QPSK\_RB100#0\_2(1GHz-26.5GHz)



Date: 1.DEC.2023 00:01:42




Band-7\_20-MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 1.DEC.2023 00:02:16

Band-7\_20-MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 1.DEC.2023 00:02:39

Band-7\_20-MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 1.DEC.2023 00:03:13

Band-7\_20-MHz\_High\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 1.DEC.2023 00:03:39

Band-41\_5-MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 30.NOV.2023 21:37:18

Band-41-CSE-5MHz-Low-CH-QPSK(1GHz-27GHz)




Date: 1.DEC.2023 19:39:54

Band-41\_5-MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 30.NOV.2023 21:38:10

Band-41-CSE-5MHz-Middle-CH-QPSK(1GHz-27GHz)




Date: 1.DEC.2023 19:40:19

Band-41\_5-MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 30.NOV.2023 21:39:05

Band-41-CSE-5MHz-High-CH-QPSK(1GHz-27GHz)




Date: 1.DEC.2023 19:42:11

Band-41\_10-MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 30.NOV.2023 21:40:01

Band-41-CSE-10MHz-Low-CH-QPSK(1GHz-27GHz)




Date: 1.DEC.2023 19:44:01

Band-41\_10-MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 30.NOV.2023 21:40:50

Band-41-CSE-10MHz-Middle-CH-QPSK(1GHz-27GHz)




Date: 1.DEC.2023 19:20:20

Band-41\_10-MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)



Date: 30.NOV.2023 21:41:42


Band-41-CSE-10MHz-High-CH-QPSK(1GHz-27GHz)



Date: 1.DEC.2023 19:21:10




Band-41\_15-MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 30.NOV.2023 21:42:48

Band-41-CSE-15MHz-Low-CH-QPSK(1GHz-27GHz)




Date: 1.DEC.2023 19:21:57

Band-41\_15-MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 30.NOV.2023 21:43:39

Band-41-CSE-15MHz-Middle-CH-QPSK(1GHz-27GHz)




Date: 1.DEC.2023 19:22:45

Band-41\_15-MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 30.NOV.2023 21:44:28

Band-41-CSE-15MHz-High-CH-QPSK(1GHz-27GHz)




Date: 1.DEC.2023 19:26:23

Band-41\_20-MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 30.NOV.2023 21:45:31

Band-41-CSE-20MHz-Low-CH-QPSK(1GHz-27GHz)




Date: 1.DEC.2023 19:28:06

Band-41\_20-MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 30.NOV.2023 21:46:26

Band-41-CSE-20MHz-Middle-CH-QPSK(1GHz-27GHz)




Date: 1.DEC.2023 19:30:04

Band-41\_20-MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)



Date: 30.NOV.2023 21:47:17

Band-41-CSE-20MHz-High-CH-QPSK(1GHz-27GHz)



Date: 1.DEC.2023 19:30:53