



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0




Date: 8.JUN.2023 10:41:38

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 8.JUN.2023 10:42:03

Band 2_1.4 MHz_Middle_QPSK_RB6#0




Date: 8.JUN.2023 10:42:25

Band 2_1.4 MHz_Middle_16QAM_RB6#0




Date: 8.JUN.2023 10:42:46

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 8.JUN.2023 10:43:01

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 8.JUN.2023 10:43:22

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 8.JUN.2023 10:43:51

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 8.JUN.2023 10:44:09

Band 2_3 MHz_Middle_QPSK_RB15#0




Date: 8.JUN.2023 10:44:31

Band 2_3 MHz_Middle_16QAM_RB15#0




Date: 8.JUN.2023 10:44:49

Band 2_3 MHz_High_QPSK_RB15#0




Date: 8.JUN.2023 10:45:17

Band 2_3 MHz_High_16QAM_RB15#0




Date: 8.JUN.2023 10:45:35

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 8.JUN.2023 10:45:58

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 8.JUN.2023 10:46:17

Band 2_5 MHz_Middle_QPSK_RB25#0




Date: 8.JUN.2023 10:46:42

Band 2_5 MHz_Middle_16QAM_RB25#0




Date: 8.JUN.2023 10:47:10

Band 2_5 MHz_High_QPSK_RB25#0




Date: 8.JUN.2023 10:47:29

Band 2_5 MHz_High_16QAM_RB25#0




Date: 8.JUN.2023 10:47:51

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 8.JUN.2023 10:48:31

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 8.JUN.2023 10:48:56

Band 2_10 MHz_Middle_QPSK_RB50#0




Date: 8.JUN.2023 10:49:23

Band 2_10 MHz_Middle_16QAM_RB50#0




Date: 8.JUN.2023 10:49:57

Band 2_10 MHz_High_QPSK_RB50#0




Date: 8.JUN.2023 10:50:24

Band 2_10 MHz_High_16QAM_RB50#0




Date: 8.JUN.2023 10:50:52

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 8.JUN.2023 10:51:29

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 8.JUN.2023 10:52:00

Band 2_15 MHz_Middle_QPSK_RB75#0




Date: 8.JUN.2023 10:52:29

Band 2_15 MHz_Middle_16QAM_RB75#0




Date: 8.JUN.2023 10:52:53

Band 2_15 MHz_High_QPSK_RB75#0




Date: 8.JUN.2023 10:53:25

Band 2_15 MHz_High_16QAM_RB75#0




Date: 8.JUN.2023 10:54:06

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 8.JUN.2023 10:54:34

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 8.JUN.2023 10:55:00

Band 2_20 MHz_Middle_QPSK_RB100#0




Date: 8.JUN.2023 10:55:26

Band 2_20 MHz_Middle_16QAM_RB100#0




Date: 8.JUN.2023 10:55:54

Band 2_20 MHz_High_QPSK_RB100#0




Date: 8.JUN.2023 10:56:27

Band 2_20 MHz_High_16QAM_RB100#0




Date: 8.JUN.2023 10:57:05

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 8.JUN.2023 10:57:38

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 8.JUN.2023 10:57:56

Band 7_5 MHz_Middle_QPSK_RB25#0




Date: 8.JUN.2023 10:58:16

Band 7_5 MHz_Middle_16QAM_RB25#0




Date: 8.JUN.2023 10:58:37

Band 7_5 MHz_High_QPSK_RB25#0




Date: 8.JUN.2023 10:59:03

Band 7_5 MHz_High_16QAM_RB25#0




Date: 8.JUN.2023 10:59:25

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 8.JUN.2023 10:59:55

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 8.JUN.2023 11:00:17

Band 7_10 MHz_Middle_QPSK_RB50#0




Date: 8.JUN.2023 11:00:50

Band 7_10 MHz_Middle_16QAM_RB50#0




Date: 8.JUN.2023 11:01:15

Band 7_10 MHz_High_QPSK_RB50#0




Date: 8.JUN.2023 11:01:39

Band 7_10 MHz_High_16QAM_RB50#0




Date: 8.JUN.2023 11:02:10

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 8.JUN.2023 11:02:50

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 8.JUN.2023 11:03:21

Band 7_15 MHz_Middle_QPSK_RB75#0




Date: 8.JUN.2023 11:03:47

Band 7_15 MHz_Middle_16QAM_RB75#0




Date: 8.JUN.2023 11:04:27

Band 7_15 MHz_High_QPSK_RB75#0




Date: 8.JUN.2023 11:05:00

Band 7_15 MHz_High_16QAM_RB75#0




Date: 8.JUN.2023 11:05:38

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 8.JUN.2023 11:06:11

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 8.JUN.2023 11:06:46

Band 7_20 MHz_Middle_QPSK_RB100#0




Date: 8.JUN.2023 11:07:19

Band 7_20 MHz_Middle_16QAM_RB100#0




Date: 8.JUN.2023 11:07:47

Band 7_20 MHz_High_QPSK_RB100#0




Date: 8.JUN.2023 11:08:32

Band 7_20 MHz_High_16QAM_RB100#0




Date: 8.JUN.2023 11:09:04

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 9.JUN.2023 00:25:19

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 9.JUN.2023 00:25:36

Band 5_1.4 MHz_Middle_QPSK_RB6#0




Date: 9.JUN.2023 00:25:55

Band 5_1.4 MHz_Middle_16QAM_RB6#0




Date: 9.JUN.2023 00:26:12

Band 5_1.4 MHz_High_QPSK_RB6#0



Date: 9.JUN.2023 00:26:34

Band 5_1.4 MHz_High_16QAM_RB6#0



Date: 9.JUN.2023 00:26:51