



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 20.OCT.2021 00:41:11

Band 2_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 20.OCT.2021 00:41:33

Band 2_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 20.OCT.2021 00:42:09

Band 2_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 20.OCT.2021 00:42:41

Band 2_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 20.OCT.2021 00:43:11

Band 2_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 20.OCT.2021 00:43:30

Band 2_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 20.OCT.2021 00:44:08

Band 2_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 20.OCT.2021 00:44:30

Band 2_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 20.OCT.2021 00:44:57

Band 2_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 20.OCT.2021 00:45:26

Band 2_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 20.OCT.2021 00:45:55

Band 2_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 20.OCT.2021 00:46:21

Band 2_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 20.OCT.2021 00:46:53

Band 2_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 20.OCT.2021 00:47:18


Band 2_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)



Band 2_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Band 2_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 20.OCT.2021 00:48:49

Band 2_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 20.OCT.2021 00:49:18

Band 2_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 20.OCT.2021 00:49:54

Band 2_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 20.OCT.2021 00:50:19

Band 2_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 20.OCT.2021 00:50:56

Band 2_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 20.OCT.2021 00:51:25

Band 2_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 20.OCT.2021 00:52:02

Band 2_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 20.OCT.2021 00:52:25

Band 2_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 20.OCT.2021 00:53:00

Band 2_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 20.OCT.2021 00:53:19


Band 2_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)



Band 2_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Band 2_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 20.OCT.2021 00:54:50

Band 2_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 20.OCT.2021 00:55:15


Band 2_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)



Band 2_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Band 2_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 20.OCT.2021 00:56:52

Band 2_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 20.OCT.2021 00:57:14

Band 2_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 20.OCT.2021 00:57:44

Band 2_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 20.OCT.2021 00:58:03


Band 5_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Band 5_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Band 5_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Band 5_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Band 5_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Band 5_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Band 5_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Band 5_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Band 5_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Band 5_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Band 5_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)



Band 5_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Band 5_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 20.OCT.2021 01:04:16

Band 5_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 20.OCT.2021 01:04:41


Band 5_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)



Band 5_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Band 5_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 20.OCT.2021 01:06:12

Band 5_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 20.OCT.2021 01:06:41


Band 5_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Band 5_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Band 5_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Band 5_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Band 5_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)



Band 5_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Band 7_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 20.OCT.2021 01:10:06

Band 7_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 20.OCT.2021 01:10:35

Band 7_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 20.OCT.2021 01:11:05

Band 7_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 20.OCT.2021 01:11:30

Band 7_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 20.OCT.2021 01:11:57

Band 7_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 20.OCT.2021 01:12:19

Band 7_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 20.OCT.2021 01:12:52

Band 7_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 20.OCT.2021 01:13:08

Band 7_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 20.OCT.2021 01:13:36

Band 7_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 20.OCT.2021 01:13:58

Band 7_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 20.OCT.2021 01:14:29

Band 7_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 20.OCT.2021 01:14:51

Band 7_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 20.OCT.2021 01:15:23

Band 7_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 20.OCT.2021 01:15:39

Band 7_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 20.OCT.2021 01:16:16

Band 7_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 20.OCT.2021 01:16:41

Band 7_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 20.OCT.2021 01:17:11

Band 7_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 20.OCT.2021 01:17:34

Band 7_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 20.OCT.2021 01:18:05

Band 7_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 20.OCT.2021 01:18:25

Band 7_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 20.OCT.2021 01:18:58

Band 7_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 20.OCT.2021 01:19:20

Band 7_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 20.OCT.2021 01:19:53

Band 7_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 20.OCT.2021 01:20:12


Band 41_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)



Band 41_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Band 41_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 20.OCT.2021 21:30:03

Band 41_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 20.OCT.2021 21:30:35

Band 41_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 20.OCT.2021 21:31:04

Band 41_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 20.OCT.2021 21:31:26

Band 41_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 20.OCT.2021 21:32:04

Band 41_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 20.OCT.2021 21:32:26

Band 41_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 20.OCT.2021 21:33:00

Band 41_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 20.OCT.2021 21:33:22


Band 41_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Band 41_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Band 41_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Band 41_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Band 41_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)



Band 41_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Band 41_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 20.OCT.2021 21:36:51

Band 41_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 20.OCT.2021 21:37:14

Band 41_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 20.OCT.2021 21:37:48

Band 41_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 20.OCT.2021 21:38:13

Band 41_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 20.OCT.2021 21:38:49

Band 41_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 20.OCT.2021 21:39:15

Band 41_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)



Date: 20.OCT.2021 21:39:47

Band 41_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)



Date: 20.OCT.2021 21:40:16