



Appendix C

Band 2_1.4 MHz_Low_QPSK_RB6#0




Date: 22.DEC.2021 14:12:03

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 22.DEC.2021 14:12:23

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 22.DEC.2021 14:12:44

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 22.DEC.2021 14:13:01

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 22.DEC.2021 14:13:19

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 22.DEC.2021 14:13:36

Band 2_3 MHz_High_QPSK_RB15#0




Date: 22.DEC.2021 14:13:56

Band 2_3 MHz_High_16QAM_RB15#0




Date: 22.DEC.2021 14:14:13

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 22.DEC.2021 14:14:31

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 22.DEC.2021 14:14:48

Band 2_5 MHz_High_QPSK_RB25#0




Date: 22.DEC.2021 14:15:05

Band 2_5 MHz_High_16QAM_RB25#0




Date: 22.DEC.2021 14:15:22

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 22.DEC.2021 14:15:43

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 22.DEC.2021 14:16:05

Band 2_10 MHz_High_QPSK_RB50#0




Date: 22.DEC.2021 14:16:24

Band 2_10 MHz_High_16QAM_RB50#0




Date: 22.DEC.2021 14:16:43

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 11.JAN.2022 18:10:03

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 22.DEC.2021 14:17:32

Band 2_15 MHz_High_QPSK_RB75#0




Date: 22.DEC.2021 14:18:11

Band 2_15 MHz_High_16QAM_RB75#0




Date: 22.DEC.2021 14:18:34

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 11.JAN.2022 18:11:23

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 11.JAN.2022 18:12:11

Band 2_20 MHz_High_QPSK_RB100#0




Date: 11.JAN.2022 18:13:24

Band 2_20 MHz_High_QPSK_RB100#0




Date: 11.JAN.2022 18:14:02

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 27.JAN.2022 10:04:21

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 27.JAN.2022 10:04:38

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 27.JAN.2022 10:04:59

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 27.JAN.2022 10:05:16

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 27.JAN.2022 13:43:58

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 27.JAN.2022 13:55:25

Band 5_3 MHz_High_QPSK_RB15#0




Date: 27.JAN.2022 10:06:26

Band 5_3 MHz_High_16QAM_RB15#0




Date: 27.JAN.2022 10:06:43

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 27.JAN.2022 13:49:14

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 27.JAN.2022 10:07:23

Band 5_5 MHz_High_QPSK_RB25#0




Date: 27.JAN.2022 10:07:40

Band 5_5 MHz_High_16QAM_RB25#0




Date: 27.JAN.2022 10:07:57

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 27.JAN.2022 13:50:56

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 27.JAN.2022 13:51:42

Band 5_10 MHz_High_QPSK_RB50#0




Date: 27.JAN.2022 10:08:59

Band 5_10 MHz_High_16QAM_RB50#0




Date: 27.JAN.2022 10:09:18

Band 12_1.4 MHz_Low_QPSK_RB6#0




Date: 27.JAN.2022 10:09:39

Band 12_1.4 MHz_Low_16QAM_RB6#0




Date: 27.JAN.2022 10:09:59

Band 12_1.4 MHz_High_QPSK_RB6#0




Date: 27.JAN.2022 10:10:16

Band 12_1.4 MHz_High_16QAM_RB6#0




Date: 27.JAN.2022 10:10:36

Band 12_3 MHz_Low_QPSK_RB15#0




Date: 27.JAN.2022 10:10:57

Band 12_3 MHz_Low_16QAM_RB15#0




Date: 27.JAN.2022 10:11:14

Band 12_3 MHz_High_QPSK_RB15#0




Date: 27.JAN.2022 10:11:35

Band 12_3 MHz_High_16QAM_RB15#0




Date: 27.JAN.2022 10:11:52

Band 12_5 MHz_Low_QPSK_RB25#0




Date: 27.JAN.2022 10:12:12

Band 12_5 MHz_Low_16QAM_RB25#0




Date: 27.JAN.2022 10:12:32

Band 12_5 MHz_High_QPSK_RB25#0




Date: 27.JAN.2022 10:12:50

Band 12_5 MHz_High_16QAM_RB25#0




Date: 27.JAN.2022 10:13:07

Band 12_10 MHz_Low_QPSK_RB50#0




Date: 27.JAN.2022 10:13:33

Band 12_10 MHz_Low_16QAM_RB50#0




Date: 27.JAN.2022 10:13:52

Band 12_10 MHz_High_QPSK_RB50#0




Date: 27.JAN.2022 10:14:12

Band 12_10 MHz_High_16QAM_RB50#0




Date: 27.JAN.2022 10:14:31

Band 41_5 MHz_Low_QPSK_RB25#0




Date: 23.DEC.2021 09:41:30

Band 41_5 MHz_Low_16QAM_RB25#0




Date: 23.DEC.2021 09:07:27

Band 41_5 MHz_High_QPSK_RB25#0




Date: 23.DEC.2021 09:42:49

Band 41_5 MHz_High_16QAM_RB25#0




Date: 23.DEC.2021 09:43:33

Band 41_10 MHz_Low_QPSK_RB50#0




Date: 23.DEC.2021 09:08:28

Band 41_10 MHz_Low_16QAM_RB50#0




Date: 23.DEC.2021 09:08:47

Band 41_10 MHz_High_QPSK_RB50#0




Date: 23.DEC.2021 09:09:10

Band 41_10 MHz_High_16QAM_RB50#0




Date: 23.DEC.2021 09:09:29

Band 41_15 MHz_Low_QPSK_RB75#0




Date: 23.DEC.2021 09:09:54

Band 41_15 MHz_Low_16QAM_RB75#0




Date: 23.DEC.2021 09:10:21

Band 41_15 MHz_High_QPSK_RB75#0




Date: 23.DEC.2021 09:58:00

Band 41_15 MHz_High_16QAM_RB75#0




Date: 23.DEC.2021 09:59:00

Band 41_20 MHz_Low_QPSK_RB100#0




Date: 23.DEC.2021 09:11:36

Band 41_20 MHz_Low_16QAM_RB100#0




Date: 23.DEC.2021 09:12:00

Band 41_20 MHz_High_QPSK_RB100#0



Date: 23.DEC.2021 09:12:24

Band 41_20 MHz_High_16QAM_RB100#0



Date: 23.DEC.2021 09:12:47