



Please refer to following plots:




Date: 13.JAN.2022 16:51:18




Date: 13.JAN.2022 16:51:38

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 13.JAN.2022 16:51:58

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 13.JAN.2022 16:52:18

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 13.JAN.2022 16:52:36

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 13.JAN.2022 16:52:53

Band 2_3 MHz_High_QPSK_RB15#0




Date: 13.JAN.2022 16:53:10

Band 2_3 MHz_High_16QAM_RB15#0




Date: 13.JAN.2022 16:53:30

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 13.JAN.2022 16:53:50

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 13.JAN.2022 16:54:07

Band 2_5 MHz_High_QPSK_RB25#0




Date: 14.JAN.2022 13:09:16

Band 2_5 MHz_High_16QAM_RB25#0




Date: 13.JAN.2022 16:54:44

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 13.JAN.2022 16:55:06

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 13.JAN.2022 16:55:25

Band 2_10 MHz_High_QPSK_RB50#0




Date: 13.JAN.2022 16:55:45

Band 2_10 MHz_High_16QAM_RB50#0




Date: 13.JAN.2022 16:56:04

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 13.JAN.2022 16:56:29

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 13.JAN.2022 16:56:52

Band 2_15 MHz_High_QPSK_RB75#0




Date: 14.JAN.2022 13:11:55

Band 2_15 MHz_High_16QAM_RB75#0




Date: 14.JAN.2022 13:11:07

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 13.JAN.2022 16:58:06

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 13.JAN.2022 16:58:29

Band 2_20 MHz_High_QPSK_RB100#0




Date: 13.JAN.2022 16:58:53

Band 2_20 MHz_High_16QAM_RB100#0




Date: 13.JAN.2022 16:59:20

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 13.JAN.2022 16:59:43

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 13.JAN.2022 17:00:00

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 13.JAN.2022 17:00:20

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 13.JAN.2022 17:00:40

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 13.JAN.2022 17:00:59

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 13.JAN.2022 17:01:16

Band 5_3 MHz_High_QPSK_RB15#0




Date: 13.JAN.2022 17:01:33

Band 5_3 MHz_High_16QAM_RB15#0




Date: 13.JAN.2022 17:01:53

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 14.JAN.2022 13:12:58

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 13.JAN.2022 17:02:29

Band 5_5 MHz_High_QPSK_RB25#0




Date: 13.JAN.2022 17:02:52


Band 5_5 MHz_High_16QAM_RB25#0



Date: 13.JAN.2022 17:03:12




Date: 13.JAN.2022 17:03:34




Date: 13.JAN.2022 17:03:53

Band 5_10 MHz_High_QPSK_RB50#0




Date: 13.JAN.2022 17:04:13

Band 5_10 MHz_High_16QAM_RB50#0




Date: 13.JAN.2022 17:04:32

Band 12_1.4 MHz_Low_QPSK_RB6#0




Date: 13.JAN.2022 17:04:58

Band 12_1.4 MHz_Low_16QAM_RB6#0




Date: 13.JAN.2022 17:05:21

Band 12_1.4 MHz_High_QPSK_RB6#0




Date: 13.JAN.2022 17:05:39


Band 12_1.4 MHz_High_16QAM_RB6#0



Date: 13.JAN.2022 17:06:02




Date: 13.JAN.2022 17:06:25




Date: 13.JAN.2022 17:06:45

Band 12_3 MHz_High_QPSK_RB15#0




Date: 13.JAN.2022 17:07:02

Band 12_3 MHz_High_16QAM_RB15#0




Date: 13.JAN.2022 17:07:19

Band 12_5 MHz_Low_QPSK_RB25#0




Date: 13.JAN.2022 17:07:42

Band 12_5 MHz_Low_16QAM_RB25#0




Date: 13.JAN.2022 17:08:01

Band 12_5 MHz_High_QPSK_RB25#0




Date: 13.JAN.2022 17:08:19

Band 12_5 MHz_High_16QAM_RB25#0




Date: 13.JAN.2022 17:08:39

Band 12_10 MHz_Low_QPSK_RB50#0




Date: 13.JAN.2022 17:09:01

Band 12_10 MHz_Low_16QAM_RB50#0




Date: 13.JAN.2022 17:09:20

Band 12_10 MHz_High_QPSK_RB50#0




Date: 13.JAN.2022 17:09:39

Band 12_10 MHz_High_16QAM_RB50#0




Date: 13.JAN.2022 17:09:58

Band 41_5 MHz_Low_QPSK_RB25#0




Date: 14.JAN.2022 13:20:38

Band 41_5 MHz_Low_16QAM_RB25#0




Date: 13.JAN.2022 18:46:47

Band 41_5 MHz_High_QPSK_RB25#0




Date: 14.JAN.2022 13:21:36


Band 41_5 MHz_High_16QAM_RB25#0



Date: 14.JAN.2022 13:22:16




Date: 13.JAN.2022 18:47:57




Date: 13.JAN.2022 18:48:19

Band 41_10 MHz_High_QPSK_RB50#0




Date: 13.JAN.2022 18:48:42


Band 41_10 MHz_High_16QAM_RB50#0



Date: 13.JAN.2022 18:49:01




Date: 14.JAN.2022 13:25:26




Date: 14.JAN.2022 13:27:30

Band 41_15 MHz_High_QPSK_RB75#0




Date: 14.JAN.2022 13:30:43

Band 41_15 MHz_High_16QAM_RB75#0




Date: 14.JAN.2022 13:31:23

Band 41_20 MHz_Low_QPSK_RB100#0




Date: 13.JAN.2022 18:51:39

Band 41_20 MHz_Low_16QAM_RB100#0




Date: 13.JAN.2022 18:52:06

Band 41_20 MHz_High_QPSK_RB100#0



Date: 13.JAN.2022 18:52:33

Band 41_20 MHz_High_16QAM_RB100#0



Date: 13.JAN.2022 18:53:00