



Please refer to following plots:




Date: 12.NOV.2022 11:45:43




Date: 12.NOV.2022 11:45:54

Band 2_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 12.NOV.2022 11:46:08

Band 2_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 12.NOV.2022 11:46:19

Band 2_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 12.NOV.2022 11:46:32

Band 2_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 12.NOV.2022 11:46:43

Band 2_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 12.NOV.2022 11:46:59

Band 2_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 12.NOV.2022 11:47:11

Band 2_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 12.NOV.2022 11:47:24

Band 2_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 12.NOV.2022 11:47:35

Band 2_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 12.NOV.2022 11:47:49

Band 2_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 12.NOV.2022 11:48:00

Band 2_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 12.NOV.2022 11:48:16

Band 2_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 12.NOV.2022 11:48:27

Band 2_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 12.NOV.2022 11:48:41

Band 2_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 12.NOV.2022 11:48:52

Band 2_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 12.NOV.2022 11:49:06

Band 2_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 12.NOV.2022 11:49:17

Band 2_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 12.NOV.2022 11:49:36

Band 2_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 12.NOV.2022 11:49:47

Band 2_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 12.NOV.2022 11:50:01

Band 2_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 12.NOV.2022 11:50:16

Band 2_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 12.NOV.2022 11:50:30

Band 2_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 12.NOV.2022 11:50:41

Band 2_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 12.NOV.2022 11:51:01

Band 2_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 12.NOV.2022 11:51:12

Band 2_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 12.NOV.2022 11:51:27

Band 2_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 12.NOV.2022 11:51:38

Band 2_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 12.NOV.2022 11:51:55

Band 2_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 12.NOV.2022 11:52:06

Band 2_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 12.NOV.2022 11:52:24

Band 2_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 12.NOV.2022 11:52:35

Band 2_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 12.NOV.2022 11:52:52

Band 2_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 12.NOV.2022 11:53:03

Band 2_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 12.NOV.2022 11:53:18

Band 2_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 12.NOV.2022 11:53:29

Band 5_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 12.NOV.2022 13:47:33

Band 5_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 12.NOV.2022 13:47:44

Band 5_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 12.NOV.2022 13:47:58

Band 5_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 12.NOV.2022 13:48:09

Band 5_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 12.NOV.2022 13:48:22

Band 5_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 12.NOV.2022 13:48:33

Band 5_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 12.NOV.2022 13:48:50

Band 5_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 12.NOV.2022 13:49:01

Band 5_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 12.NOV.2022 13:49:17

Band 5_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 12.NOV.2022 13:49:28

Band 5_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 12.NOV.2022 13:49:42

Band 5_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 12.NOV.2022 13:49:53

Band 5_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 12.NOV.2022 13:50:13

Band 5_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 12.NOV.2022 13:50:24

Band 5_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 12.NOV.2022 13:50:41

Band 5_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 12.NOV.2022 13:50:52

Band 5_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 12.NOV.2022 13:51:09

Band 5_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 12.NOV.2022 13:51:20

Band 5_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 12.NOV.2022 13:51:36

Band 5_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 12.NOV.2022 13:51:47

Band 5_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 12.NOV.2022 13:52:05

Band 5_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 12.NOV.2022 13:52:16

Band 5_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 12.NOV.2022 13:52:33

Band 5_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 12.NOV.2022 13:52:44

Band 12_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 12.NOV.2022 13:53:05

Band 12_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 12.NOV.2022 13:53:16

Band 12_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 12.NOV.2022 13:53:36

Band 12_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 12.NOV.2022 13:53:47

Band 12_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 12.NOV.2022 13:54:01

Band 12_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 12.NOV.2022 13:54:12

Band 12_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 12.NOV.2022 13:54:31

Band 12_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 12.NOV.2022 13:54:42

Band 12_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 12.NOV.2022 13:54:55

Band 12_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 12.NOV.2022 13:55:06

Band 12_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 12.NOV.2022 13:55:23

Band 12_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 12.NOV.2022 13:55:34

Band 12_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 12.NOV.2022 13:55:53

Band 12_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 12.NOV.2022 13:56:04

Band 12_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 12.NOV.2022 13:56:21

Band 12_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 12.NOV.2022 13:56:32

Band 12_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 12.NOV.2022 13:56:49

Band 12_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 12.NOV.2022 13:57:00

Band 12_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 12.NOV.2022 13:57:16

Band 12_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 12.NOV.2022 13:57:27

Band 12_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 12.NOV.2022 13:57:41

Band 12_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 12.NOV.2022 13:57:52

Band 12_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 12.NOV.2022 13:58:06

Band 12_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 12.NOV.2022 13:58:18

Band 7_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 12.NOV.2022 15:26:25

Band 7_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 12.NOV.2022 15:26:36

Band 7_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 12.NOV.2022 15:26:50

Band 7_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 12.NOV.2022 15:27:01

Band 7_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 12.NOV.2022 15:27:14

Band 7_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 12.NOV.2022 15:27:25

Band 7_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 12.NOV.2022 15:27:40

Band 7_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 12.NOV.2022 15:27:51

Band 7_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 12.NOV.2022 15:28:04

Band 7_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 12.NOV.2022 15:28:15

Band 7_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 12.NOV.2022 15:28:32

Band 7_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 12.NOV.2022 15:28:43

Band 7_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 12.NOV.2022 15:28:58

Band 7_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 12.NOV.2022 15:29:09

Band 7_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 12.NOV.2022 15:29:23

Band 7_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 12.NOV.2022 15:29:34

Band 7_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 12.NOV.2022 15:29:51

Band 7_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 12.NOV.2022 15:30:02

Band 7_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 12.NOV.2022 15:30:17

Band 7_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 12.NOV.2022 15:30:28

Band 7_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 12.NOV.2022 15:30:45

Band 7_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 12.NOV.2022 15:30:56

Band 7_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 12.NOV.2022 15:31:10

Band 7_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 12.NOV.2022 15:31:21

Band 41_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 12.NOV.2022 16:10:17

Band 41_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 12.NOV.2022 16:10:28

Band 41_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 12.NOV.2022 16:10:41

Band 41_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 12.NOV.2022 16:10:52

Band 41_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 12.NOV.2022 16:11:09

Band 41_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 12.NOV.2022 16:11:19

Band 41_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 12.NOV.2022 16:11:35

Band 41_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 12.NOV.2022 16:11:49

Band 41_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 12.NOV.2022 16:12:03

Band 41_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 12.NOV.2022 16:12:14

Band 41_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 12.NOV.2022 16:12:28

Band 41_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 12.NOV.2022 16:12:38

Band 41_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 12.NOV.2022 16:12:56

Band 41_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 12.NOV.2022 16:13:07

Band 41_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 12.NOV.2022 16:13:21

Band 41_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 12.NOV.2022 16:13:32

Band 41_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 12.NOV.2022 16:13:46

Band 41_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 12.NOV.2022 16:13:56

Band 41_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 12.NOV.2022 16:14:13

Band 41_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 12.NOV.2022 16:14:24

Band 41_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 12.NOV.2022 16:14:38

Band 41_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 12.NOV.2022 16:14:49

Band 41_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)



Date: 12.NOV.2022 16:15:03

Band 41_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)



Date: 12.NOV.2022 16:15:14