



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0




Date: 30.AUG.2022 17:44:02

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 30.AUG.2022 17:44:17

Band 2_1.4 MHz_Middle_QPSK_RB6#0




Date: 30.AUG.2022 17:44:39

Band 2_1.4 MHz_Middle_16QAM_RB6#0




Date: 30.AUG.2022 17:44:56

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 30.AUG.2022 17:45:14

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 30.AUG.2022 17:45:32

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 30.AUG.2022 17:50:44

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 30.AUG.2022 17:51:00

Band 2_3 MHz_Middle_QPSK_RB15#0




Date: 30.AUG.2022 17:51:19

Band 2_3 MHz_Middle_16QAM_RB15#0




Date: 30.AUG.2022 17:51:34

Band 2_3 MHz_High_QPSK_RB15#0




Date: 30.AUG.2022 17:51:50

Band 2_3 MHz_High_16QAM_RB15#0




Date: 30.AUG.2022 17:52:08

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 30.AUG.2022 17:53:42

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 30.AUG.2022 17:54:04

Band 2_5 MHz_Middle_QPSK_RB25#0




Date: 30.AUG.2022 17:54:23

Band 2_5 MHz_Middle_16QAM_RB25#0




Date: 30.AUG.2022 17:54:42

Band 2_5 MHz_High_QPSK_RB25#0




Date: 30.AUG.2022 17:55:08

Band 2_5 MHz_High_16QAM_RB25#0




Date: 30.AUG.2022 17:55:30

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 30.AUG.2022 17:56:16

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 30.AUG.2022 17:56:36

Band 2_10 MHz_Middle_QPSK_RB50#0




Date: 30.AUG.2022 17:56:59

Band 2_10 MHz_Middle_16QAM_RB50#0




Date: 30.AUG.2022 17:57:18

Band 2_10 MHz_High_QPSK_RB50#0




Date: 30.AUG.2022 17:57:35

Band 2_10 MHz_High_16QAM_RB50#0




Date: 30.AUG.2022 17:57:54

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 30.AUG.2022 17:59:34

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 30.AUG.2022 17:59:56

Band 2_15 MHz_Middle_QPSK_RB75#0




Date: 30.AUG.2022 18:00:22

Band 2_15 MHz_Middle_16QAM_RB75#0




Date: 30.AUG.2022 18:00:44

Band 2_15 MHz_High_QPSK_RB75#0




Date: 30.AUG.2022 18:01:06

Band 2_15 MHz_High_16QAM_RB75#0




Date: 30.AUG.2022 18:01:28

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 30.AUG.2022 18:02:16

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 30.AUG.2022 18:02:39

Band 2_20 MHz_Middle_QPSK_RB100#0




Date: 30.AUG.2022 18:03:02

Band 2_20 MHz_Middle_16QAM_RB100#0




Date: 30.AUG.2022 18:03:21

Band 2_20 MHz_High_QPSK_RB100#0




Date: 30.AUG.2022 18:03:44

Band 2_20 MHz_High_16QAM_RB100#0




Date: 30.AUG.2022 18:04:07

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 30.AUG.2022 19:04:22

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 30.AUG.2022 19:04:40

Band 5_1.4 MHz_Middle_QPSK_RB6#0




Date: 30.AUG.2022 19:04:55

Band 5_1.4 MHz_Middle_16QAM_RB6#0




Date: 30.AUG.2022 19:05:13

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 30.AUG.2022 19:05:28

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 30.AUG.2022 19:05:42

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 30.AUG.2022 19:06:22

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 30.AUG.2022 19:06:37

Band 5_3 MHz_Middle_QPSK_RB15#0




Date: 30.AUG.2022 19:06:55

Band 5_3 MHz_Middle_16QAM_RB15#0




Date: 30.AUG.2022 19:07:12

Band 5_3 MHz_High_QPSK_RB15#0




Date: 30.AUG.2022 19:07:27

Band 5_3 MHz_High_16QAM_RB15#0




Date: 30.AUG.2022 19:07:41

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 30.AUG.2022 19:08:40

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 30.AUG.2022 19:08:58

Band 5_5 MHz_Middle_QPSK_RB25#0




Date: 30.AUG.2022 19:09:18

Band 5_5 MHz_Middle_16QAM_RB25#0




Date: 30.AUG.2022 19:09:36

Band 5_5 MHz_High_QPSK_RB25#0




Date: 30.AUG.2022 19:09:52

Band 5_5 MHz_High_16QAM_RB25#0




Date: 30.AUG.2022 19:10:08

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 30.AUG.2022 19:11:18

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 30.AUG.2022 19:11:38

Band 5_10 MHz_Middle_QPSK_RB50#0




Date: 30.AUG.2022 19:12:01

Band 5_10 MHz_Middle_16QAM_RB50#0




Date: 30.AUG.2022 19:12:20

Band 5_10 MHz_High_QPSK_RB50#0




Date: 30.AUG.2022 19:12:40

Band 5_10 MHz_High_16QAM_RB50#0




Date: 30.AUG.2022 19:12:59

Band 12_1.4 MHz_Low_QPSK_RB6#0




Date: 30.AUG.2022 19:13:29

Band 12_1.4 MHz_Low_16QAM_RB6#0




Date: 30.AUG.2022 19:13:44

Band 12_1.4 MHz_Middle_QPSK_RB6#0




Date: 30.AUG.2022 19:14:03

Band 12_1.4 MHz_Middle_16QAM_RB6#0




Date: 30.AUG.2022 19:14:21

Band 12_1.4 MHz_High_QPSK_RB6#0




Date: 30.AUG.2022 19:14:39

Band 12_1.4 MHz_High_16QAM_RB6#0




Date: 30.AUG.2022 19:14:54

Band 12_3 MHz_Low_QPSK_RB15#0




Date: 30.AUG.2022 19:15:57

Band 12_3 MHz_Low_16QAM_RB15#0




Date: 30.AUG.2022 19:16:12

Band 12_3 MHz_Middle_QPSK_RB15#0




Date: 30.AUG.2022 19:16:27

Band 12_3 MHz_Middle_16QAM_RB15#0




Date: 30.AUG.2022 19:16:42

Band 12_3 MHz_High_QPSK_RB15#0




Date: 30.AUG.2022 19:16:58

Band 12_3 MHz_High_16QAM_RB15#0




Date: 30.AUG.2022 19:17:13

Band 12_5 MHz_Low_QPSK_RB25#0




Date: 30.AUG.2022 19:18:24

Band 12_5 MHz_Low_16QAM_RB25#0




Date: 30.AUG.2022 19:18:43

Band 12_5 MHz_Middle_QPSK_RB25#0




Date: 30.AUG.2022 19:19:02

Band 12_5 MHz_Middle_16QAM_RB25#0




Date: 30.AUG.2022 19:19:21

Band 12_5 MHz_High_QPSK_RB25#0




Date: 30.AUG.2022 19:19:45

Band 12_5 MHz_High_16QAM_RB25#0




Date: 30.AUG.2022 19:20:04

Band 12_10 MHz_Low_QPSK_RB50#0




Date: 30.AUG.2022 19:20:46

Band 12_10 MHz_Low_16QAM_RB50#0




Date: 30.AUG.2022 19:21:06

Band 12_10 MHz_Middle_QPSK_RB50#0




Date: 30.AUG.2022 19:21:26

Band 12_10 MHz_Middle_16QAM_RB50#0




Date: 30.AUG.2022 19:21:45

Band 12_10 MHz_High_QPSK_RB50#0




Date: 30.AUG.2022 19:22:05

Band 12_10 MHz_High_16QAM_RB50#0




Date: 30.AUG.2022 19:22:21

Band 13_5 MHz_Low_QPSK_RB25#0




Date: 30.AUG.2022 19:22:55

Band 13_5 MHz_Low_16QAM_RB25#0




Date: 30.AUG.2022 19:23:13

Band 13_5 MHz_Middle_QPSK_RB25#0




Date: 30.AUG.2022 19:23:33

Band 13_5 MHz_Middle_16QAM_RB25#0




Date: 30.AUG.2022 19:23:48

Band 13_5 MHz_High_QPSK_RB25#0




Date: 30.AUG.2022 19:24:08

Band 13_5 MHz_High_16QAM_RB25#0




Date: 30.AUG.2022 19:24:27

Band 13_10 MHz_Middle_QPSK_RB50#0




Date: 30.AUG.2022 19:25:35

Band 13_10 MHz_Middle_16QAM_RB50#0




Date: 30.AUG.2022 19:25:54

Band 41_5 MHz_Low_QPSK_RB25#0




Date: 10.SEP.2022 09:36:56

Band 41_5 MHz_Low_16QAM_RB25#0




Date: 10.SEP.2022 09:37:25

Band 41_5 MHz_Middle_QPSK_RB25#0




Date: 10.SEP.2022 09:37:48

Band 41_5 MHz_Middle_16QAM_RB25#0




Date: 10.SEP.2022 09:38:07

Band 41_5 MHz_High_QPSK_RB25#0




Date: 10.SEP.2022 09:38:32

Band 41_5 MHz_High_16QAM_RB25#0




Date: 10.SEP.2022 09:38:54

Band 41_10 MHz_Low_QPSK_RB50#0




Date: 10.SEP.2022 09:40:02

Band 41_10 MHz_Low_16QAM_RB50#0




Date: 10.SEP.2022 09:40:22

Band 41_10 MHz_Middle_QPSK_RB50#0




Date: 10.SEP.2022 09:40:38

Band 41_10 MHz_Middle_16QAM_RB50#0




Date: 10.SEP.2022 09:40:58

Band 41_10 MHz_High_QPSK_RB50#0




Date: 10.SEP.2022 09:41:18

Band 41_10 MHz_High_16QAM_RB50#0




Date: 10.SEP.2022 09:41:37

Band 41_15 MHz_Low_QPSK_RB75#0




Date: 10.SEP.2022 09:42:24

Band 41_15 MHz_Low_16QAM_RB75#0




Date: 10.SEP.2022 09:42:46

Band 41_15 MHz_Middle_QPSK_RB75#0




Date: 10.SEP.2022 09:43:09

Band 41_15 MHz_Middle_16QAM_RB75#0




Date: 10.SEP.2022 09:43:41

Band 41_15 MHz_High_QPSK_RB75#0




Date: 10.SEP.2022 09:44:13

Band 41_15 MHz_High_16QAM_RB75#0




Date: 12.SEP.2022 16:25:27

Band 41_20 MHz_Low_QPSK_RB100#0




Date: 10.SEP.2022 09:45:50

Band 41_20 MHz_Low_16QAM_RB100#0




Date: 10.SEP.2022 09:46:16

Band 41_20 MHz_Middle_QPSK_RB100#0




Date: 10.SEP.2022 09:46:36

Band 41_20 MHz_Middle_16QAM_RB100#0




Date: 10.SEP.2022 09:46:58

Band 41_20 MHz_High_QPSK_RB100#0



Date: 10.SEP.2022 09:47:24

Band 41_20 MHz_High_16QAM_RB100#0



Date: 12.SEP.2022 16:29:05