



Please refer to following plots:

### Band 2\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 19.MAY.2023 19:17:28

### Band 2\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 19.MAY.2023 19:17:45

### Band 2\_1.4 MHz\_Middle\_QPSK\_RB6#0




Date: 19.MAY.2023 19:18:02

### Band 2\_1.4 MHz\_Middle\_16QAM\_RB6#0




Date: 19.MAY.2023 19:18:18

### Band 2\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 19.MAY.2023 19:18:35

### Band 2\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 19.MAY.2023 19:18:52

### Band 2\_3 MHz\_Low\_QPSK\_RB15#0




Date: 19.MAY.2023 19:19:09

### Band 2\_3 MHz\_Low\_16QAM\_RB15#0




Date: 19.MAY.2023 19:19:26

### Band 2\_3 MHz\_Middle\_QPSK\_RB15#0




Date: 19.MAY.2023 19:19:40

### Band 2\_3 MHz\_Middle\_16QAM\_RB15#0




Date: 19.MAY.2023 19:19:53

### Band 2\_3 MHz\_High\_QPSK\_RB15#0




Date: 19.MAY.2023 19:20:07

### Band 2\_3 MHz\_High\_16QAM\_RB15#0




Date: 19.MAY.2023 19:20:24

### Band 2\_5 MHz\_Low\_QPSK\_RB25#0




Date: 19.MAY.2023 19:20:48

### Band 2\_5 MHz\_Low\_16QAM\_RB25#0




Date: 19.MAY.2023 19:21:08

### Band 2\_5 MHz\_Middle\_QPSK\_RB25#0



Date: 19.MAY.2023 19:21:28


### Band 2\_5 MHz\_Middle\_16QAM\_RB25#0



Date: 19.MAY.2023 19:21:48




### Band 2\_5 MHz\_High\_QPSK\_RB25#0




Date: 19.MAY.2023 19:22:15

### Band 2\_5 MHz\_High\_16QAM\_RB25#0




Date: 19.MAY.2023 19:22:38

### Band 2\_10 MHz\_Low\_QPSK\_RB50#0




Date: 19.MAY.2023 19:22:56

### Band 2\_10 MHz\_Low\_16QAM\_RB50#0




Date: 19.MAY.2023 19:23:10

### Band 2\_10 MHz\_Middle\_QPSK\_RB50#0




Date: 19.MAY.2023 19:23:27

### Band 2\_10 MHz\_Middle\_16QAM\_RB50#0




Date: 19.MAY.2023 19:23:44

### Band 2\_10 MHz\_High\_QPSK\_RB50#0




Date: 19.MAY.2023 19:24:01

### Band 2\_10 MHz\_High\_16QAM\_RB50#0




Date: 19.MAY.2023 19:24:18

### Band 2\_15 MHz\_Low\_QPSK\_RB75#0




Date: 19.MAY.2023 19:24:44

### Band 2\_15 MHz\_Low\_16QAM\_RB75#0




Date: 19.MAY.2023 19:25:04

### Band 2\_15 MHz\_Middle\_QPSK\_RB75#0




Date: 19.MAY.2023 19:25:23

### Band 2\_15 MHz\_Middle\_16QAM\_RB75#0




Date: 19.MAY.2023 19:25:47

### Band 2\_15 MHz\_High\_QPSK\_RB75#0




Date: 19.MAY.2023 19:26:02

### Band 2\_15 MHz\_High\_16QAM\_RB75#0




Date: 19.MAY.2023 19:26:23

### Band 2\_20 MHz\_Low\_QPSK\_RB100#0



Date: 19.MAY.2023 19:26:49


### Band 2\_20 MHz\_Low\_16QAM\_RB100#0



Date: 19.MAY.2023 19:27:07




### Band 2\_20 MHz\_Middle\_QPSK\_RB100#0




Date: 19.MAY.2023 19:27:29

### Band 2\_20 MHz\_Middle\_16QAM\_RB100#0




Date: 19.MAY.2023 19:27:49

### Band 2\_20 MHz\_High\_QPSK\_RB100#0




Date: 19.MAY.2023 19:28:08

### Band 2\_20 MHz\_High\_16QAM\_RB100#0




Date: 19.MAY.2023 19:28:26

### Band 5\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 19.MAY.2023 19:48:28

### Band 5\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 19.MAY.2023 19:48:45

### Band 5\_1.4 MHz\_Middle\_QPSK\_RB6#0




Date: 19.MAY.2023 19:49:05

### Band 5\_1.4 MHz\_Middle\_16QAM\_RB6#0




Date: 19.MAY.2023 19:49:21

### Band 5\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 19.MAY.2023 19:49:45

### Band 5\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 19.MAY.2023 19:50:04

### Band 5\_3 MHz\_Low\_QPSK\_RB15#0




Date: 19.MAY.2023 19:50:25

### Band 5\_3 MHz\_Low\_16QAM\_RB15#0




Date: 19.MAY.2023 19:50:38

### Band 5\_3 MHz\_Middle\_QPSK\_RB15#0




Date: 19.MAY.2023 19:50:55

### Band 5\_3 MHz\_Middle\_16QAM\_RB15#0




Date: 19.MAY.2023 19:51:12

### Band 5\_3 MHz\_High\_QPSK\_RB15#0



Date: 19.MAY.2023 19:51:29


### Band 5\_3 MHz\_High\_16QAM\_RB15#0



Date: 19.MAY.2023 19:51:42




### Band 5\_5 MHz\_Low\_QPSK\_RB25#0




Date: 19.MAY.2023 19:52:04

### Band 5\_5 MHz\_Low\_16QAM\_RB25#0




Date: 19.MAY.2023 19:52:24

### Band 5\_5 MHz\_Middle\_QPSK\_RB25#0




Date: 19.MAY.2023 19:52:47

### Band 5\_5 MHz\_Middle\_16QAM\_RB25#0




Date: 19.MAY.2023 19:53:10

### Band 5\_5 MHz\_High\_QPSK\_RB25#0




Date: 19.MAY.2023 19:53:34

### Band 5\_5 MHz\_High\_16QAM\_RB25#0




Date: 19.MAY.2023 19:53:57

### Band 5\_10 MHz\_Low\_QPSK\_RB50#0




Date: 19.MAY.2023 19:54:18

### Band 5\_10 MHz\_Low\_16QAM\_RB50#0




Date: 19.MAY.2023 19:54:31

### Band 5\_10 MHz\_Middle\_QPSK\_RB50#0




Date: 19.MAY.2023 19:54:49

### Band 5\_10 MHz\_Middle\_16QAM\_RB50#0




Date: 19.MAY.2023 19:55:05

### Band 5\_10 MHz\_High\_QPSK\_RB50#0




Date: 19.MAY.2023 19:55:23

### Band 5\_10 MHz\_High\_16QAM\_RB50#0




Date: 19.MAY.2023 19:55:40

### Band 12\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 19.MAY.2023 19:56:09

### Band 12\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 19.MAY.2023 19:56:22

### Band 12\_1.4 MHz\_Middle\_QPSK\_RB6#0



Date: 19.MAY.2023 19:56:36


### Band 12\_1.4 MHz\_Middle\_16QAM\_RB6#0



Date: 19.MAY.2023 19:56:53




### Band 12\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 19.MAY.2023 19:57:13

### Band 12\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 19.MAY.2023 19:57:32

### Band 12\_3 MHz\_Low\_QPSK\_RB15#0




Date: 19.MAY.2023 19:57:53

### Band 12\_3 MHz\_Low\_16QAM\_RB15#0




Date: 19.MAY.2023 19:58:10

### Band 12\_3 MHz\_Middle\_QPSK\_RB15#0




Date: 19.MAY.2023 19:58:24

### Band 12\_3 MHz\_Middle\_16QAM\_RB15#0




Date: 19.MAY.2023 19:58:40

### Band 12\_3 MHz\_High\_QPSK\_RB15#0




Date: 19.MAY.2023 19:58:54

### Band 12\_3 MHz\_High\_16QAM\_RB15#0




Date: 19.MAY.2023 19:59:07

### Band 12\_5 MHz\_Low\_QPSK\_RB25#0




Date: 19.MAY.2023 19:59:35

### Band 12\_5 MHz\_Low\_16QAM\_RB25#0




Date: 19.MAY.2023 19:59:54

### Band 12\_5 MHz\_Middle\_QPSK\_RB25#0




Date: 19.MAY.2023 20:00:21

### Band 12\_5 MHz\_Middle\_16QAM\_RB25#0




Date: 19.MAY.2023 20:00:44

### Band 12\_5 MHz\_High\_QPSK\_RB25#0




Date: 19.MAY.2023 20:01:05

### Band 12\_5 MHz\_High\_16QAM\_RB25#0




Date: 19.MAY.2023 20:01:24

### Band 12\_10 MHz\_Low\_QPSK\_RB50#0



Date: 19.MAY.2023 20:01:43


### Band 12\_10 MHz\_Low\_16QAM\_RB50#0



Date: 19.MAY.2023 20:01:59




### Band 12\_10 MHz\_Middle\_QPSK\_RB50#0




Date: 19.MAY.2023 20:02:17

### Band 12\_10 MHz\_Middle\_16QAM\_RB50#0




Date: 19.MAY.2023 20:02:30

### Band 12\_10 MHz\_High\_QPSK\_RB50#0




Date: 19.MAY.2023 20:02:48

### Band 12\_10 MHz\_High\_16QAM\_RB50#0




Date: 19.MAY.2023 20:03:01

### Band 7\_5 MHz\_Low\_QPSK\_RB25#0




Date: 19.MAY.2023 00:55:43

### Band 7\_5 MHz\_Low\_16QAM\_RB25#0




Date: 19.MAY.2023 00:56:03

### Band 7\_5 MHz\_Middle\_QPSK\_RB25#0




Date: 19.MAY.2023 00:56:21

### Band 7\_5 MHz\_Middle\_16QAM\_RB25#0




Date: 19.MAY.2023 00:56:38

### Band 7\_5 MHz\_High\_QPSK\_RB25#0




Date: 19.MAY.2023 00:56:55

### Band 7\_5 MHz\_High\_16QAM\_RB25#0




Date: 19.MAY.2023 00:57:15

### Band 7\_10 MHz\_Low\_QPSK\_RB50#0




Date: 19.MAY.2023 00:57:37

### Band 7\_10 MHz\_Low\_16QAM\_RB50#0




Date: 19.MAY.2023 00:57:54

### Band 7\_10 MHz\_Middle\_QPSK\_RB50#0




Date: 19.MAY.2023 00:58:08

### Band 7\_10 MHz\_Middle\_16QAM\_RB50#0




Date: 19.MAY.2023 00:58:25

### Band 7\_10 MHz\_High\_QPSK\_RB50#0



Date: 19.MAY.2023 18:27:29


### Band 7\_10 MHz\_High\_16QAM\_RB50#0



Date: 19.MAY.2023 18:27:47




### Band 7\_15 MHz\_Low\_QPSK\_RB75#0




Date: 19.MAY.2023 18:28:13

### Band 7\_15 MHz\_Low\_16QAM\_RB75#0




Date: 19.MAY.2023 18:28:35

### Band 7\_15 MHz\_Middle\_QPSK\_RB75#0




Date: 19.MAY.2023 18:28:58

### Band 7\_15 MHz\_Middle\_16QAM\_RB75#0




Date: 19.MAY.2023 18:29:23

### Band 7\_15 MHz\_High\_QPSK\_RB75#0




Date: 19.MAY.2023 18:29:50

### Band 7\_15 MHz\_High\_16QAM\_RB75#0




Date: 19.MAY.2023 18:30:12

### Band 7\_20 MHz\_Low\_QPSK\_RB100#0




Date: 19.MAY.2023 18:30:35

### Band 7\_20 MHz\_Low\_16QAM\_RB100#0




Date: 19.MAY.2023 18:30:54

### Band 7\_20 MHz\_Middle\_QPSK\_RB100#0




Date: 19.MAY.2023 18:31:11

### Band 7\_20 MHz\_Middle\_16QAM\_RB100#0




Date: 19.MAY.2023 18:31:30

### Band 7\_20 MHz\_High\_QPSK\_RB100#0




Date: 19.MAY.2023 18:31:47

### Band 7\_20 MHz\_High\_16QAM\_RB100#0




Date: 19.MAY.2023 18:32:06

### Band 41\_5 MHz\_Low\_QPSK\_RB25#0




Date: 19.MAY.2023 00:10:29

### Band 41\_5 MHz\_Low\_16QAM\_RB25#0




Date: 19.MAY.2023 00:10:47

### Band 41\_5 MHz\_Middle\_QPSK\_RB25#0



Date: 19.MAY.2023 00:11:04


### Band 41\_5 MHz\_Middle\_16QAM\_RB25#0



Date: 19.MAY.2023 00:11:24




### Band 41\_5 MHz\_High\_QPSK\_RB25#0




Date: 19.MAY.2023 00:11:42

### Band 41\_5 MHz\_High\_16QAM\_RB25#0




Date: 19.MAY.2023 00:11:59

### Band 41\_10 MHz\_Low\_QPSK\_RB50#0




Date: 19.MAY.2023 00:12:20

### Band 41\_10 MHz\_Low\_16QAM\_RB50#0




Date: 19.MAY.2023 00:12:36

### Band 41\_10 MHz\_Middle\_QPSK\_RB50#0




Date: 19.MAY.2023 00:12:54

### Band 41\_10 MHz\_Middle\_16QAM\_RB50#0




Date: 19.MAY.2023 00:13:11

### Band 41\_10 MHz\_High\_QPSK\_RB50#0




Date: 19.MAY.2023 00:13:28

### Band 41\_10 MHz\_High\_16QAM\_RB50#0




Date: 19.MAY.2023 00:13:45

### Band 41\_15 MHz\_Low\_QPSK\_RB75#0




Date: 19.MAY.2023 00:14:04

### Band 41\_15 MHz\_Low\_16QAM\_RB75#0




Date: 19.MAY.2023 00:14:22

### Band 41\_15 MHz\_Middle\_QPSK\_RB75#0




Date: 19.MAY.2023 00:14:44

### Band 41\_15 MHz\_Middle\_16QAM\_RB75#0




Date: 19.MAY.2023 00:15:02

### Band 41\_15 MHz\_High\_QPSK\_RB75#0




Date: 19.MAY.2023 00:15:17

### Band 41\_15 MHz\_High\_16QAM\_RB75#0




Date: 19.MAY.2023 00:15:32

### Band 41\_20 MHz\_Low\_QPSK\_RB100#0



Date: 19.MAY.2023 00:15:51


### Band 41\_20 MHz\_Low\_16QAM\_RB100#0



Date: 19.MAY.2023 00:16:09




### Band 41\_20 MHz\_Middle\_QPSK\_RB100#0




Date: 19.MAY.2023 00:16:28

### Band 41\_20 MHz\_Middle\_16QAM\_RB100#0




Date: 19.MAY.2023 00:16:46

### Band 41\_20 MHz\_High\_QPSK\_RB100#0



Date: 19.MAY.2023 00:17:04

### Band 41\_20 MHz\_High\_16QAM\_RB100#0



Date: 19.MAY.2023 00:17:25