



n41

10MHz\_30kHz\_2501.01MHz\_DFT-s-OFDM QPSK\_RB1@0&20.13 dBm




Date: 31.JAN.2024 23:50:55

10MHz\_30kHz\_2501.01MHz\_DFT-s-OFDM QPSK\_RB24@0&-16.03 dBm




Date: 31.JAN.2024 23:51:48

10MHz\_30kHz\_2685MHz\_DFT-s-OFDM QPSK\_RB1@23&-42.42 dBm




Date: 31.JAN.2024 23:52:54

10MHz\_30kHz\_2685MHz\_DFT-s-OFDM QPSK\_RB24@0&-16.95 dBm




Date: 31.JAN.2024 23:53:49

15MHz\_30kHz\_2503.5MHz\_DFT-s-OFDM QPSK\_RB1@0&19.79 dBm




Date: 31.JAN.2024 23:56:36

15MHz\_30kHz\_2503.5MHz\_DFT-s-OFDM QPSK\_RB36@0&-27.57 dBm




Date: 31.JAN.2024 23:57:29

15MHz\_30kHz\_2682.48MHz\_DFT-s-OFDM QPSK\_RB1@37&-42.48 dBm




Date: 31.JAN.2024 23:58:30

15MHz\_30kHz\_2682.48MHz\_DFT-s-OFDM QPSK\_RB36@0&-17.95 dBm




Date: 1.FEB.2024 00:01:31

20MHz\_30kHz\_2506.02MHz\_DFT-s-OFDM QPSK\_RB1@0&18.51 dBm




Date: 1.FEB.2024 00:05:52

20MHz\_30kHz\_2506.02MHz\_DFT-s-OFDM QPSK\_RB50@0&-29.03 dBm




Date: 1.FEB.2024 00:06:50

20MHz\_30kHz\_2679.99MHz\_DFT-s-OFDM QPSK\_RB1@50&-42.44 dBm



Date: 1.FEB.2024 00:09:01

20MHz\_30kHz\_2679.99MHz\_DFT-s-OFDM QPSK\_RB50@0&-18.99 dBm



Date: 1.FEB.2024 00:09:00