



100MHz\_30kHz\_2546.01MHz\_DFT-s-OFDM QPSK\_RB1@0&-21.07 dBm




Date: 1.FEB.2024 00:55:56

100MHz\_30kHz\_2546.01MHz\_DFT-s-OFDM QPSK\_RB270@0&-16.88 dBm




Date: 1.FEB.2024 00:56:48

100MHz\_30kHz\_2640MHz\_DFT-s-OFDM QPSK\_RB1@272&-18.89 dBm




Date: 1.FEB.2024 00:58:20

100MHz\_30kHz\_2640MHz\_DFT-s-OFDM QPSK\_RB270@0&-23.38 dBm




Date: 1.FEB.2024 00:59:16

5MHz\_15kHz\_1712.5MHz\_DFT-s-OFDM QPSK\_RB1@0&-16.47 dBm




Date: 31.JAN.2024 20:12:51

5MHz\_15kHz\_1712.5MHz\_DFT-s-OFDM QPSK\_RB25@0&-22.14 dBm




Date: 31.JAN.2024 20:13:30

5MHz\_15kHz\_1777.5MHz\_DFT-s-OFDM QPSK\_RB1@24&-17.01 dBm




Date: 31.JAN.2024 20:14:30

5MHz\_15kHz\_1777.5MHz\_DFT-s-OFDM QPSK\_RB25@0&-25.83 dBm




Date: 31.JAN.2024 20:15:09

10MHz\_15kHz\_1715MHz\_DFT-s-OFDM QPSK\_RB1@0&-16.67 dBm



Date: 31.JAN.2024 20:18:22

10MHz\_15kHz\_1715MHz\_DFT-s-OFDM QPSK\_RB50@0&-28.09 dBm



Date: 31.JAN.2024 20:19:01