



25MHz\_15kHz\_1767.5MHz\_DFT-s-OFDM QPSK\_RB1@132&-22.32 dBm




Date: 31.JAN.2024 20:39:56

25MHz\_15kHz\_1767.5MHz\_DFT-s-OFDM QPSK\_RB128@0&-22.35 dBm




Date: 31.JAN.2024 20:36:39

30MHz\_15kHz\_1725MHz\_DFT-s-OFDM QPSK\_RB1@0&-18.63 dBm




Date: 31.JAN.2024 20:50:05

30MHz\_15kHz\_1725MHz\_DFT-s-OFDM QPSK\_RB160@0&-25.39 dBm




Date: 31.JAN.2024 20:44:45

30MHz\_15kHz\_1765MHz\_DFT-s-OFDM QPSK\_RB1@159&-13.82 dBm




Date: 31.JAN.2024 20:45:38

30MHz\_15kHz\_1765MHz\_DFT-s-OFDM QPSK\_RB160@0&-23.81 dBm




Date: 31.JAN.2024 20:46:26

40MHz\_15kHz\_1730MHz\_DFT-s-OFDM QPSK\_RB1@0&-13.56 dBm




Date: 31.JAN.2024 20:57:52

40MHz\_15kHz\_1730MHz\_DFT-s-OFDM QPSK\_RB216@0&-13.86 dBm




Date: 31.JAN.2024 20:52:28

40MHz\_15kHz\_1760MHz\_DFT-s-OFDM QPSK\_RB1@215&-16.74 dBm



Date: 31.JAN.2024 20:54:09

40MHz\_15kHz\_1760MHz\_DFT-s-OFDM QPSK\_RB216@0&-16.37 dBm



Date: 31.JAN.2024 20:54:49