

Report No.: EED32P80349001 Page 35 of 57

10PHOTOGRAPHS OF EUT Constructional Details



View of Product-1



View of Product-2














Page 36 of 57 Report No.: EED32P80349001



View of Product-3



View of Product-4














Page 37 of 57 Report No.: EED32P80349001



View of Product-5



View of Product-6














Page 38 of 57 Report No.: EED32P80349001



View of Product-7



View of Product-8














Page 39 of 57 Report No.: EED32P80349001



View of Product-9 Ear L



View of Product-10 Ear L














Page 40 of 57 Report No.: EED32P80349001



View of Product-11 Ear L



View of Product-12 Ear L














Page 41 of 57 Report No.: EED32P80349001



View of Product-13 Ear L



View of Product-14 Ear L













Report No.: EED32P80349001 Page 42 of 57



View of Product-15 Ear R



View of Product-16 Ear R















Page 43 of 57 Report No.: EED32P80349001



View of Product-17 Ear R



View of Product-18 Ear R













Report No.: EED32P80349001 Page 44 of 57



View of Product-19 Ear R



View of Product-20 Ear R













Page 45 of 57 Report No.: EED32P80349001



View of Product-21 Ear R



View of Product-22









