



NTNV_N77-3450-
3550_PC3_30_10_L_TID10_NS_01_6000_26000
#1


NTNV_N77-3450-
3550_PC3_30_10_L_TID10_NS_01_26000_4000
0_#1




NTNV_N77-3450-
3550_PC3_30_10_L_TID11_NS_01_0.009_0.15
#1




NTNV_N77-3450-
3550_PC3_30_10_L_TID11_NS_01_0.15_30_#1




NTNV_N77-3450-
3550_PC3_30_10_L_TID11_NS_01_30_1000_#1




NTNV_N77-3450-
3550_PC3_30_10_L_TID11_NS_01_1000_3000_#1




NTNV_N77-3450-
3550_PC3_30_10_L_TID11_NS_01_3000_6000_#1




NTNV_N77-3450-
3550_PC3_30_10_L_TID11_NS_01_6000_26000_#1




NTNV_N77-3450-
3550_PC3_30_10_L_TID11_NS_01_26000_4000
0_#1




NTNV_N77-3450-
3550_PC3_30_10_L_TID12_NS_01_0.009_0.15_
#1



NTNV_N77-3450-
3550_PC3_30_10_L_TID12_NS_01_0.15_30_#1




NTNV_N77-3450-
3550_PC3_30_10_L_TID12_NS_01_30_1000_#1




NTNV_N77-3450-
3550_PC3_30_10_L_TID12_NS_01_1000_3000_
#1


NTNV_N77-3450-
3550_PC3_30_10_L_TID12_NS_01_3000_6000_
#1




NTNV_N77-3450-
3550_PC3_30_10_L_TID12_NS_01_6000_26000
_#1




NTNV_N77-3450-
3550_PC3_30_10_L_TID12_NS_01_26000_4000
0_#1




NTVN_N77-3450-
 3550_PC3_30_10_L_TID13_NS_01_0.009_0.15_
 #1




NTVN_N77-3450-
 3550_PC3_30_10_L_TID13_NS_01_0.15_30_#1




NTVN_N77-3450-
 3550_PC3_30_10_L_TID13_NS_01_30_1000_#1




NTVN_N77-3450-
 3550_PC3_30_10_L_TID13_NS_01_1000_3000_
 #1




NTNV_N77-3450-
3550_PC3_30_10_L_TID13_NS_01_3000_6000_
#1




NTNV_N77-3450-
3550_PC3_30_10_L_TID13_NS_01_6000_26000_
#1



NTNV_N77-3450-
3550_PC3_30_10_L_TID13_NS_01_26000_4000_
0_#1




NTNV_N77-3450-
3550_PC3_30_10_L_TID14_NS_01_0.009_0.15_
#1




22:57:21 14.01.2014

NTNV_N77-3450-
3550_PC3_30_10_L_TID14_NS_01_0.15_30_#1




22:57:41 14.01.2014

NTNV_N77-3450-
3550_PC3_30_10_L_TID14_NS_01_30_1000_#1




22:57:51 14.01.2014

NTNV_N77-3450-
3550_PC3_30_10_L_TID14_NS_01_1000_3000_#1




22:58:04 14.01.2014

NTNV_N77-3450-
3550_PC3_30_10_L_TID14_NS_01_3000_6000_#1




NTNV_N77-3450-
3550_PC3_30_10_L_TID14_NS_01_6000_26000
_#1


NTNV_N77-3450-
3550_PC3_30_10_L_TID14_NS_01_26000_4000
0_#1




NTNV_N77-3450-
3550_PC3_30_10_L_TID15_NS_01_0.009_0.15_#1




NTNV_N77-3450-
3550_PC3_30_10_L_TID15_NS_01_0.15_30_#1




NTNV_N77-3450-3550_PC3_30_10_L_TID15_NS_01_30_1000_#1




NTNV_N77-3450-3550_PC3_30_10_L_TID15_NS_01_1000_3000_#1



NTNV_N77-3450-3550_PC3_30_10_L_TID15_NS_01_3000_6000_#1




NTNV_N77-3450-3550_PC3_30_10_L_TID15_NS_01_6000_26000_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID1_NS_01_1000_3000_#
1


NTNV_N77-3450-
3550_PC3_30_10_M_TID1_NS_01_3000_6000_#
1




NTNV_N77-3450-
3550_PC3_30_10_M_TID1_NS_01_6000_26000_#
#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID1_NS_01_26000_40000_#
_#1




NTVN_N77-3450-
 3550_PC3_30_10_M_TID2_NS_01_0.009_0.15_#
 1




NTVN_N77-3450-
 3550_PC3_30_10_M_TID2_NS_01_0.15_30_#1




NTVN_N77-3450-
 3550_PC3_30_10_M_TID2_NS_01_30_1000_#1




NTVN_N77-3450-
 3550_PC3_30_10_M_TID2_NS_01_1000_3000_#
 1




NTNV_N77-3450-
3550_PC3_30_10_M_TID2_NS_01_3000_6000_#
1




NTNV_N77-3450-
3550_PC3_30_10_M_TID2_NS_01_6000_26000_#
#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID2_NS_01_26000_40000_#
#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID3_NS_01_0.009_0.15_#
1




NTNV_N77-3450-
3550_PC3_30_10_M_TID3_NS_01_0.15_30_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID3_NS_01_30_1000_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID3_NS_01_1000_3000_#
1




NTNV_N77-3450-
3550_PC3_30_10_M_TID3_NS_01_3000_6000_#
1




NTNV_N77-3450-
3550_PC3_30_10_M_TID3_NS_01_6000_26000_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID3_NS_01_26000_40000_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID4_NS_01_0.009_0.15_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID4_NS_01_0.15_30_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID4_NS_01_30_1000_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID4_NS_01_1000_3000_#
1




NTNV_N77-3450-
3550_PC3_30_10_M_TID4_NS_01_3000_6000_#
1




NTNV_N77-3450-
3550_PC3_30_10_M_TID4_NS_01_6000_26000_#
1




NTNV_N77-3450-
3550_PC3_30_10_M_TID4_NS_01_26000_40000
_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID5_NS_01_0.009_0.15_#
1



NTNV_N77-3450-
3550_PC3_30_10_M_TID5_NS_01_0.15_30_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID5_NS_01_30_1000_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID5_NS_01_1000_3000_#
1


NTNV_N77-3450-
3550_PC3_30_10_M_TID5_NS_01_3000_6000_#
1



NTNV_N77-3450-
3550_PC3_30_10_M_TID5_NS_01_6000_26000_#
#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID5_NS_01_26000_40000_#
_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID6_NS_01_0.009_0.15_#
1


NTNV_N77-3450-
3550_PC3_30_10_M_TID6_NS_01_0.15_30_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID6_NS_01_30_1000_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID6_NS_01_1000_3000_#
1




NTNV_N77-3450-3550_PC3_30_10_M_TID6_NS_01_3000_6000_#1




NTNV_N77-3450-3550_PC3_30_10_M_TID6_NS_01_6000_26000_#1



NTNV_N77-3450-3550_PC3_30_10_M_TID6_NS_01_26000_40000_#1




NTNV_N77-3450-3550_PC3_30_10_M_TID7_NS_01_0.009_0.15_#1




23-23-17 14:01:1014

NTNV_N77-3450-
3550_PC3_30_10_M_TID7_NS_01_0.15_30_#1



23-23-28 14:01:1014


NTNV_N77-3450-
3550_PC3_30_10_M_TID7_NS_01_30_1000_#1



23-23-29 14:01:1014

NTNV_N77-3450-
3550_PC3_30_10_M_TID7_NS_01_1000_3000_#


1



23-23-51 14:01:1014


NTNV_N77-3450-
3550_PC3_30_10_M_TID7_NS_01_3000_6000_#

1




NTNV_N77-3450-
3550_PC3_30_10_M_TID7_NS_01_6000_26000_
#1


NTNV_N77-3450-
3550_PC3_30_10_M_TID7_NS_01_26000_40000
#1



NTNV_N77-3450-
3550_PC3_30_10_M_TID8_NS_01_0.009_0.15_
#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID8_NS_01_0.15_30_
#1




23:28:28 14.01.2014

NTNV_N77-3450-
3550_PC3_30_10_M_TID8_NS_01_30_1000_#1




23:28:28 14.01.2014

NTNV_N77-3450-
3550_PC3_30_10_M_TID8_NS_01_1000_3000_#
1




23:26:50 14.01.2014

NTNV_N77-3450-
3550_PC3_30_10_M_TID8_NS_01_3000_6000_#
1




23:27:01 14.01.2014


NTNV_N77-3450-
3550_PC3_30_10_M_TID8_NS_01_6000_26000_#
1




NTNV_N77-3450-
3550_PC3_30_10_M_TID8_NS_01_26000_40000
_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID9_NS_01_0.009_0.15_#
1



NTNV_N77-3450-
3550_PC3_30_10_M_TID9_NS_01_0.15_30_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID9_NS_01_30_1000_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID9_NS_01_1000_3000_#
1


NTNV_N77-3450-
3550_PC3_30_10_M_TID9_NS_01_3000_6000_#
1




NTNV_N77-3450-
3550_PC3_30_10_M_TID9_NS_01_6000_26000_#
#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID9_NS_01_26000_40000_#
_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID10_NS_01_0.009_0.15_
#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID10_NS_01_0.15_30_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID10_NS_01_30_1000_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID10_NS_01_1000_3000_
#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID10_NS_01_3000_6000_
#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID10_NS_01_6000_26000_
#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID10_NS_01_26000_4000_
0_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID11_NS_01_0.009_0.15_
#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID11_NS_01_0.15_30_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID11_NS_01_30_1000_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID11_NS_01_1000_3000_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID11_NS_01_3000_6000_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID11_NS_01_6000_26000
_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID11_NS_01_26000_4000
0_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID12_NS_01_0.009_0.15_
_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID12_NS_01_0.15_30_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID12_NS_01_30_1000_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID12_NS_01_1000_3000_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID12_NS_01_3000_6000_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID12_NS_01_6000_26000_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID12_NS_01_26000_4000
0_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID13_NS_01_0.009_0.15_
#1



NTNV_N77-3450-
3550_PC3_30_10_M_TID13_NS_01_0.15_30_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID13_NS_01_30_1000_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID13_NS_01_1000_3000_
#1


NTNV_N77-3450-
3550_PC3_30_10_M_TID13_NS_01_3000_6000_
#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID13_NS_01_6000_26000_
#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID13_NS_01_26000_4000
0_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID14_NS_01_0.009_0.15_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID14_NS_01_0.15_30_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID14_NS_01_30_1000_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID14_NS_01_1000_3000_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID14_NS_01_3000_6000_
#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID14_NS_01_6000_26000
_#1



NTNV_N77-3450-
3550_PC3_30_10_M_TID14_NS_01_26000_4000
0_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID15_NS_01_0.009_0.15_
#1




23:48:44 14.01.2014

NTNV_N77-3450-
3550_PC3_30_10_M_TID15_NS_01_0.15_30_#1




23:48:55 14.01.2014

NTNV_N77-3450-
3550_PC3_30_10_M_TID15_NS_01_30_1000_#1




23:48:05 14.01.2014

NTNV_N77-3450-
3550_PC3_30_10_M_TID15_NS_01_1000_3000_#1




23:48:17 14.01.2014

NTNV_N77-3450-
3550_PC3_30_10_M_TID15_NS_01_3000_6000_#1




NTNV_N77-3450-
3550_PC3_30_10_M_TID15_NS_01_6000_26000
_#1


NTNV_N77-3450-
3550_PC3_30_10_M_TID15_NS_01_26000_4000
0_#1



NTNV_N77-3450-
3550_PC3_30_10_H_TID1_NS_01_0.009_0.15_#
1




NTNV_N77-3450-
3550_PC3_30_10_H_TID1_NS_01_0.15_30_#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID1_NS_01_30_1000_#1


NTNV_N77-3450-
3550_PC3_30_10_H_TID1_NS_01_1000_3000_#
1




NTNV_N77-3450-
3550_PC3_30_10_H_TID1_NS_01_3000_6000_#
1




NTNV_N77-3450-
3550_PC3_30_10_H_TID1_NS_01_6000_26000_#
#1




NTNV_N77-3450-3550_PC3_30_10_H_TID1_NS_01_26000_40000_#1




NTNV_N77-3450-3550_PC3_30_10_H_TID2_NS_01_0.009_0.15_#1



NTNV_N77-3450-3550_PC3_30_10_H_TID2_NS_01_0.15_30_#1




NTNV_N77-3450-3550_PC3_30_10_H_TID2_NS_01_30_1000_#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID2_NS_01_1000_3000_#
1


NTNV_N77-3450-
3550_PC3_30_10_H_TID2_NS_01_3000_6000_#
1




NTNV_N77-3450-
3550_PC3_30_10_H_TID2_NS_01_6000_26000_#
#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID2_NS_01_26000_40000_#
_#1




NTVN_N77-3450-
 3550_PC3_30_10_H_TID3_NS_01_0.009_0.15_#
 1




NTVN_N77-3450-
 3550_PC3_30_10_H_TID3_NS_01_0.15_30_#1




NTVN_N77-3450-
 3550_PC3_30_10_H_TID3_NS_01_30_1000_#1




NTVN_N77-3450-
 3550_PC3_30_10_H_TID3_NS_01_1000_3000_#
 1




NTNV_N77-3450-
3550_PC3_30_10_H_TID3_NS_01_3000_6000_#
1




NTNV_N77-3450-
3550_PC3_30_10_H_TID3_NS_01_6000_26000_#
1




NTNV_N77-3450-
3550_PC3_30_10_H_TID3_NS_01_26000_40000_#
1




NTNV_N77-3450-
3550_PC3_30_10_H_TID4_NS_01_0.009_0.15_#
1



NTNV_N77-3450-
3550_PC3_30_10_H_TID4_NS_01_0.15_30_#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID4_NS_01_30_1000_#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID4_NS_01_1000_3000_#

1




NTNV_N77-3450-
3550_PC3_30_10_H_TID4_NS_01_3000_6000_#

1




NTNV_N77-3450-
3550_PC3_30_10_H_TID4_NS_01_6000_26000_
#1


NTNV_N77-3450-
3550_PC3_30_10_H_TID4_NS_01_26000_40000_
#1



NTNV_N77-3450-
3550_PC3_30_10_H_TID5_NS_01_0.009_0.15_
#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID5_NS_01_0.15_30_
#1




03:04:59 15.01.2014

NTNV_N77-3450-3550_PC3_30_10_H_TID5_NS_01_30_1000_#1




03:05:19 15.01.2014

NTNV_N77-3450-3550_PC3_30_10_H_TID5_NS_01_1000_3000_#1




03:05:21 15.01.2014

NTNV_N77-3450-3550_PC3_30_10_H_TID5_NS_01_3000_6000_#1




03:05:25 15.01.2014


NTNV_N77-3450-3550_PC3_30_10_H_TID5_NS_01_6000_26000_#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID5_NS_01_26000_40000
_#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID6_NS_01_0.009_0.15_#
1



NTNV_N77-3450-
3550_PC3_30_10_H_TID6_NS_01_0.15_30_#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID6_NS_01_30_1000_#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID6_NS_01_1000_3000_#
1


NTNV_N77-3450-
3550_PC3_30_10_H_TID6_NS_01_3000_6000_#
1




NTNV_N77-3450-
3550_PC3_30_10_H_TID6_NS_01_6000_26000_#
#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID6_NS_01_26000_40000_#
_#1




NTNV_N77-3450-3550_PC3_30_10_H_TID7_NS_01_0.009_0.15_#1




NTNV_N77-3450-3550_PC3_30_10_H_TID7_NS_01_0.15_30_#1



NTNV_N77-3450-3550_PC3_30_10_H_TID7_NS_01_30_1000_#1




NTNV_N77-3450-3550_PC3_30_10_H_TID7_NS_01_1000_3000_#1




09:11:24 15.01.2014

NTNV_N77-3450-
3550_PC3_30_10_H_TID7_NS_01_3000_6000_#
1




09:11:26 15.01.2014

NTNV_N77-3450-
3550_PC3_30_10_H_TID7_NS_01_6000_26000_#
1




09:11:47 15.01.2014

NTNV_N77-3450-
3550_PC3_30_10_H_TID7_NS_01_26000_40000_#
1




09:14:08 15.01.2014

NTNV_N77-3450-
3550_PC3_30_10_H_TID8_NS_01_0.009_0.15_#
1




09:14:18 15.01.2014

NTNV_N77-3450-3550_PC3_30_10_H_TID8_NS_01_0.15_30_#1




09:14:29 15.01.2014

NTNV_N77-3450-3550_PC3_30_10_H_TID8_NS_01_30_1000_#1




09:14:40 15.01.2014

NTNV_N77-3450-3550_PC3_30_10_H_TID8_NS_01_1000_3000_#1




09:14:59 15.01.2014

NTNV_N77-3450-3550_PC3_30_10_H_TID8_NS_01_3000_6000_#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID8_NS_01_6000_26000_#1


NTNV_N77-3450-
3550_PC3_30_10_H_TID8_NS_01_26000_40000_#1



NTNV_N77-3450-
3550_PC3_30_10_H_TID9_NS_01_0.009_0.15_#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID9_NS_01_0.15_30_#1




09:17:40 15.01.2014

NTNV_N77-3450-3550_PC3_30_10_H_TID9_NS_01_30_1000_#1




09:17:59 15.01.2014

NTNV_N77-3450-3550_PC3_30_10_H_TID9_NS_01_1000_3000_#1




09:18:11 15.01.2014

NTNV_N77-3450-3550_PC3_30_10_H_TID9_NS_01_3000_6000_#1




09:18:24 15.01.2014


NTNV_N77-3450-3550_PC3_30_10_H_TID9_NS_01_6000_26000_#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID9_NS_01_26000_40000
_#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID10_NS_01_0.009_0.15_
_#1



NTNV_N77-3450-
3550_PC3_30_10_H_TID10_NS_01_0.15_30_#1



NTNV_N77-3450-
3550_PC3_30_10_H_TID10_NS_01_30_1000_#1




09:21:19 15.01.2014


09:21:21 15.01.2014

NTNV_N77-3450-
3550_PC3_30_10_H_TID10_NS_01_1000_3000_
#1

NTNV_N77-3450-
3550_PC3_30_10_H_TID10_NS_01_3000_6000_
#1




09:21:44 15.01.2014




09:21:55 15.01.2014

NTNV_N77-3450-
3550_PC3_30_10_H_TID10_NS_01_6000_26000_
#1


NTNV_N77-3450-
3550_PC3_30_10_H_TID10_NS_01_26000_4000
0_#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID11_NS_01_0.009_0.15_
#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID11_NS_01_0.15_30_#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID11_NS_01_30_1000_#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID11_NS_01_1000_3000_
#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID11_NS_01_3000_6000_#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID11_NS_01_6000_26000_#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID11_NS_01_26000_4000_0_#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID12_NS_01_0.009_0.15_#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID12_NS_01_0.15_30_#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID12_NS_01_30_1000_#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID12_NS_01_1000_3000_#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID12_NS_01_3000_6000_#1







NTNV_N77-3450-
3550_PC3_30_10_H_TID13_NS_01_30_1000_#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID13_NS_01_1000_3000_#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID13_NS_01_3000_6000_#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID13_NS_01_6000_26000_#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID13_NS_01_26000_4000
0_#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID14_NS_01_0.009_0.15_#1



NTNV_N77-3450-
3550_PC3_30_10_H_TID14_NS_01_0.15_30_#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID14_NS_01_30_1000_#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID14_NS_01_1000_3000_
#1


NTNV_N77-3450-
3550_PC3_30_10_H_TID14_NS_01_3000_6000_
#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID14_NS_01_6000_26000_
#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID14_NS_01_26000_4000
0_#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID15_NS_01_0.009_0.15_
#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID15_NS_01_0.15_30_#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID15_NS_01_30_1000_#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID15_NS_01_1000_3000_
#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID15_NS_01_3000_6000_#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID15_NS_01_6000_26000_#1




NTNV_N77-3450-
3550_PC3_30_10_H_TID15_NS_01_26000_4000_0_#1




NTNV_N77-3450-
3550_PC3_30_15_L_TID1_NS_01_0.009_0.15_#1




NTNV_N77-3450-
3550_PC3_30_15_L_TID1_NS_01_0.15_30_#1




NTNV_N77-3450-
3550_PC3_30_15_L_TID1_NS_01_30_1000_#1



NTNV_N77-3450-
3550_PC3_30_15_L_TID1_NS_01_1000_3000_#
1




NTNV_N77-3450-
3550_PC3_30_15_L_TID1_NS_01_3000_6000_#
1




NTNV_N77-3450-
3550_PC3_30_15_L_TID1_NS_01_6000_26000_
#1


NTNV_N77-3450-
3550_PC3_30_15_L_TID1_NS_01_26000_40000
#1




NTNV_N77-3450-
3550_PC3_30_15_L_TID2_NS_01_0.009_0.15_
#1




NTNV_N77-3450-
3550_PC3_30_15_L_TID2_NS_01_0.15_30_#1




NTNV_N77-3450-
3550_PC3_30_15_L_TID2_NS_01_30_1000_#1




NTNV_N77-3450-
3550_PC3_30_15_L_TID2_NS_01_1000_3000_#
1




NTNV_N77-3450-
3550_PC3_30_15_L_TID2_NS_01_3000_6000_#
1




NTNV_N77-3450-
3550_PC3_30_15_L_TID2_NS_01_6000_26000_#
#1




NTVN_N77-3450-
 3550_PC3_30_15_L_TID2_NS_01_26000_40000
 #1




NTVN_N77-3450-
 3550_PC3_30_15_L_TID3_NS_01_0.009_0.15 #
 1



NTVN_N77-3450-
 3550_PC3_30_15_L_TID3_NS_01_0.15_30 #1



NTVN_N77-3450-
 3550_PC3_30_15_L_TID3_NS_01_30_1000 #1




03:45:57 15.01.2014


03:46:09 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_L_TID3_NS_01_1000_3000_#
1

NTNV_N77-3450-
3550_PC3_30_15_L_TID3_NS_01_3000_6000_#
1




03:46:21 15.01.2014




03:46:24 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_L_TID3_NS_01_6000_26000_#
#1


NTNV_N77-3450-
3550_PC3_30_15_L_TID3_NS_01_26000_40000_#
_#1




NTNV_N77-3450-
3550_PC3_30_15_L_TID4_NS_01_0.009_0.15_#
1




NTNV_N77-3450-
3550_PC3_30_15_L_TID4_NS_01_0.15_30_#1




NTNV_N77-3450-
3550_PC3_30_15_L_TID4_NS_01_30_1000_#1




NTNV_N77-3450-
3550_PC3_30_15_L_TID4_NS_01_1000_3000_#
1




NTNV_N77-3450-
3550_PC3_30_15_L_TID4_NS_01_3000_6000_#
1




NTNV_N77-3450-
3550_PC3_30_15_L_TID4_NS_01_6000_26000_#
#1



NTNV_N77-3450-
3550_PC3_30_15_L_TID4_NS_01_26000_40000_#
#1




NTNV_N77-3450-
3550_PC3_30_15_L_TID5_NS_01_0.009_0.15_#
1




01:51:46 15.01.2014

NTNV_N77-3450-3550_PC3_30_15_L_TID5_NS_01_0.15_30_#1




01:51:57 15.01.2014

NTNV_N77-3450-3550_PC3_30_15_L_TID5_NS_01_30_1000_#1




01:52:07 15.01.2014

NTNV_N77-3450-3550_PC3_30_15_L_TID5_NS_01_1000_3000_#1



01:52:19 15.01.2014

NTNV_N77-3450-3550_PC3_30_15_L_TID5_NS_01_3000_6000_#1




01:52:21 15.01.2014


01:52:49 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_L_TID5_NS_01_6000_26000_
#1

NTNV_N77-3450-
3550_PC3_30_15_L_TID5_NS_01_26000_40000
#1




01:54:29 15.01.2014




01:54:50 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_L_TID6_NS_01_0.009_0.15_
#1


NTNV_N77-3450-
3550_PC3_30_15_L_TID6_NS_01_0.15_30_#1




NTNV_N77-3450-3550_PC3_30_15_L_TID6_NS_01_30_1000_#1




NTNV_N77-3450-3550_PC3_30_15_L_TID6_NS_01_1000_3000_#1




NTNV_N77-3450-3550_PC3_30_15_L_TID6_NS_01_3000_6000_#1




NTNV_N77-3450-3550_PC3_30_15_L_TID6_NS_01_6000_26000_#1




NTNV_N77-3450-
3550_PC3_30_15_L_TID6_NS_01_26000_40000
_#1




NTNV_N77-3450-
3550_PC3_30_15_L_TID7_NS_01_0.009_0.15_#
1



NTNV_N77-3450-
3550_PC3_30_15_L_TID7_NS_01_0.15_30_#1



NTNV_N77-3450-
3550_PC3_30_15_L_TID7_NS_01_30_1000_#1




01:58:29 15.01.2014


01:58:41 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_L_TID7_NS_01_1000_3000_#
1

NTNV_N77-3450-
3550_PC3_30_15_L_TID7_NS_01_3000_6000_#
1




01:58:54 15.01.2014




01:58:05 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_L_TID7_NS_01_6000_26000_#
#1


NTNV_N77-3450-
3550_PC3_30_15_L_TID7_NS_01_26000_40000_#
_#1




NTVN_N77-3450-
 3550_PC3_30_15_L_TID8_NS_01_0.009_0.15_#
 1




NTVN_N77-3450-
 3550_PC3_30_15_L_TID8_NS_01_0.15_30_#1



NTVN_N77-3450-
 3550_PC3_30_15_L_TID8_NS_01_30_1000_#1




NTVN_N77-3450-
 3550_PC3_30_15_L_TID8_NS_01_1000_3000_#
 1




01:01:22 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_L_TID8_NS_01_3000_6000_#
1




01:01:25 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_L_TID8_NS_01_6000_26000_#
#1




01:01:46 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_L_TID8_NS_01_26000_40000_#
#1




01:03:50 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_L_TID9_NS_01_0.009_0.15_#
1




01.04.01 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_L_TID9_NS_01_0.15_30_#1



01.04.11 15.01.2014


NTNV_N77-3450-
3550_PC3_30_15_L_TID9_NS_01_30_1000_#1



01.04.22 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_L_TID9_NS_01_1000_3000_#


1




01.04.25 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_L_TID9_NS_01_3000_6000_#


1




NTNV_N77-3450-
3550_PC3_30_15_L_TID9_NS_01_6000_26000_
#1




NTNV_N77-3450-
3550_PC3_30_15_L_TID9_NS_01_26000_40000_
#1




NTNV_N77-3450-
3550_PC3_30_15_L_TID10_NS_01_0.009_0.15_
#1




NTNV_N77-3450-
3550_PC3_30_15_L_TID10_NS_01_0.15_30_
#1




NTNV_N77-3450-
3550_PC3_30_15_L_TID10_NS_01_30_1000_#1




NTNV_N77-3450-
3550_PC3_30_15_L_TID10_NS_01_1000_3000_#1




NTNV_N77-3450-
3550_PC3_30_15_L_TID10_NS_01_3000_6000_#1




NTNV_N77-3450-
3550_PC3_30_15_L_TID10_NS_01_6000_26000_#1




NTNV_N77-3450-3550_PC3_30_15_L_TID10_NS_01_26000_4000_0_#1




NTNV_N77-3450-3550_PC3_30_15_L_TID11_NS_01_0.009_0.15_#1



NTNV_N77-3450-3550_PC3_30_15_L_TID11_NS_01_0.15_30_#1



NTNV_N77-3450-3550_PC3_30_15_L_TID11_NS_01_30_1000_#1




01:19:17 15.01.2014


01:19:29 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_L_TID11_NS_01_1000_3000_
#1

NTNV_N77-3450-
3550_PC3_30_15_L_TID11_NS_01_3000_6000_
#1




01:19:41 15.01.2014




01:19:59 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_L_TID11_NS_01_6000_26000_
#1


NTNV_N77-3450-
3550_PC3_30_15_L_TID11_NS_01_26000_4000_
0_#1




NTNV_N77-3450-
 3550_PC3_30_15_L_TID12_NS_01_0.009_0.15_
 #1




NTNV_N77-3450-
 3550_PC3_30_15_L_TID12_NS_01_0.15_30_#1




NTNV_N77-3450-
 3550_PC3_30_15_L_TID12_NS_01_30_1000_#1




NTNV_N77-3450-
 3550_PC3_30_15_L_TID12_NS_01_1000_3000_
 #1




NTNV_N77-3450-
3550_PC3_30_15_L_TID12_NS_01_3000_6000_
#1




NTNV_N77-3450-
3550_PC3_30_15_L_TID12_NS_01_6000_26000
#1



NTNV_N77-3450-
3550_PC3_30_15_L_TID12_NS_01_26000_4000
0_#1




NTNV_N77-3450-
3550_PC3_30_15_L_TID13_NS_01_0.009_0.15_
#1




01:15:34 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_L_TID13_NS_01_0.15_30_#1




01:15:45 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_L_TID13_NS_01_30_1000_#1




01:15:56 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_L_TID13_NS_01_1000_3000_#1



01:16:07 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_L_TID13_NS_01_3000_6000_#1




01:18:20 15.01.2014


01:18:21 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_L_TID13_NS_01_6000_26000
_#1

NTNV_N77-3450-
3550_PC3_30_15_L_TID13_NS_01_26000_4000
0_#1




01:18:19 15.01.2014




01:18:20 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_L_TID14_NS_01_0.009_0.15_#1


NTNV_N77-3450-
3550_PC3_30_15_L_TID14_NS_01_0.15_30_#1




NTNV_N77-3450-
3550_PC3_30_15_L_TID14_NS_01_30_1000_#1




NTNV_N77-3450-
3550_PC3_30_15_L_TID14_NS_01_1000_3000_#1



NTNV_N77-3450-
3550_PC3_30_15_L_TID14_NS_01_3000_6000_#1




NTNV_N77-3450-
3550_PC3_30_15_L_TID14_NS_01_6000_26000_#1




01:19:27 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_L_TID14_NS_01_26000_4000
0_#1




01:21:09 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_L_TID15_NS_01_0.009_0.15_
#1




01:21:14 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_L_TID15_NS_01_0.15_30_#1



01:21:25 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_L_TID15_NS_01_30_1000_#1




01:21:26 15.01.2014


01:21:48 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_L_TID15_NS_01_1000_3000_
#1

NTNV_N77-3450-
3550_PC3_30_15_L_TID15_NS_01_3000_6000_
#1




01:22:00 15.01.2014




01:22:11 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_L_TID15_NS_01_6000_26000_
#1


NTNV_N77-3450-
3550_PC3_30_15_L_TID15_NS_01_26000_4000
0_#1




NTNV_N77-3450-
3550_PC3_30_15_M_TID1_NS_01_3000_6000_#
1




NTNV_N77-3450-
3550_PC3_30_15_M_TID1_NS_01_6000_26000_#
#1



NTNV_N77-3450-
3550_PC3_30_15_M_TID1_NS_01_26000_40000_#
#1



NTNV_N77-3450-
3550_PC3_30_15_M_TID2_NS_01_0.009_0.15_#
1




01:28:14 15.01.2014


01:28:25 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_M_TID2_NS_01_0.15_30_#1

NTNV_N77-3450-
3550_PC3_30_15_M_TID2_NS_01_30_1000_#1




01:28:36 15.01.2014



01:28:48 15.01.2014


NTNV_N77-3450-
3550_PC3_30_15_M_TID2_NS_01_1000_3000_#

NTNV_N77-3450-
3550_PC3_30_15_M_TID2_NS_01_3000_6000_#




01:29:00 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_M_TID2_NS_01_6000_26000_
#1




01:29:11 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_M_TID2_NS_01_26000_40000_
#1




01:30:41 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_M_TID3_NS_01_0.009_0.15_
#1




01:31:51 15.01.2014


NTNV_N77-3450-
3550_PC3_30_15_M_TID3_NS_01_0.15_30_
#1




NTNV_N77-3450-
3550_PC3_30_15_M_TID3_NS_01_30_1000_#1




NTNV_N77-3450-
3550_PC3_30_15_M_TID3_NS_01_1000_3000_#
1




NTNV_N77-3450-
3550_PC3_30_15_M_TID3_NS_01_3000_6000_#
1




NTNV_N77-3450-
3550_PC3_30_15_M_TID3_NS_01_6000_26000_#
#1




NTNV_N77-3450-
3550_PC3_30_15_M_TID3_NS_01_26000_40000
_#1




NTNV_N77-3450-
3550_PC3_30_15_M_TID4_NS_01_0.009_0.15_#
1



NTNV_N77-3450-
3550_PC3_30_15_M_TID4_NS_01_0.15_30_#1



NTNV_N77-3450-
3550_PC3_30_15_M_TID4_NS_01_30_1000_#1




01:35:16 15.01.2014


01:35:28 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_M_TID4_NS_01_1000_3000_#
1

NTNV_N77-3450-
3550_PC3_30_15_M_TID4_NS_01_3000_6000_#
1




01:35:41 15.01.2014




01:35:51 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_M_TID4_NS_01_6000_26000_#
#1


NTNV_N77-3450-
3550_PC3_30_15_M_TID4_NS_01_26000_40000_#
_#1




NTVN_N77-3450-
 3550_PC3_30_15_M_TID5_NS_01_0.009_0.15_#
 1




NTVN_N77-3450-
 3550_PC3_30_15_M_TID5_NS_01_0.15_30_#1




NTVN_N77-3450-
 3550_PC3_30_15_M_TID5_NS_01_30_1000_#1




NTVN_N77-3450-
 3550_PC3_30_15_M_TID5_NS_01_1000_3000_#
 1




NTNV_N77-3450-
3550_PC3_30_15_M_TID5_NS_01_3000_6000_#
1




NTNV_N77-3450-
3550_PC3_30_15_M_TID5_NS_01_6000_26000_#
#1



NTNV_N77-3450-
3550_PC3_30_15_M_TID5_NS_01_26000_40000_#
#1




NTNV_N77-3450-
3550_PC3_30_15_M_TID6_NS_01_0.009_0.15_#
1




01:40:44 15.01.2014

NTNV_N77-3450-3550_PC3_30_15_M_TID6_NS_01_0.15_30_#1



01:40:55 15.01.2014


NTNV_N77-3450-3550_PC3_30_15_M_TID6_NS_01_30_1000_#1



01:40:06 15.01.2014

NTNV_N77-3450-3550_PC3_30_15_M_TID6_NS_01_1000_3000_#


1



01:40:18 15.01.2014


NTNV_N77-3450-3550_PC3_30_15_M_TID6_NS_01_3000_6000_#

1




NTNV_N77-3450-
3550_PC3_30_15_M_TID6_NS_01_6000_26000_
#1


NTNV_N77-3450-
3550_PC3_30_15_M_TID6_NS_01_26000_40000
#1




NTNV_N77-3450-
3550_PC3_30_15_M_TID7_NS_01_0.009_0.15_
#1




NTNV_N77-3450-
3550_PC3_30_15_M_TID7_NS_01_0.15_30_
#1




NTNV_N77-3450-
3550_PC3_30_15_M_TID7_NS_01_30_1000_#1




NTNV_N77-3450-
3550_PC3_30_15_M_TID7_NS_01_1000_3000_#
1



NTNV_N77-3450-
3550_PC3_30_15_M_TID7_NS_01_3000_6000_#
1




NTNV_N77-3450-
3550_PC3_30_15_M_TID7_NS_01_6000_26000_#
#1




01-46:51 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_M_TID7_NS_01_26000_40000
_#1




01-46:05 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_M_TID8_NS_01_0.009_0.15_#
1




01-46:16 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_M_TID8_NS_01_0.15_30_#1



01-46:26 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_M_TID8_NS_01_30_1000_#1




01:49:37 15.01.2014


01:49:50 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_M_TID8_NS_01_1000_3000_#
1

NTNV_N77-3450-
3550_PC3_30_15_M_TID8_NS_01_3000_6000_#
1




01:50:09 15.01.2014



01:50:14 15.01.2014


NTNV_N77-3450-
3550_PC3_30_15_M_TID8_NS_01_6000_26000_#
#1

NTNV_N77-3450-
3550_PC3_30_15_M_TID8_NS_01_26000_40000_#
_#1




01:52:08 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_M_TID9_NS_01_0.009_0.15_#
1




01:52:18 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_M_TID9_NS_01_0.15_30_#1




01:52:29 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_M_TID9_NS_01_30_1000_#1




01:52:40 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_M_TID9_NS_01_1000_3000_#
1




01:53:51 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_M_TID9_NS_01_3000_6000_#
1




01:53:04 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_M_TID9_NS_01_6000_26000_#
1




01:53:15 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_M_TID9_NS_01_26000_40000_#
1




01:53:09 15.01.2014


NTNV_N77-3450-
3550_PC3_30_15_M_TID10_NS_01_0.009_0.15_#
1




NTNV_N77-3450-3550_PC3_30_15_M_TID10_NS_01_0.15_30_#1




NTNV_N77-3450-3550_PC3_30_15_M_TID10_NS_01_30_1000_#1



NTNV_N77-3450-3550_PC3_30_15_M_TID10_NS_01_1000_3000_#1




NTNV_N77-3450-3550_PC3_30_15_M_TID10_NS_01_3000_6000_#1




NTNV_N77-3450-
3550_PC3_30_15_M_TID10_NS_01_6000_26000
_#1


NTNV_N77-3450-
3550_PC3_30_15_M_TID10_NS_01_26000_4000
0_#1



NTNV_N77-3450-
3550_PC3_30_15_M_TID11_NS_01_0.009_0.15_#1




NTNV_N77-3450-
3550_PC3_30_15_M_TID11_NS_01_0.15_30_#1




01:58:25 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_M_TID11_NS_01_30_1000_#1




01:58:26 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_M_TID11_NS_01_1000_3000_#1




01:58:40 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_M_TID11_NS_01_3000_6000_#1




02:00:00 15.01.2014


NTNV_N77-3450-
3550_PC3_30_15_M_TID11_NS_01_6000_26000_#1




NTNV_N77-3450-
3550_PC3_30_15_M_TID11_NS_01_26000_4000
0_#1




NTNV_N77-3450-
3550_PC3_30_15_M_TID12_NS_01_0.009_0.15_
#1



NTNV_N77-3450-
3550_PC3_30_15_M_TID12_NS_01_0.15_30_#1



NTNV_N77-3450-
3550_PC3_30_15_M_TID12_NS_01_30_1000_#1




02:03:29 15.01.2014


02:03:41 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_M_TID12_NS_01_1000_3000_
#1

NTNV_N77-3450-
3550_PC3_30_15_M_TID12_NS_01_3000_6000_
#1




02:03:53 15.01.2014




02:04:04 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_M_TID12_NS_01_6000_26000_
#1


NTNV_N77-3450-
3550_PC3_30_15_M_TID12_NS_01_26000_4000
0_#1




NTNV_N77-3450-
 3550_PC3_30_15_M_TID13_NS_01_0.009_0.15_
 #1




NTNV_N77-3450-
 3550_PC3_30_15_M_TID13_NS_01_0.15_30_#1




NTNV_N77-3450-
 3550_PC3_30_15_M_TID13_NS_01_30_1000_#1




NTNV_N77-3450-
 3550_PC3_30_15_M_TID13_NS_01_1000_3000_
 #1




NTNV_N77-3450-
3550_PC3_30_15_M_TID13_NS_01_3000_6000_
#1




NTNV_N77-3450-
3550_PC3_30_15_M_TID13_NS_01_6000_26000
_#1




NTNV_N77-3450-
3550_PC3_30_15_M_TID13_NS_01_26000_4000
0_#1




NTNV_N77-3450-
3550_PC3_30_15_M_TID14_NS_01_0.009_0.15_
#1




NTNV_N77-3450-
3550_PC3_30_15_M_TID14_NS_01_0.15_30_#1




NTNV_N77-3450-
3550_PC3_30_15_M_TID14_NS_01_30_1000_#1



NTNV_N77-3450-
3550_PC3_30_15_M_TID14_NS_01_1000_3000_#1




NTNV_N77-3450-
3550_PC3_30_15_M_TID14_NS_01_3000_6000_#1




NTNV_N77-3450-
3550_PC3_30_15_M_TID14_NS_01_6000_26000
_#1


NTNV_N77-3450-
3550_PC3_30_15_M_TID14_NS_01_26000_4000
0_#1




NTNV_N77-3450-
3550_PC3_30_15_M_TID15_NS_01_0.009_0.15_#1




NTNV_N77-3450-
3550_PC3_30_15_M_TID15_NS_01_0.15_30_#1




NTNV_N77-3450-
3550_PC3_30_15_M_TID15_NS_01_30_1000_#1




NTNV_N77-3450-
3550_PC3_30_15_M_TID15_NS_01_1000_3000_#1



NTNV_N77-3450-
3550_PC3_30_15_M_TID15_NS_01_3000_6000_#1




NTNV_N77-3450-
3550_PC3_30_15_M_TID15_NS_01_6000_26000_#1




02:19:17 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_M_TID15_NS_01_26000_4000
0_#1




02:17:59 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_H_TID1_NS_01_0.009_0.15_#
1




02:18:04 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_H_TID1_NS_01_0.15_30_#1



02:18:15 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_H_TID1_NS_01_30_1000_#1




02:18:27 15.01.2014


02:18:39 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_H_TID1_NS_01_1000_3000_#
1

NTNV_N77-3450-
3550_PC3_30_15_H_TID1_NS_01_3000_6000_#
1




02:18:51 15.01.2014




02:18:59 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_H_TID1_NS_01_6000_26000_#
#1


NTNV_N77-3450-
3550_PC3_30_15_H_TID1_NS_01_26000_40000_#
_#1




NTNV_N77-3450-
3550_PC3_30_15_H_TID2_NS_01_0.009_0.15_#
1




NTNV_N77-3450-
3550_PC3_30_15_H_TID2_NS_01_0.15_30_#1




NTNV_N77-3450-
3550_PC3_30_15_H_TID2_NS_01_30_1000_#1




NTNV_N77-3450-
3550_PC3_30_15_H_TID2_NS_01_1000_3000_#
1




NTNV_N77-3450-
3550_PC3_30_15_H_TID2_NS_01_3000_6000_#
1




NTNV_N77-3450-
3550_PC3_30_15_H_TID2_NS_01_6000_26000_#
#1



NTNV_N77-3450-
3550_PC3_30_15_H_TID2_NS_01_26000_40000_#
#1



NTNV_N77-3450-
3550_PC3_30_15_H_TID3_NS_01_0.009_0.15_#
1




02:24:00 15.01.2014

02:24:11 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_H_TID3_NS_01_0.15_30_#1

NTNV_N77-3450-
3550_PC3_30_15_H_TID3_NS_01_30_1000_#1



02:24:22 15.01.2014


02:24:34 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_H_TID3_NS_01_1000_3000_#

NTNV_N77-3450-
3550_PC3_30_15_H_TID3_NS_01_3000_6000_#


1

1




NTNV_N77-3450-
3550_PC3_30_15_H_TID3_NS_01_6000_26000_#1


NTNV_N77-3450-
3550_PC3_30_15_H_TID3_NS_01_26000_40000_#1




NTNV_N77-3450-
3550_PC3_30_15_H_TID4_NS_01_0.009_0.15_#1




NTNV_N77-3450-
3550_PC3_30_15_H_TID4_NS_01_0.15_30_#1




NTNV_N77-3450-3550_PC3_30_15_H_TID4_NS_01_30_1000_#1




NTNV_N77-3450-3550_PC3_30_15_H_TID4_NS_01_1000_3000_#1




NTNV_N77-3450-3550_PC3_30_15_H_TID4_NS_01_3000_6000_#1




NTNV_N77-3450-3550_PC3_30_15_H_TID4_NS_01_6000_26000_#1




NTNV_N77-3450-
3550_PC3_30_15_H_TID4_NS_01_26000_40000
_#1




NTNV_N77-3450-
3550_PC3_30_15_H_TID5_NS_01_0.009_0.15_#
1



NTNV_N77-3450-
3550_PC3_30_15_H_TID5_NS_01_0.15_30_#1



NTNV_N77-3450-
3550_PC3_30_15_H_TID5_NS_01_30_1000_#1




02:30:22 15.01.2014


02:30:24 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_H_TID5_NS_01_1000_3000_#
1

NTNV_N77-3450-
3550_PC3_30_15_H_TID5_NS_01_3000_6000_#
1




02:30:46 15.01.2014




02:30:57 15.01.2014

NTNV_N77-3450-
3550_PC3_30_15_H_TID5_NS_01_6000_26000_#
1


NTNV_N77-3450-
3550_PC3_30_15_H_TID5_NS_01_26000_40000_#
1




NTNV_N77-3450-
3550_PC3_30_15_H_TID6_NS_01_0.009_0.15_#
1



NTNV_N77-3450-
3550_PC3_30_15_H_TID6_NS_01_0.15_30_#1



NTNV_N77-3450-
3550_PC3_30_15_H_TID6_NS_01_30_1000_#1



NTNV_N77-3450-
3550_PC3_30_15_H_TID6_NS_01_1000_3000_#
1