




NTNV\_N77-3450-  
 3550\_PC3\_30\_15\_H\_TID6\_NS\_01\_3000\_6000\_#  
 1




NTNV\_N77-3450-  
 3550\_PC3\_30\_15\_H\_TID6\_NS\_01\_6000\_26000\_#  
 #1




NTNV\_N77-3450-  
 3550\_PC3\_30\_15\_H\_TID6\_NS\_01\_26000\_40000\_#  
 #1




NTNV\_N77-3450-  
 3550\_PC3\_30\_15\_H\_TID7\_NS\_01\_0.009\_0.15\_#  
 1




NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID7\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID7\_NS\_01\_30\_1000\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID7\_NS\_01\_1000\_3000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID7\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID7\_NS\_01\_6000\_26000\_#1


NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID7\_NS\_01\_26000\_40000\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID8\_NS\_01\_0.009\_0.15\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID8\_NS\_01\_0.15\_30\_#1




02:39:28 15.01.2014


02:39:39 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID8\_NS\_01\_30\_1000\_#1

NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID8\_NS\_01\_1000\_3000\_#  
1




02:39:52 15.01.2014




02:40:04 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID8\_NS\_01\_3000\_6000\_#  
1


NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID8\_NS\_01\_6000\_26000\_#  
1




NTNV\_N77-3450-3550\_PC3\_30\_15\_H\_TID8\_NS\_01\_26000\_40000\_#1




NTNV\_N77-3450-3550\_PC3\_30\_15\_H\_TID9\_NS\_01\_0.009\_0.15\_#1



NTNV\_N77-3450-3550\_PC3\_30\_15\_H\_TID9\_NS\_01\_0.15\_30\_#1



NTNV\_N77-3450-3550\_PC3\_30\_15\_H\_TID9\_NS\_01\_30\_1000\_#1




02:40:57 15.01.2014


02:43:09 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID9\_NS\_01\_1000\_3000\_#  
1

NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID9\_NS\_01\_3000\_6000\_#  
1




02:40:21 15.01.2014




02:40:21 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID9\_NS\_01\_6000\_26000\_#  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID9\_NS\_01\_26000\_40000\_#  
\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_15\_H\_TID10\_NS\_01\_0.009\_0.15\_  
 #1




NTVN\_N77-3450-  
 3550\_PC3\_30\_15\_H\_TID10\_NS\_01\_0.15\_30\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_15\_H\_TID10\_NS\_01\_30\_1000\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_15\_H\_TID10\_NS\_01\_1000\_3000\_  
 #1




NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID10\_NS\_01\_3000\_6000\_  
#1



NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID10\_NS\_01\_6000\_26000\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID10\_NS\_01\_26000\_4000\_  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID11\_NS\_01\_0.009\_0.15\_  
#1







NTNV\_N77-3450-3550\_PC3\_30\_15\_H\_TID11\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-3550\_PC3\_30\_15\_H\_TID11\_NS\_01\_30\_1000\_#1



NTNV\_N77-3450-3550\_PC3\_30\_15\_H\_TID11\_NS\_01\_1000\_3000\_#1




NTNV\_N77-3450-3550\_PC3\_30\_15\_H\_TID11\_NS\_01\_3000\_6000\_#1




02:50:04 15.01.2014  
 NTVN\_N77-3450-  
 3550\_PC3\_30\_15\_H\_TID11\_NS\_01\_6000\_26000  
 #1


02:50:15 15.01.2014  
 NTVN\_N77-3450-  
 3550\_PC3\_30\_15\_H\_TID11\_NS\_01\_26000\_4000  
 0\_#1




02:50:01 15.01.2014  
 NTVN\_N77-3450-  
 3550\_PC3\_30\_15\_H\_TID12\_NS\_01\_0.009\_0.15  
 #1




02:50:11 15.01.2014  
 NTVN\_N77-3450-  
 3550\_PC3\_30\_15\_H\_TID12\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID12\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID12\_NS\_01\_1000\_3000\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID12\_NS\_01\_3000\_6000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID12\_NS\_01\_6000\_26000\_#1




02:56:10 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID12\_NS\_01\_26000\_4000  
0\_#1




02:56:09 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID13\_NS\_01\_0.009\_0.15\_#1




02:56:20 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID13\_NS\_01\_0.15\_30\_#1




02:56:21 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID13\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID13\_NS\_01\_1000\_3000\_  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID13\_NS\_01\_3000\_6000\_  
#1



NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID13\_NS\_01\_6000\_26000\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID13\_NS\_01\_26000\_4000  
0\_#1




02:58:07 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID14\_NS\_01\_0.009\_0.15\_  
#1




02:58:17 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID14\_NS\_01\_0.15\_30\_#1




02:58:28 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID14\_NS\_01\_30\_1000\_#1




02:58:39 15.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID14\_NS\_01\_1000\_3000\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID14\_NS\_01\_3000\_6000\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID14\_NS\_01\_6000\_26000  
\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID14\_NS\_01\_26000\_4000  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID15\_NS\_01\_0.009\_0.15\_  
#1




03:02:20 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID15\_NS\_01\_0.15\_30\_#1




03:02:44 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID15\_NS\_01\_30\_1000\_#1



03:02:55 15.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID15\_NS\_01\_1000\_3000\_#1



03:03:00 15.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID15\_NS\_01\_3000\_6000\_#1






NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID15\_NS\_01\_6000\_26000  
\_#1


NTNV\_N77-3450-  
3550\_PC3\_30\_15\_H\_TID15\_NS\_01\_26000\_4000  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID1\_NS\_01\_0.009\_0.15\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID1\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID1\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID1\_NS\_01\_1000\_3000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID1\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID1\_NS\_01\_6000\_26000\_#  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID1\_NS\_01\_26000\_40000  
\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID2\_NS\_01\_0.009\_0.15\_#  
1



NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID2\_NS\_01\_0.15\_30\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID2\_NS\_01\_30\_1000\_#1




03:09:51 15.01.2014


03:10:09 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID2\_NS\_01\_1000\_3000\_#  
1

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID2\_NS\_01\_3000\_6000\_#  
1




03:10:15 15.01.2014




03:10:26 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID2\_NS\_01\_6000\_26000\_#  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID2\_NS\_01\_26000\_40000\_#  
\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_20\_L\_TID3\_NS\_01\_0.009\_0.15\_#  
 1




NTVN\_N77-3450-  
 3550\_PC3\_30\_20\_L\_TID3\_NS\_01\_0.15\_30\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_20\_L\_TID3\_NS\_01\_30\_1000\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_20\_L\_TID3\_NS\_01\_1000\_3000\_#  
 1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID3\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID3\_NS\_01\_6000\_26000\_#  
#1



NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID3\_NS\_01\_26000\_40000\_#  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID4\_NS\_01\_0.009\_0.15\_#  
1




03:15:11 15.01.2014

NTNV\_N77-3450-3550\_PC3\_30\_20\_L\_TID4\_NS\_01\_0.15\_30\_#1




03:15:21 15.01.2014

NTNV\_N77-3450-3550\_PC3\_30\_20\_L\_TID4\_NS\_01\_30\_1000\_#1




03:15:39 15.01.2014

NTNV\_N77-3450-3550\_PC3\_30\_20\_L\_TID4\_NS\_01\_1000\_3000\_#1



03:15:45 15.01.2014

NTNV\_N77-3450-3550\_PC3\_30\_20\_L\_TID4\_NS\_01\_3000\_6000\_#1




03:15:57 15.01.2014


03:19:08 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID4\_NS\_01\_6000\_26000\_  
#1

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID4\_NS\_01\_26000\_40000  
#1



03:18:28 15.01.2014




03:18:49 15.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID5\_NS\_01\_0.009\_0.15\_  
#1

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID5\_NS\_01\_0.15\_30\_#1







NTNV\_N77-3450-3550\_PC3\_30\_20\_L\_TID5\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-3550\_PC3\_30\_20\_L\_TID5\_NS\_01\_1000\_3000\_#1



NTNV\_N77-3450-3550\_PC3\_30\_20\_L\_TID5\_NS\_01\_3000\_6000\_#1




NTNV\_N77-3450-3550\_PC3\_30\_20\_L\_TID5\_NS\_01\_6000\_26000\_#1




03:19:47 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID5\_NS\_01\_26000\_40000  
\_#1




03:21:22 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID6\_NS\_01\_0.009\_0.15\_#  
1




03:21:39 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID6\_NS\_01\_0.15\_30\_#1



03:21:44 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID6\_NS\_01\_30\_1000\_#1




03:21:55 15.01.2014


03:22:00 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID6\_NS\_01\_1000\_3000\_#  
1

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID6\_NS\_01\_3000\_6000\_#  
1




03:22:20 15.01.2014




03:22:21 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID6\_NS\_01\_6000\_26000\_#  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID6\_NS\_01\_26000\_40000\_#  
\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_20\_L\_TID7\_NS\_01\_0.009\_0.15\_#  
 1




NTVN\_N77-3450-  
 3550\_PC3\_30\_20\_L\_TID7\_NS\_01\_0.15\_30\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_20\_L\_TID7\_NS\_01\_30\_1000\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_20\_L\_TID7\_NS\_01\_1000\_3000\_#  
 1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID7\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID7\_NS\_01\_6000\_26000\_#  
#1



NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID7\_NS\_01\_26000\_40000\_#  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID8\_NS\_01\_0.009\_0.15\_#  
1




03:28:06 15.01.2014

NTNV\_N77-3450-3550\_PC3\_30\_20\_L\_TID8\_NS\_01\_0.15\_30\_#1



03:28:17 15.01.2014


NTNV\_N77-3450-3550\_PC3\_30\_20\_L\_TID8\_NS\_01\_30\_1000\_#1



03:28:28 15.01.2014

NTNV\_N77-3450-3550\_PC3\_30\_20\_L\_TID8\_NS\_01\_1000\_3000\_#


1



03:28:40 15.01.2014


NTNV\_N77-3450-3550\_PC3\_30\_20\_L\_TID8\_NS\_01\_3000\_6000\_#

1




03:28:51 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID8\_NS\_01\_6000\_26000\_  
#1




03:29:09 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID8\_NS\_01\_26000\_40000\_  
#1




03:31:46 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID9\_NS\_01\_0.009\_0.15\_  
#1




03:31:56 15.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID9\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID9\_NS\_01\_30\_1000\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID9\_NS\_01\_1000\_3000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID9\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID9\_NS\_01\_6000\_26000\_#  
#1






03:30:59 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID9\_NS\_01\_26000\_40000  
\_#1




03:34:28 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID10\_NS\_01\_0.009\_0.15\_  
\_#1




03:34:39 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID10\_NS\_01\_0.15\_30\_#1



03:34:49 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID10\_NS\_01\_30\_1000\_#1




03:35:00 15.01.2014


03:35:17 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID10\_NS\_01\_1000\_3000\_  
#1

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID10\_NS\_01\_3000\_6000\_  
#1




03:35:25 15.01.2014




03:35:26 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID10\_NS\_01\_6000\_26000\_  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID10\_NS\_01\_26000\_4000  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID11\_NS\_01\_0.009\_0.15\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID11\_NS\_01\_0.15\_30\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID11\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID11\_NS\_01\_1000\_3000\_#1




03:37:56 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID11\_NS\_01\_3000\_6000\_  
#1




03:38:00 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID11\_NS\_01\_6000\_26000\_  
#1




03:38:19 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID11\_NS\_01\_26000\_4000\_  
0\_#1




03:38:56 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID12\_NS\_01\_0.009\_0.15\_  
#1




03-00-06 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID12\_NS\_01\_0.15\_30\_#1




03-00-17 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID12\_NS\_01\_30\_1000\_#1




03-00-29 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID12\_NS\_01\_1000\_3000\_#1



03-00-41 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID12\_NS\_01\_3000\_6000\_#1




03:40:53 15.01.2014


03:41:04 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID12\_NS\_01\_6000\_26000  
\_#1

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID12\_NS\_01\_26000\_4000  
0\_#1




03:43:27 15.01.2014




03:43:47 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID13\_NS\_01\_0.009\_0.15\_#1


NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID13\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID13\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID13\_NS\_01\_1000\_3000\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID13\_NS\_01\_3000\_6000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID13\_NS\_01\_6000\_26000\_#1




03-04-05 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID13\_NS\_01\_26000\_4000  
0\_#1




03-04-20 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID14\_NS\_01\_0.009\_0.15\_  
#1



03-04-20 15.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID14\_NS\_01\_0.15\_30\_#1



03-04-01 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID14\_NS\_01\_30\_1000\_#1






03:46:51 15.01.2014


03:47:04 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID14\_NS\_01\_1000\_3000\_  
#1

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID14\_NS\_01\_3000\_6000\_  
#1




03:47:16 15.01.2014



03:47:27 15.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID14\_NS\_01\_6000\_26000\_  
#1

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID14\_NS\_01\_26000\_4000  
0\_#1




03-49-21 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID15\_NS\_01\_0.009\_0.15\_  
#1




03-49-21 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID15\_NS\_01\_0.15\_30\_#1




03-49-49 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID15\_NS\_01\_30\_1000\_#1




03-49-57 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID15\_NS\_01\_1000\_3000\_  
#1




03:50:06 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID15\_NS\_01\_3000\_6000\_  
#1




03:50:19 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID15\_NS\_01\_6000\_26000  
\_#1




03:50:20 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_L\_TID15\_NS\_01\_26000\_4000  
0\_#1




03:50:20 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID1\_NS\_01\_0.009\_0.15\_#  
1




03:52:30 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID1\_NS\_01\_0.15\_30\_#1




03:52:41 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID1\_NS\_01\_30\_1000\_#1




03:52:59 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID1\_NS\_01\_1000\_3000\_#  
1




03:53:05 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID1\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID1\_NS\_01\_6000\_26000\_  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID1\_NS\_01\_26000\_40000\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID2\_NS\_01\_0.009\_0.15\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID2\_NS\_01\_0.15\_30\_  
#1







NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID2\_NS\_01\_26000\_40000  
\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID3\_NS\_01\_0.009\_0.15\_#  
1



NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID3\_NS\_01\_0.15\_30\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID3\_NS\_01\_30\_1000\_#1




94:01:29 15.81.2014


94:01:25 15.81.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID3\_NS\_01\_1000\_3000\_#  
1

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID3\_NS\_01\_3000\_6000\_#  
1



94:01:47 15.81.2014




94:02:00 15.81.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID3\_NS\_01\_6000\_26000\_#  
#1

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID3\_NS\_01\_26000\_40000\_#  
\_#1







NTNV\_N77-3450-  
 3550\_PC3\_30\_20\_M\_TID4\_NS\_01\_0.009\_0.15\_#  
 1




NTNV\_N77-3450-  
 3550\_PC3\_30\_20\_M\_TID4\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
 3550\_PC3\_30\_20\_M\_TID4\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
 3550\_PC3\_30\_20\_M\_TID4\_NS\_01\_1000\_3000\_#  
 1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID4\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID4\_NS\_01\_6000\_26000\_#  
#1



NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID4\_NS\_01\_26000\_40000\_#  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID5\_NS\_01\_0.009\_0.15\_#  
1




04:10:45 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID5\_NS\_01\_0.15\_30\_#1



04:10:56 15.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID5\_NS\_01\_30\_1000\_#1



04:11:07 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID5\_NS\_01\_1000\_3000\_#


1



04:11:19 15.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID5\_NS\_01\_3000\_6000\_#

1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID5\_NS\_01\_6000\_26000\_  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID5\_NS\_01\_26000\_40000\_  
#1



NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID6\_NS\_01\_0.009\_0.15\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID6\_NS\_01\_0.15\_30\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID6\_NS\_01\_30\_1000\_#1


NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID6\_NS\_01\_1000\_3000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID6\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID6\_NS\_01\_6000\_26000\_#  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID6\_NS\_01\_26000\_40000  
\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID7\_NS\_01\_0.009\_0.15\_#  
1



NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID7\_NS\_01\_0.15\_30\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID7\_NS\_01\_30\_1000\_#1




94:29:28 15.01.2014


94:29:50 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID7\_NS\_01\_1000\_3000\_#  
1

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID7\_NS\_01\_3000\_6000\_#  
1




94:21:01 15.01.2014




94:21:19 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID7\_NS\_01\_6000\_26000\_#  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID7\_NS\_01\_26000\_40000\_#  
\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_20\_M\_TID8\_NS\_01\_0.009\_0.15\_#  
 1



NTVN\_N77-3450-  
 3550\_PC3\_30\_20\_M\_TID8\_NS\_01\_0.15\_30\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_20\_M\_TID8\_NS\_01\_30\_1000\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_20\_M\_TID8\_NS\_01\_1000\_3000\_#  
 1






94:23:21 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID8\_NS\_01\_3000\_6000\_#  
1




94:23:44 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID8\_NS\_01\_6000\_26000\_#  
#1




94:23:55 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID8\_NS\_01\_26000\_40000\_#  
#1




94:25:49 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID9\_NS\_01\_0.009\_0.15\_#  
1




94:25:59 15.01.2014

NTNV\_N77-3450-3550\_PC3\_30\_20\_M\_TID9\_NS\_01\_0.15\_30\_#1




94:26:19 15.01.2014

NTNV\_N77-3450-3550\_PC3\_30\_20\_M\_TID9\_NS\_01\_30\_1000\_#1




94:26:21 15.01.2014

NTNV\_N77-3450-3550\_PC3\_30\_20\_M\_TID9\_NS\_01\_1000\_3000\_#1




94:26:39 15.01.2014

NTNV\_N77-3450-3550\_PC3\_30\_20\_M\_TID9\_NS\_01\_3000\_6000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID9\_NS\_01\_6000\_26000\_  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID9\_NS\_01\_26000\_40000\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID10\_NS\_01\_0.009\_0.15\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID10\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID10\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID10\_NS\_01\_1000\_3000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID10\_NS\_01\_3000\_6000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID10\_NS\_01\_6000\_26000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID10\_NS\_01\_26000\_4000  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID11\_NS\_01\_0.009\_0.15\_  
#1



NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID11\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID11\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID11\_NS\_01\_1000\_3000\_  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID11\_NS\_01\_3000\_6000\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID11\_NS\_01\_6000\_26000\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID11\_NS\_01\_26000\_4000  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID12\_NS\_01\_0.009\_0.15\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID12\_NS\_01\_0.15\_30\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID12\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID12\_NS\_01\_1000\_3000\_#1




04:36:41 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID12\_NS\_01\_3000\_6000\_#1




04:36:54 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID12\_NS\_01\_6000\_26000\_#1



04:36:05 15.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID12\_NS\_01\_26000\_4000\_0\_#1




04:36:54 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID13\_NS\_01\_0.009\_0.15\_#1







NTNV\_N77-3450-3550\_PC3\_30\_20\_M\_TID13\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-3550\_PC3\_30\_20\_M\_TID13\_NS\_01\_30\_1000\_#1



NTNV\_N77-3450-3550\_PC3\_30\_20\_M\_TID13\_NS\_01\_1000\_3000\_#1




NTNV\_N77-3450-3550\_PC3\_30\_20\_M\_TID13\_NS\_01\_3000\_6000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID13\_NS\_01\_6000\_26000  
\_#1


NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID13\_NS\_01\_26000\_4000  
0\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID14\_NS\_01\_0.009\_0.15\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID14\_NS\_01\_0.15\_30\_#1




04:41:16 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID14\_NS\_01\_30\_1000\_#1




04:41:27 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID14\_NS\_01\_1000\_3000\_#1




04:41:29 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID14\_NS\_01\_3000\_6000\_#1




04:41:51 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID14\_NS\_01\_6000\_26000\_#1




04:40:04 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID14\_NS\_01\_26000\_4000  
0\_#1




04:40:39 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID15\_NS\_01\_0.009\_0.15\_  
#1




04:40:50 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID15\_NS\_01\_0.15\_30\_#1




04:44:01 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID15\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID15\_NS\_01\_1000\_3000\_  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID15\_NS\_01\_3000\_6000\_  
#1



NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID15\_NS\_01\_6000\_26000\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_M\_TID15\_NS\_01\_26000\_4000  
0\_#1




04:40:29 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID1\_NS\_01\_0.009\_0.15\_#  
1




04:40:29 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID1\_NS\_01\_0.15\_30\_#1




04:47:01 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID1\_NS\_01\_30\_1000\_#1




04:47:19 15.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID1\_NS\_01\_1000\_3000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID1\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID1\_NS\_01\_6000\_26000\_#  
#1



NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID1\_NS\_01\_26000\_40000\_#  
#1



NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID2\_NS\_01\_0.009\_0.15\_#  
1




04:49:58 15.11.2014


04:50:00 15.11.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID2\_NS\_01\_0.15\_30\_#1

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID2\_NS\_01\_30\_1000\_#1



04:50:19 15.11.2014



04:50:21 15.11.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID2\_NS\_01\_1000\_3000\_#

1

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID2\_NS\_01\_3000\_6000\_#


1






NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID2\_NS\_01\_6000\_26000\_  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID2\_NS\_01\_26000\_40000\_  
#1



NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID3\_NS\_01\_0.009\_0.15\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID3\_NS\_01\_0.15\_30\_  
#1




9453:19 15.01.2014

NTNV\_N77-3450-3550\_PC3\_30\_20\_H\_TID3\_NS\_01\_30\_1000\_#1




9453:21 15.01.2014

NTNV\_N77-3450-3550\_PC3\_30\_20\_H\_TID3\_NS\_01\_1000\_3000\_#1




9453:29 15.01.2014

NTNV\_N77-3450-3550\_PC3\_30\_20\_H\_TID3\_NS\_01\_3000\_6000\_#1




9453:46 15.01.2014

NTNV\_N77-3450-3550\_PC3\_30\_20\_H\_TID3\_NS\_01\_6000\_26000\_#1




9453:57 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID3\_NS\_01\_26000\_40000  
\_#1




9456:01 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID4\_NS\_01\_0.009\_0.15\_#  
1




9456:11 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID4\_NS\_01\_0.15\_30\_#1




9456:29 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID4\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID4\_NS\_01\_1000\_3000\_#  
1


NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID4\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID4\_NS\_01\_6000\_26000\_#  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID4\_NS\_01\_26000\_40000\_#  
\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID5\_NS\_01\_0.009\_0.15\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID5\_NS\_01\_0.15\_30\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID5\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID5\_NS\_01\_1000\_3000\_#  
1




04:58:27 15.11.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID5\_NS\_01\_3000\_6000\_#  
1




04:58:49 15.11.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID5\_NS\_01\_6000\_26000\_#  
1




05:00:00 15.11.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID5\_NS\_01\_26000\_40000\_#  
1




05:01:56 15.11.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID6\_NS\_01\_0.009\_0.15\_#  
1



NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID6\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID6\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID6\_NS\_01\_1000\_3000\_#

1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID6\_NS\_01\_3000\_6000\_#

1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID6\_NS\_01\_6000\_26000\_  
#1

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID6\_NS\_01\_26000\_40000\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID7\_NS\_01\_0.009\_0.15\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID7\_NS\_01\_0.15\_30\_  
#1







NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID7\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID7\_NS\_01\_1000\_3000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID7\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID7\_NS\_01\_6000\_26000\_#  
1




NTVN\_N77-3450-  
 3550\_PC3\_30\_20\_H\_TID7\_NS\_01\_26000\_40000  
 #1




NTVN\_N77-3450-  
 3550\_PC3\_30\_20\_H\_TID8\_NS\_01\_0.009\_0.15\_#  
 1



NTVN\_N77-3450-  
 3550\_PC3\_30\_20\_H\_TID8\_NS\_01\_0.15\_30\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_20\_H\_TID8\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID8\_NS\_01\_1000\_3000\_#  
1


NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID8\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID8\_NS\_01\_6000\_26000\_#  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID8\_NS\_01\_26000\_40000\_#  
\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID9\_NS\_01\_0.009\_0.15\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID9\_NS\_01\_0.15\_30\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID9\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID9\_NS\_01\_1000\_3000\_#  
1




09-11-55 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID9\_NS\_01\_3000\_6000\_#  
1




09-12-09 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID9\_NS\_01\_6000\_26000\_#  
1




09-12-20 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID9\_NS\_01\_26000\_40000\_#  
1




09-14-22 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID10\_NS\_01\_0.009\_0.15\_#  
1




85-14-20 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID10\_NS\_01\_0.15\_30\_#1




85-14-44 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID10\_NS\_01\_30\_1000\_#1




85-14-55 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID10\_NS\_01\_1000\_3000\_#1




85-15-07 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID10\_NS\_01\_3000\_6000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID10\_NS\_01\_6000\_26000  
\_#1

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID10\_NS\_01\_26000\_4000  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID11\_NS\_01\_0.009\_0.15\_#1

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID11\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID11\_NS\_01\_30\_1000\_#1

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID11\_NS\_01\_1000\_3000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID11\_NS\_01\_3000\_6000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID11\_NS\_01\_6000\_26000\_#1







NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID11\_NS\_01\_26000\_4000  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID12\_NS\_01\_0.009\_0.15\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID12\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID12\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID12\_NS\_01\_1000\_3000\_  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID12\_NS\_01\_3000\_6000\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID12\_NS\_01\_6000\_26000\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID12\_NS\_01\_26000\_4000  
0\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_20\_H\_TID13\_NS\_01\_0.009\_0.15\_  
 #1





NTVN\_N77-3450-  
 3550\_PC3\_30\_20\_H\_TID13\_NS\_01\_0.15\_30\_#1



NTVN\_N77-3450-  
 3550\_PC3\_30\_20\_H\_TID13\_NS\_01\_30\_1000\_#1





NTVN\_N77-3450-  
 3550\_PC3\_30\_20\_H\_TID13\_NS\_01\_1000\_3000\_  
 #1




NTNV\_N77-3450-3550\_PC3\_30\_20\_H\_TID13\_NS\_01\_3000\_6000\_#1

NTNV\_N77-3450-3550\_PC3\_30\_20\_H\_TID13\_NS\_01\_6000\_26000\_#1




NTNV\_N77-3450-3550\_PC3\_30\_20\_H\_TID13\_NS\_01\_26000\_4000\_0\_#1

NTNV\_N77-3450-3550\_PC3\_30\_20\_H\_TID14\_NS\_01\_0.009\_0.15\_#1




05:29:15 15.01.2014

NTNV\_N77-3450-3550\_PC3\_30\_20\_H\_TID14\_NS\_01\_0.15\_30\_#1




05:29:16 15.01.2014

NTNV\_N77-3450-3550\_PC3\_30\_20\_H\_TID14\_NS\_01\_30\_1000\_#1




05:29:37 15.01.2014

NTNV\_N77-3450-3550\_PC3\_30\_20\_H\_TID14\_NS\_01\_1000\_3000\_#1




05:29:49 15.01.2014

NTNV\_N77-3450-3550\_PC3\_30\_20\_H\_TID14\_NS\_01\_3000\_6000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID14\_NS\_01\_6000\_26000  
\_#1


NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID14\_NS\_01\_26000\_4000  
0\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID15\_NS\_01\_0.009\_0.15\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID15\_NS\_01\_0.15\_30\_#1




09:30:26 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID15\_NS\_01\_30\_1000\_#1




09:30:37 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID15\_NS\_01\_1000\_3000\_#1




09:30:49 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID15\_NS\_01\_3000\_6000\_#1




09:33:01 15.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID15\_NS\_01\_6000\_26000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_20\_H\_TID15\_NS\_01\_26000\_4000  
0\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID1\_NS\_01\_0.009\_0.15\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID1\_NS\_01\_0.15\_30\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID1\_NS\_01\_30\_1000\_#1






09:35:36 15.01.2014


09:35:40 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID1\_NS\_01\_1000\_3000\_#  
1

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID1\_NS\_01\_3000\_6000\_#  
1




09:36:00 15.01.2014




09:36:11 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID1\_NS\_01\_6000\_26000\_#  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID1\_NS\_01\_26000\_40000\_#  
\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_25\_L\_TID2\_NS\_01\_0.009\_0.15\_#  
 1




NTVN\_N77-3450-  
 3550\_PC3\_30\_25\_L\_TID2\_NS\_01\_0.15\_30\_#1



NTVN\_N77-3450-  
 3550\_PC3\_30\_25\_L\_TID2\_NS\_01\_30\_1000\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_25\_L\_TID2\_NS\_01\_1000\_3000\_#  
 1




05:38:42 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID2\_NS\_01\_3000\_6000\_#  
1




05:38:54 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID2\_NS\_01\_6000\_26000\_#  
#1




05:39:06 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID2\_NS\_01\_26000\_40000\_#  
#1




05:40:13 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID3\_NS\_01\_0.009\_0.15\_#  
1




05:41:24 15.01.2024

NTNV\_N77-3450-3550\_PC3\_30\_25\_L\_TID3\_NS\_01\_0.15\_30\_#1




05:41:25 15.01.2024

NTNV\_N77-3450-3550\_PC3\_30\_25\_L\_TID3\_NS\_01\_30\_1000\_#1




05:41:46 15.01.2024

NTNV\_N77-3450-3550\_PC3\_30\_25\_L\_TID3\_NS\_01\_1000\_3000\_#1



05:41:58 15.01.2024

NTNV\_N77-3450-3550\_PC3\_30\_25\_L\_TID3\_NS\_01\_3000\_6000\_#1




05:40:11 15.01.2014


05:40:29 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID3\_NS\_01\_6000\_26000\_  
#1

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID3\_NS\_01\_26000\_40000  
#1




05:44:59 15.01.2014




05:45:10 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID4\_NS\_01\_0.009\_0.15\_  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID4\_NS\_01\_0.15\_30\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID4\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID4\_NS\_01\_1000\_3000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID4\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID4\_NS\_01\_6000\_26000\_#  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID4\_NS\_01\_26000\_40000  
\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID5\_NS\_01\_0.009\_0.15\_#  
1



NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID5\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID5\_NS\_01\_30\_1000\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID5\_NS\_01\_1000\_3000\_#  
1


NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID5\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID5\_NS\_01\_6000\_26000\_#  
#1

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID5\_NS\_01\_26000\_40000\_#  
\_#1







NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID6\_NS\_01\_0.009\_0.15\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID6\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID6\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID6\_NS\_01\_1000\_3000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID6\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID6\_NS\_01\_6000\_26000\_#  
#1



NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID6\_NS\_01\_26000\_40000\_#  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID7\_NS\_01\_0.009\_0.15\_#  
1




05:56:36 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID7\_NS\_01\_0.15\_30\_#1



05:56:47 15.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID7\_NS\_01\_30\_1000\_#1



05:56:58 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID7\_NS\_01\_1000\_3000\_#


1



05:57:11 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID7\_NS\_01\_3000\_6000\_#

1




05:57:24 15.01.2014


05:57:26 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID7\_NS\_01\_6000\_26000\_  
#1

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID7\_NS\_01\_26000\_40000  
#1




05:58:10 15.01.2014



05:58:21 15.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID8\_NS\_01\_0.009\_0.15\_  
#1

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID8\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID8\_NS\_01\_30\_1000\_#1


NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID8\_NS\_01\_1000\_3000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID8\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID8\_NS\_01\_6000\_26000\_#  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID8\_NS\_01\_26000\_40000  
\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID9\_NS\_01\_0.009\_0.15\_#  
1



NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID9\_NS\_01\_0.15\_30\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID9\_NS\_01\_30\_1000\_#1




06:02:27 15.11.2014


06:02:29 15.11.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID9\_NS\_01\_1000\_3000\_#  
1

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID9\_NS\_01\_3000\_6000\_#  
1




06:02:51 15.11.2014




06:03:09 15.11.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID9\_NS\_01\_6000\_26000\_#  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID9\_NS\_01\_26000\_40000\_#  
\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID10\_NS\_01\_0.009\_0.15\_  
#1



NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID10\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID10\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID10\_NS\_01\_1000\_3000\_  
#1






05:06:29 15.11.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID10\_NS\_01\_3000\_6000\_  
#1




05:06:41 15.11.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID10\_NS\_01\_6000\_26000  
#1




05:06:53 15.11.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID10\_NS\_01\_26000\_4000  
0\_#1




05:08:28 15.11.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID11\_NS\_01\_0.009\_0.15\_  
#1




06:08:39 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID11\_NS\_01\_0.15\_30\_#1




06:08:51 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID11\_NS\_01\_30\_1000\_#1




06:09:01 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID11\_NS\_01\_1000\_3000\_#1




06:09:15 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID11\_NS\_01\_3000\_6000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID11\_NS\_01\_6000\_26000  
\_#1


NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID11\_NS\_01\_26000\_4000  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID12\_NS\_01\_0.009\_0.15\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID12\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID12\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID12\_NS\_01\_1000\_3000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID12\_NS\_01\_3000\_6000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID12\_NS\_01\_6000\_26000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID12\_NS\_01\_26000\_4000  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID13\_NS\_01\_0.009\_0.15\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID13\_NS\_01\_0.15\_30\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID13\_NS\_01\_30\_1000\_#1




05:17:47 15.01.2014


05:17:59 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID13\_NS\_01\_1000\_3000\_  
#1

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID13\_NS\_01\_3000\_6000\_  
#1





05:18:11 15.01.2014



05:18:29 15.01.2014



NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID13\_NS\_01\_6000\_26000\_  
#1

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID13\_NS\_01\_26000\_4000\_  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID14\_NS\_01\_0.009\_0.15\_  
#1

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID14\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID14\_NS\_01\_30\_1000\_#1


NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID14\_NS\_01\_1000\_3000\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID14\_NS\_01\_3000\_6000\_  
#1



NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID14\_NS\_01\_6000\_26000  
\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID14\_NS\_01\_26000\_4000  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID15\_NS\_01\_0.009\_0.15\_  
#1







NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID15\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID15\_NS\_01\_30\_1000\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID15\_NS\_01\_1000\_3000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID15\_NS\_01\_3000\_6000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID15\_NS\_01\_6000\_26000  
\_#1


NTNV\_N77-3450-  
3550\_PC3\_30\_25\_L\_TID15\_NS\_01\_26000\_4000  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID1\_NS\_01\_0.009\_0.15\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID1\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID1\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID1\_NS\_01\_1000\_3000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID1\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID1\_NS\_01\_6000\_26000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID1\_NS\_01\_26000\_40000  
\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID2\_NS\_01\_0.009\_0.15\_#  
1



NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID2\_NS\_01\_0.15\_30\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID2\_NS\_01\_30\_1000\_#1