



NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID2\_NS\_01\_1000\_3000\_#  
1


NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID2\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID2\_NS\_01\_6000\_26000\_#  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID2\_NS\_01\_26000\_40000\_#  
\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_25\_M\_TID3\_NS\_01\_0.009\_0.15\_#  
 1




NTVN\_N77-3450-  
 3550\_PC3\_30\_25\_M\_TID3\_NS\_01\_0.15\_30\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_25\_M\_TID3\_NS\_01\_30\_1000\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_25\_M\_TID3\_NS\_01\_1000\_3000\_#  
 1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID3\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID3\_NS\_01\_6000\_26000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID3\_NS\_01\_26000\_40000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID4\_NS\_01\_0.009\_0.15\_#  
1




NTNV\_N77-3450-3550\_PC3\_30\_25\_M\_TID4\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-3550\_PC3\_30\_25\_M\_TID4\_NS\_01\_30\_1000\_#1



NTNV\_N77-3450-3550\_PC3\_30\_25\_M\_TID4\_NS\_01\_1000\_3000\_#1




NTNV\_N77-3450-3550\_PC3\_30\_25\_M\_TID4\_NS\_01\_3000\_6000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID4\_NS\_01\_6000\_26000\_  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID4\_NS\_01\_26000\_40000\_  
#1



NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID5\_NS\_01\_0.009\_0.15\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID5\_NS\_01\_0.15\_30\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID5\_NS\_01\_30\_1000\_#1

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID5\_NS\_01\_1000\_3000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID5\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID5\_NS\_01\_6000\_26000\_#  
#1







NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID5\_NS\_01\_26000\_40000  
\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID6\_NS\_01\_0.009\_0.15\_#  
1



NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID6\_NS\_01\_0.15\_30\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID6\_NS\_01\_30\_1000\_#1




05:48:16 15.01.2014


05:48:28 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID6\_NS\_01\_1000\_3000\_#  
1

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID6\_NS\_01\_3000\_6000\_#  
1



05:48:40 15.01.2014




05:48:52 15.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID6\_NS\_01\_6000\_26000\_#  
#1

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID6\_NS\_01\_26000\_40000\_#  
\_#1







NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID7\_NS\_01\_0.009\_0.15\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID7\_NS\_01\_0.15\_30\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID7\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID7\_NS\_01\_1000\_3000\_#  
1




06:52:24 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID7\_NS\_01\_3000\_6000\_#  
1




06:52:26 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID7\_NS\_01\_6000\_26000\_#  
#1




06:52:40 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID7\_NS\_01\_26000\_40000\_#  
#1




06:54:51 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID8\_NS\_01\_0.009\_0.15\_#  
1




06:55:01 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID8\_NS\_01\_0.15\_30\_#1



06:55:19 15.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID8\_NS\_01\_30\_1000\_#1



06:55:24 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID8\_NS\_01\_1000\_3000\_#


1




06:55:36 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID8\_NS\_01\_3000\_6000\_#


1




NTNV\_N77-3450-  
 3550\_PC3\_30\_25\_M\_TID8\_NS\_01\_6000\_26000\_#1




NTNV\_N77-3450-  
 3550\_PC3\_30\_25\_M\_TID8\_NS\_01\_26000\_40000\_#1



NTNV\_N77-3450-  
 3550\_PC3\_30\_25\_M\_TID9\_NS\_01\_0.009\_0.15\_#1



NTNV\_N77-3450-  
 3550\_PC3\_30\_25\_M\_TID9\_NS\_01\_0.15\_0.30\_#1




05:58:28 15.11.2014


05:58:29 15.11.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID9\_NS\_01\_30\_1000\_#1

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID9\_NS\_01\_1000\_3000\_#  
1




05:58:51 15.11.2014




05:58:09 15.11.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID9\_NS\_01\_3000\_6000\_#  
1


NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID9\_NS\_01\_6000\_26000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID9\_NS\_01\_26000\_40000  
\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID10\_NS\_01\_0.009\_0.15\_  
\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID10\_NS\_01\_0.15\_30\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID10\_NS\_01\_30\_1000\_#1






07:01:28 15.01.2014


07:01:50 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID10\_NS\_01\_1000\_3000\_  
#1

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID10\_NS\_01\_3000\_6000\_  
#1




07:02:01 15.01.2014




07:02:14 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID10\_NS\_01\_6000\_26000\_  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID10\_NS\_01\_26000\_4000  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID11\_NS\_01\_0.009\_0.15\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID11\_NS\_01\_0.15\_30\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID11\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID11\_NS\_01\_1000\_3000\_#1




07:04:54 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID11\_NS\_01\_3000\_6000\_#1




07:05:06 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID11\_NS\_01\_6000\_26000\_#1




07:05:18 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID11\_NS\_01\_26000\_4000\_0\_#1




07:07:08 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID12\_NS\_01\_0.009\_0.15\_#1




07:07:21 15.01.2014

NTNV\_N77-3450-3550\_PC3\_30\_25\_M\_TID12\_NS\_01\_0.15\_30\_#1




07:07:21 15.01.2014

NTNV\_N77-3450-3550\_PC3\_30\_25\_M\_TID12\_NS\_01\_30\_1000\_#1




07:07:49 15.01.2014

NTNV\_N77-3450-3550\_PC3\_30\_25\_M\_TID12\_NS\_01\_1000\_3000\_#1



07:07:55 15.01.2014

NTNV\_N77-3450-3550\_PC3\_30\_25\_M\_TID12\_NS\_01\_3000\_6000\_#1




07-08-07 15:01:1014


07-08-19 15:01:1014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID12\_NS\_01\_6000\_26000  
\_#1

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID12\_NS\_01\_26000\_4000  
0\_#1




07-10-19 15:01:1014



07-10-20 15:01:1014


NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID13\_NS\_01\_0.009\_0.15\_  
\_#1

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID13\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID13\_NS\_01\_30\_1000\_#1

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID13\_NS\_01\_1000\_3000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID13\_NS\_01\_3000\_6000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID13\_NS\_01\_6000\_26000\_#1







NTVN\_N77-3450-  
 3550\_PC3\_30\_25\_M\_TID13\_NS\_01\_26000\_4000  
 0\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_25\_M\_TID14\_NS\_01\_0.009\_0.15\_  
 #1



NTVN\_N77-3450-  
 3550\_PC3\_30\_25\_M\_TID14\_NS\_01\_0.15\_30\_#1



NTVN\_N77-3450-  
 3550\_PC3\_30\_25\_M\_TID14\_NS\_01\_30\_1000\_#1




07:14:00 15.01.2014


07:14:11 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID14\_NS\_01\_1000\_3000\_  
#1

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID14\_NS\_01\_3000\_6000\_  
#1




07:14:24 15.01.2014




07:14:25 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID14\_NS\_01\_6000\_26000\_  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID14\_NS\_01\_26000\_4000  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID15\_NS\_01\_0.009\_0.15\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID15\_NS\_01\_0.15\_30\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID15\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID15\_NS\_01\_1000\_3000\_  
#1




07:17:27 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID15\_NS\_01\_3000\_6000\_  
#1




07:17:29 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID15\_NS\_01\_6000\_26000  
\_#1




07:17:51 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_M\_TID15\_NS\_01\_26000\_4000  
0\_#1




07:20:07 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID1\_NS\_01\_0.009\_0.15\_#  
1




07:20:18 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID1\_NS\_01\_0.15\_30\_#1



07:20:29 15.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID1\_NS\_01\_30\_1000\_#1



07:20:41 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID1\_NS\_01\_1000\_3000\_#


1



07:20:59 15.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID1\_NS\_01\_3000\_6000\_#

1




07:21:05 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID1\_NS\_01\_6000\_26000\_  
#1




07:21:17 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID1\_NS\_01\_26000\_40000\_  
#1



07:23:29 15.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID2\_NS\_01\_0.009\_0.15\_  
#1




07:23:34 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID2\_NS\_01\_0.15\_30\_  
#1







NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID2\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID2\_NS\_01\_1000\_3000\_#  
1



NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID2\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID2\_NS\_01\_6000\_26000\_#  
1




07:24:22 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID2\_NS\_01\_26000\_40000  
\_#1




07:26:29 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID3\_NS\_01\_0.009\_0.15\_#  
1




07:26:29 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID3\_NS\_01\_0.15\_30\_#1



07:26:50 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID3\_NS\_01\_30\_1000\_#1




07:27:01 15.01.2014


07:27:19 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID3\_NS\_01\_1000\_3000\_#  
1

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID3\_NS\_01\_3000\_6000\_#  
1




07:27:26 15.01.2014




07:27:37 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID3\_NS\_01\_6000\_26000\_#  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID3\_NS\_01\_26000\_40000\_#  
\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_25\_H\_TID4\_NS\_01\_0.009\_0.15\_#  
 1




NTVN\_N77-3450-  
 3550\_PC3\_30\_25\_H\_TID4\_NS\_01\_0.15\_30\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_25\_H\_TID4\_NS\_01\_30\_1000\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_25\_H\_TID4\_NS\_01\_1000\_3000\_#  
 1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID4\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID4\_NS\_01\_6000\_26000\_#  
1



NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID4\_NS\_01\_26000\_40000\_#  
1



NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID5\_NS\_01\_0.009\_0.15\_#  
1




07:35:40 15.01.2014


07:35:51 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID5\_NS\_01\_0.15\_30\_#1

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID5\_NS\_01\_30\_1000\_#1



07:36:01 15.01.2014




07:36:14 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID5\_NS\_01\_1000\_3000\_#  
1


NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID5\_NS\_01\_3000\_6000\_#  
1






NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID5\_NS\_01\_6000\_26000\_  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID5\_NS\_01\_26000\_40000\_  
#1



NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID6\_NS\_01\_0.009\_0.15\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID6\_NS\_01\_0.15\_30\_  
#1




07-30-40 15.01.2014

NTNV\_N77-3450-3550\_PC3\_30\_25\_H\_TID6\_NS\_01\_30\_1000\_#1




07-30-51 15.01.2014

NTNV\_N77-3450-3550\_PC3\_30\_25\_H\_TID6\_NS\_01\_1000\_3000\_#1




07-34-05 15.01.2014

NTNV\_N77-3450-3550\_PC3\_30\_25\_H\_TID6\_NS\_01\_3000\_6000\_#1




07-34-17 15.01.2014

NTNV\_N77-3450-3550\_PC3\_30\_25\_H\_TID6\_NS\_01\_6000\_26000\_#1




07-06-27 15:01:2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID6\_NS\_01\_26000\_40000  
\_#1




07-06-27 15:01:2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID7\_NS\_01\_0.009\_0.15\_#  
1




07-06-27 15:01:2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID7\_NS\_01\_0.15\_30\_#1



07-06-27 15:01:2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID7\_NS\_01\_30\_1000\_#1




07:40:59 15.01.2014


07:47:11 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID7\_NS\_01\_1000\_3000\_#  
1

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID7\_NS\_01\_3000\_6000\_#  
1




07:47:25 15.01.2014




07:47:27 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID7\_NS\_01\_6000\_26000\_#  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID7\_NS\_01\_26000\_40000\_#  
\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_25\_H\_TID8\_NS\_01\_0.009\_0.15\_#  
 1




NTVN\_N77-3450-  
 3550\_PC3\_30\_25\_H\_TID8\_NS\_01\_0.15\_30\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_25\_H\_TID8\_NS\_01\_30\_1000\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_25\_H\_TID8\_NS\_01\_1000\_3000\_#  
 1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID8\_NS\_01\_3000\_6000\_#  
1



NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID8\_NS\_01\_6000\_26000\_#  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID8\_NS\_01\_26000\_40000\_#  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID9\_NS\_01\_0.009\_0.15\_#  
1






07:56:31 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID9\_NS\_01\_0.15\_30\_#1



07:56:41 15.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID9\_NS\_01\_30\_1000\_#1



07:56:53 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID9\_NS\_01\_1000\_3000\_#


1




07:57:05 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID9\_NS\_01\_3000\_6000\_#


1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID9\_NS\_01\_6000\_26000\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID9\_NS\_01\_26000\_40000\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID10\_NS\_01\_0.009\_0.15\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID10\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID10\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID10\_NS\_01\_1000\_3000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID10\_NS\_01\_3000\_6000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID10\_NS\_01\_6000\_26000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID10\_NS\_01\_26000\_4000  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID11\_NS\_01\_0.009\_0.15\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID11\_NS\_01\_0.15\_30\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID11\_NS\_01\_30\_1000\_#1




08-03-21 15:11:1014


08-03-24 15:11:1014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID11\_NS\_01\_1000\_3000\_  
#1

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID11\_NS\_01\_3000\_6000\_  
#1




08-03-27 15:11:1014




08-04-09 15:11:1014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID11\_NS\_01\_6000\_26000\_  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID11\_NS\_01\_26000\_4000  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID12\_NS\_01\_0.009\_0.15\_  
#1



NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID12\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID12\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID12\_NS\_01\_1000\_3000\_  
#1






08:15:19 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID12\_NS\_01\_3000\_6000\_  
#1




08:15:20 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID12\_NS\_01\_6000\_26000\_  
#1




08:15:49 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID12\_NS\_01\_26000\_4000\_  
0\_#1




08:18:05 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID13\_NS\_01\_0.009\_0.15\_  
#1




08:18:16 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID13\_NS\_01\_0.15\_30\_#1




08:18:27 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID13\_NS\_01\_30\_1000\_#1




08:18:38 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID13\_NS\_01\_1000\_3000\_#1



08:18:50 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID13\_NS\_01\_3000\_6000\_#1




08:19:09 15.01.2014


08:19:14 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID13\_NS\_01\_6000\_26000  
\_#1

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID13\_NS\_01\_26000\_4000  
0\_#1




08:21:26 15.01.2014



08:21:27 15.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID14\_NS\_01\_0.009\_0.15\_#1

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID14\_NS\_01\_0.15\_30\_#1




08:21:48 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID14\_NS\_01\_30\_1000\_#1




08:21:59 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID14\_NS\_01\_1000\_3000\_#1




08:22:11 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID14\_NS\_01\_3000\_6000\_#1




08:22:24 15.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID14\_NS\_01\_6000\_26000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID14\_NS\_01\_26000\_4000  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID15\_NS\_01\_0.009\_0.15\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID15\_NS\_01\_0.15\_30\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID15\_NS\_01\_30\_1000\_#1




08:26:49 15.01.2014


08:26:55 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID15\_NS\_01\_1000\_3000\_  
#1

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID15\_NS\_01\_3000\_6000\_  
#1



08:27:08 15.01.2014




08:27:19 15.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID15\_NS\_01\_6000\_26000\_  
#1

NTNV\_N77-3450-  
3550\_PC3\_30\_25\_H\_TID15\_NS\_01\_26000\_4000  
0\_#1







NTVN\_N77-3450-  
 3550\_PC3\_30\_30\_L\_TID1\_NS\_01\_0.009\_0.15\_#  
 1




NTVN\_N77-3450-  
 3550\_PC3\_30\_30\_L\_TID1\_NS\_01\_0.15\_30\_#1



NTVN\_N77-3450-  
 3550\_PC3\_30\_30\_L\_TID1\_NS\_01\_30\_1000\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_30\_L\_TID1\_NS\_01\_1000\_3000\_#  
 1




08:30:09 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID1\_NS\_01\_3000\_6000\_#  
1




08:30:22 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID1\_NS\_01\_6000\_26000\_#  
#1




08:30:29 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID1\_NS\_01\_26000\_40000\_#  
#1




08:34:09 15.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID2\_NS\_01\_0.009\_0.15\_#  
1



NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID2\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID2\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID2\_NS\_01\_1000\_3000\_#

1



NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID2\_NS\_01\_3000\_6000\_#

1




09:35:07 15.01.2014


09:35:19 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID2\_NS\_01\_6000\_26000\_  
#1

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID2\_NS\_01\_26000\_40000  
#1




09:36:56 15.01.2014




09:37:07 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID3\_NS\_01\_0.009\_0.15\_  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID3\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID3\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID3\_NS\_01\_1000\_3000\_#  
1



NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID3\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID3\_NS\_01\_6000\_26000\_#  
#1




08:38:05 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID3\_NS\_01\_26000\_40000  
\_#1




08:43:05 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID4\_NS\_01\_0.009\_0.15\_#  
1



08:43:16 15.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID4\_NS\_01\_0.15\_30\_#1



08:43:27 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID4\_NS\_01\_30\_1000\_#1






09:40:28 15.01.2014


09:40:50 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID4\_NS\_01\_1000\_3000\_#  
1

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID4\_NS\_01\_3000\_6000\_#  
1




09:44:09 15.01.2014



09:44:14 15.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID4\_NS\_01\_6000\_26000\_#  
#1

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID4\_NS\_01\_26000\_40000\_#  
\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID5\_NS\_01\_0.009\_0.15\_#  
1


NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID5\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID5\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID5\_NS\_01\_1000\_3000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID5\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID5\_NS\_01\_6000\_26000\_#  
#1



NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID5\_NS\_01\_26000\_40000\_#  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID6\_NS\_01\_0.009\_0.15\_#  
1




08:49:13 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID6\_NS\_01\_0.15\_30\_#1



08:49:14 15.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID6\_NS\_01\_30\_1000\_#1



08:49:25 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID6\_NS\_01\_1000\_3000\_#


1



08:49:47 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID6\_NS\_01\_3000\_6000\_#

1




08:50:00 15.01.2014


08:50:11 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID6\_NS\_01\_6000\_26000\_  
#1

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID6\_NS\_01\_26000\_40000  
#1




08:52:28 15.01.2014




08:52:49 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID7\_NS\_01\_0.009\_0.15\_  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID7\_NS\_01\_0.15\_30\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID7\_NS\_01\_30\_1000\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID7\_NS\_01\_1000\_3000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID7\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID7\_NS\_01\_6000\_26000\_#  
#1






08:50:47 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID7\_NS\_01\_26000\_40000  
\_#1




08:50:29 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID8\_NS\_01\_0.009\_0.15\_#  
1




08:55:04 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID8\_NS\_01\_0.15\_30\_#1



08:55:44 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID8\_NS\_01\_30\_1000\_#1




08:58:55 15.11.2014

08:58:08 15.11.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID8\_NS\_01\_1000\_3000\_#  
1

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID8\_NS\_01\_3000\_6000\_#  
1




08:56:20 15.11.2014


08:56:21 15.11.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID8\_NS\_01\_6000\_26000\_#  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID8\_NS\_01\_26000\_40000\_#  
\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_30\_L\_TID9\_NS\_01\_0.009\_0.15\_#  
 1




NTVN\_N77-3450-  
 3550\_PC3\_30\_30\_L\_TID9\_NS\_01\_0.15\_30\_#1



NTVN\_N77-3450-  
 3550\_PC3\_30\_30\_L\_TID9\_NS\_01\_30\_1000\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_30\_L\_TID9\_NS\_01\_1000\_3000\_#  
 1




08:58:51 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID9\_NS\_01\_3000\_6000\_#  
1




08:59:04 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID9\_NS\_01\_6000\_26000\_#  
1




08:58:15 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID9\_NS\_01\_26000\_40000\_#  
1




09:00:59 15.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID10\_NS\_01\_0.009\_0.15\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID10\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID10\_NS\_01\_30\_1000\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID10\_NS\_01\_1000\_3000\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID10\_NS\_01\_3000\_6000\_#1




09:01:50 15.01.2014


09:02:01 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID10\_NS\_01\_6000\_26000  
\_#1

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID10\_NS\_01\_26000\_4000  
0\_#1



09:03:26 15.01.2014




09:03:47 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID11\_NS\_01\_0.009\_0.15\_#1


NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID11\_NS\_01\_0.15\_30\_#1






09:03:58 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID11\_NS\_01\_30\_1000\_#1




09:04:09 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID11\_NS\_01\_1000\_3000\_#1




09:04:21 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID11\_NS\_01\_3000\_6000\_#1




09:04:34 15.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID11\_NS\_01\_6000\_26000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID11\_NS\_01\_26000\_4000  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID12\_NS\_01\_0.009\_0.15\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID12\_NS\_01\_0.15\_30\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID12\_NS\_01\_30\_1000\_#1




09:06:53 15.01.2014


09:07:06 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID12\_NS\_01\_1000\_3000\_  
#1

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID12\_NS\_01\_3000\_6000\_  
#1




09:07:18 15.01.2014



09:07:29 15.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID12\_NS\_01\_6000\_26000\_  
#1

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID12\_NS\_01\_26000\_4000  
0\_#1




09:11:20 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID13\_NS\_01\_0.009\_0.15\_  
#1




09:11:21 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID13\_NS\_01\_0.15\_30\_#1




09:11:41 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID13\_NS\_01\_30\_1000\_#1




09:11:59 15.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID13\_NS\_01\_1000\_3000\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID13\_NS\_01\_3000\_6000\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID13\_NS\_01\_6000\_26000\_  
#1



NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID13\_NS\_01\_26000\_4000\_  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID14\_NS\_01\_0.009\_0.15\_  
#1




09:14:16 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID14\_NS\_01\_0.15\_30\_#1




09:14:27 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID14\_NS\_01\_30\_1000\_#1



09:14:38 15.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID14\_NS\_01\_1000\_3000\_#1



09:14:51 15.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID14\_NS\_01\_3000\_6000\_#1






NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID14\_NS\_01\_6000\_26000  
\_#1


NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID14\_NS\_01\_26000\_4000  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID15\_NS\_01\_0.009\_0.15\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID15\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID15\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID15\_NS\_01\_1000\_3000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID15\_NS\_01\_3000\_6000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID15\_NS\_01\_6000\_26000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_L\_TID15\_NS\_01\_26000\_4000  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID1\_NS\_01\_0.009\_0.15\_#  
1



NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID1\_NS\_01\_0.15\_30\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID1\_NS\_01\_30\_1000\_#1




09:20:29 15.01.2014


09:20:41 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID1\_NS\_01\_1000\_3000\_#  
1

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID1\_NS\_01\_3000\_6000\_#  
1




09:20:55 15.01.2014



09:21:07 15.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID1\_NS\_01\_6000\_26000\_#  
#1

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID1\_NS\_01\_26000\_40000\_#  
\_#1




09:26:59 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID2\_NS\_01\_0.009\_0.15\_#  
1




09:27:09 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID2\_NS\_01\_0.15\_30\_#1




09:27:14 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID2\_NS\_01\_30\_1000\_#1




09:27:25 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID2\_NS\_01\_1000\_3000\_#  
1




09:27:28 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID2\_NS\_01\_3000\_6000\_#  
1




09:27:50 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID2\_NS\_01\_6000\_26000\_#  
#1



09:28:01 15.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID2\_NS\_01\_26000\_40000\_#  
#1




09:34:46 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID3\_NS\_01\_0.009\_0.15\_#  
1







NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID3\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID3\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID3\_NS\_01\_1000\_3000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID3\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID3\_NS\_01\_6000\_26000\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID3\_NS\_01\_26000\_40000\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID4\_NS\_01\_0.009\_0.15\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID4\_NS\_01\_0.15\_30\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID4\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID4\_NS\_01\_1000\_3000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID4\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID4\_NS\_01\_6000\_26000\_#  
#1




NTNV\_N77-3450-  
 3550\_PC3\_30\_30\_M\_TID4\_NS\_01\_26000\_40000  
 #1




NTNV\_N77-3450-  
 3550\_PC3\_30\_30\_M\_TID5\_NS\_01\_0.009\_0.15\_#  
 1



NTNV\_N77-3450-  
 3550\_PC3\_30\_30\_M\_TID5\_NS\_01\_0.15\_30\_#1



NTNV\_N77-3450-  
 3550\_PC3\_30\_30\_M\_TID5\_NS\_01\_30\_1000\_#1




09:40:19 15.01.2014


09:40:29 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID5\_NS\_01\_1000\_3000\_#  
1

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID5\_NS\_01\_3000\_6000\_#  
1




09:40:25 15.01.2014




09:40:46 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID5\_NS\_01\_6000\_26000\_#  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID5\_NS\_01\_26000\_40000\_#  
\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID6\_NS\_01\_0.009\_0.15\_#  
1



NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID6\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID6\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID6\_NS\_01\_1000\_3000\_#  
1






09:45:48 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID6\_NS\_01\_3000\_6000\_#  
1




09:46:00 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID6\_NS\_01\_6000\_26000\_#  
#1




09:46:11 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID6\_NS\_01\_26000\_40000\_#  
#1




09:46:46 15.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID7\_NS\_01\_0.009\_0.15\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID7\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID7\_NS\_01\_30\_1000\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID7\_NS\_01\_1000\_3000\_#  
1



NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID7\_NS\_01\_3000\_6000\_#  
1




09:50:44 15.11.2014


09:50:55 15.11.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID7\_NS\_01\_6000\_26000\_  
#1

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID7\_NS\_01\_26000\_40000  
#1




09:53:09 15.11.2014




09:53:20 15.11.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID8\_NS\_01\_0.009\_0.15\_  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID8\_NS\_01\_0.15\_30\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID8\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID8\_NS\_01\_1000\_3000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID8\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID8\_NS\_01\_6000\_26000\_#  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID8\_NS\_01\_26000\_40000  
\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID9\_NS\_01\_0.009\_0.15\_#  
1



NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID9\_NS\_01\_0.15\_30\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID9\_NS\_01\_30\_1000\_#1




09:56:51 15.01.2014


09:57:04 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID9\_NS\_01\_1000\_3000\_#  
1

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID9\_NS\_01\_3000\_6000\_#  
1



09:57:16 15.01.2014




09:57:27 15.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID9\_NS\_01\_6000\_26000\_#  
#1

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID9\_NS\_01\_26000\_40000\_#  
\_#1







NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID10\_NS\_01\_0.009\_0.15\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID10\_NS\_01\_0.15\_30\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID10\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID10\_NS\_01\_1000\_3000\_  
#1




10:00:07 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID10\_NS\_01\_3000\_6000\_  
#1




10:00:19 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID10\_NS\_01\_6000\_26000  
\_#1




10:00:20 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID10\_NS\_01\_26000\_4000  
0\_#1




10:00:20 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID11\_NS\_01\_0.009\_0.15\_  
#1




19-02-04 15:01:004

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID11\_NS\_01\_0.15\_30\_#1




19-02-04 15:01:004

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID11\_NS\_01\_30\_1000\_#1




19-03-05 15:01:004

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID11\_NS\_01\_1000\_3000\_#1




19-03-18 15:01:004

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID11\_NS\_01\_3000\_6000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID11\_NS\_01\_6000\_26000  
\_#1


NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID11\_NS\_01\_26000\_4000  
0\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID12\_NS\_01\_0.009\_0.15\_  
\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID12\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID12\_NS\_01\_30\_1000\_#1


NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID12\_NS\_01\_1000\_3000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID12\_NS\_01\_3000\_6000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID12\_NS\_01\_6000\_26000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID12\_NS\_01\_26000\_4000  
0\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID13\_NS\_01\_0.009\_0.15\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID13\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID13\_NS\_01\_30\_1000\_#1






NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID13\_NS\_01\_1000\_3000\_  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID13\_NS\_01\_3000\_6000\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID13\_NS\_01\_6000\_26000\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID13\_NS\_01\_26000\_4000  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID14\_NS\_01\_0.009\_0.15\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID14\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID14\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID14\_NS\_01\_1000\_3000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID14\_NS\_01\_3000\_6000\_  
#1





NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID14\_NS\_01\_6000\_26000  
#1



NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID14\_NS\_01\_26000\_4000  
0\_#1





NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID15\_NS\_01\_0.009\_0.15\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID15\_NS\_01\_0.15\_30\_#1

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID15\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID15\_NS\_01\_1000\_3000\_#1


NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID15\_NS\_01\_3000\_6000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID15\_NS\_01\_6000\_26000  
\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_M\_TID15\_NS\_01\_26000\_4000  
0\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID1\_NS\_01\_0.009\_0.15\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID1\_NS\_01\_0.15\_30\_#1




10:29:49 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID1\_NS\_01\_30\_1000\_#1




10:29:54 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID1\_NS\_01\_1000\_3000\_#  
1



10:30:07 15.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID1\_NS\_01\_3000\_6000\_#  
1




10:30:19 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID1\_NS\_01\_6000\_26000\_#  
1







NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID1\_NS\_01\_26000\_40000  
\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID2\_NS\_01\_0.009\_0.15\_#  
1



NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID2\_NS\_01\_0.15\_30\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID2\_NS\_01\_30\_1000\_#1




19:32:49 15.01.2014


19:32:56 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID2\_NS\_01\_1000\_3000\_#  
1

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID2\_NS\_01\_3000\_6000\_#  
1




19:33:08 15.01.2014




19:33:19 15.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID2\_NS\_01\_6000\_26000\_#  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID2\_NS\_01\_26000\_40000\_#  
\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID3\_NS\_01\_0.009\_0.15\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID3\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID3\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID3\_NS\_01\_1000\_3000\_#  
1




NTNV\_N77-3450-  
 3550\_PC3\_30\_30\_H\_TID3\_NS\_01\_3000\_6000\_#  
 1




NTNV\_N77-3450-  
 3550\_PC3\_30\_30\_H\_TID3\_NS\_01\_6000\_26000\_#  
 #1




NTNV\_N77-3450-  
 3550\_PC3\_30\_30\_H\_TID3\_NS\_01\_26000\_40000\_#  
 #1




NTNV\_N77-3450-  
 3550\_PC3\_30\_30\_H\_TID4\_NS\_01\_0.009\_0.15\_#  
 1




NTNV\_N77-3450-3550\_PC3\_30\_30\_H\_TID4\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-3550\_PC3\_30\_30\_H\_TID4\_NS\_01\_30\_1000\_#1



NTNV\_N77-3450-3550\_PC3\_30\_30\_H\_TID4\_NS\_01\_1000\_3000\_#1




NTNV\_N77-3450-3550\_PC3\_30\_30\_H\_TID4\_NS\_01\_3000\_6000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID4\_NS\_01\_6000\_26000\_  
#1

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID4\_NS\_01\_26000\_40000\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID5\_NS\_01\_0.009\_0.15\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID5\_NS\_01\_0.15\_30\_  
#1







NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID5\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID5\_NS\_01\_1000\_3000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID5\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID5\_NS\_01\_6000\_26000\_#  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID5\_NS\_01\_26000\_40000  
\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID6\_NS\_01\_0.009\_0.15\_#  
1



NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID6\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID6\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID6\_NS\_01\_1000\_3000\_#  
1


NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID6\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID6\_NS\_01\_6000\_26000\_#  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID6\_NS\_01\_26000\_40000\_#  
\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID7\_NS\_01\_0.009\_0.15\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID7\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID7\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID7\_NS\_01\_1000\_3000\_#  
1




NTNV\_N77-3450-  
 3550\_PC3\_30\_30\_H\_TID7\_NS\_01\_3000\_6000\_#  
 1




NTNV\_N77-3450-  
 3550\_PC3\_30\_30\_H\_TID7\_NS\_01\_6000\_26000\_#  
 #1



NTNV\_N77-3450-  
 3550\_PC3\_30\_30\_H\_TID7\_NS\_01\_26000\_40000\_#  
 #1




NTNV\_N77-3450-  
 3550\_PC3\_30\_30\_H\_TID8\_NS\_01\_0.009\_0.15\_#  
 1



NTNV\_N77-3450-3550\_PC3\_30\_30\_H\_TID8\_NS\_01\_0.15\_30\_#1


NTNV\_N77-3450-3550\_PC3\_30\_30\_H\_TID8\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-3550\_PC3\_30\_30\_H\_TID8\_NS\_01\_1000\_3000\_#1

NTNV\_N77-3450-3550\_PC3\_30\_30\_H\_TID8\_NS\_01\_3000\_6000\_#1







NTVN\_N77-3450-  
 3550\_PC3\_30\_30\_H\_TID8\_NS\_01\_6000\_26000\_  
 #1




NTVN\_N77-3450-  
 3550\_PC3\_30\_30\_H\_TID8\_NS\_01\_26000\_40000\_  
 #1




NTVN\_N77-3450-  
 3550\_PC3\_30\_30\_H\_TID9\_NS\_01\_0.009\_0.15\_  
 #1




NTVN\_N77-3450-  
 3550\_PC3\_30\_30\_H\_TID9\_NS\_01\_0.15\_30\_  
 #1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID9\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID9\_NS\_01\_1000\_3000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID9\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID9\_NS\_01\_6000\_26000\_#  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID9\_NS\_01\_26000\_40000  
\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID10\_NS\_01\_0.009\_0.15\_  
\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID10\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID10\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID10\_NS\_01\_1000\_3000\_  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID10\_NS\_01\_3000\_6000\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID10\_NS\_01\_6000\_26000\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID10\_NS\_01\_26000\_4000  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID11\_NS\_01\_0.009\_0.15\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID11\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID11\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID11\_NS\_01\_1000\_3000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID11\_NS\_01\_3000\_6000\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID11\_NS\_01\_6000\_26000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID11\_NS\_01\_26000\_4000\_0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID12\_NS\_01\_0.009\_0.15\_#1






NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID12\_NS\_01\_0.15\_30\_#1

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID12\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID12\_NS\_01\_1000\_3000\_#1

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID12\_NS\_01\_3000\_6000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID12\_NS\_01\_6000\_26000  
\_#1

NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID12\_NS\_01\_26000\_4000  
0\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID13\_NS\_01\_0.009\_0.15\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_30\_H\_TID13\_NS\_01\_0.15\_30\_#1