




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_M\_TID15\_NS\_01\_26000\_4000  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID1\_NS\_01\_0.009\_0.15\_#  
1



NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID1\_NS\_01\_0.15\_30\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID1\_NS\_01\_30\_1000\_#1




02:46:32 16.01.2014


02:46:45 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID1\_NS\_01\_1000\_3000\_#  
1

NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID1\_NS\_01\_3000\_6000\_#  
1




02:46:57 16.01.2014




02:47:09 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID1\_NS\_01\_6000\_26000\_#  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID1\_NS\_01\_26000\_40000\_#  
\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_80\_H\_TID2\_NS\_01\_0.009\_0.15\_#  
 1




NTVN\_N77-3450-  
 3550\_PC3\_30\_80\_H\_TID2\_NS\_01\_0.15\_30\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_80\_H\_TID2\_NS\_01\_30\_1000\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_80\_H\_TID2\_NS\_01\_1000\_3000\_#  
 1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID2\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID2\_NS\_01\_6000\_26000\_#  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID2\_NS\_01\_26000\_40000\_#  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID3\_NS\_01\_0.009\_0.15\_#  
1



NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID3\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID3\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID3\_NS\_01\_1000\_3000\_#

1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID3\_NS\_01\_3000\_6000\_#


1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID3\_NS\_01\_6000\_26000\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID3\_NS\_01\_26000\_40000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID4\_NS\_01\_0.009\_0.15\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID4\_NS\_01\_0.15\_0.30\_#1







NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID4\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID4\_NS\_01\_1000\_3000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID4\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID4\_NS\_01\_6000\_26000\_#  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID4\_NS\_01\_26000\_40000  
\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID5\_NS\_01\_0.009\_0.15\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID5\_NS\_01\_0.15\_30\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID5\_NS\_01\_30\_1000\_#1






03:09:41 16.01.2014


03:09:54 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID5\_NS\_01\_1000\_3000\_#  
1

NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID5\_NS\_01\_3000\_6000\_#  
1




03:01:07 16.01.2014




03:01:19 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID5\_NS\_01\_6000\_26000\_#  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID5\_NS\_01\_26000\_40000\_#  
\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID6\_NS\_01\_0.009\_0.15\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID6\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID6\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID6\_NS\_01\_1000\_3000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID6\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID6\_NS\_01\_6000\_26000\_#  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID6\_NS\_01\_26000\_40000\_#  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID7\_NS\_01\_0.009\_0.15\_#  
1



NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID7\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID7\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID7\_NS\_01\_1000\_3000\_#

1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID7\_NS\_01\_3000\_6000\_#

1




03-08-17 16:01:014

NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID7\_NS\_01\_6000\_26000\_  
#1




03-08-18 16:01:014

NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID7\_NS\_01\_26000\_40000\_  
#1




03-10-51 16:01:014

NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID8\_NS\_01\_0.009\_0.15\_  
#1




03-11-09 16:01:014


NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID8\_NS\_01\_0.15\_30\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID8\_NS\_01\_30\_1000\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID8\_NS\_01\_1000\_3000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID8\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID8\_NS\_01\_6000\_26000\_#  
1







NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID8\_NS\_01\_26000\_40000  
\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID9\_NS\_01\_0.009\_0.15\_#  
1



NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID9\_NS\_01\_0.15\_30\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID9\_NS\_01\_30\_1000\_#1




03:15:01 16.01.2014


03:15:13 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID9\_NS\_01\_1000\_3000\_#  
1

NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID9\_NS\_01\_3000\_6000\_#  
1




03:15:26 16.01.2014




03:15:28 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID9\_NS\_01\_6000\_26000\_#  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID9\_NS\_01\_26000\_40000\_#  
\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID10\_NS\_01\_0.009\_0.15\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID10\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID10\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID10\_NS\_01\_1000\_3000\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID10\_NS\_01\_3000\_6000\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID10\_NS\_01\_6000\_26000  
\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID10\_NS\_01\_26000\_4000  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID11\_NS\_01\_0.009\_0.15\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID11\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID11\_NS\_01\_30\_1000\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID11\_NS\_01\_1000\_3000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID11\_NS\_01\_3000\_6000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID11\_NS\_01\_6000\_26000  
\_#1

NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID11\_NS\_01\_26000\_4000  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID12\_NS\_01\_0.009\_0.15\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID12\_NS\_01\_0.15\_30\_#1







NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID12\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID12\_NS\_01\_1000\_3000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID12\_NS\_01\_3000\_6000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID12\_NS\_01\_6000\_26000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID12\_NS\_01\_26000\_4000  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID13\_NS\_01\_0.009\_0.15\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID13\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID13\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID13\_NS\_01\_1000\_3000\_  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID13\_NS\_01\_3000\_6000\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID13\_NS\_01\_6000\_26000  
\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID13\_NS\_01\_26000\_4000  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID14\_NS\_01\_0.009\_0.15\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID14\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID14\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID14\_NS\_01\_1000\_3000\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID14\_NS\_01\_3000\_6000\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID14\_NS\_01\_6000\_26000\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID14\_NS\_01\_26000\_4000\_  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID15\_NS\_01\_0.009\_0.15\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID15\_NS\_01\_0.15\_30\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID15\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID15\_NS\_01\_1000\_3000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID15\_NS\_01\_3000\_6000\_#1






NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID15\_NS\_01\_6000\_26000  
\_#1


NTNV\_N77-3450-  
3550\_PC3\_30\_80\_H\_TID15\_NS\_01\_26000\_4000  
0\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID1\_NS\_01\_0.009\_0.15\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID1\_NS\_01\_0.15\_30\_#1




03:40:01 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID1\_NS\_01\_30\_1000\_#1




03:40:13 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID1\_NS\_01\_1000\_3000\_#  
1




03:40:25 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID1\_NS\_01\_3000\_6000\_#  
1




03:40:28 16.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID1\_NS\_01\_6000\_26000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID1\_NS\_01\_26000\_40000  
\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID2\_NS\_01\_0.009\_0.15\_#  
1



NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID2\_NS\_01\_0.15\_30\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID2\_NS\_01\_30\_1000\_#1




03-03-21 16:01:2014


03-03-07 16:01:2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID2\_NS\_01\_1000\_3000\_#  
1

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID2\_NS\_01\_3000\_6000\_#  
1




03-03-26 16:01:2014




03-04-08 16:01:2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID2\_NS\_01\_6000\_26000\_#  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID2\_NS\_01\_26000\_40000\_#  
\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_90\_L\_TID3\_NS\_01\_0.009\_0.15\_#  
 1




NTVN\_N77-3450-  
 3550\_PC3\_30\_90\_L\_TID3\_NS\_01\_0.15\_30\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_90\_L\_TID3\_NS\_01\_30\_1000\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_90\_L\_TID3\_NS\_01\_1000\_3000\_#  
 1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID3\_NS\_01\_3000\_6000\_#  
1



NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID3\_NS\_01\_6000\_26000\_#  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID3\_NS\_01\_26000\_40000\_#  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID4\_NS\_01\_0.009\_0.15\_#  
1






NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID4\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID4\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID4\_NS\_01\_1000\_3000\_#

1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID4\_NS\_01\_3000\_6000\_#

1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID4\_NS\_01\_6000\_26000\_  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID4\_NS\_01\_26000\_40000  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID5\_NS\_01\_0.009\_0.15\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID5\_NS\_01\_0.15\_30\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID5\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID5\_NS\_01\_1000\_3000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID5\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID5\_NS\_01\_6000\_26000\_#  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID5\_NS\_01\_26000\_40000  
\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID6\_NS\_01\_0.009\_0.15\_#  
1



NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID6\_NS\_01\_0.15\_30\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID6\_NS\_01\_30\_1000\_#1




03:58:28 16.01.2014


03:58:50 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID6\_NS\_01\_1000\_3000\_#  
1

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID6\_NS\_01\_3000\_6000\_#  
1




03:57:09 16.01.2014



03:57:15 16.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID6\_NS\_01\_6000\_26000\_#  
#1

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID6\_NS\_01\_26000\_40000\_#  
\_#1




03:58:22 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID7\_NS\_01\_0.009\_0.15\_#  
1




03:58:39 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID7\_NS\_01\_0.15\_30\_#1



03:58:45 16.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID7\_NS\_01\_30\_1000\_#1




03:58:56 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID7\_NS\_01\_1000\_3000\_#  
1







NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID7\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID7\_NS\_01\_6000\_26000\_#  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID7\_NS\_01\_26000\_40000\_#  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID8\_NS\_01\_0.009\_0.15\_#  
1



NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID8\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID8\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID8\_NS\_01\_1000\_3000\_#

1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID8\_NS\_01\_3000\_6000\_#

1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID8\_NS\_01\_6000\_26000\_  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID8\_NS\_01\_26000\_40000  
#1



NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID9\_NS\_01\_0.009\_0.15\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID9\_NS\_01\_0.15\_30\_#1




04:06:27 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID9\_NS\_01\_30\_1000\_#1




04:06:28 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID9\_NS\_01\_1000\_3000\_#  
1




04:06:50 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID9\_NS\_01\_3000\_6000\_#  
1




04:07:03 16.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID9\_NS\_01\_6000\_26000\_#  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID9\_NS\_01\_26000\_40000  
\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID10\_NS\_01\_0.009\_0.15\_  
\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID10\_NS\_01\_0.15\_30\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID10\_NS\_01\_30\_1000\_#1




94:10:54 16.01.2014


94:10:06 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID10\_NS\_01\_1000\_3000\_  
#1

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID10\_NS\_01\_3000\_6000\_  
#1



94:10:19 16.01.2014




94:10:21 16.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID10\_NS\_01\_6000\_26000\_  
#1

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID10\_NS\_01\_26000\_4000  
0\_#1







NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID11\_NS\_01\_0.009\_0.15\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID11\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID11\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID11\_NS\_01\_1000\_3000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID11\_NS\_01\_3000\_6000\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID11\_NS\_01\_6000\_26000  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID11\_NS\_01\_26000\_4000  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID12\_NS\_01\_0.009\_0.15\_  
#1




NTNV\_N77-3450-3550\_PC3\_30\_90\_L\_TID12\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-3550\_PC3\_30\_90\_L\_TID12\_NS\_01\_30\_1000\_#1



NTNV\_N77-3450-3550\_PC3\_30\_90\_L\_TID12\_NS\_01\_1000\_3000\_#1



NTNV\_N77-3450-3550\_PC3\_30\_90\_L\_TID12\_NS\_01\_3000\_6000\_#1




04:16:55 16.01.2014


04:17:07 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID12\_NS\_01\_6000\_26000  
\_#1

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID12\_NS\_01\_26000\_4000  
0\_#1




04:18:24 16.01.2014




04:18:25 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID13\_NS\_01\_0.009\_0.15\_#1


NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID13\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID13\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID13\_NS\_01\_1000\_3000\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID13\_NS\_01\_3000\_6000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID13\_NS\_01\_6000\_26000\_#1




94:29:35 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID13\_NS\_01\_26000\_4000  
0\_#1




94:22:21 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID14\_NS\_01\_0.009\_0.15\_  
#1



94:22:49 16.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID14\_NS\_01\_0.15\_30\_#1



94:22:56 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID14\_NS\_01\_30\_1000\_#1






94:23:08 16.01.2014


94:23:20 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID14\_NS\_01\_1000\_3000\_  
#1

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID14\_NS\_01\_3000\_6000\_  
#1




94:23:32 16.01.2014




94:23:44 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID14\_NS\_01\_6000\_26000\_  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID14\_NS\_01\_26000\_4000  
0\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_90\_L\_TID15\_NS\_01\_0.009\_0.15\_  
 #1




NTVN\_N77-3450-  
 3550\_PC3\_30\_90\_L\_TID15\_NS\_01\_0.15\_30\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_90\_L\_TID15\_NS\_01\_30\_1000\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_90\_L\_TID15\_NS\_01\_1000\_3000\_  
 #1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID15\_NS\_01\_3000\_6000\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID15\_NS\_01\_6000\_26000  
\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_90\_L\_TID15\_NS\_01\_26000\_4000  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID1\_NS\_01\_0.009\_0.15\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID1\_NS\_01\_0.15\_30\_#1

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID1\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID1\_NS\_01\_1000\_3000\_#  
1

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID1\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID1\_NS\_01\_6000\_26000\_#1


NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID1\_NS\_01\_26000\_40000\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID2\_NS\_01\_0.009\_0.15\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID2\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID2\_NS\_01\_30\_1000\_#1

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID2\_NS\_01\_1000\_3000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID2\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID2\_NS\_01\_6000\_26000\_#  
#1







NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID2\_NS\_01\_26000\_40000  
\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID3\_NS\_01\_0.009\_0.15\_#  
1



NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID3\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID3\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID3\_NS\_01\_1000\_3000\_#  
1


NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID3\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID3\_NS\_01\_6000\_26000\_#  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID3\_NS\_01\_26000\_40000\_#  
\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID4\_NS\_01\_0.009\_0.15\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID4\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID4\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID4\_NS\_01\_1000\_3000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID4\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID4\_NS\_01\_6000\_26000\_#  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID4\_NS\_01\_26000\_40000\_#  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID5\_NS\_01\_0.009\_0.15\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID5\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID5\_NS\_01\_30\_1000\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID5\_NS\_01\_1000\_3000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID5\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID5\_NS\_01\_6000\_26000\_#1

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID5\_NS\_01\_26000\_40000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID6\_NS\_01\_0.009\_0.15\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID6\_NS\_01\_0.15\_30\_#1







NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID6\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID6\_NS\_01\_1000\_3000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID6\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID6\_NS\_01\_6000\_26000\_#  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID6\_NS\_01\_26000\_40000  
\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID7\_NS\_01\_0.009\_0.15\_#  
1



NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID7\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID7\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-3550\_PC3\_30\_90\_M\_TID7\_NS\_01\_1000\_3000\_#1


NTNV\_N77-3450-3550\_PC3\_30\_90\_M\_TID7\_NS\_01\_3000\_6000\_#1




NTNV\_N77-3450-3550\_PC3\_30\_90\_M\_TID7\_NS\_01\_6000\_26000\_#1




NTNV\_N77-3450-3550\_PC3\_30\_90\_M\_TID7\_NS\_01\_26000\_40000\_#1




NTNV\_N77-3450-3550\_PC3\_30\_90\_M\_TID8\_NS\_01\_0.009\_0.15\_#1




NTNV\_N77-3450-3550\_PC3\_30\_90\_M\_TID8\_NS\_01\_0.15\_30\_#1



NTNV\_N77-3450-3550\_PC3\_30\_90\_M\_TID8\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-3550\_PC3\_30\_90\_M\_TID8\_NS\_01\_1000\_3000\_#1




04:56:17 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID8\_NS\_01\_3000\_6000\_#  
1




04:56:29 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID8\_NS\_01\_6000\_26000\_#  
1




04:56:41 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID8\_NS\_01\_26000\_40000\_#  
1




04:58:11 16.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID9\_NS\_01\_0.009\_0.15\_#  
1



NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID9\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID9\_NS\_01\_30\_1000\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID9\_NS\_01\_1000\_3000\_#


1



NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID9\_NS\_01\_3000\_6000\_#


1






NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID9\_NS\_01\_6000\_26000\_  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID9\_NS\_01\_26000\_40000\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID10\_NS\_01\_0.009\_0.15\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID10\_NS\_01\_0.15\_30\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID10\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID10\_NS\_01\_1000\_3000\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID10\_NS\_01\_3000\_6000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID10\_NS\_01\_6000\_26000\_#1




05:04:01 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID10\_NS\_01\_26000\_4000  
0\_#1




05:06:26 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID11\_NS\_01\_0.009\_0.15\_#1




05:06:48 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID11\_NS\_01\_0.15\_30\_#1




05:07:00 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID11\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID11\_NS\_01\_1000\_3000\_  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID11\_NS\_01\_3000\_6000\_  
#1



NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID11\_NS\_01\_6000\_26000\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID11\_NS\_01\_26000\_4000  
0\_#1




05:10:17 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID12\_NS\_01\_0.009\_0.15\_  
#1




05:10:28 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID12\_NS\_01\_0.15\_30\_#1







05:10:40 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID12\_NS\_01\_30\_1000\_#1





05:10:52 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID12\_NS\_01\_1000\_3000\_  
#1










NTNV\_N77-3450-3550\_PC3\_30\_90\_M\_TID13\_NS\_01\_0.15\_30\_#1

NTNV\_N77-3450-3550\_PC3\_30\_90\_M\_TID13\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-3550\_PC3\_30\_90\_M\_TID13\_NS\_01\_1000\_3000\_#1

NTNV\_N77-3450-3550\_PC3\_30\_90\_M\_TID13\_NS\_01\_3000\_6000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID13\_NS\_01\_6000\_26000  
\_#1


NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID13\_NS\_01\_26000\_4000  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID14\_NS\_01\_0.009\_0.15\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID14\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID14\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID14\_NS\_01\_1000\_3000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID14\_NS\_01\_3000\_6000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID14\_NS\_01\_6000\_26000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID14\_NS\_01\_26000\_4000  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID15\_NS\_01\_0.009\_0.15\_  
#1



NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID15\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID15\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID15\_NS\_01\_1000\_3000\_  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID15\_NS\_01\_3000\_6000\_  
#1



NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID15\_NS\_01\_6000\_26000\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_M\_TID15\_NS\_01\_26000\_4000  
0\_#1




05:24:49 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID1\_NS\_01\_0.009\_0.15\_#  
1




05:25:00 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID1\_NS\_01\_0.15\_30\_#1



05:25:11 16.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID1\_NS\_01\_30\_1000\_#1




05:25:29 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID1\_NS\_01\_1000\_3000\_#  
1







NTNV\_N77-3450-3550\_PC3\_30\_90\_H\_TID1\_NS\_01\_3000\_6000\_#1




NTNV\_N77-3450-3550\_PC3\_30\_90\_H\_TID1\_NS\_01\_6000\_26000\_#1



NTNV\_N77-3450-3550\_PC3\_30\_90\_H\_TID1\_NS\_01\_26000\_40000\_#1




NTNV\_N77-3450-3550\_PC3\_30\_90\_H\_TID2\_NS\_01\_0.009\_0.15\_#1




05:28:10 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID2\_NS\_01\_0.15\_30\_#1



05:28:21 16.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID2\_NS\_01\_30\_1000\_#1



05:28:25 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID2\_NS\_01\_1000\_3000\_#1


1




05:28:44 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID2\_NS\_01\_3000\_6000\_#1


1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID2\_NS\_01\_6000\_26000\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID2\_NS\_01\_26000\_40000\_  
#1



NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID3\_NS\_01\_0.009\_0.15\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID3\_NS\_01\_0.15\_30\_  
#1




05:31:40 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID3\_NS\_01\_30\_1000\_#1




05:31:51 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID3\_NS\_01\_1000\_3000\_#  
1



05:32:04 16.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID3\_NS\_01\_3000\_6000\_#  
1



05:32:16 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID3\_NS\_01\_6000\_26000\_#  
1






09:35:29 16.01.2014


09:35:39 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID4\_NS\_01\_1000\_3000\_#  
1

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID4\_NS\_01\_3000\_6000\_#  
1



09:35:46 16.01.2014




09:35:58 16.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID4\_NS\_01\_6000\_26000\_#  
#1

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID4\_NS\_01\_26000\_40000\_#  
\_#1







NTVN\_N77-3450-  
 3550\_PC3\_30\_90\_H\_TID5\_NS\_01\_0.009\_0.15\_#  
 1




NTVN\_N77-3450-  
 3550\_PC3\_30\_90\_H\_TID5\_NS\_01\_0.15\_30\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_90\_H\_TID5\_NS\_01\_30\_1000\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_90\_H\_TID5\_NS\_01\_1000\_3000\_#  
 1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID5\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID5\_NS\_01\_6000\_26000\_#  
1



NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID5\_NS\_01\_26000\_40000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID6\_NS\_01\_0.009\_0.15\_#  
1




05:41:29 16.01.2024

NTNV\_N77-3450-3550\_PC3\_30\_90\_H\_TID6\_NS\_01\_0.15\_30\_#1




05:41:41 16.01.2024

NTNV\_N77-3450-3550\_PC3\_30\_90\_H\_TID6\_NS\_01\_30\_1000\_#1




05:41:51 16.01.2024

NTNV\_N77-3450-3550\_PC3\_30\_90\_H\_TID6\_NS\_01\_1000\_3000\_#1




05:42:04 16.01.2024


NTNV\_N77-3450-3550\_PC3\_30\_90\_H\_TID6\_NS\_01\_3000\_6000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID6\_NS\_01\_6000\_26000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID6\_NS\_01\_26000\_40000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID7\_NS\_01\_0.009\_0.15\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID7\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID7\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID7\_NS\_01\_1000\_3000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID7\_NS\_01\_3000\_6000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID7\_NS\_01\_6000\_26000\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID7\_NS\_01\_26000\_40000  
\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID8\_NS\_01\_0.009\_0.15\_#  
1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID8\_NS\_01\_0.15\_30\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID8\_NS\_01\_30\_1000\_#1






05:48:22 16.01.2014


05:48:24 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID8\_NS\_01\_1000\_3000\_#  
1

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID8\_NS\_01\_3000\_6000\_#  
1




05:48:49 16.01.2014



05:49:01 16.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID8\_NS\_01\_6000\_26000\_#  
#1

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID8\_NS\_01\_26000\_40000\_#  
\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID9\_NS\_01\_0.009\_0.15\_#  
1


NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID9\_NS\_01\_0.15\_30\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID9\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID9\_NS\_01\_1000\_3000\_#  
1




05:51:47 16.01.2014

NTNV\_N77-3450-  
 3550\_PC3\_30\_90\_H\_TID9\_NS\_01\_3000\_6000\_#  
 1




05:52:00 16.01.2014

NTNV\_N77-3450-  
 3550\_PC3\_30\_90\_H\_TID9\_NS\_01\_6000\_26000\_#  
 #1




05:52:11 16.01.2014

NTNV\_N77-3450-  
 3550\_PC3\_30\_90\_H\_TID9\_NS\_01\_26000\_40000\_#  
 #1




05:54:16 16.01.2014

NTNV\_N77-3450-  
 3550\_PC3\_30\_90\_H\_TID10\_NS\_01\_0.009\_0.15\_#  
 #1




05:54:28 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID10\_NS\_01\_0.15\_30\_#1




05:54:29 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID10\_NS\_01\_30\_1000\_#1




05:54:52 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID10\_NS\_01\_1000\_3000\_#1




05:55:05 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID10\_NS\_01\_3000\_6000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID10\_NS\_01\_6000\_26000  
\_#1


NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID10\_NS\_01\_26000\_4000  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID11\_NS\_01\_0.009\_0.15\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID11\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID11\_NS\_01\_30\_1000\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID11\_NS\_01\_1000\_3000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID11\_NS\_01\_3000\_6000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID11\_NS\_01\_6000\_26000\_#1






05:58:43 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID11\_NS\_01\_26000\_4000  
0\_#1




06:00:45 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID12\_NS\_01\_0.009\_0.15\_#1




06:00:57 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID12\_NS\_01\_0.15\_30\_#1




06:01:08 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID12\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID12\_NS\_01\_1000\_3000\_  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID12\_NS\_01\_3000\_6000\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID12\_NS\_01\_6000\_26000\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID12\_NS\_01\_26000\_4000  
0\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_90\_H\_TID13\_NS\_01\_0.009\_0.15\_  
 #1




NTVN\_N77-3450-  
 3550\_PC3\_30\_90\_H\_TID13\_NS\_01\_0.15\_30\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_90\_H\_TID13\_NS\_01\_30\_1000\_#1




NTVN\_N77-3450-  
 3550\_PC3\_30\_90\_H\_TID13\_NS\_01\_1000\_3000\_  
 #1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID13\_NS\_01\_3000\_6000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID13\_NS\_01\_6000\_26000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID13\_NS\_01\_26000\_4000\_0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID14\_NS\_01\_0.009\_0.15\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID14\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID14\_NS\_01\_30\_1000\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID14\_NS\_01\_1000\_3000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID14\_NS\_01\_3000\_6000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID14\_NS\_01\_6000\_26000  
\_#1

NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID14\_NS\_01\_26000\_4000  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID15\_NS\_01\_0.009\_0.15\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID15\_NS\_01\_0.15\_30\_#1







NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID15\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID15\_NS\_01\_1000\_3000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID15\_NS\_01\_3000\_6000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID15\_NS\_01\_6000\_26000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_90\_H\_TID15\_NS\_01\_26000\_4000  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID1\_NS\_01\_0.009\_0.15\_  
#1



NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID1\_NS\_01\_0.15\_30\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID1\_NS\_01\_30\_1000\_#1




05:15:06 16.01.2014


05:15:21 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID1\_NS\_01\_1000\_3000\_  
#1

NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID1\_NS\_01\_3000\_6000\_  
#1




05:15:39 16.01.2014




05:15:45 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID1\_NS\_01\_6000\_26000\_  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID1\_NS\_01\_26000\_4000  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID2\_NS\_01\_0.009\_0.15\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID2\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID2\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID2\_NS\_01\_1000\_3000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID2\_NS\_01\_3000\_6000\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID2\_NS\_01\_6000\_26000  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID2\_NS\_01\_26000\_4000  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID3\_NS\_01\_0.009\_0.15\_  
#1




NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID3\_NS\_01\_0.15\_30\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID3\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID3\_NS\_01\_1000\_3000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID3\_NS\_01\_3000\_6000\_#1






NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID3\_NS\_01\_6000\_26000  
\_#1


NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID3\_NS\_01\_26000\_4000  
0\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID4\_NS\_01\_0.009\_0.15\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID4\_NS\_01\_0.15\_30\_#1




05:24:49 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID4\_NS\_01\_30\_1000\_#1




05:25:01 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID4\_NS\_01\_1000\_3000\_#1




05:25:13 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID4\_NS\_01\_3000\_6000\_#1




05:25:26 16.01.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID4\_NS\_01\_6000\_26000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID4\_NS\_01\_26000\_4000  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID5\_NS\_01\_0.009\_0.15\_  
#1



NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID5\_NS\_01\_0.15\_30\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID5\_NS\_01\_30\_1000\_#1




05:28:09 16.01.2014


05:28:22 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID5\_NS\_01\_1000\_3000\_  
#1

NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID5\_NS\_01\_3000\_6000\_  
#1




05:28:34 16.01.2014




05:28:46 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID5\_NS\_01\_6000\_26000\_  
#1


NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID5\_NS\_01\_26000\_4000  
0\_#1




NTNV\_N77-3450-  
 3550\_PC3\_30\_100\_M\_TID6\_NS\_01\_0.009\_0.15\_  
 #1




NTNV\_N77-3450-  
 3550\_PC3\_30\_100\_M\_TID6\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
 3550\_PC3\_30\_100\_M\_TID6\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
 3550\_PC3\_30\_100\_M\_TID6\_NS\_01\_1000\_3000\_  
 #1




NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID6\_NS\_01\_3000\_6000\_  
#1



NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID6\_NS\_01\_6000\_26000  
\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID6\_NS\_01\_26000\_4000  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID7\_NS\_01\_0.009\_0.15\_  
#1







NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID7\_NS\_01\_0.15\_30\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID7\_NS\_01\_30\_1000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID7\_NS\_01\_1000\_3000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID7\_NS\_01\_3000\_6000\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID7\_NS\_01\_6000\_26000  
\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID7\_NS\_01\_26000\_4000  
0\_#1




NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID8\_NS\_01\_0.009\_0.15\_  
\_#1



NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID8\_NS\_01\_0.15\_30\_#1




05:37:51 16.11.2014




05:38:05 16.11.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID8\_NS\_01\_30\_1000\_#1

NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID8\_NS\_01\_1000\_3000\_#1




05:38:17 16.11.2014



05:38:20 16.11.2014


NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID8\_NS\_01\_3000\_6000\_#1

NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID8\_NS\_01\_6000\_26000\_#1




05:38:42 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID8\_NS\_01\_26000\_4000  
0\_#1




05:40:47 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID9\_NS\_01\_0.009\_0.15\_  
#1




05:40:58 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID9\_NS\_01\_0.15\_30\_#1




05:41:09 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID9\_NS\_01\_30\_1000\_#1




05:41:29 16.01.2014  
 NTVN\_N77-3450-  
 3550\_PC3\_30\_100\_M\_TID9\_NS\_01\_1000\_3000\_  
 #1


05:41:29 16.01.2014  
 NTVN\_N77-3450-  
 3550\_PC3\_30\_100\_M\_TID9\_NS\_01\_3000\_6000\_  
 #1




05:41:46 16.01.2014  
 NTVN\_N77-3450-  
 3550\_PC3\_30\_100\_M\_TID9\_NS\_01\_6000\_26000  
 #1




05:41:56 16.01.2014  
 NTVN\_N77-3450-  
 3550\_PC3\_30\_100\_M\_TID9\_NS\_01\_26000\_4000  
 0\_#1




NTNV\_N77-3450-  
 3550\_PC3\_30\_100\_M\_TID10\_NS\_01\_0.009\_0.15  
 #1



NTNV\_N77-3450-  
 3550\_PC3\_30\_100\_M\_TID10\_NS\_01\_0.15\_30\_#  
 1




NTNV\_N77-3450-  
 3550\_PC3\_30\_100\_M\_TID10\_NS\_01\_30\_1000\_#  
 1




NTNV\_N77-3450-  
 3550\_PC3\_30\_100\_M\_TID10\_NS\_01\_1000\_3000  
 #1






05:44:53 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID10\_NS\_01\_3000\_6000  
\_#1




05:45:05 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID10\_NS\_01\_6000\_2600  
0\_#1




05:45:18 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID10\_NS\_01\_26000\_400  
00\_#1




05:47:24 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID11\_NS\_01\_0.009\_0.15  
\_#1




05:47:25 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID11\_NS\_01\_0.15\_30\_#  
1




05:47:46 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID11\_NS\_01\_30\_1000\_#  
1



05:47:57 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID11\_NS\_01\_1000\_3000  
\_#1



05:48:19 16.01.2014

NTNV\_N77-3450-  
3550\_PC3\_30\_100\_M\_TID11\_NS\_01\_3000\_6000  
\_#1