Coverletter:

Harman Professional, Inc. wants to get FCC-Certification for the following device: HT4025B.

The unit will get the following FCC-ID: 2AUHEHT4025B

List of documents:

Exhibit	Thema	File
Exhibit 01	Label and placement	label_and_placement.pdf
Exhibit 02	Authorization	Authorization.pdf
	Covered List	FCC Attestation Statements Part 2.911(d)(5)(i)&(ii) Filing1_AKG_HT40 (signed).pdf
	US Agent for Service of Process	FCC Service of Process Letter (signed).pdf
Exhibit 03	External Photos	photo_external.pdf
* Exhibit 04	Block Diagrams	HT40_v11_US25B Blockdiagram.pdf
* Exhibit 05	Schematic Diagrams	HT40_v11_US25B.pdf
Exhibit 06	Testreport	2022-IN-AT-TICL-E-EX-000246-FG-
	Dort 45 Antonno Info	002_Rev1_noPhoto.pdf
F. h : h : 4 0.7	Part 15 Antenna Info	Test Report with Part 15 Antenna Information.pdf
Exhibit 07	Test Set-up Photos	photo_setup.pdf
Exhibit 08	User Manual	5061618_B_LIT_ADD_MANUAL SUPPLEMENT-RED_WMS40Mini2.pdf
Exhibit 09	Internal Photos	photo_internal.pdf
Exhibit 10	Part 15 antenna	see test report
	information	see internal photo exhibit
Exhibit 11	RF exposure	2022-IN-AT-TICL-E-EX-000246-FG-
		002_Rev1_noPhoto.pdf
	RF Exp Production Tolerance	FCC Production Tolerance.pdf
* Exhibit 12	Operational Description	Short_description_HT40.pdf
Exhibit 13	Cover letter	this file
EXHIBIT 13	Request for	FCC Confidentiality Letter (signed).pdf
	confidentiality	, , , , , , , , , , , , , , , , , , , ,

For the Exhibits marked with '*' Harman Professional, Inc. requested Long-Term Confidentiality according to 47 CFR 0.457 and 0.459 of the FCC rules because these are sensitive parts owned by this company and include much of know-how or sensitive data, it will not be provided to the public.

The labelling on some photos may be not the actual status. The correct labelling is shown on the label photo in Exhibit 1.