



16:17:36 15.11.2023

Band5-3MHz-16QAM-20415-15RB#0-PASS




16:18:27 15.11.2023

Band5-3MHz-16QAM-20525-15RB#0-PASS




16:19:18 15.11.2023

Band5-3MHz-16QAM-20635-15RB#0-PASS




16:17:52 15.11.2023

Band5-3MHz-64QAM-20415-15RB#0-PASS




16:18:43 15.11.2023

Band5-3MHz-64QAM-20525-15RB#0-PASS




16:19:34 15.11.2023

Band5-3MHz-64QAM-20635-15RB#0-PASS




16:20:20 15.11.2023

Band5-5MHz-QPSK-20425-25RB#0-PASS




16:22:11 15.11.2023

Band5-5MHz-QPSK-20525-25RB#0-PASS




16:22:08 15.11.2023

Band5-5MHz-QPSK-20625-25RB#0-PASS




16:20:36 15.11.2023

Band5-5MHz-16QAM-20425-25RB#0-PASS




16:22:27 15.11.2023

Band5-5MHz-16QAM-20525-25RB#0-PASS




16:22:19 15.11.2023


Band5-5MHz-16QAM-20625-25RB#0-PASS



Band5-5MHz-64QAM-20425-25RB#0-PASS




Band5-5MHz-64QAM-20525-25RB#0-PASS



Band5-5MHz-64QAM-20625-25RB#0-PASS




Band5-10MHz-QPSK-20450-50RB#0-PASS




16:24:06 15.11.2023

Band5-10MHz-QPSK-20525-50RB#0-PASS




16:24:07 15.11.2023

Band5-10MHz-QPSK-20600-50RB#0-PASS




16:23:31 15.11.2023

Band5-10MHz-16QAM-20450-50RB#0-PASS




16:24:22 15.11.2023

Band5-10MHz-16QAM-20525-50RB#0-PASS




16:28:12 15.11.2023

Band5-10MHz-16QAM-20600-50RB#0-PASS




16:23:47 15.11.2023

Band5-10MHz-64QAM-20450-50RB#0-PASS



16:24:38 15.11.2023


Band5-10MHz-64QAM-20525-50RB#0-PASS



16:28:28 15.11.2023


Band5-10MHz-64QAM-20600-50RB#0-PASS






16:26:14 15.11.2023

Band7-5MHz-QPSK-20775-25RB#0-PASS




16:27:09 15.11.2023

Band7-5MHz-QPSK-21100-25RB#0-PASS




16:27:57 15.11.2023

Band7-5MHz-QPSK-21425-25RB#0-PASS




16:28:30 15.11.2023

Band7-5MHz-16QAM-20775-25RB#0-PASS




16:27:21 15.11.2023

Band7-5MHz-16QAM-21100-25RB#0-PASS




16:28:12 15.11.2023

Band7-5MHz-16QAM-21425-25RB#0-PASS



16:26:56 15.11.2023


Band7-5MHz-64QAM-20775-25RB#0-PASS



16:27:38 15.11.2023


Band7-5MHz-64QAM-21100-25RB#0-PASS






16:28:29 15.11.2023

Band7-5MHz-64QAM-21425-25RB#0-PASS




16:29:15 15.11.2023

Band7-10MHz-QPSK-20800-50RB#0-PASS




16:30:06 15.11.2023

Band7-10MHz-QPSK-21100-50RB#0-PASS




16:30:57 15.11.2023

Band7-10MHz-QPSK-21400-50RB#0-PASS




16:29:31 15.11.2023

Band7-10MHz-16QAM-20800-50RB#0-PASS




16:30:22 15.11.2023

Band7-10MHz-16QAM-21100-50RB#0-PASS




16:31:13 15.11.2023

Band7-10MHz-16QAM-21400-50RB#0-PASS




16:29:47 15.11.2023

Band7-10MHz-64QAM-20800-50RB#0-PASS




16:30:38 15.11.2023

Band7-10MHz-64QAM-21100-50RB#0-PASS




16:31:29 15.11.2023

Band7-10MHz-64QAM-21400-50RB#0-PASS




16:32:11 15.11.2023

Band7-15MHz-QPSK-20825-75RB#0-PASS




16:33:02 15.11.2023

Band7-15MHz-QPSK-21100-75RB#0-PASS



16:33:53 15.11.2023

Band7-15MHz-QPSK-21375-75RB#0-PASS




16:32:27 15.11.2023

Band7-15MHz-16QAM-20825-75RB#0-PASS




16:33:18 15.11.2023

Band7-15MHz-16QAM-21100-75RB#0-PASS




16:34:09 15.11.2023

Band7-15MHz-16QAM-21375-75RB#0-PASS




16:32:43 15.11.2023

Band7-15MHz-64QAM-20825-75RB#0-PASS




16:33:34 15.11.2023

Band7-15MHz-64QAM-21100-75RB#0-PASS




16:34:26 15.11.2023

Band7-15MHz-64QAM-21375-75RB#0-PASS




16:38:06 15.11.2023

Band7-20MHz-QPSK-20850-100RB#0-PASS




16:38:55 15.11.2023

Band7-20MHz-QPSK-21100-100RB#0-PASS




16:39:05 15.11.2023

Band7-20MHz-QPSK-21350-100RB#0-PASS



16:38:21 15.11.2023


Band7-20MHz-16QAM-20850-100RB#0-PASS



16:36:11 15.11.2023


Band7-20MHz-16QAM-21100-100RB#0-PASS






16:37:01 15.11.2023

Band7-20MHz-16QAM-21350-100RB#0-PASS




16:38:36 15.11.2023

Band7-20MHz-64QAM-20850-100RB#0-PASS




16:36:26 15.11.2023

Band7-20MHz-64QAM-21100-100RB#0-PASS




16:37:17 15.11.2023

Band7-20MHz-64QAM-21350-100RB#0-PASS



16:49:04 18.11.2023

Band12-1.4MHz-QPSK-23017-6RB#0-PASS




16:49:56 18.11.2023

Band12-1.4MHz-QPSK-23095-6RB#0-PASS




16:49:17 18.11.2023

Band12-1.4MHz-QPSK-23173-6RB#0-PASS




16:49:20 18.11.2023

Band12-1.4MHz-16QAM-23017-6RB#0-PASS



16:50:12 15.11.2023

Band12-1.4MHz-16QAM-23095-6RB#0-PASS




16:51:04 15.11.2023

Band12-1.4MHz-16QAM-23173-6RB#0-PASS




16:59:37 15.11.2023

Band12-1.4MHz-64QAM-23017-6RB#0-PASS




16:50:28 15.11.2023

Band12-1.4MHz-64QAM-23095-6RB#0-PASS




16:51:20 15.11.2023

Band12-1.4MHz-64QAM-23173-6RB#0-PASS




16:52:08 15.11.2023

Band12-3MHz-QPSK-23025-15RB#0-PASS




16:52:58 15.11.2023

Band12-3MHz-QPSK-23095-15RB#0-PASS




16:53:49 15.11.2023

Band12-3MHz-QPSK-23165-15RB#0-PASS




16:52:24 15.11.2023

Band12-3MHz-16QAM-23025-15RB#0-PASS




16:53:15 15.11.2023

Band12-3MHz-16QAM-23095-15RB#0-PASS




16:54:06 15.11.2023

Band12-3MHz-16QAM-23165-15RB#0-PASS




16:52:40 15.11.2023

Band12-3MHz-64QAM-23025-15RB#0-PASS




16:53:31 15.11.2023

Band12-3MHz-64QAM-23095-15RB#0-PASS




16:54:22 15.11.2023

Band12-3MHz-64QAM-23165-15RB#0-PASS



16:55:08 15.11.2023


Band12-5MHz-QPSK-23035-25RB#0-PASS



16:55:59 15.11.2023


Band12-5MHz-QPSK-23095-25RB#0-PASS






16:56:50 15.11.2023

Band12-5MHz-QPSK-23155-25RB#0-PASS




16:58:24 15.11.2023

Band12-5MHz-16QAM-23035-25RB#0-PASS




16:56:15 15.11.2023

Band12-5MHz-16QAM-23095-25RB#0-PASS




16:57:06 15.11.2023

Band12-5MHz-16QAM-23155-25RB#0-PASS




16:58:40 15.11.2023

Band12-5MHz-64QAM-23035-25RB#0-PASS




16:58:31 15.11.2023

Band12-5MHz-64QAM-23095-25RB#0-PASS




16:57:22 15.11.2023

Band12-5MHz-64QAM-23155-25RB#0-PASS




16:58:22 15.11.2023

Band12-10MHz-QPSK-23060-50RB#0-PASS




16:59:18 15.11.2023

Band12-10MHz-QPSK-23095-50RB#0-PASS




21:00:04 15.11.2023

Band12-10MHz-QPSK-23130-50RB#0-PASS




16:59:38 15.11.2023

Band12-10MHz-16QAM-23060-50RB#0-PASS




16:59:29 15.11.2023

Band12-10MHz-16QAM-23095-50RB#0-PASS




21:00:20 15.11.2023

Band12-10MHz-16QAM-23130-50RB#0-PASS




16:38:54 15.11.2023

Band12-10MHz-64QAM-23060-50RB#0-PASS




16:39:16 15.11.2023

Band12-10MHz-64QAM-23095-50RB#0-PASS




21:00:36 15.11.2023

Band12-10MHz-64QAM-23130-50RB#0-PASS




21:01:57 15.11.2023

Band13-5MHz-QPSK-23205-25RB#0-PASS




21:02:58 15.11.2023

Band13-5MHz-QPSK-23230-25RB#0-PASS




21:03:49 15.11.2023

Band13-5MHz-QPSK-23255-25RB#0-PASS




21:02:13 15.11.2023

Band13-5MHz-16QAM-23205-25RB#0-PASS




21:03:14 15.11.2023

Band13-5MHz-16QAM-23230-25RB#0-PASS




21:04:06 15.11.2023

Band13-5MHz-16QAM-23255-25RB#0-PASS



21:02:39 15.11.2023


Band13-5MHz-64QAM-23205-25RB#0-PASS



21:03:30 15.11.2023


Band13-5MHz-64QAM-23230-25RB#0-PASS






21:04:22 15.11.2023

Band13-5MHz-64QAM-23255-25RB#0-PASS




08:54:59 16.11.2023

Band13-10MHz-QPSK-23230-50RB#0-PASS




08:55:15 16.11.2023

Band13-10MHz-16QAM-23230-50RB#0-PASS




08:55:31 16.11.2023

Band13-10MHz-64QAM-23230-50RB#0-PASS




08:59:22 16.11.2023

Band17-5MHz-QPSK-23755-25RB#0-PASS




09:00:12 16.11.2023

Band17-5MHz-QPSK-23790-25RB#0-PASS




09:01:04 16.11.2023

Band17-5MHz-QPSK-23825-25RB#0-PASS




08:59:38 16.11.2023

Band17-5MHz-16QAM-23755-25RB#0-PASS




09:00:29 16.11.2023

Band17-5MHz-16QAM-23790-25RB#0-PASS




09:01:20 16.11.2023

Band17-5MHz-16QAM-23825-25RB#0-PASS




08:59:54 16.11.2023

Band17-5MHz-64QAM-23755-25RB#0-PASS




09:00:46 16.11.2023

Band17-5MHz-64QAM-23790-25RB#0-PASS




09:01:36 16.11.2023

Band17-5MHz-64QAM-23825-25RB#0-PASS




09:02:49 16.11.2023

Band17-10MHz-QPSK-23780-50RB#0-PASS




09:03:40 16.11.2023

Band17-10MHz-QPSK-23790-50RB#0-PASS




09:04:30 16.11.2023

Band17-10MHz-QPSK-23800-50RB#0-PASS




09:03:06 16.11.2023

Band17-10MHz-16QAM-23780-50RB#0-PASS




09:03:06 16.11.2023

Band17-10MHz-16QAM-23790-50RB#0-PASS




09:04:06 16.11.2023

Band17-10MHz-16QAM-23800-50RB#0-PASS




09:03:21 16.11.2023

Band17-10MHz-64QAM-23780-50RB#0-PASS




09:04:12 16.11.2023

Band17-10MHz-64QAM-23790-50RB#0-PASS




09:08:02 16.11.2023

Band17-10MHz-64QAM-23800-50RB#0-PASS



09:40:10 16.11.2023


Band38-5MHz-QPSK-37775-25RB#0-PASS



09:43:01 16.11.2023


Band38-5MHz-QPSK-38000-25RB#0-PASS






09:41:52 16.11.2023

Band38-5MHz-QPSK-38225-25RB#0-PASS




09:40:26 16.11.2023

Band38-5MHz-16QAM-37775-25RB#0-PASS




09:41:17 16.11.2023

Band38-5MHz-16QAM-38000-25RB#0-PASS




09:42:08 16.11.2023

Band38-5MHz-16QAM-38225-25RB#0-PASS




09:40:42 16.11.2023

Band38-5MHz-64QAM-37775-25RB#0-PASS




09:41:39 16.11.2023

Band38-5MHz-64QAM-38000-25RB#0-PASS




09:42:24 16.11.2023

Band38-5MHz-64QAM-38225-25RB#0-PASS




09:46:04 16.11.2023

Band38-10MHz-QPSK-37800-50RB#0-PASS




09:46:55 16.11.2023

Band38-10MHz-QPSK-38000-50RB#0-PASS




09:47:06 16.11.2023

Band38-10MHz-QPSK-38200-50RB#0-PASS




09:46:20 16.11.2023

Band38-10MHz-16QAM-37800-50RB#0-PASS




09:47:11 16.11.2023

Band38-10MHz-16QAM-38000-50RB#0-PASS




09:48:02 16.11.2023

Band38-10MHz-16QAM-38200-50RB#0-PASS




09:48:36 16.11.2023

Band38-10MHz-64QAM-37800-50RB#0-PASS




09:47:27 16.11.2023

Band38-10MHz-64QAM-38000-50RB#0-PASS




09:48:18 16.11.2023


Band38-10MHz-64QAM-38200-50RB#0-PASS




Band38-15MHz-QPSK-37825-75RB#0-PASS




Band38-15MHz-QPSK-38000-75RB#0-PASS



Band38-15MHz-QPSK-38175-75RB#0-PASS




Band38-15MHz-16QAM-37825-75RB#0-PASS




09:50:07 16.11.2023

Band38-15MHz-16QAM-38000-75RB#0-PASS




09:50:08 16.11.2023

Band38-15MHz-16QAM-38175-75RB#0-PASS



09:50:32 16.11.2023


Band38-15MHz-64QAM-37825-75RB#0-PASS



09:50:23 16.11.2023


Band38-15MHz-64QAM-38000-75RB#0-PASS






09:51:14 16.11.2023

Band38-15MHz-64QAM-38175-75RB#0-PASS




09:51:56 16.11.2023

Band38-20MHz-QPSK-37850-100RB#0-PASS




09:52:47 16.11.2023

Band38-20MHz-QPSK-38000-100RB#0-PASS




09:53:46 16.11.2023


Band38-20MHz-QPSK-38150-100RB#0-PASS




Band38-20MHz-16QAM-37850-100RB#0-PASS




Band38-20MHz-16QAM-38000-100RB#0-PASS



Band38-20MHz-16QAM-38150-100RB#0-PASS




Band38-20MHz-64QAM-37850-100RB#0-PASS




09:53:18 16.11.2023

Band38-20MHz-64QAM-38000-100RB#0-PASS




09:54:17 16.11.2023

Band38-20MHz-64QAM-38150-100RB#0-PASS




09:21:36 27.11.2023

Band41-5MHz-QPSK-39675-25RB#0-PASS




09:22:26 27.11.2023

Band41-5MHz-QPSK-40620-25RB#0-PASS




09:23:17 27.11.2023

Band41-5MHz-QPSK-41565-25RB#0-PASS




09:23:54 27.11.2023

Band41-5MHz-16QAM-39675-25RB#0-PASS




09:22:42 27.11.2023

Band41-5MHz-16QAM-40620-25RB#0-PASS




09:23:33 27.11.2023

Band41-5MHz-16QAM-41565-25RB#0-PASS




09:22:07 27.11.2023

Band41-5MHz-64QAM-39675-25RB#0-PASS




09:22:58 27.11.2023

Band41-5MHz-64QAM-40620-25RB#0-PASS




09:23:49 27.11.2023

Band41-5MHz-64QAM-41565-25RB#0-PASS




09:25:49 27.11.2023

Band41-10MHz-QPSK-39700-50RB#0-PASS




09:26:36 27.11.2023

Band41-10MHz-QPSK-40620-50RB#0-PASS




09:27:26 27.11.2023

Band41-10MHz-QPSK-41540-50RB#0-PASS



09:28:59 27.11.2023


Band41-10MHz-16QAM-39700-50RB#0-PASS



09:28:50 27.11.2023


Band41-10MHz-16QAM-40620-50RB#0-PASS






09:27:41 27.11.2023

Band41-10MHz-16QAM-41540-50RB#0-PASS




09:26:15 27.11.2023

Band41-10MHz-64QAM-39700-50RB#0-PASS




09:27:06 27.11.2023

Band41-10MHz-64QAM-40620-50RB#0-PASS




09:27:57 27.11.2023


Band41-10MHz-64QAM-41540-50RB#0-PASS




Band41-15MHz-QPSK-39725-75RB#0-PASS




Band41-15MHz-QPSK-40620-75RB#0-PASS



Band41-15MHz-QPSK-41515-75RB#0-PASS




Band41-15MHz-16QAM-39725-75RB#0-PASS




09:29:16 27.11.2023

Band41-15MHz-16QAM-40620-75RB#0-PASS




09:30:40 27.11.2023

Band41-15MHz-16QAM-41515-75RB#0-PASS




09:29:14 27.11.2023

Band41-15MHz-64QAM-39725-75RB#0-PASS




09:30:06 27.11.2023

Band41-15MHz-64QAM-40620-75RB#0-PASS




09:30:56 27.11.2023

Band41-15MHz-64QAM-41515-75RB#0-PASS




09:31:36 27.11.2023

Band41-20MHz-QPSK-39750-100RB#0-PASS




09:32:27 27.11.2023

Band41-20MHz-QPSK-40620-100RB#0-PASS




09:33:18 27.11.2023

Band41-20MHz-QPSK-41490-100RB#0-PASS




09:31:52 27.11.2023

Band41-20MHz-16QAM-39750-100RB#0-PASS




09:32:49 27.11.2023

Band41-20MHz-16QAM-40620-100RB#0-PASS




09:33:36 27.11.2023

Band41-20MHz-16QAM-41490-100RB#0-PASS




09:32:08 27.11.2023

Band41-20MHz-64QAM-39750-100RB#0-PASS



Band41-20MHz-64QAM-40620-100RB#0-PASS



Band41-20MHz-64QAM-41490-100RB#0-PASS




Band66-1.4MHz-QPSK-131979-6RB#0-PASS




Band66-1.4MHz-QPSK-132322-6RB#0-PASS





09:07:27 16.11.2023

Band66-1.4MHz-QPSK-132665-6RB#0-PASS



09:04:00 16.11.2023

Band66-1.4MHz-16QAM-131979-6RB#0-PASS




09:04:52 16.11.2023

Band66-1.4MHz-16QAM-132322-6RB#0-PASS




09:07:44 16.11.2023

Band66-1.4MHz-16QAM-132665-6RB#0-PASS




09:06:16 16.11.2023

Band66-1.4MHz-64QAM-131979-6RB#0-PASS




09:07:08 16.11.2023

Band66-1.4MHz-64QAM-132322-6RB#0-PASS




09:08:00 16.11.2023

Band66-1.4MHz-64QAM-132665-6RB#0-PASS




09:08:40 16.11.2023


Band66-3MHz-QPSK-131987-15RB#0-PASS




Band66-3MHz-QPSK-132322-15RB#0-PASS




Band66-3MHz-QPSK-132657-15RB#0-PASS



Band66-3MHz-16QAM-131987-15RB#0-PASS




Band66-3MHz-16QAM-132322-15RB#0-PASS




09:10:37 16.11.2023

Band66-3MHz-16QAM-132657-15RB#0-PASS




09:09:12 16.11.2023

Band66-3MHz-64QAM-131987-15RB#0-PASS




09:10:02 16.11.2023

Band66-3MHz-64QAM-132322-15RB#0-PASS




09:10:52 16.11.2023


Band66-3MHz-64QAM-132657-15RB#0-PASS




Band66-5MHz-QPSK-131997-25RB#0-PASS



Band66-5MHz-QPSK-132322-25RB#0-PASS



Band66-5MHz-QPSK-132647-25RB#0-PASS



Band66-5MHz-16QAM-131997-25RB#0-PASS