Report No: HK22040253

#### **Configuration Photographs**

#### Worst-Case Line-Conducted Emissions

# (Front View)

# Powered by Notebook USB Port + 2.4GHz Operating



Report No: HK22040253

**Configuration Photographs** 

## Worst-Case Line-Conducted Emissions

(Rear View)

# Powered by Notebook USB Port + 2.4GHz Operating



Report No: HK22040253

**Configuration Photographs** 

## Worst-Case Line-Conducted Emissions

(Side View)

# Powered by Notebook USB Port + 2.4GHz Operating



Report No: HK22040253

#### **Configuration Photographs**

#### Worst-Case Line-Conducted Emissions

#### (Front View)

# Powered by Notebook USB Port + 2.4GHz Operating with Docking (Cradle)



Report No: HK22040253

#### **Configuration Photographs**

#### Worst-Case Line-Conducted Emissions

(Rear View)

Powered by Notebook USB Port + 2.4GHz Operating with Docking (Cradle)



Report No: HK22040253

#### **Configuration Photographs**

#### Worst-Case Line-Conducted Emissions

(Side View)

Powered by Notebook USB Port + 2.4GHz Operating with Docking (Cradle)

