

Hyundai Technology Group, Inc  
Address: 2601 Walnut Ave. Tustin, CA, USA  
Tel: 1.949.679.7960; Fax: 714-409-3091  
Email: moe@hyundaitechnology.com

## Attestation Letter

2020-03-19

Dear Sir or Madam,

The Main chip and RF chip, model: Mstar648, RTL8192, RTL8812, installed in our product Interactive Digital Display Solution 65", model: HWM10LA65; FCC ID: 2AVTH-HWM10LA65, this chip supports WIFI 2.4G & WIFI 5G function, but for marketing purpose, this chip only supports WIFI 2.4G (2412~2462 MHz, 2422~2452 MHz); WIFI 5G (5150~5250 MHz, 5725~5850 MHz), not support 5G (5250-5350 MHz, 5470-5725 MHz), which were disabled to use by manufacture in the software, the end user has no capability to activate it. The OPS connector on the left side of Machine back, were disabled to use as well by manufacture in the software, the end user has no capability to activate it.

Sincerely Yours,

Signature:



Moe Kalbouneh

Product Manager