



5785MHz




5825MHz




IEEE 802.11ax HE40 Mode / 5725 ~ 5850MHz (Chain 0)

5755MHz




5795MHz




IEEE 802.1ax HE40 Mode / 5725 ~ 5850MHz (Chain 1)

5755MHz




5795MHz




IEEE 802.11ax HE40 Mode / 5725 ~ 5850MHz (Chain 2)

5755MHz



Date: 6.DEC.2024 11:36:14


5795MHz




Date: 6.DEC.2024 11:38:35

IEEE 802.11ax HE40 Mode / 5725 ~ 5850MHz (Chain 3)


5755MHz




5795MHz



IEEE 802.11ax HE80 Mode / 5725 ~ 5850MHz (Chain 0)




IEEE 802.11ax HE80 Mode / 5725 ~ 5850MHz (Chain 1)




IEEE 802.11ax HE80 Mode / 5725 ~ 5850MHz (Chain 2)

5775MHz



IEEE 802.11ax HE80 Mode / 5725 ~ 5850MHz (Chain 3)


5775MHz




UNII-1 Band I / OBW 99%

IEEE 802.11a Mode / 5150 ~ 5250MHz (Chain 0)

5180MHz



5200MHz



5240MHz




IEEE 802.11a Mode / 5150 ~ 5250MHz (Chain 1)


5180MH



5200MHz



5240MHz




IEEE 802.11a Mode / 5150 ~ 5250MHz (Chain 2)


5180MHz



5200MHz




5240MHz




IEEE 802.11a Mode / 5150 ~ 5250MHz (Chain 3)

5180MHz




5200MHz



Date: 10.DEC.2024 14:42:17


5240MHz




Date: 10.DEC.2024 14:44:29

IEEE 802.11ac VHT20 Mode / 5150 ~ 5250MHz (Chain 0)

5180MHz



5200MHz




5240MHz




IEEE 802.11ac VHT20 Mode / 5150 ~ 5250MHz (Chain 1)


5180MHz



5200MHz



5240MHz



IEEE 802.11ac VHT20 Mode / 5150 ~ 5250MHz (Chain 2)


5180MHz



5200MHz




5240MHz




IEEE 802.11ac VHT20 Mode / 5150 ~ 5250MHz (Chain 3)

5180MHz




5200MHz



Date: 10.DEC.2024 15:00:54


5240MHz




Date: 10.DEC.2024 15:01:50

IEEE 802.11ac VHT40 Mode / 5150 ~ 5250MHz (Chain 0)

5190MHz



5230MHz




5190MHz




Date: 9.DEC.2024 14:33:46

IEEE 802.11ac VHT40 Mode / 5150 ~ 5250MHz (Chain 2)

5190MHz




5230MHz




IEEE 802.11ac VHT40 Mode / 5150 ~ 5250MHz (Chain 3)


5190MHz




5230MHz




IEEE 802.11ac VHT80 Mode / 5150 ~ 5250MHz (Chain 0)




IEEE 802.11ac VHT80 Mode / 5150 ~ 5250MHz (Chain 1)



IEEE 802.11ac VHT80 Mode / 5150 ~ 5250MHz (Chain 2)




IEEE 802.11ac VHT80 Mode / 5150 ~ 5250MHz (Chain 3)




IEEE 802.11ax HE20 Mode / 5150 ~ 5250MHz (Chain 0)

5180MHz



5200MHz




5240MHz




IEEE 802.11ax HE20 Mode / 5150 ~ 5250MHz (Chain 1)

5180MHz



5200MHz



Date: 9.DEC.2024 15:21:53


5240MHz



Date: 9.DEC.2024 15:23:17

IEEE 802.11ax HE20 Mode / 5150 ~ 5250MHz (Chain 2)

5180MHz



5200MHz




5240MHz




IEEE 802.11ax HE20 Mode / 5150 ~ 5250MHz (Chain 3)

5180MHz



5200MHz



Date: 10.DEC.2024 15:54:31


5240MHz




Date: 10.DEC.2024 15:55:30

IEEE 802.11ax HE40 Mode / 5150 ~ 5250MHz (Chain 0)

5190MHz




5230MHz




IEEE 802.11ax HE40 Mode / 5150 ~ 5250MHz (Chain 1)

5190MHz




5230MHz




IEEE 802.11ax HE40 Mode / 5150 ~ 5250MHz (Chain 2)

5190MHz




5230MHz




IEEE 802.11ax HE40 Mode / 5150 ~ 5250MHz (Chain 3)


5190MHz




5230MHz




IEEE 802.11ax HE80 Mode / 5150 ~ 5250MHz (Chain 0)




IEEE 802.11ax HE80 Mode / 5150 ~ 5250MHz (Chain 1)



IEEE 802.11ax HE80 Mode / 5150 ~ 5250MHz (Chain 2)




IEEE 802.11ax HE80 Mode / 5150 ~ 5250MHz (Chain 3)



UNII-2A Band II / OBW 99%

IEEE 802.11a Mode / 5250 ~ 5250MHz (Chain 0)

5260MHz




Date: 9.DEC.2024 08:54:13

5300MHz




Date: 9.DEC.2024 08:55:17

5320MHz




IEEE 802.11a Mode / 5250 ~ 5250MHz (Chain 1)

5260MHz




5300MHz



Date: 9.DEC.2024 13:14:13


5320MHz



Date: 9.DEC.2024 13:15:23

IEEE 802.11a Mode / 5250 ~ 5250MHz (Chain 2)


5260MHz



5300MHz



5320MHz




IEEE 802.11a Mode / 5250 ~ 5250MHz (Chain 3)


5260MHz



5300MHz




5320MHz



IEEE 802.11ac VHT20 Mode / 5250 ~ 5350MHz (Chain 0)

5260MHz



5300MHz




5320MHz




IEEE 802.11ac VHT20 Mode / 5250 ~ 5350MHz (Chain 1)

5260MHz




5300MHz



Date: 9.DEC.2024 13:57:27

5320MHz




Date: 9.DEC.2024 13:59:27

IEEE 802.11ac VHT20 Mode / 5250 ~ 5350MHz (Chain 2)


5260MHz



5300MHz



5320MHz



Date: 10.DEC.2024 09:49:53


IEEE 802.11ac VHT20 Mode / 5250 ~ 5350MHz (Chain 3)

5260MHz



Date: 10.DEC.2024 15:05:56

5300MHz



Date: 10.DEC.2024 15:06:40


5320MHz




Date: 10.DEC.2024 15:07:27

IEEE 802.11ac VHT40 Mode / 5250 ~ 5350MHz (Chain 0)

5270MHz




5310MHz




IEEE 802.11ac VHT40 Mode / 5250 ~ 5350MHz (Chain 1)

5270MHz




5310MHz




IEEE 802.11ac VHT40 Mode / 5250 ~ 5350MHz (Chain 2)

5270MHz




5310MHz




IEEE 802.11ac VHT40 Mode / 5250 ~ 5350MHz (Chain 3)

5270MHz




5310MHz




IEEE 802.11ac VHT80 Mode / 5250 ~ 5350MHz (Chain 0)

5290MHz




IEEE 802.11ac VHT80 Mode / 5250 ~ 5350MHz (Chain 1)


5290MHz



IEEE 802.11ac VHT80 Mode / 5250 ~ 5350MHz (Chain 2)




IEEE 802.11ac VHT80 Mode / 5250 ~ 5350MHz (Chain 3)




IEEE 802.11ax HE20 Mode / 5250 ~ 5350MHz (Chain 0)


5260MHz



5300MHz




5320MHz




IEEE 802.11ax HE20 Mode / 5250 ~ 5350MHz (Chain 1)


5260MHz




5300MHz



5320MHz




5260MHz




Date: 10.DEC.2024 11:33:06

5320MHz




IEEE 802.11ax HE20 Mode / 5250 ~ 5350MHz (Chain 3)

5260MHz




5300MHz



Date: 10.DEC.2024 16:01:40


5320MHz




Date: 10.DEC.2024 16:04:17

IEEE 802.11ax HE40 Mode / 5250 ~ 5350MHz (Chain 0)

5270MHz




5310MHz




IEEE 802.11ax HE40 Mode / 5250 ~ 5350MHz (Chain 1)

5270MHz




5310MHz




IEEE 802.11ax HE40 Mode / 5250 ~ 5350MHz (Chain 2)

5270MHz




5310MHz




IEEE 802.11ax HE40 Mode / 5250 ~ 5350MHz (Chain 3)


5270MHz




5310MHz




5290MHz



IEEE 802.11ax HE80 Mode / 5250 ~ 5350MHz (Chain 2)




IEEE 802.11ax HE80 Mode / 5250 ~ 5350MHz (Chain 3)



UNII-2C Band III / OBW 99%


IEEE 802.11a Mode / 5470 ~ 5725MHz (Chain 0)

5500MHz




Date: 9, DEC, 2024 08:58:24

5580MHz



Date: 9, DEC, 2024 09:00:10

5700MHz




IEEE 802.11a Mode / 5470 ~ 5725MHz (Chain 1)

5500MHz



5580MHz



Date: 9.DEC.2024 13:19:44


5700MHz



Date: 9.DEC.2024 13:22:11

IEEE 802.11a Mode / 5470 ~ 5725MHz (Chain 2)


5500MHz



5580MHz




5700MHz




IEEE 802.11a Mode / 5470 ~ 5725MHz (Chain 3)

5500MHz



5580MHz



Date: 10.DEC.2024 14:49:57

5700MHz




Date: 10.DEC.2024 14:51:00

IEEE 802.11ac VHT20 Mode / 5470 ~ 5725MHz (Chain 0)


5500MHz



5580MHz



5700MHz




IEEE 802.11ac VHT20 Mode / 5470 ~ 5725MHz (Chain 1)

5500MHz



5580MHz



Date: 7.JAN.2025 13:54:19

5700MHz




Date: 9.DEC.2024 14:06:05

IEEE 802.11ac VHT20 Mode / 5470 ~ 5725MHz (Chain 2)

5500MHz



5580MHz




5700MHz




IEEE 802.11ac VHT20 Mode / 5470 ~ 5725MHz (Chain 3)

5500MHz



5580MHz



Date: 10.DEC.2024 15:09:20

5700MHz




Date: 10.DEC.2024 15:11:00

5510MHz


Date: 9.DEC.2024 10:00:26

5670MHz




IEEE 802.11ac VHT40 Mode / 5470 ~ 5725MHz (Chain 1)

5510MHz




5550MHz



Date: 9.DEC.2024 14:41:23


5670MHz




Date: 9.DEC.2024 14:42:20

IEEE 802.11ac VHT40 Mode / 5470 ~ 5725MHz (Chain 2)


5510MHz



5550MHz




5670MHz



Date: 10.DEC.2024 10:46:30


IEEE 802.11ac VHT40 Mode / 5470 ~ 5725MHz (Chain 3)

5510MHz




Date: 10.DEC.2024 15:24:28

5550MHz



Date: 10.DEC.2024 15:25:27


5670MHz




Date: 10.DEC.2024 15:26:36

IEEE 802.11ac VHT80 Mode / 5470 ~ 5725MHz (Chain 0)

5530MHz




5610MHz




IEEE 802.11ac VHT80 Mode / 5470 ~ 5725MHz (Chain 1)

5530MHz



5610MHz




IEEE 802.11ac VHT80 Mode / 5470 ~ 5725MHz (Chain 2)

5530MHz




5610MHz




IEEE 802.11ac VHT80 Mode / 5470 ~ 5725MHz (Chain 3)

5530MHz




5610MHz




IEEE 802.11ax HE20 Mode / 5470 ~ 5725MHz (Chain 0)


5500MHz



5580MHz




5700MHz




IEEE 802.11ax HE20 Mode / 5470 ~ 5725MHz (Chain 1)

5500MHz



5580MHz



Date: 9.DEC.2024 15:43:35


5700MHz



Date: 9.DEC.2024 15:49:58

IEEE 802.11ax HE20 Mode / 5470 ~ 5725MHz (Chain 2)

5500MHz



5580MHz

