



Canada

## Exhibit: Internal Photos

FCC ID: 2AW7V-93004022

IC: 26602-93004022

Report File #: 7169009082RF -000

© TÜV SÜD Canada Inc. This test report shall not be reproduced except in full, without written approval of TÜV SÜD Canada Inc.

Client	<b>Taco Comfort Solutions, Inc</b>	 Canada
Product	<b>Next-Generation Electronic Controller Model: SR506-5 &amp; ZVC406-5</b>	
Standard(s)	<b>RSS 247 Issue 2:2017 FCC Part 15 Subpart 15.247</b>	




Figure 1 – EUT (SR) Internal Photo

Client	Taco Comfort Solutions, Inc	 Canada
Product	Next-Generation Electronic Controller Model: SR506-5 & ZVC406-5	
Standard(s)	RSS 247 Issue 2:2017 FCC Part 15 Subpart 15.247	




Figure 2 – EUT (SR) Internal Photo PCB Top

Client	<b>Taco Comfort Solutions, Inc</b>	 Canada
Product	<b>Next-Generation Electronic Controller Model: SR506-5 &amp; ZVC406-5</b>	
Standard(s)	<b>RSS 247 Issue 2:2017 FCC Part 15 Subpart 15.247</b>	




Figure 3 – EUT (SR) Internal Photo PCB Bottom

Client	<b>Taco Comfort Solutions, Inc</b>	 Canada
Product	<b>Next-Generation Electronic Controller Model: SR506-5 &amp; ZVC406-5</b>	
Standard(s)	<b>RSS 247 Issue 2:2017 FCC Part 15 Subpart 15.247</b>	




Figure 4 – EUT (ZVC) Internal Photo PCB Top

Client	<b>Taco Comfort Solutions, Inc</b>	 Canada
Product	<b>Next-Generation Electronic Controller Model: SR506-5 &amp; ZVC406-5</b>	
Standard(s)	<b>RSS 247 Issue 2:2017 FCC Part 15 Subpart 15.247</b>	




Figure 5 – EUT (ZVC) Internal Photo PCB Bottom