


POWER DOCK INSTRUCTION MANUAL


O2 WHAT'S INSIDE:



A: Power Dock


B: USB-C Power Cord

QUICK START:



Using the USB-C Power Cord fully charge the Power Dock before first use. The LED indicators will illuminate 4 WHITE dots when fully charged.

04




To charge an external device, plug directly into the USB-A input port. To charge the Power Dock, plug directly into the USB-C output port.



Tilt the Peak Pro forward into the Power Dock and then push down into the base to begin wireless charging.

06



An indicator will illuminate BLUE on the Power Dock when connection is established. The Peak Pro will also illuminate and pulse while charging. *Tip - Align Peak Pro charging port towards area indicated with arrow for faster charge.



Remove the Peak Pro in the reverse order shown in step 3 to initiate Ready Mode. Ready Mode is the pre-set bowl temperature of your choosing which can specified in the Peak Pro App.

TIPS AND WARNINGS

If the Power Dock does not respond once it is powered on, the battery capacity may be low. Follow the instructions for charging the Power Dock and check the WHITE illuminated battery level indicator.

Do not charge or operate below 32°F or above 100°F. Keep away from moisture and high-humidity. Store in a cool, well-ventilated place when possible.

LEGAL

2020 Puff Corp. All rights reserved, Puffco and Peak Pro are trademarks of Puff Corp., registered in the U.S. and other countries. Printed in China.



Product marketing name: 051894

Responsible party Info:

Company: Puff Corporation

Address: 1201 W 5th Street Suite T530, Los Angeles 90017

Contact Tel: +1 949 292 7260

Email address/Website: Manuel@puffco.com