FCC ID: 2AWHPR232

**Description of Permissive Change** 

The application is prepared for FCC class III permissive change. The differences with

the original application are:

1. Adding DFS band (5250 ~ 5320 MHz, 5500 ~ 5720 MHz) via software (Software/

Firmware version: DFS\_CERT\_20230918), and

2. Enabling bandwidth 160 MHz mode via software (Software/ Firmware version:

DFS\_CERT\_20230918).

SpaceX software configures the Wi-Fi router while communicating with the Starlink

network. Software is installed in the router and automatically updates without

end-user's intervention. Firmware is set and updated by the SpaceX Starlink network

and is not end-user accessible.

Both devices, original and updated versions, are electrically identical in all aspects

except the abovementioned.

Regards,

Trista Tsai / Specialist

- (rista

Bureau Veritas Consumer Products Services (H.K.) Ltd., Taoyuan Branch

Tel: 886-3-318 3232 ext. 4311812

Fax: 886-3-327 0892

Email: trista.tsai@bureauveritas.com

Data: 2023-12-18