



Date: 2.JUL.2024 22:23:27




Date: 2.JUL.2024 22:23:42

Band2_1.4MHz_16QAM_19193_1RB#0_1000~3000_1000~3000

Band2_1.4MHz_16QAM_19193_1RB#0_3000~20000_3000~20000





Date: 2.JUL.2024 22:23:53



Date: 2.JUL.2024 22:24:08

Band2_1.4MHz_QPSK_19193_1RB#5_0.009~0.15_0.009~0.15

Band2_1.4MHz_QPSK_19193_1RB#5_0.15~30_0.15~30





Date: 2.JUL.2024 22:24:22

Date: 2.JUL.2024 22:24:35

Band2_1.4MHz_QPSK_19193_1RB#5_30~1000_30~1000

Band2_1.4MHz_QPSK_19193_1RB#5_1000~3000_0_1000~3000




Date: 2.JUL.2024 22:24:50


Date: 2.JUL.2024 22:24:59

Band2_1.4MHz_QPSK_19193_1RB#5_3000~20000_00_3000~20000

Band2_1.4MHz_16QAM_19193_1RB#5_0.009~0.15_0.009~0.15




Date: 2.JUL.2024 22:25:14




Date: 2.JUL.2024 22:25:27

Band2_1.4MHz_16QAM_19193_1RB#5_0.15~30
 _0.15~30

Band2_1.4MHz_16QAM_19193_1RB#5_30~1000
 _30~1000




Date: 2.JUL.2024 22:25:41



Date: 2.JUL.2024 22:25:56


Band2_1.4MHz_16QAM_19193_1RB#5_1000~3000
 000_1000~3000

Band2_1.4MHz_16QAM_19193_1RB#5_3000~20000
 000_3000~20000




Date: 2.JUL.2024 22:26:07

Band2_1.4MHz_QPSK_19193_6RB#0_0.009~0.15_5_0.009~0.15




Date: 2.JUL.2024 22:26:22

Band2_1.4MHz_QPSK_19193_6RB#0_0.15~30_0.15~30




Date: 2.JUL.2024 22:26:35

Band2_1.4MHz_QPSK_19193_6RB#0_30~1000_30~1000




Date: 2.JUL.2024 22:26:49

Band2_1.4MHz_QPSK_19193_6RB#0_1000~3000_0_1000~3000




Date: 2.JUL.2024 22:27:04




Date: 2.JUL.2024 22:27:12

Band2_1.4MHz_QPSK_19193_6RB#0_3000~2000_00_3000~20000

Band2_1.4MHz_16QAM_19193_6RB#0_0.009~0.15_0.009~0.15




Date: 2.JUL.2024 22:27:27




Date: 2.JUL.2024 22:27:41

Band2_1.4MHz_16QAM_19193_6RB#0_0.15~30_0.15~30

Band2_1.4MHz_16QAM_19193_6RB#0_30~1000_30~1000




Date: 2.JUL.2024 22:27:54




Date: 2.JUL.2024 22:28:09

Band2_1.4MHz_16QAM_19193_6RB#0_1000~3000_1000~3000

Band2_1.4MHz_16QAM_19193_6RB#0_3000~20000_3000~20000




Date: 2.JUL.2024 23:00:34




Date: 2.JUL.2024 23:00:49

Band2_3MHz_QPSK_18615_1RB#0_0.009~0.15_0.009~0.15

Band2_3MHz_QPSK_18615_1RB#0_0.15~30_0.15~30




Date: 2.JUL.2024 23:01:02




Date: 2.JUL.2024 23:01:16

Band2_3MHz_QPSK_18615_1RB#0_30~1000_3
0~1000

Band2_3MHz_QPSK_18615_1RB#0_1000~3000_
1000~3000




Date: 2.JUL.2024 23:01:31




Date: 2.JUL.2024 23:01:40

Band2_3MHz_QPSK_18615_1RB#0_3000~2000
0_3000~20000

Band2_3MHz_16QAM_18615_1RB#0_0.009~0.15
_0.009~0.15




Date: 2.JUL.2024 23:01:55




Date: 2.JUL.2024 23:02:09

Band2_3MHz_16QAM_18615_1RB#0_0.15~30_0.15~30

Band2_3MHz_16QAM_18615_1RB#0_30~1000_3_0~1000




Date: 2.JUL.2024 23:02:23



Date: 2.JUL.2024 23:02:37


Band2_3MHz_16QAM_18615_1RB#0_1000~300_0_1000~3000

Band2_3MHz_16QAM_18615_1RB#0_3000~2000_0_3000~20000




Date: 2.JUL.2024 23:02:48

Band2_3MHz_QPSK_18615_1RB#14_0.009~0.15
5_0.009~0.15




Date: 2.JUL.2024 23:03:03

Band2_3MHz_QPSK_18615_1RB#14_0.15~30_0.
15~30




Date: 2.JUL.2024 23:03:17

Band2_3MHz_QPSK_18615_1RB#14_30~1000_
30~1000




Date: 2.JUL.2024 23:03:30

Band2_3MHz_QPSK_18615_1RB#14_1000~3000_
_1000~3000




Date: 2.JUL.2024 23:03:45




Date: 2.JUL.2024 23:03:55

Band2_3MHz_QPSK_18615_1RB#14_3000~20000_00_3000~20000

Band2_3MHz_16QAM_18615_1RB#14_0.009~0.15_5_0.009~0.15




Date: 2.JUL.2024 23:04:10




Date: 2.JUL.2024 23:04:24

Band2_3MHz_16QAM_18615_1RB#14_0.15~30_0.15~30

Band2_3MHz_16QAM_18615_1RB#14_30~1000_30~1000




Date: 2.JUL.2024 23:04:37




Date: 2.JUL.2024 23:04:52

Band2_3MHz_16QAM_18615_1RB#14_1000~30
 00_1000~3000

Band2_3MHz_16QAM_18615_1RB#14_3000~200
 00_3000~20000




Date: 2.JUL.2024 23:05:03



Date: 2.JUL.2024 23:05:18


Band2_3MHz_QPSK_18615_15RB#0_0.009~0.1
 5_0.009~0.15

Band2_3MHz_QPSK_18615_15RB#0_0.15~30_0.
 15~30




Date: 2.JUL.2024 23:05:33

Band2_3MHz_QPSK_18615_15RB#0_30~1000_30~1000




Date: 2.JUL.2024 23:05:46

Band2_3MHz_QPSK_18615_15RB#0_1000~3000_1000~3000




Date: 2.JUL.2024 23:06:01

Band2_3MHz_QPSK_18615_15RB#0_3000~20000_00_3000~20000




Date: 2.JUL.2024 23:06:11

Band2_3MHz_16QAM_18615_15RB#0_0.009~0.15_5_0.009~0.15




Date: 2.JUL.2024 23:06:26




Date: 2.JUL.2024 23:06:39

Band2_3MHz_16QAM_18615_15RB#0_0.15~30
 _0.15~30

Band2_3MHz_16QAM_18615_15RB#0_30~1000_
 30~1000




Date: 2.JUL.2024 23:06:53



Date: 2.JUL.2024 23:07:08


Band2_3MHz_16QAM_18615_15RB#0_1000~30
 00_1000~3000

Band2_3MHz_16QAM_18615_15RB#0_3000~200
 00_3000~20000




Date: 2.JUL.2024 23:07:20

Band2_3MHz_QPSK_18900_1RB#0_0.009~0.15
_0.009~0.15




Date: 2.JUL.2024 23:07:35

Band2_3MHz_QPSK_18900_1RB#0_0.15~30_0.1
5~30




Date: 2.JUL.2024 23:07:49

Band2_3MHz_QPSK_18900_1RB#0_30~1000_3
0~1000




Date: 2.JUL.2024 23:08:03

Band2_3MHz_QPSK_18900_1RB#0_1000~3000_3
1000~3000




Date: 2.JUL.2024 23:08:18




Date: 2.JUL.2024 23:08:27

Band2_3MHz_QPSK_18900_1RB#0_3000~2000
 0_3000~20000

Band2_3MHz_16QAM_18900_1RB#0_0.009~0.15
 _0.009~0.15




Date: 2.JUL.2024 23:08:42




Date: 2.JUL.2024 23:08:56

Band2_3MHz_16QAM_18900_1RB#0_0.15~30
 0.15~30

Band2_3MHz_16QAM_18900_1RB#0_30~1000_3
 0~1000




Date: 2.JUL.2024 23:09:10




Date: 2.JUL.2024 23:09:25

Band2_3MHz_16QAM_18900_1RB#0_1000~300
 0_1000~3000

Band2_3MHz_16QAM_18900_1RB#0_3000~2000
 0_3000~20000




Date: 2.JUL.2024 23:09:35




Date: 2.JUL.2024 23:09:50

Band2_3MHz_QPSK_18900_1RB#14_0.009~0.1
 5_0.009~0.15

Band2_3MHz_QPSK_18900_1RB#14_0.15~30_0.
 15~30




Date: 2.JUL.2024 23:10:04




Date: 2.JUL.2024 23:10:17

Band2_3MHz_QPSK_18900_1RB#14_30~1000_30~1000

Band2_3MHz_QPSK_18900_1RB#14_1000~3000_1000~3000




Date: 2.JUL.2024 23:10:32




Date: 2.JUL.2024 23:10:42

Band2_3MHz_QPSK_18900_1RB#14_3000~20000_00_3000~20000

Band2_3MHz_16QAM_18900_1RB#14_0.009~0.15_5_0.009~0.15




Date: 2.JUL.2024 23:10:57




Date: 2.JUL.2024 23:11:10

Band2_3MHz_16QAM_18900_1RB#14_0.15~30
 _0.15~30

Band2_3MHz_16QAM_18900_1RB#14_30~1000_
 30~1000




Date: 2.JUL.2024 23:11:24



Date: 2.JUL.2024 23:11:39


Band2_3MHz_16QAM_18900_1RB#14_1000~30
 00_1000~3000

Band2_3MHz_16QAM_18900_1RB#14_3000~200
 00_3000~20000




Date: 2.JUL.2024 23:11:50

Band2_3MHz_QPSK_18900_15RB#0_0.009~0.15
5_0.009~0.15




Date: 2.JUL.2024 23:12:05

Band2_3MHz_QPSK_18900_15RB#0_0.15~30_0.
15~30




Date: 2.JUL.2024 23:12:18

Band2_3MHz_QPSK_18900_15RB#0_30~1000_
30~1000




Date: 2.JUL.2024 23:12:32

Band2_3MHz_QPSK_18900_15RB#0_1000~3000
_1000~3000




Date: 2.JUL.2024 23:12:47




Date: 2.JUL.2024 23:12:56

Band2_3MHz_QPSK_18900_15RB#0_3000~20000_00_3000~20000

Band2_3MHz_16QAM_18900_15RB#0_0.009~0.15_5_0.009~0.15




Date: 2.JUL.2024 23:13:11




Date: 2.JUL.2024 23:13:25

Band2_3MHz_16QAM_18900_15RB#0_0.15~30_0.15~30

Band2_3MHz_16QAM_18900_15RB#0_30~1000_30~1000




Date: 2.JUL.2024 23:13:39




Date: 2.JUL.2024 23:13:54

Band2_3MHz_16QAM_18900_15RB#0_1000~30_00_1000~3000

Band2_3MHz_16QAM_18900_15RB#0_3000~200_00_3000~20000




Date: 2.JUL.2024 23:14:06




Date: 2.JUL.2024 23:14:21

Band2_3MHz_QPSK_19185_1RB#0_0.009~0.15_0.009~0.15

Band2_3MHz_QPSK_19185_1RB#0_0.15~30_0.15~30




Date: 2.JUL.2024 23:14:35




Date: 2.JUL.2024 23:14:48

Band2_3MHz_QPSK_19185_1RB#0_30~1000_3
0~1000

Band2_3MHz_QPSK_19185_1RB#0_1000~3000_
1000~3000




Date: 2.JUL.2024 23:15:03




Date: 2.JUL.2024 23:15:13

Band2_3MHz_QPSK_19185_1RB#0_3000~2000
0_3000~20000

Band2_3MHz_16QAM_19185_1RB#0_0.009~0.15
_0.009~0.15




Date: 2.JUL.2024 23:15:28




Date: 2.JUL.2024 23:15:41

Band2_3MHz_16QAM_19185_1RB#0_0.15~30_0.15~30

Band2_3MHz_16QAM_19185_1RB#0_30~1000_3_0~1000




Date: 2.JUL.2024 23:15:55




Date: 2.JUL.2024 23:16:10

Band2_3MHz_16QAM_19185_1RB#0_1000~3000_0_1000~3000

Band2_3MHz_16QAM_19185_1RB#0_3000~20000_0_3000~20000




Date: 2.JUL.2024 23:16:21




Date: 2.JUL.2024 23:16:36

Band2_3MHz_QPSK_19185_1RB#14_0.009~0.15
5_0.009~0.15

Band2_3MHz_QPSK_19185_1RB#14_0.15~30_0.
15~30




Date: 2.JUL.2024 23:16:50




Date: 2.JUL.2024 23:17:03

Band2_3MHz_QPSK_19185_1RB#14_30~1000_
30~1000

Band2_3MHz_QPSK_19185_1RB#14_1000~3000
_1000~3000




Date: 2.JUL.2024 23:17:18




Date: 2.JUL.2024 23:17:28

Band2_3MHz_QPSK_19185_1RB#14_3000~20000_00_3000~20000

Band2_3MHz_16QAM_19185_1RB#14_0.009~0.15_5_0.009~0.15




Date: 2.JUL.2024 23:17:43




Date: 2.JUL.2024 23:17:56

Band2_3MHz_16QAM_19185_1RB#14_0.15~30_0.15~30

Band2_3MHz_16QAM_19185_1RB#14_30~1000_30~1000




Date: 2.JUL.2024 23:18:10




Date: 2.JUL.2024 23:18:25

Band2_3MHz_16QAM_19185_1RB#14_1000~30
 00_1000~3000

Band2_3MHz_16QAM_19185_1RB#14_3000~200
 00_3000~20000




Date: 2.JUL.2024 23:18:36




Date: 2.JUL.2024 23:18:51

Band2_3MHz_QPSK_19185_15RB#0_0.009~0.1
 5_0.009~0.15

Band2_3MHz_QPSK_19185_15RB#0_0.15~30_0.
 15~30




Date: 2.JUL.2024 23:19:05




Date: 2.JUL.2024 23:19:18

Band2_3MHz_QPSK_19185_15RB#0_30~1000_30~1000

Band2_3MHz_QPSK_19185_15RB#0_1000~3000_1000~3000




Date: 2.JUL.2024 23:19:33




Date: 2.JUL.2024 23:19:43

Band2_3MHz_QPSK_19185_15RB#0_3000~20000_00_3000~20000

Band2_3MHz_16QAM_19185_15RB#0_0.009~0.15_5_0.009~0.15




Date: 2.JUL.2024 23:19:58




Date: 2.JUL.2024 23:20:12

Band2_3MHz_16QAM_19185_15RB#0_0.15~30
 _0.15~30

Band2_3MHz_16QAM_19185_15RB#0_30~1000_
 30~1000




Date: 2.JUL.2024 23:20:25



Date: 2.JUL.2024 23:20:40


Band2_3MHz_16QAM_19185_15RB#0_1000~3000
 00_1000~3000

Band2_3MHz_16QAM_19185_15RB#0_3000~20000
 00_3000~20000




Date: 2.JUL.2024 23:53:21

Band2_5MHz_QPSK_18625_1RB#0_0.009~0.15
_0.009~0.15




Date: 2.JUL.2024 23:53:36

Band2_5MHz_QPSK_18625_1RB#0_0.15~30_0.15~30_0.15




Date: 2.JUL.2024 23:53:50

Band2_5MHz_QPSK_18625_1RB#0_30~1000_30~1000




Date: 2.JUL.2024 23:54:03

Band2_5MHz_QPSK_18625_1RB#0_1000~3000_1000~3000




Date: 2.JUL.2024 23:54:18




Date: 2.JUL.2024 23:54:26

Band2_5MHz_QPSK_18625_1RB#0_3000~2000
 0_3000~20000

Band2_5MHz_16QAM_18625_1RB#0_0.009~0.15
 _0.009~0.15




Date: 2.JUL.2024 23:54:41




Date: 2.JUL.2024 23:54:55

Band2_5MHz_16QAM_18625_1RB#0_0.15~30
 0.15~30

Band2_5MHz_16QAM_18625_1RB#0_30~1000_3
 0~1000




Date: 2.JUL.2024 23:55:09




Date: 2.JUL.2024 23:55:24

Band2_5MHz_16QAM_18625_1RB#0_1000~300
0_1000~3000

Band2_5MHz_16QAM_18625_1RB#0_3000~2000
0_3000~20000




Date: 2.JUL.2024 23:55:35




Date: 2.JUL.2024 23:55:50

Band2_5MHz_QPSK_18625_1RB#24_0.009~0.1
5_0.009~0.15

Band2_5MHz_QPSK_18625_1RB#24_0.15~30_0.
15~30




Date: 2.JUL.2024 23:56:03




Date: 2.JUL.2024 23:56:17

Band2_5MHz_QPSK_18625_1RB#24_30~1000_30~1000

Band2_5MHz_QPSK_18625_1RB#24_1000~3000_1000~3000




Date: 2.JUL.2024 23:56:31




Date: 2.JUL.2024 23:56:40

Band2_5MHz_QPSK_18625_1RB#24_3000~20000_00_3000~20000

Band2_5MHz_16QAM_18625_1RB#24_0.009~0.15_5_0.009~0.15




Date: 2.JUL.2024 23:56:54




Date: 2.JUL.2024 23:57:08

Band2_5MHz_16QAM_18625_1RB#24_0.15~30_0.15~30

Band2_5MHz_16QAM_18625_1RB#24_30~1000_30~1000




Date: 2.JUL.2024 23:57:21



Date: 2.JUL.2024 23:57:36


Band2_5MHz_16QAM_18625_1RB#24_1000~3000_1000~3000

Band2_5MHz_16QAM_18625_1RB#24_3000~20000_3000~20000




Date: 2.JUL.2024 23:57:47

Band2_5MHz_QPSK_18625_25RB#0_0.009~0.15
5_0.009~0.15




Date: 2.JUL.2024 23:58:02

Band2_5MHz_QPSK_18625_25RB#0_0.15~30_0.
15~30




Date: 2.JUL.2024 23:58:15

Band2_5MHz_QPSK_18625_25RB#0_30~1000_
30~1000




Date: 2.JUL.2024 23:58:29

Band2_5MHz_QPSK_18625_25RB#0_1000~3000_
_1000~3000




Date: 2.JUL.2024 23:58:43




Date: 2.JUL.2024 23:58:52

Band2_5MHz_QPSK_18625_25RB#0_3000~20000_00_3000~20000

Band2_5MHz_16QAM_18625_25RB#0_0.009~0.15_5_0.009~0.15




Date: 2.JUL.2024 23:59:06




Date: 2.JUL.2024 23:59:20

Band2_5MHz_16QAM_18625_25RB#0_0.15~30_0.15~30

Band2_5MHz_16QAM_18625_25RB#0_30~1000_30~1000




Date: 2.JUL.2024 23:59:33




Date: 2.JUL.2024 23:59:48

Band2_5MHz_16QAM_18625_25RB#0_1000~30
 00_1000~3000

Band2_5MHz_16QAM_18625_25RB#0_3000~200
 00_3000~20000




Date: 3.JUL.2024 00:00:00




Date: 3.JUL.2024 00:00:15

Band2_5MHz_QPSK_18900_1RB#0_0.009~0.15
 _0.009~0.15

Band2_5MHz_QPSK_18900_1RB#0_0.15~30_0.1
 5~30




Date: 3.JUL.2024 00:00:28




Date: 3.JUL.2024 00:00:42

Band2_5MHz_QPSK_18900_1RB#0_30~1000_3
0~1000

Band2_5MHz_QPSK_18900_1RB#0_1000~3000_
1000~3000




Date: 3.JUL.2024 00:00:57




Date: 3.JUL.2024 00:01:05

Band2_5MHz_QPSK_18900_1RB#0_3000~2000
0_3000~20000

Band2_5MHz_16QAM_18900_1RB#0_0.009~0.15
_0.009~0.15




Date: 3.JUL.2024 00:01:20




Date: 3.JUL.2024 00:01:33

Band2_5MHz_16QAM_18900_1RB#0_0.15~30_0.15~30

Band2_5MHz_16QAM_18900_1RB#0_30~1000_3_0~1000




Date: 3.JUL.2024 00:01:47



Date: 3.JUL.2024 00:02:02


Band2_5MHz_16QAM_18900_1RB#0_1000~300_0_1000~3000

Band2_5MHz_16QAM_18900_1RB#0_3000~2000_0_3000~20000




Date: 3.JUL.2024 00:02:13

Band2_5MHz_QPSK_18900_1RB#24_0.009~0.15
5_0.009~0.15




Date: 3.JUL.2024 00:02:28

Band2_5MHz_QPSK_18900_1RB#24_0.15~30_0.
15~30




Date: 3.JUL.2024 00:02:41

Band2_5MHz_QPSK_18900_1RB#24_30~1000_
30~1000




Date: 3.JUL.2024 00:02:55

Band2_5MHz_QPSK_18900_1RB#24_1000~3000
_1000~3000




Date: 3.JUL.2024 00:03:10




Date: 3.JUL.2024 00:03:18

Band2_5MHz_QPSK_18900_1RB#24_3000~20000_00_3000~20000

Band2_5MHz_16QAM_18900_1RB#24_0.009~0.15_5_0.009~0.15




Date: 3.JUL.2024 00:03:33




Date: 3.JUL.2024 00:03:47

Band2_5MHz_16QAM_18900_1RB#24_0.15~30_0.15~30

Band2_5MHz_16QAM_18900_1RB#24_30~1000_30~1000




Date: 3.JUL.2024 00:04:01




Date: 3.JUL.2024 00:04:16

Band2_5MHz_16QAM_18900_1RB#24_1000~30
 00_1000~3000

Band2_5MHz_16QAM_18900_1RB#24_3000~200
 00_3000~20000




Date: 3.JUL.2024 00:04:26




Date: 3.JUL.2024 00:04:41

Band2_5MHz_QPSK_18900_25RB#0_0.009~0.1
 5_0.009~0.15

Band2_5MHz_QPSK_18900_25RB#0_0.15~30_0.
 15~30




Date: 3.JUL.2024 00:04:55




Date: 3.JUL.2024 00:05:09

Band2_5MHz_QPSK_18900_25RB#0_30~1000_30~1000

Band2_5MHz_QPSK_18900_25RB#0_1000~3000_1000~3000




Date: 3.JUL.2024 00:05:24




Date: 3.JUL.2024 00:05:32

Band2_5MHz_QPSK_18900_25RB#0_3000~20000_00_3000~20000

Band2_5MHz_16QAM_18900_25RB#0_0.009~0.15_5_0.009~0.15




Date: 3.JUL.2024 00:05:47




Date: 3.JUL.2024 00:06:00

Band2_5MHz_16QAM_18900_25RB#0_0.15~30
 _0.15~30

Band2_5MHz_16QAM_18900_25RB#0_30~1000_
 30~1000




Date: 3.JUL.2024 00:06:14



Date: 3.JUL.2024 00:06:29


Band2_5MHz_16QAM_18900_25RB#0_1000~30
 00_1000~3000

Band2_5MHz_16QAM_18900_25RB#0_3000~200
 00_3000~20000




Date: 3.JUL.2024 00:06:42

Band2_5MHz_QPSK_19175_1RB#0_0.009~0.15
_0.009~0.15




Date: 3.JUL.2024 00:06:57

Band2_5MHz_QPSK_19175_1RB#0_0.15~30_0.1
5~30




Date: 3.JUL.2024 00:07:11

Band2_5MHz_QPSK_19175_1RB#0_30~1000_3
0~1000




Date: 3.JUL.2024 00:07:24

Band2_5MHz_QPSK_19175_1RB#0_1000~3000_
1000~3000




Date: 3.JUL.2024 00:07:40




Date: 3.JUL.2024 00:07:48

Band2_5MHz_QPSK_19175_1RB#0_3000~2000
 0_3000~20000

Band2_5MHz_16QAM_19175_1RB#0_0.009~0.15
 _0.009~0.15




Date: 3.JUL.2024 00:08:03




Date: 3.JUL.2024 00:08:17

Band2_5MHz_16QAM_19175_1RB#0_0.15~30
 0.15~30

Band2_5MHz_16QAM_19175_1RB#0_30~1000_3
 0~1000




Date: 3.JUL.2024 00:08:30




Date: 3.JUL.2024 00:08:45

Band2_5MHz_16QAM_19175_1RB#0_1000~300
0_1000~3000

Band2_5MHz_16QAM_19175_1RB#0_3000~2000
0_3000~20000




Date: 3.JUL.2024 00:08:56



Date: 3.JUL.2024 00:09:11


Band2_5MHz_QPSK_19175_1RB#24_0.009~0.1
5_0.009~0.15

Band2_5MHz_QPSK_19175_1RB#24_0.15~30_0.
15~30




Date: 3.JUL.2024 00:09:25

Band2_5MHz_QPSK_19175_1RB#24_30~1000_30~1000




Date: 3.JUL.2024 00:09:38

Band2_5MHz_QPSK_19175_1RB#24_1000~3000_1000~3000




Date: 3.JUL.2024 00:09:53

Band2_5MHz_QPSK_19175_1RB#24_3000~2000_00_3000~20000




Date: 3.JUL.2024 00:10:02

Band2_5MHz_16QAM_19175_1RB#24_0.009~0.1_5_0.009~0.15




Date: 3.JUL.2024 00:10:17




Date: 3.JUL.2024 00:10:30

Band2_5MHz_16QAM_19175_1RB#24_0.15~30_0.15~30

Band2_5MHz_16QAM_19175_1RB#24_30~1000_30~1000




Date: 3.JUL.2024 00:10:44



Date: 3.JUL.2024 00:10:59


Band2_5MHz_16QAM_19175_1RB#24_1000~30_00_1000~3000

Band2_5MHz_16QAM_19175_1RB#24_3000~2000_00_3000~20000




Date: 3.JUL.2024 00:11:09

Band2_5MHz_QPSK_19175_25RB#0_0.009~0.15
5_0.009~0.15




Date: 3.JUL.2024 00:11:25

Band2_5MHz_QPSK_19175_25RB#0_0.15~30_0.
15~30




Date: 3.JUL.2024 00:11:38

Band2_5MHz_QPSK_19175_25RB#0_30~1000_
30~1000




Date: 3.JUL.2024 00:11:52

Band2_5MHz_QPSK_19175_25RB#0_1000~3000
_1000~3000




Date: 3.JUL.2024 00:12:07




Date: 3.JUL.2024 00:12:15

Band2_5MHz_QPSK_19175_25RB#0_3000~20000_00_3000~20000

Band2_5MHz_16QAM_19175_25RB#0_0.009~0.15_5_0.009~0.15




Date: 3.JUL.2024 00:12:30




Date: 3.JUL.2024 00:12:43

Band2_5MHz_16QAM_19175_25RB#0_0.15~30_0.15~30

Band2_5MHz_16QAM_19175_25RB#0_30~1000_30~1000




Date: 3.JUL.2024 00:12:57




Date: 3.JUL.2024 00:13:12

Band2_5MHz_16QAM_19175_25RB#0_1000~30
 00_1000~3000

Band2_5MHz_16QAM_19175_25RB#0_3000~200
 00_3000~20000




Date: 3.JUL.2024 00:44:39



Date: 3.JUL.2024 00:44:54


Band2_10MHz_QPSK_18650_1RB#0_0.009~0.1
 5_0.009~0.15

Band2_10MHz_QPSK_18650_1RB#0_0.15~30_0.
 15~30




Date: 3.JUL.2024 00:45:07

Band2_10MHz_QPSK_18650_1RB#0_30~1000_30~1000




Date: 3.JUL.2024 00:45:21

Band2_10MHz_QPSK_18650_1RB#0_1000~3000_1000~3000




Date: 3.JUL.2024 00:45:36

Band2_10MHz_QPSK_18650_1RB#0_3000~20000_00_3000~20000




Date: 3.JUL.2024 00:45:44

Band2_10MHz_16QAM_18650_1RB#0_0.009~0.15_5_0.009~0.15




Date: 3.JUL.2024 00:45:59




Date: 3.JUL.2024 00:46:12

Band2_10MHz_16QAM_18650_1RB#0_0.15~30
 _0.15~30

Band2_10MHz_16QAM_18650_1RB#0_30~1000_
 30~1000




Date: 3.JUL.2024 00:46:25



Date: 3.JUL.2024 00:46:40


Band2_10MHz_16QAM_18650_1RB#0_1000~30
 00_1000~3000

Band2_10MHz_16QAM_18650_1RB#0_3000~200
 00_3000~20000




Date: 3.JUL.2024 00:46:51

Band2_10MHz_QPSK_18650_1RB#49_0.009~0.15_0.009~0.15




Date: 3.JUL.2024 00:47:06

Band2_10MHz_QPSK_18650_1RB#49_0.15~30_0.15~30




Date: 3.JUL.2024 00:47:19

Band2_10MHz_QPSK_18650_1RB#49_30~1000_30~1000




Date: 3.JUL.2024 00:47:33

Band2_10MHz_QPSK_18650_1RB#49_1000~3000_0_1000~3000




Date: 3.JUL.2024 00:47:47




Date: 3.JUL.2024 00:47:55

Band2_10MHz_QPSK_18650_1RB#49_3000~20000_3000~20000

Band2_10MHz_16QAM_18650_1RB#49_0.009~0.15_0.009~0.15




Date: 3.JUL.2024 00:48:10




Date: 3.JUL.2024 00:48:24

Band2_10MHz_16QAM_18650_1RB#49_0.15~30_0.15~30

Band2_10MHz_16QAM_18650_1RB#49_30~1000_30~1000




Date: 3.JUL.2024 00:48:37




Date: 3.JUL.2024 00:48:52

Band2_10MHz_16QAM_18650_1RB#49_1000~3000_1000~3000

Band2_10MHz_16QAM_18650_1RB#49_3000~20000_3000~20000




Date: 3.JUL.2024 00:49:03




Date: 3.JUL.2024 00:49:18

Band2_10MHz_QPSK_18650_50RB#0_0.009~0.15_0.009~0.15

Band2_10MHz_QPSK_18650_50RB#0_0.15~30_0.15~30




Date: 3.JUL.2024 00:49:31




Date: 3.JUL.2024 00:49:44

Band2_10MHz_QPSK_18650_50RB#0_30~1000
_30~1000

Band2_10MHz_QPSK_18650_50RB#0_1000~300
0_1000~3000




Date: 3.JUL.2024 00:49:59




Date: 3.JUL.2024 00:50:07

Band2_10MHz_QPSK_18650_50RB#0_3000~20
000_3000~20000

Band2_10MHz_16QAM_18650_50RB#0_0.009~0.
15_0.009~0.15




Date: 3.JUL.2024 00:50:22




Date: 3.JUL.2024 00:50:36

Band2_10MHz_16QAM_18650_50RB#0_0.15~3
 0_0.15~30

Band2_10MHz_16QAM_18650_50RB#0_30~1000
 _30~1000




Date: 3.JUL.2024 00:50:49




Date: 3.JUL.2024 00:51:04

Band2_10MHz_16QAM_18650_50RB#0_1000~3
 000_1000~3000

Band2_10MHz_16QAM_18650_50RB#0_3000~20
 000_3000~20000




Date: 3.JUL.2024 00:51:16




Date: 3.JUL.2024 00:51:31

Band2_10MHz_QPSK_18900_1RB#0_0.009~0.15
5_0.009~0.15

Band2_10MHz_QPSK_18900_1RB#0_0.15~30_0.
15~30




Date: 3.JUL.2024 00:51:44




Date: 3.JUL.2024 00:51:58

Band2_10MHz_QPSK_18900_1RB#0_30~1000_
30~1000

Band2_10MHz_QPSK_18900_1RB#0_1000~3000_
_1000~3000




Date: 3.JUL.2024 00:52:12




Date: 3.JUL.2024 00:52:20

Band2_10MHz_QPSK_18900_1RB#0_3000~20000_00_3000~20000

Band2_10MHz_16QAM_18900_1RB#0_0.009~0.15_5_0.009~0.15




Date: 3.JUL.2024 00:52:35




Date: 3.JUL.2024 00:52:49

Band2_10MHz_16QAM_18900_1RB#0_0.15~30_0.15~30

Band2_10MHz_16QAM_18900_1RB#0_30~1000_30~1000




Date: 3.JUL.2024 00:53:02




Date: 3.JUL.2024 00:53:17

Band2_10MHz_16QAM_18900_1RB#0_1000~30_00_1000~3000

Band2_10MHz_16QAM_18900_1RB#0_3000~200_00_3000~20000




Date: 3.JUL.2024 00:53:28




Date: 3.JUL.2024 00:53:42

Band2_10MHz_QPSK_18900_1RB#49_0.009~0.15_0.009~0.15

Band2_10MHz_QPSK_18900_1RB#49_0.15~30_0.15~30




Date: 3.JUL.2024 00:53:56




Date: 3.JUL.2024 00:54:09

Band2_10MHz_QPSK_18900_1RB#49_30~1000_30~1000

Band2_10MHz_QPSK_18900_1RB#49_1000~300_0_1000~3000




Date: 3.JUL.2024 00:54:24




Date: 3.JUL.2024 00:54:32

Band2_10MHz_QPSK_18900_1RB#49_3000~20000_000_3000~20000

Band2_10MHz_16QAM_18900_1RB#49_0.009~0.15_0.009~0.15




Date: 3.JUL.2024 00:54:47




Date: 3.JUL.2024 00:55:00

Band2_10MHz_16QAM_18900_1RB#49_0.15~3
 0_0.15~30

Band2_10MHz_16QAM_18900_1RB#49_30~1000
 _30~1000




Date: 3.JUL.2024 00:55:14




Date: 3.JUL.2024 00:55:28

Band2_10MHz_16QAM_18900_1RB#49_1000~3
 000_1000~3000

Band2_10MHz_16QAM_18900_1RB#49_3000~20
 000_3000~20000




Date: 3.JUL.2024 00:55:39




Date: 3.JUL.2024 00:55:54

Band2_10MHz_QPSK_18900_50RB#0_0.009~0.15_0.009~0.15

Band2_10MHz_QPSK_18900_50RB#0_0.15~30_0.15~30




Date: 3.JUL.2024 00:56:08




Date: 3.JUL.2024 00:56:21

Band2_10MHz_QPSK_18900_50RB#0_30~1000_30~1000

Band2_10MHz_QPSK_18900_50RB#0_1000~3000_0_1000~3000




Date: 3.JUL.2024 00:56:36




Date: 3.JUL.2024 00:56:44

Band2_10MHz_QPSK_18900_50RB#0_3000~20000_3000~20000

Band2_10MHz_16QAM_18900_50RB#0_0.009~0.15_0.009~0.15




Date: 3.JUL.2024 00:57:00




Date: 3.JUL.2024 00:57:15

Band2_10MHz_16QAM_18900_50RB#0_0.15~30_0.15~30

Band2_10MHz_16QAM_18900_50RB#0_30~1000_30~1000




Date: 3.JUL.2024 00:57:28




Date: 3.JUL.2024 00:57:43

Band2_10MHz_16QAM_18900_50RB#0_1000~3000_1000~3000

Band2_10MHz_16QAM_18900_50RB#0_3000~20000_000_3000~20000




Date: 3.JUL.2024 00:57:55




Date: 3.JUL.2024 00:58:10

Band2_10MHz_QPSK_19150_1RB#0_0.009~0.15_5_0.009~0.15

Band2_10MHz_QPSK_19150_1RB#0_0.15~30_0.15~30




Date: 3.JUL.2024 00:58:24




Date: 3.JUL.2024 00:58:37

Band2_10MHz_QPSK_19150_1RB#0_30~1000_30~1000

Band2_10MHz_QPSK_19150_1RB#0_1000~3000_1000~3000




Date: 3.JUL.2024 00:58:52



Date: 3.JUL.2024 00:59:00


Band2_10MHz_QPSK_19150_1RB#0_3000~20000_3000~20000

Band2_10MHz_16QAM_19150_1RB#0_0.009~0.15_5_0.009~0.15




Date: 3.JUL.2024 00:59:15

Band2_10MHz_16QAM_19150_1RB#0_0.15~30




Date: 3.JUL.2024 00:59:28

Band2_10MHz_16QAM_19150_1RB#0_30~1000_30~1000




Date: 3.JUL.2024 00:59:41

Band2_10MHz_16QAM_19150_1RB#0_1000~3000_00_1000~3000




Date: 3.JUL.2024 00:59:56

Band2_10MHz_16QAM_19150_1RB#0_3000~20000_00_3000~20000




Date: 3.JUL.2024 01:00:07

Band2_10MHz_QPSK_19150_1RB#49_0.009~0.15_0.009~0.15




Date: 3.JUL.2024 01:00:22

Band2_10MHz_QPSK_19150_1RB#49_0.15~30_0.15~30




Date: 3.JUL.2024 01:00:35

Band2_10MHz_QPSK_19150_1RB#49_30~1000_30~1000




Date: 3.JUL.2024 01:00:49

Band2_10MHz_QPSK_19150_1RB#49_1000~3000_0_1000~3000




Date: 3.JUL.2024 01:01:03




Date: 3.JUL.2024 01:01:11

Band2_10MHz_QPSK_19150_1RB#49_3000~20000_3000~20000

Band2_10MHz_16QAM_19150_1RB#49_0.009~0.15_0.009~0.15



Date: 3.JUL.2024 01:01:26



Date: 3.JUL.2024 01:01:40

Band2_10MHz_16QAM_19150_1RB#49_0.15~30_0.15~30

Band2_10MHz_16QAM_19150_1RB#49_30~1000_30~1000