

Tonal Systems Inc

617 Bryant St, San Francisco, California, United States 94107

January 26, 2022

CKC Certification Services, LLC

CB: US0103; NB: 0976

5046 Sierra Pines Drive

Mariposa, CA 95338

Ref: FCC ID 2AXL7-1102 BCM

To Whom It May Concern:

In consideration of the FCC Type Approval application for the referenced FCC IDs above, and following the guidelines of FCC Document 784748 D01 General Labeling and Notification v09r01, which describes that "*Physical FCC ID labels must be located on the surface of the product, or within a user-accessible non-detachable compartment (such as the battery compartment). The label shall be permanently affixed, permitting the device to be positively identified.*"

We would like to justify the placement of the FCC label inside the battery compartment due to the following circumstances: Because the Trainer product is an exercise equipment and due to the continuous handling of the BCM by the end user, over time and with the effect of perspiration, the FCC label may become unreadable, smudged or dislodged, and placement in the battery compartment avoids defacing and degradation.

Additionally, we would like to confirm that the batteries provided with this product are not installed at manufacturing nor at any step of the distribution chain, and only the customer is responsible for installing them into the product.

Sincerely,



Thomas Watt

VP Hardware

Tonal Systems Inc.

thomas@tonal.com

Tel: 415-335-1064