



Band2_10MHz_16QAM_19150_1RB#49_1000~3000_1000~3000




Band2_10MHz_16QAM_19150_1RB#49_3000~20000_3000~20000




Band2_10MHz_QPSK_19150_50RB#0_0.009~0.15_0.009~0.15



Band2_10MHz_QPSK_19150_50RB#0_0.15~30_0.15~30




Band2_10MHz_QPSK_19150_50RB#0_30~1000_30~1000




Band2_10MHz_QPSK_19150_50RB#0_1000~3000_1000~3000


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band2_10MHz_QPSK_19150_50RB#0_3000~20000_3000~20000




Band2_10MHz_16QAM_19150_50RB#0_0.009~0.15_0.009~0.15




Band2_10MHz_16QAM_19150_50RB#0_0.15~30_0.15~30



Band2_10MHz_16QAM_19150_50RB#0_30~1000_30~1000




Band2_10MHz_16QAM_19150_50RB#0_1000~3000_1000~3000




Band2_10MHz_16QAM_19150_50RB#0_3000~20000_3000~20000


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band2_15MHz_QPSK_18675_1RB#0_0.009~0.15_0.009~0.15




Band2_15MHz_QPSK_18675_1RB#0_0.15~30_0.15~30



Band2_15MHz_QPSK_18675_1RB#0_30~1000_30~1000



Band2_15MHz_QPSK_18675_1RB#0_1000~3000_1000~3000




Band2_15MHz_QPSK_18675_1RB#0_3000~20000_3000~20000




Band2_15MHz_16QAM_18675_1RB#0_0.009~0.15_0.009~0.15


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band2_15MHz_16QAM_18675_1RB#0_0.15~30_0.15~30




Band2_15MHz_16QAM_18675_1RB#0_30~1000_30~1000



Band2_15MHz_16QAM_18675_1RB#0_1000~3000_1000~3000



Band2_15MHz_16QAM_18675_1RB#0_3000~20000_3000~20000




Band2_15MHz_QPSK_18675_1RB#74_0.009~0.15_0.009~0.15




Band2_15MHz_QPSK_18675_1RB#74_0.15~30_0.15~30


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band2_15MHz_QPSK_18675_1RB#74_30~1000_30~1000




Band2_15MHz_QPSK_18675_1RB#74_1000~3000_1000~3000



Band2_15MHz_QPSK_18675_1RB#74_3000~20000_3000~20000



Band2_15MHz_16QAM_18675_1RB#74_0.009~0.15_0.009~0.15



Band2_15MHz_16QAM_18675_1RB#74_0.15~30_0.15~30




Band2_15MHz_16QAM_18675_1RB#74_30~1000_30~1000


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band2_15MHz_16QAM_18675_1RB#74_1000-3000_1000-3000



Band2_15MHz_16QAM_18675_1RB#74_3000-20000_3000-20000



Band2_15MHz_QPSK_18675_75RB#0_0.009-0.15_0.009-0.15



Band2_15MHz_QPSK_18675_75RB#0_0.15-30_0.15-30




Band2_15MHz_QPSK_18675_75RB#0_30-1000_30-1000




Band2_15MHz_QPSK_18675_75RB#0_1000-3000_1000-3000


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band2_15MHz_QPSK_18675_75RB#0_3000~20000_3000~20000




Band2_15MHz_16QAM_18675_75RB#0_0.009~0.15_0.009~0.15




Band2_15MHz_16QAM_18675_75RB#0_0.15~30_0.15~30



Band2_15MHz_16QAM_18675_75RB#0_30~1000_30~1000




Band2_15MHz_16QAM_18675_75RB#0_1000~3000_1000~3000




Band2_15MHz_16QAM_18675_75RB#0_3000~20000_3000~20000

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band2_15MHz_QPSK_18900_1RB#0_0.009~0.15_0.009~0.15



Band2_15MHz_QPSK_18900_1RB#0_0.15~30_0.15~30




Band2_15MHz_QPSK_18900_1RB#0_30~1000_30~1000



Band2_15MHz_QPSK_18900_1RB#0_1000~3000_1000~3000




Band2_15MHz_QPSK_18900_1RB#0_3000~20000_3000~20000




Band2_15MHz_16QAM_18900_1RB#0_0.009~0.15_0.009~0.15

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.


Attestation of Global Compliance(Shenzhen)Co., Ltd
Attestation of Global Compliance(Shenzhen)Std & Tech Co., Ltd
Tel: +86-755 2523 4088 E-mail: agc@agccert.com Web: http://www.agccert.com/




Band2_15MHz_16QAM_18900_1RB#0_0.15~30_0.15~30




Band2_15MHz_16QAM_18900_1RB#0_30~1000_30~1000




Band2_15MHz_16QAM_18900_1RB#0_1000~3000_1000~3000



Band2_15MHz_16QAM_18900_1RB#0_3000~20000_3000~20000




Band2_15MHz_QPSK_18900_1RB#74_0.009~0.15_0.009~0.15




Band2_15MHz_QPSK_18900_1RB#74_0.15~30_0.15~30


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.



Band2_15MHz_QPSK_18900_1RB#74_30~1000_30~1000




Band2_15MHz_QPSK_18900_1RB#74_1000~3000_1000~3000




Band2_15MHz_QPSK_18900_1RB#74_3000~20000_3000~20000



Band2_15MHz_16QAM_18900_1RB#74_0.009~0.15_0.009~0.15




Band2_15MHz_16QAM_18900_1RB#74_0.15~30_0.15~30




Band2_15MHz_16QAM_18900_1RB#74_30~1000_30~1000


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band2_15MHz_16QAM_18900_1RB#74_1000-3000_1000-3000




Band2_15MHz_16QAM_18900_1RB#74_3000-20000_3000-20000




Band2_15MHz_QPSK_18900_75RB#0_0.009-0.15_0.009-0.15



Band2_15MHz_QPSK_18900_75RB#0_0.15-30_0.15-30




Band2_15MHz_QPSK_18900_75RB#0_30-1000_30-1000




Band2_15MHz_QPSK_18900_75RB#0_1000-3000_1000-3000


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band2_15MHz_QPSK_18900_75RB#0_3000~20000_3000~20000




Band2_15MHz_16QAM_18900_75RB#0_0.009~0.15_0.009~0.15




Band2_15MHz_16QAM_18900_75RB#0_0.15~30_0.15~30



Band2_15MHz_16QAM_18900_75RB#0_30~1000_30~1000




Band2_15MHz_16QAM_18900_75RB#0_1000~3000_1000~3000




Band2_15MHz_16QAM_18900_75RB#0_3000~20000_3000~20000


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band2_15MHz_QPSK_19125_1RB#0_0.009~0.15_0.009~0.15




Band2_15MHz_QPSK_19125_1RB#0_0.15~30_0.15~30



Band2_15MHz_QPSK_19125_1RB#0_30~1000_30~1000



Band2_15MHz_QPSK_19125_1RB#0_1000~3000_1000~3000




Band2_15MHz_QPSK_19125_1RB#0_3000~20000_3000~20000




Band2_15MHz_16QAM_19125_1RB#0_0.009~0.15_0.009~0.15


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band2_15MHz_16QAM_19125_1RB#0_0.15~30_0.15~30




Band2_15MHz_16QAM_19125_1RB#0_30~1000_30~1000




Band2_15MHz_16QAM_19125_1RB#0_1000~3000_1000~3000



Band2_15MHz_16QAM_19125_1RB#0_3000~20000_3000~20000




Band2_15MHz_QPSK_19125_1RB#74_0.009~0.15_0.009~0.15




Band2_15MHz_QPSK_19125_1RB#74_0.15~30_0.15~30


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band2_15MHz_QPSK_19125_1RB#74_30~1000_30~1000




Band2_15MHz_QPSK_19125_1RB#74_1000~3000_1000~3000




Band2_15MHz_QPSK_19125_1RB#74_3000~20000_3000~20000



Band2_15MHz_16QAM_19125_1RB#74_0.009~0.15_0.009~0.15



Band2_15MHz_16QAM_19125_1RB#74_0.15~30_0.15~30



Band2_15MHz_16QAM_19125_1RB#74_30~1000_30~1000

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.