



Band41_10MHz_QPSK_41190_1RB#0_30~1000_30~1000




Band41_10MHz_QPSK_41190_1RB#0_1000~20000_1000~20000




Band41_10MHz_QPSK_41190_1RB#0_20000~27000_20000~27000



Band41_10MHz_16QAM_41190_1RB#0_0.009~0.15_0.009~0.15




Band41_10MHz_16QAM_41190_1RB#0_0.15~30_0.15~30



Band41_10MHz_16QAM_41190_1RB#0_30~1000_30~1000


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band41_10MHz_16QAM_41190_1RB#0_1000~20000_1000~20000




Band41_10MHz_16QAM_41190_1RB#0_20000~27000_20000~27000




Band41_10MHz_QPSK_41190_1RB#49_0.009~0.15_0.009~0.15



Band41_10MHz_QPSK_41190_1RB#49_0.15~30_0.15~30



Band41_10MHz_QPSK_41190_1RB#49_30~1000_30~1000




Band41_10MHz_QPSK_41190_1RB#49_1000~20000_1000~20000


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band41_10MHz_QPSK_41190_1RB#49_20000~27000_20000~27000




Band41_10MHz_16QAM_41190_1RB#49_0.009~0.15_0.009~0.15




Band41_10MHz_16QAM_41190_1RB#49_0.15~30_0.15~30



Band41_10MHz_16QAM_41190_1RB#49_30~1000_30~1000




Band41_10MHz_16QAM_41190_1RB#49_1000~20000_1000~20000




Band41_10MHz_16QAM_41190_1RB#49_20000~27000_20000~27000


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band41_10MHz_QPSK_41190_50RB#0_0.009~0.15_0.009~0.15




Band41_10MHz_QPSK_41190_50RB#0_0.15~30_0.15~30




Band41_10MHz_QPSK_41190_50RB#0_30~1000_30~1000



Band41_10MHz_QPSK_41190_50RB#0_1000~20000_1000~20000




Band41_10MHz_QPSK_41190_50RB#0_20000~27000_20000~27000




Band41_10MHz_16QAM_41190_50RB#0_0.009~0.15_0.009~0.15


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band41_10MHz_16QAM_41190_50RB#0_0.15~30_0.15~30




Band41_10MHz_16QAM_41190_50RB#0_30~1000_30~1000




Band41_10MHz_16QAM_41190_50RB#0_1000~20000_1000~20000



Band41_10MHz_16QAM_41190_50RB#0_20000~27000_20000~27000




Band41_15MHz_QPSK_40115_1RB#0_0.009~0.15_0.009~0.15




Band41_15MHz_QPSK_40115_1RB#0_0.15~30_0.15~30


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.



Band41_15MHz_QPSK_40115_1RB#0_30~1000_30~1000




Band41_15MHz_QPSK_40115_1RB#0_1000~20000_1000~20000




Band41_15MHz_QPSK_40115_1RB#0_20000~27000_20000~27000



Band41_15MHz_16QAM_40115_1RB#0_0.009~0.15_0.009~0.15




Band41_15MHz_16QAM_40115_1RB#0_0.15~30_0.15~30



Band41_15MHz_16QAM_40115_1RB#0_30~1000_30~1000


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band41_15MHz_16QAM_40115_1RB#0_1000~20000_1000~20000




Band41_15MHz_16QAM_40115_1RB#0_20000~27000_20000~27000




Band41_15MHz_QPSK_40115_1RB#74_0.009~0.15_0.009~0.15



Band41_15MHz_QPSK_40115_1RB#74_0.15~30_0.15~30



Band41_15MHz_QPSK_40115_1RB#74_30~1000_30~1000




Band41_15MHz_QPSK_40115_1RB#74_1000~20000_1000~20000


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band41_15MHz_QPSK_40115_1RB#74_20000~27000_20000~27000




Band41_15MHz_16QAM_40115_1RB#74_0.009~0.15_0.009~0.15




Band41_15MHz_16QAM_40115_1RB#74_0.15~30_0.15~30



Band41_15MHz_16QAM_40115_1RB#74_30~1000_30~1000




Band41_15MHz_16QAM_40115_1RB#74_1000~20000_1000~20000




Band41_15MHz_16QAM_40115_1RB#74_20000~27000_20000~27000


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.



Band41_15MHz_QPSK_40115_75RB#0_0.009~0.15_0.009~0.15



Band41_15MHz_QPSK_40115_75RB#0_0.15~30_0.15~30



Band41_15MHz_QPSK_40115_75RB#0_30~1000_30~1000



Band41_15MHz_QPSK_40115_75RB#0_1000~20000_1000~20000




Band41_15MHz_QPSK_40115_75RB#0_20000~27000_20000~27000




Band41_15MHz_16QAM_40115_75RB#0_0.009~0.15_0.009~0.15


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band41_15MHz_16QAM_40115_75RB#0_0.15-30_0.15-30




Band41_15MHz_16QAM_40115_75RB#0_30-1000_30-1000




Band41_15MHz_16QAM_40115_75RB#0_1000-20000_1000-20000



Band41_15MHz_16QAM_40115_75RB#0_20000-27000_20000-27000




Band41_15MHz_QPSK_40590_1RB#0_0.009-0.15_0.009-0.15




Band41_15MHz_QPSK_40590_1RB#0_0.15-30_0.15-30

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band41_15MHz_QPSK_40590_1RB#0_30~1000_30~1000




Band41_15MHz_QPSK_40590_1RB#0_1000~20000_1000~20000




Band41_15MHz_QPSK_40590_1RB#0_20000~27000_20000~27000



Band41_15MHz_16QAM_40590_1RB#0_0.009~0.15_0.009~0.15




Band41_15MHz_16QAM_40590_1RB#0_0.15~30_0.15~30



Band41_15MHz_16QAM_40590_1RB#0_30~1000_30~1000


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band41_15MHz_16QAM_40590_1RB#0_1000~20000_1000~20000




Band41_15MHz_16QAM_40590_1RB#0_20000~27000_20000~27000




Band41_15MHz_QPSK_40590_1RB#74_0.009~0.15_0.009~0.15



Band41_15MHz_QPSK_40590_1RB#74_0.15~30_0.15~30




Band41_15MHz_QPSK_40590_1RB#74_30~1000_30~1000




Band41_15MHz_QPSK_40590_1RB#74_1000~20000_1000~20000


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band41_15MHz_QPSK_40590_1RB#74_2000~27000_20000~27000




Band41_15MHz_16QAM_40590_1RB#74_0.009~0.15_0.009~0.15




Band41_15MHz_16QAM_40590_1RB#74_0.15~30_0.15~30



Band41_15MHz_16QAM_40590_1RB#74_30~1000_30~1000




Band41_15MHz_16QAM_40590_1RB#74_1000~20000_1000~20000




Band41_15MHz_16QAM_40590_1RB#74_20000~27000_20000~27000


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band41_15MHz_QPSK_40590_75RB#0_0.009~0.15_0.009~0.15



Band41_15MHz_QPSK_40590_75RB#0_0.15~30_0.15~30




Band41_15MHz_QPSK_40590_75RB#0_30~1000_30~1000



Band41_15MHz_QPSK_40590_75RB#0_1000~20000_1000~20000




Band41_15MHz_QPSK_40590_75RB#0_20000~27000_20000~27000




Band41_15MHz_16QAM_40590_75RB#0_0.009~0.15_0.009~0.15


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.



Band41_15MHz_16QAM_40590_75RB#0_0.15~30_0.15~30



Band41_15MHz_16QAM_40590_75RB#0_30~1000_30~1000




Band41_15MHz_16QAM_40590_75RB#0_1000~20000_1000~20000



Band41_15MHz_16QAM_40590_75RB#0_20000~27000_20000~27000



Band41_15MHz_QPSK_41165_1RB#0_0.009~0.15_0.009~0.15



Band41_15MHz_QPSK_41165_1RB#0_0.15~30_0.15~30

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.