




Band66_3MHz_QPSK_132657_15RB#0_3000~20000_3000~20000



Band66_3MHz_16QAM_132657_15RB#0_0.009~0.15_0.009~0.15




Band66_3MHz_16QAM_132657_15RB#0_0.15~30_0.15~30



Band66_3MHz_16QAM_132657_15RB#0_30~1000_30~1000




Band66_3MHz_16QAM_132657_15RB#0_1000~3000_1000~3000




Band66_3MHz_16QAM_132657_15RB#0_3000~20000_3000~20000


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band66_5MHz_QPSK_131997_1RB#0_0.009-0.15_0.009-0.15




Band66_5MHz_QPSK_131997_1RB#0_0.15-30_0.15-30



Band66_5MHz_QPSK_131997_1RB#0_30-1000_30-1000



Band66_5MHz_QPSK_131997_1RB#0_1000-3000_1000-3000




Band66_5MHz_QPSK_131997_1RB#0_3000-20000_3000-20000




Band66_5MHz_16QAM_131997_1RB#0_0.009-0.15_0.009-0.15


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band66_5MHz_16QAM_131997_1RB#0_0.15~30_0.15~30



Band66_5MHz_16QAM_131997_1RB#0_30~1000_30~1000




Band66_5MHz_16QAM_131997_1RB#0_1000~3000_1000~3000



Band66_5MHz_16QAM_131997_1RB#0_3000~20000_3000~20000




Band66_5MHz_QPSK_131997_1RB#24_0.009~0.15_0.009~0.15



Band66_5MHz_QPSK_131997_1RB#24_0.15~30_0.15~30


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band66_5MHz_QPSK_131997_1RB#24_30~1000_30~1000




Band66_5MHz_QPSK_131997_1RB#24_1000~3000_1000~3000




Band66_5MHz_QPSK_131997_1RB#24_3000~20000_3000~20000



Band66_5MHz_16QAM_131997_1RB#24_0.009~0.15_0.009~0.15




Band66_5MHz_16QAM_131997_1RB#24_0.15~30_0.15~30




Band66_5MHz_16QAM_131997_1RB#24_30~1000_30~1000


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band66_5MHz_16QAM_131997_1RB#24_1000~3000_1000~3000




Band66_5MHz_16QAM_131997_1RB#24_3000~20000_3000~20000



Band66_5MHz_QPSK_131997_25RB#0_0.009~0.15_0.009~0.15



Band66_5MHz_QPSK_131997_25RB#0_0.15~30_0.15~30




Band66_5MHz_QPSK_131997_25RB#0_30~1000_30~1000



Band66_5MHz_QPSK_131997_25RB#0_1000~3000_1000~3000


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band66_5MHz_QPSK_131997_25RB#0_3000~20000_3000~20000




Band66_5MHz_16QAM_131997_25RB#0_0.009~0.15_0.009~0.15



Band66_5MHz_16QAM_131997_25RB#0_0.15~30_0.15~30



Band66_5MHz_16QAM_131997_25RB#0_30~1000_30~1000




Band66_5MHz_16QAM_131997_25RB#0_1000~3000_1000~3000




Band66_5MHz_16QAM_131997_25RB#0_3000~20000_3000~20000


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band66_5MHz_QPSK_132322_1RB#0_0.009-0.15_0.009-0.15




Band66_5MHz_QPSK_132322_1RB#0_0.15-30_0.15-30




Band66_5MHz_QPSK_132322_1RB#0_30-1000_30-1000



Band66_5MHz_QPSK_132322_1RB#0_1000-3000_1000-3000




Band66_5MHz_QPSK_132322_1RB#0_3000-20000_3000-20000




Band66_5MHz_16QAM_132322_1RB#0_0.009-0.15_0.009-0.15


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.



Band66_5MHz_16QAM_132322_1RB#0_0.15~30_0.15~30




Band66_5MHz_16QAM_132322_1RB#0_30~1000_30~1000




Band66_5MHz_16QAM_132322_1RB#0_1000~3000_1000~3000



Band66_5MHz_16QAM_132322_1RB#0_3000~20000_3000~20000




Band66_5MHz_QPSK_132322_1RB#24_0.009~0.15_0.009~0.15




Band66_5MHz_QPSK_132322_1RB#24_0.15~30_0.15~30

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band66_5MHz_QPSK_132322_1RB#24_30~1000_30~1000




Band66_5MHz_QPSK_132322_1RB#24_1000~3000_1000~3000




Band66_5MHz_QPSK_132322_1RB#24_3000~20000_3000~20000



Band66_5MHz_16QAM_132322_1RB#24_0.009~0.15_0.009~0.15




Band66_5MHz_16QAM_132322_1RB#24_0.15~30_0.15~30




Band66_5MHz_16QAM_132322_1RB#24_30~1000_30~1000

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band66_5MHz_16QAM_132322_1RB#24_1000~3000_1000~3000




Band66_5MHz_16QAM_132322_1RB#24_3000~20000_3000~20000



Band66_5MHz_QPSK_132322_25RB#0_0.009~0.15_0.009~0.15



Band66_5MHz_QPSK_132322_25RB#0_0.15~30_0.15~30




Band66_5MHz_QPSK_132322_25RB#0_30~1000_30~1000



Band66_5MHz_QPSK_132322_25RB#0_1000~3000_1000~3000


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band66_5MHz_QPSK_132322_25RB#0_3000~20000_3000~20000




Band66_5MHz_16QAM_132322_25RB#0_0.009~0.15_0.009~0.15




Band66_5MHz_16QAM_132322_25RB#0_0.15~30_0.15~30



Band66_5MHz_16QAM_132322_25RB#0_30~1000_30~1000




Band66_5MHz_16QAM_132322_25RB#0_1000~3000_1000~3000




Band66_5MHz_16QAM_132322_25RB#0_3000~20000_3000~20000


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band66_5MHz_QPSK_132647_1RB#0_0.009-0.15_0.009-0.15




Band66_5MHz_QPSK_132647_1RB#0_0.15-30_0.15-30




Band66_5MHz_QPSK_132647_1RB#0_30-1000_30-1000



Band66_5MHz_QPSK_132647_1RB#0_1000-3000_1000-3000




Band66_5MHz_QPSK_132647_1RB#0_3000-20000_3000-20000




Band66_5MHz_16QAM_132647_1RB#0_0.009-0.15_0.009-0.15


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.



Band66_5MHz_16QAM_132647_1RB#0_0.15~30_0.15~30




Band66_5MHz_16QAM_132647_1RB#0_30~1000_30~1000




Band66_5MHz_16QAM_132647_1RB#0_1000~3000_1000~3000



Band66_5MHz_16QAM_132647_1RB#0_3000~20000_3000~20000




Band66_5MHz_QPSK_132647_1RB#24_0.009~0.15_0.009~0.15




Band66_5MHz_QPSK_132647_1RB#24_0.15~30_0.15~30


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band66_5MHz_QPSK_132647_1RB#24_30~1000_30~1000




Band66_5MHz_QPSK_132647_1RB#24_1000~3000_1000~3000




Band66_5MHz_QPSK_132647_1RB#24_3000~20000_3000~20000



Band66_5MHz_16QAM_132647_1RB#24_0.009~0.15_0.009~0.15




Band66_5MHz_16QAM_132647_1RB#24_0.15~30_0.15~30




Band66_5MHz_16QAM_132647_1RB#24_30~1000_30~1000


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band66_5MHz_16QAM_132647_1RB#24_1000~3000_1000~3000




Band66_5MHz_16QAM_132647_1RB#24_3000~20000_3000~20000



Band66_5MHz_QPSK_132647_25RB#0_0.009~0.15_0.009~0.15



Band66_5MHz_QPSK_132647_25RB#0_0.15~30_0.15~30



Band66_5MHz_QPSK_132647_25RB#0_30~1000_30~1000



Band66_5MHz_QPSK_132647_25RB#0_1000~3000_1000~3000

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.