



Please refer to following plots:

Band 2 1.4 MHz Low QPSK RB6#0 1(30MHz-1GHz)




Date: 23.APR.2022 14:12:09

Band 2 1.4 MHz Low QPSK RB6#0 2(1GHz-20GHz)




Date: 23.APR.2022 13:23:27

Band 2 1.4 MHz Middle QPSK RB6#0 1(30MHz-1GHz)




Date: 23.APR.2022 14:14:08

Band 2_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 23.APR.2022 13:30:17

Band 2 1.4 MHz High QPSK RB6#0 1(30MHz-1GHz)




Date: 23.APR.2022 14:14:28

Band 2_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 23.APR.2022 13:27:12

Band 2 3 MHz Low QPSK RB15#0 1(30MHz-1GHz)




Date: 23.APR.2022 14:10:18

Band 2 3 MHz Low QPSK RB15#0 2(1GHz-20GHz)




Date: 23.APR.2022 13:36:08

Band 2 3 MHz Middle QPSK RB15#0 1(30MHz-1GHz)




Date: 23.APR.2022 14:10:45

Band 2_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 23.APR.2022 13:31:33

Band 2 3 MHz High QPSK RB15#0 1(30MHz-1GHz)




Date: 23.APR.2022 14:11:47

Band 2_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 23.APR.2022 13:34:50

Band 2 5 MHz Low QPSK RB25#0 1(30MHz-1GHz)




Date: 23.APR.2022 14:07:10

Band 2_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 23.APR.2022 13:41:23

Band 2 5 MHz Middle QPSK RB25#0 1(30MHz-1GHz)




Date: 23.APR.2022 14:07:47

Band 2_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 23.APR.2022 13:38:35

Band 2 5 MHz High QPSK RB25#0 1(30MHz-1GHz)




Date: 23.APR.2022 14:09:13

Band 2_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 23.APR.2022 13:40:18

Band 2 10 MHz Low QPSK RB50#0 1(30MHz-1GHz)




Date: 23.APR.2022 14:01:17

Band 2_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 23.APR.2022 13:47:13

Band 2 10 MHz Middle QPSK RB50#0 1(30MHz-1GHz)




Date: 23.APR.2022 14:02:21

Band 2_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 23.APR.2022 13:43:30

Band 2 10 MHz High QPSK RB50#0 1(30MHz-1GHz)




Date: 23.APR.2022 14:03:19

Band 2_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 23.APR.2022 13:46:06

Band 2 15 MHz Low QPSK RB75#0 1(30MHz-1GHz)




Date: 23.APR.2022 14:04:34

Band 2_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 23.APR.2022 13:52:31

Band 2_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 23.APR.2022 14:05:39

Band 2_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 23.APR.2022 13:55:21

Band 2_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 23.APR.2022 14:06:17

Band 2_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 23.APR.2022 13:49:11

Band 2 20 MHz Low QPSK RB100#0 1(30MHz-1GHz)




Date: 23.APR.2022 13:57:50

Band 2 20 MHz Low QPSK RB100#0 2(1GHz-20GHz)




Date: 23.APR.2022 13:56:12

Band 2 20 MHz Middle QPSK RB100#0 1(30MHz-1GHz)




Date: 23.APR.2022 14:00:38

Band 2 20 MHz Middle QPSK RB100#0 2(1GHz-20GHz)




Date: 23.APR.2022 13:53:14

Band 2 20 MHz High QPSK RB100#0 1(30MHz-1GHz)




Date: 23.APR.2022 13:59:26

Band 2 20 MHz High QPSK RB100#0 2(1GHz-20GHz)




Date: 23.APR.2022 13:54:49

Band 4 1.4 MHz Low QPSK RB6#0 1(30MHz-1GHz)




Date: 23.APR.2022 16:52:33

Band 4 1.4 MHz Low QPSK RB6#0 2(1GHz-18GHz)




Date: 23.APR.2022 17:16:59

Band 4 1.4 MHz Middle QPSK RB6#0 1(30MHz-1GHz)




Date: 23.APR.2022 16:54:10

Band 4 1.4 MHz Middle QPSK RB6#0 2(1GHz-18GHz)




Date: 23.APR.2022 17:16:00

Band 4 1.4 MHz High QPSK RB6#0 1(30MHz-1GHz)




Date: 23.APR.2022 16:54:50

Band 4_1.4 MHz_High_QPSK_RB6#0_2(1GHz-18GHz)




Date: 23.APR.2022 17:14:44

Band 4 3 MHz Low QPSK RB15#0 1(30MHz-1GHz)




Date: 23.APR.2022 16:56:57

Band 4 3 MHz Low QPSK RB15#0 2(1GHz-18GHz)




Date: 23.APR.2022 17:18:54

Band 4 3 MHz Middle QPSK RB15#0 1(30MHz-1GHz)




Date: 23.APR.2022 16:56:20

Band 4_3 MHz_Middle_QPSK_RB15#0_2(1GHz-18GHz)




Date: 23.APR.2022 17:19:49

Band 4 3 MHz High QPSK RB15#0 1(30MHz-1GHz)




Date: 23.APR.2022 16:55:35

Band 4_3 MHz_High_QPSK_RB15#0_2(1GHz-18GHz)




Date: 23.APR.2022 17:21:02

Band 4 5 MHz Low QPSK RB25#0 1(30MHz-1GHz)




Date: 23.APR.2022 16:59:40

Band 4_5 MHz_Low_QPSK_RB25#0_2(1GHz-18GHz)




Date: 23.APR.2022 17:31:38

Band 4 5 MHz Middle QPSK RB25#0 1(30MHz-1GHz)




Date: 23.APR.2022 16:59:06

Band 4_5 MHz_Middle_QPSK_RB25#0_2(1GHz-18GHz)




Date: 23.APR.2022 17:30:59

Band 4 5 MHz High QPSK RB25#0 1(30MHz-1GHz)




Date: 23.APR.2022 16:58:31

Band 4_5 MHz_High_QPSK_RB25#0_2(1GHz-18GHz)




Date: 23.APR.2022 17:28:41

Band 4 10 MHz Low QPSK RB50#0 1(30MHz-1GHz)




Date: 23.APR.2022 17:02:59

Band 4_10 MHz_Low_QPSK_RB50#0_2(1GHz-18GHz)




Date: 23.APR.2022 17:32:55

Band 4 10 MHz Middle QPSK RB50#0 1(30MHz-1GHz)




Date: 23.APR.2022 17:02:25

Band 4_10 MHz_Middle_QPSK_RB50#0_2(1GHz-18GHz)




Date: 23.APR.2022 17:34:10

Band 4 10 MHz High QPSK RB50#0 1(30MHz-1GHz)




Date: 23.APR.2022 17:01:53

Band 4 10 MHz High QPSK RB50#0 2(1GHz-18GHz)




Date: 23.APR.2022 17:35:07

Band 4 15 MHz Low QPSK RB75#0 1(30MHz-1GHz)




Date: 23.APR.2022 17:08:02

Band 4_15 MHz_Low_QPSK_RB75#0_2(1GHz-18GHz)




Date: 23.APR.2022 17:38:09

Band 4_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 23.APR.2022 17:07:27

Band 4_15 MHz_Middle_QPSK_RB75#0_2(1GHz-18GHz)




Date: 23.APR.2022 17:37:15

Band 4_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 23.APR.2022 17:05:15

Band 4_15 MHz_High_QPSK_RB75#0_2(1GHz-18GHz)




Date: 23.APR.2022 17:36:19

Band 4 20 MHz Low QPSK RB100#0 1(30MHz-1GHz)




Date: 23.APR.2022 17:09:53

Band 4 20 MHz Low QPSK RB100#0 2(1GHz-18GHz)




Date: 23.APR.2022 17:39:23

Band 4 20 MHz Middle QPSK RB100#0 1(30MHz-1GHz)




Date: 23.APR.2022 17:09:14

Band 4_20 MHz_Middle_QPSK_RB100#0_2(1GHz-18GHz)




Date: 23.APR.2022 17:40:21

Band 4 20 MHz High QPSK RB100#0 1(30MHz-1GHz)




Date: 23.APR.2022 17:08:42

Band 4 20 MHz High QPSK RB100#0 2(1GHz-18GHz)




Date: 23.APR.2022 17:41:17

Band 5 1.4 MHz Low QPSK RB6#0 1(30MHz-1GHz)




Date: 24.APR.2022 13:31:12

Band 5 1.4 MHz Low QPSK RB6#0 2(1GHz-10GHz)




Date: 24.APR.2022 13:49:53

Band 5 1.4 MHz Middle QPSK RB6#0 1(30MHz-1GHz)




Date: 24.APR.2022 13:26:37

Band 5_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 24.APR.2022 13:47:20

Band 5 1.4 MHz High QPSK RB6#0 1(30MHz-1GHz)




Date: 24.APR.2022 13:29:57

Band 5_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 24.APR.2022 13:49:30

Band 5 3 MHz Low QPSK RB15#0 1(30MHz-1GHz)




Date: 24. APR.2022 13:34:56

Band 5_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 24. APR.2022 13:53:07

Band 5 3 MHz Middle QPSK RB15#0 1(30MHz-1GHz)




Date: 24.APR.2022 13:35:43

Band 5_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 24.APR.2022 13:53:52

Band 5 3 MHz High QPSK RB15#0 1(30MHz-1GHz)




Date: 24.APR.2022 13:32:59

Band 5_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 24.APR.2022 13:51:02

Band 5 5 MHz Low QPSK RB25#0 1(30MHz-1GHz)




Date: 24.APR.2022 13:40:38

Band 5_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 24.APR.2022 14:00:15

Band 5 5 MHz Middle QPSK RB25#0 1(30MHz-1GHz)




Date: 24.APR.2022 13:38:03

Band 5_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 24.APR.2022 13:57:43

Band 5 5 MHz High QPSK RB25#0 1(30MHz-1GHz)




Date: 24. APR.2022 13:38:42

Band 5_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 24. APR.2022 13:58:51

Band 5 10 MHz Low QPSK RB50#0 1(30MHz-1GHz)




Date: 24.APR.2022 13:45:09

Band 5_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 24.APR.2022 14:02:41

Band 5 10 MHz Middle QPSK RB50#0 1(30MHz-1GHz)




Date: 24.APR.2022 13:41:37

Band 5_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 24.APR.2022 14:03:03

Band 5 10 MHz High QPSK RB50#0 1(30MHz-1GHz)




Date: 24.APR.2022 13:44:13

Band 5_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 24.APR.2022 14:01:03

Band 7 5 MHz Low QPSK RB25#0 1(30MHz-1GHz)




Date: 24.APR.2022 16:07:37

Band 7_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 24.APR.2022 15:53:35

Band 7 5 MHz Middle QPSK RB25#0 1(30MHz-1GHz)




Date: 24.APR.2022 16:08:39

Band 7_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 24.APR.2022 15:55:21

Band 7 5 MHz High QPSK RB25#0 1(30MHz-1GHz)




Date: 24.APR.2022 16:05:53

Band 7 5 MHz High QPSK RB25#0 2(1GHz-26.5GHz)




Date: 24.APR.2022 15:52:43

Band 7 10 MHz Low QPSK RB50#0 1(30MHz-1GHz)



Date: 24.APR.2022 16:10:06

Band 7_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)



Date: 24.APR.2022 15:58:32