

00:0C:AA: E0:2B:25

4400-57030

RTF D-1 94V-0 E231499 2024 RA ET
CUBIC
2200-53003-D
2200-57003-REV D

INSTALLED
3/17/20

made in Ind
TR4 AAB









DANGER
Electrical Hazards
Authorized Personnel Only

DANGER
Electrical Hazards
Authorized Personnel Only

FUSE PANEL LAYOUT


FUSE NO.	RATING	TYPE	LOCATION
1	10A	AG	MAIN SUPPLY
2	5A	AG	CONTROL CIRCUIT
3	15A	AG	HEATING ELEMENT
4	20A	AG	MOTOR WINDING
5	10A	AG	RELAY COILS
6	5A	AG	CONTROL TRANSFORMER
7	10A	AG	PLC POWER SUPPLY
8	5A	AG	PLC I/O MODULES
9	10A	AG	PLC CPU MODULE
10	5A	AG	PLC BACKUP BATTERY
11	10A	AG	PLC COMMUNICATIONS
12	5A	AG	PLC PROGRAM MEMORY
13	10A	AG	PLC DATA MEMORY
14	5A	AG	PLC I/O TERMINALS
15	10A	AG	PLC POWER TERMINALS
16	5A	AG	PLC GROUNDING
17	10A	AG	PLC SIGNALING
18	5A	AG	PLC ALARMS
19	10A	AG	PLC MAINTENANCE
20	5A	AG	PLC TESTING

AC 85 5.0/0.5 5.0V 12.0V 24.0V

UN
1500x1000
1000
KTR



PLC
Power Supply



QUORX
COND-19
8.12.20



B34711

MUA-00004
 WINDOWS 10 32 BIT ENT 2019 LIC ENTRY
 GEN SOFTWARE
 HONORABLE.COM
 14-08 JT
 Product Key: Microsoft HP-DJ-GV-30002-07150

ADVANTECH
 ADVANTECH Co., Ltd. <http://www.advantech.com>
 制造商: 研华股份有限公司(研华股份有限公司)
 生产商: 研华科技(中国)有限公司

This device complies with part 15 of the FCC rules. Operation is subject to the following two conditions:
 (1) This device must not cause harmful interference.
 (2) This device must accept any interference received, including interference that may cause undesired operation.

此设备符合 FCC 第 15 部分的规定。操作受以下两个条件的限制：
 (1) 本设备不得对无线电通信造成有害干扰。
 (2) 本设备必须接受其所接收到的任何干扰，包括可能对设备操作造成不希望有的干扰。

ATTENTION!
 Do not open the cover. No user serviceable parts inside.
 注意：产品请勿拆盖。机内无用户可更换零件。

Model No.: ITA-1T11
 型号/型号: ITA171120017
 Part No.: 8-38106
 零件号/零件号: 8-5A-3-254
 8-5A-3-254
 研华股份有限公司
 研华科技(中国)有限公司

KSA4318655
 Factory: C2
 Made in China (中国制造)

CE
 FCC
 RoHS
 UL
 E183841
 I.T.E.

