

Exhibit: Test Setup Photos

FCC ID: 2AXVL-UW02 IC: 26604-UW02

Report File #: 7169009345RF-000

© TÜV SÜD Canada Inc. This test report shall not be reproduced except in full, without written approval of TÜV SÜD Canada Inc.

Client	Myant Inc.	
Product	SKIIN Underwear	
Standard(s)	RSS 247 Issue 2:2017 FCC Part 15 Subpart 15.247	SUD




Figure 1 – EUT Close Up

Page 2 of 11 Report Issued: 4/26/2021 Report File #: 7169009345RF-000

Client	Myant Inc.	
Product	SKIIN Underwear	
Standard(s)	RSS 247 Issue 2:2017 FCC Part 15 Subpart 15.247	SUD




Figure 2 – Radiated Emissions Setup Z-Axis

Page 3 of 11 Report Issued: 4/26/2021 Report File #: 7169009345R	-000
--	------

Client	Myant Inc.	
Product	SKIIN Underwear	
Standard(s)	RSS 247 Issue 2:2017 FCC Part 15 Subpart 15.247	SUD



Figure 3 – Radiated Emissions Setup 9kHz to 30MHz

Page 4 of 11 Report Issued: 4/26/2021 Report File #: 7169009345RF-000

Client	Myant Inc.	
Product	SKIIN Underwear	
Standard(s)	RSS 247 Issue 2:2017 FCC Part 15 Subpart 15.247	SUD



Figure 4 – Radiated Emissions Setup 30MHz to 1GHz

Page 5 of 11	Report Issued: 4/26/2021	Report File #: 7169009345RF-000
--------------	--------------------------	---------------------------------

Note: As per ANSI C63.10-2013 Clause 6.3.1, below 1GHz, the height of the EUT was set to 80cm. Above 1GHz, the height was raised to 1.5m.

Client	Myant Inc.	
Product	SKIIN Underwear	
Standard(s)	RSS 247 Issue 2:2017 FCC Part 15 Subpart 15.247	SUD




Figure 5 – Radiated Emissions Setup 1GHz to 4GHz Spurious Scans

Note: As per ANSI C63.10-2013 Clause 6.3.1, above 1GHz, the height of the EUT was set to 1.5m.

Page 6 of 11	Report Issued: 4/26/2021	Report File #: 7169009345RF-000
--------------	--------------------------	---------------------------------

Client	Myant Inc.	
Product	SKIIN Underwear	
Standard(s)	RSS 247 Issue 2:2017 FCC Part 15 Subpart 15.247	SUD



Figure 6 – Radiated Emissions Setup 4GHz to 18GHz Spurious Scans & Band-Edge Measurements

Page 7 of 11Report Issued: 4/26/2021Report File #: 7169009	345RF-000
--	-----------

Client	Myant Inc.	
Product	SKIIN Underwear	
Standard(s)	RSS 247 Issue 2:2017 FCC Part 15 Subpart 15.247	SUD




Figure 7 – Radiated Emissions Setup 18GHz to 26GHz Spurious Scans

Page 8 of 11 Repo	ort Issued: 4/26/2021 Report File #:	7169009345RF-000
-------------------	--------------------------------------	------------------

Client	Myant Inc.	
Product	SKIIN Underwear	
Standard(s)	RSS 247 Issue 2:2017 FCC Part 15 Subpart 15.247	SUD




Figure 8 – Antenna Port Conducted Emissions Setup

Page 9 of 11 Report Issued: 4/	26/2021 Report File #: 7169009345RF-000
--------------------------------	---

Client	Myant Inc.	
Product	SKIIN Underwear	
Standard(s)	RSS 247 Issue 2:2017 FCC Part 15 Subpart 15.247	SUD



Figure 9 – Conducted Emissions Setup

Page 10 of 11 Report Issued: 4/26/2021 Report File #: 7169009345RF-00	0
---	---

Client	Myant Inc.	
Product	SKIIN Underwear	TÜV
Standard(s)	RSS 247 Issue 2:2017 FCC Part 15 Subpart 15.247	SUD



Figure 10 – Conducted Emissions Setup

	Page 11 of 11	Report Issued: 4/26/2021	Report File #: 7169009345RF-000
--	---------------	--------------------------	---------------------------------