

ORAIMO TECHNOLOGY LIMITED

Address: FLAT N 16/F BLOCK B UNIVERSAL INDUSTRIAL CENTRE 19-25 SHAN MEI STREET

FOTAN NT HONGKONG

Tel.: +86-0755-61803856

Email: dollyphin@oraimo.com

FCC ID certification No. Cover Letter

We, ORAIMO TECHNOLOGY LIMITED here by submits justification for placing the FCC ID in the Associated charging case.

According to the FCC Regulation and Guidance(KDB Publication 784748 D01 v09r01) allows for FCC ID to be moved to charging case if the device is unquestionable too small for the FCC ID to be printed.

Referring to the above quote, as the device is too small (FCC ID: 2AXYP-OEB-E06DN-R) to be printed.

The FCC ID will be moved to the charging case. The details are as below:

- A. Top cover (A): The top cover does not provide enough physical space to fit the printing of the FCC ID according to below reference picture




- B. Side surface (B): The side surface does not provide enough physical space to fit the printing of the FCC ID according to below reference picture.



Conclusion: Based on the above description of area A to B, we conclude that the device is unquestionably too small for enabling the FCC ID to be printed onto any surface. We therefore request to move the FCC ID to the charging case.



FCC ID Label Location Information



Best regards,

Signature: *Greeny.Xian*

Greeny Xian

Manager