## ORAIMO TECHNOLOGY LIMITED

Address:

Flat 39, 8/F., Block D, Wah Lok Industrial Centre, 31-35 Shan Mei Street, Fotan, NT, Hong Kong

Tel.: +86-0755-61803856

Email: dollyphin@oraimo.com

Date: 2021-12-23

FEDERAL COMMUNICATIONS COMMISSIONS Authorization and Evaluation Division 7435 Oakland Mills Road Columbia, MD 21046

To whom it may concern:

The RF chip, model BES2500IH, which installed in our product True wireless earbuds, Model: OEB-E108D, FCC ID: 2AXYP-OEB-E108D-L, supports BDR (GFSK), EDR ( $\pi$ /4-DQPSK, 8DPSK), BLE 1M and BLE 2M functions. For use in America and this chip will not support/enable BLE 2M. The BLE 2M has been shielded by the manufacturer using the software.

Sincerely Yours, Signature:

Greeny. Xian

Greeny Xian Manager