

ORAIMO TECHNOLOGY LIMITED

Address:

FLAT N 16/F BLOCK B UNIVERSAL INDUSTRIAL CENTRE 19-25 SHAN MEI  
STREET FOTAN, Hong Kong

Tel.: +86-0755-61803856

Email: dollyphin@oraimo.com

Date: 2022-08-01

FEDERAL COMMUNICATIONS COMMISSIONS

Authorization and Evaluation Division

7435 Oakland Mills Road

Columbia, MD 21046

To whom it may concern:

The RF chip, model DA14695, which installed in our product Smart Watch, Model: OSW-31N, FCC ID: 2AXYP-OSW-31N, supports BDR (GFSK), EDR ( $\pi/4$ -DQPSK, 8DPSK), BLE 1M and BLE 2M functions. For use in America and this chip will not support/enable BDR (GFSK), EDR ( $\pi/4$ -DQPSK, 8DPSK). The BDR (GFSK), EDR ( $\pi/4$ -DQPSK, 8DPSK) has been shielded by the manufacturer using the software.

Sincerely Yours,

Signature:

A handwritten signature in black ink that reads "Greeny Xian". The signature is written in a cursive, slightly slanted style.

Greeny Xian

Manager