




20:02:59 09.04.2024
Band2-20MHz-QPSK-19100-100RB#0-PASS




20:03:18 09.04.2024
Band2-20MHz-16QAM-18700-100RB#0-PASS




20:03:37 09.04.2024
Band2-20MHz-16QAM-18900-100RB#0-PASS




20:03:08 09.04.2024
Band2-20MHz-16QAM-19100-100RB#0-PASS





20:03:27 09.04.2024
Band5-1.4MHz-QPSK-20407-6RB#0-PASS





20:03:46 09.04.2024
Band5-1.4MHz-QPSK-20525-6RB#0-PASS














22:11:27 31.07.2024




22:11:42 31.07.2024




22:18:13 31.07.2024



22:18:21 31.07.2024




22:25:11 31.07.2024



22:25:20 31.07.2024


Band7-20MHz-QPSK-21100-100RB#0-PASS

Band7-20MHz-16QAM-21100-100RB#0-PASS




22:31:02 31.07.2024

Band12-1.4MHz-QPSK-23017-6RB#0-PASS




22:31:11 31.07.2024

Band12-1.4MHz-QPSK-23095-6RB#0-PASS




22:02:22 09.04.2024

Band12-1.4MHz-QPSK-23173-6RB#0-PASS




22:02:40 09.04.2024

Band12-1.4MHz-QPSK-23095-6RB#0-PASS




22:02:58 09.04.2024

Band12-1.4MHz-16QAM-23173-6RB#0-PASS




22:02:29 09.04.2024


Band12-1.4MHz-16QAM-23095-6RB#0-PASS




Band12-3MHz-QPSK-23025-15RB#0-PASS




Band12-3MHz-QPSK-23095-15RB#0-PASS




Band12-3MHz-QPSK-23165-15RB#0-PASS




Band12-3MHz-QPSK-23095-15RB#0-PASS





Band12-3MHz-16QAM-23025-15RB#0-PASS





Band12-3MHz-16QAM-23165-15RB#0-PASS













11:24:50 16.04.2024

Band38-15MHz-QPSK-37825-75RB#0-PASS




11:25:09 16.04.2024

Band38-15MHz-QPSK-38000-75RB#0-PASS




11:51:36 16.04.2024

Band38-15MHz-QPSK-38175-75RB#0-PASS




11:51:55 16.04.2024

Band38-15MHz-16QAM-38000-75RB#0-PASS




11:51:15 16.04.2024

Band38-15MHz-16QAM-38175-75RB#0-PASS




11:51:45 16.04.2024


Band38-15MHz-16QAM-38000-75RB#0-PASS




Band38-20MHz-QPSK-37850-100RB#0-PASS




Band38-20MHz-QPSK-38000-100RB#0-PASS




Band38-20MHz-QPSK-38150-100RB#0-PASS




Band38-20MHz-16QAM-37850-100RB#0-PASS



Band38-20MHz-16QAM-38000-100RB#0-PASS




Band38-20MHz-16QAM-38150-100RB#0-PASS




12:59:27 16.04.2024

Band41-5MHz-QPSK-39675-25RB#0-PASS




12:59:47 16.04.2024

Band41-5MHz-QPSK-40620-25RB#0-PASS




13:44:28 16.04.2024

Band41-5MHz-QPSK-41565-25RB#0-PASS




13:45:00 16.04.2024

Band41-5MHz-QPSK-40620-25RB#0-PASS



13:45:33 16.04.2024

Band41-5MHz-16QAM-40620-25RB#0-PASS



13:44:43 16.04.2024

Band41-5MHz-16QAM-41565-25RB#0-PASS