


Tel: +886 2 26099301 Fax: +886 2 26099303


B.1 Radiated Measurement at Chamber

Frequency Below to 1GHz

Lie








File Number: C1M2011110

Report Number: EM-F200553

This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.


AUDIX Technology Corp. No. 53-11, Dingfu, Linkou, Dist., New Taipei City244, Taiwan Tel: +886 2 26099301 Fax: +886 2 26099303

Stand



Frequency Above to 1GHz






File Number: C1M2011110

Report Number: EM-F200553



AUDIX Technology Corp. No. 53-11, Dingfu, Linkou, Dist., New Taipei City244, Taiwan Tel: +886 2 26099301 Fax: +886 2 26099303







Tel: +886 2 26099301 Fax: +886 2 26099303

B.2 RF Conducted Measurement

