



Please refer to following plots:




Date: 1.JAN.2021 16:16:02




Date: 1.JAN.2021 16:16:21

### Band 2\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 1.JAN.2021 16:16:37

### Band 2\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 1.JAN.2021 16:16:56

### Band 2\_3 MHz\_Low\_QPSK\_RB15#0




Date: 1.JAN.2021 16:17:17

### Band 2\_3 MHz\_Low\_16QAM\_RB15#0




Date: 1.JAN.2021 16:17:33

### Band 2\_3 MHz\_High\_QPSK\_RB15#0




Date: 1.JAN.2021 16:17:49

### Band 2\_3 MHz\_High\_16QAM\_RB15#0




Date: 1.JAN.2021 16:18:08

### Band 2\_5 MHz\_Low\_QPSK\_RB25#0




Date: 4.FEB.2021 20:46:08

### Band 2\_5 MHz\_Low\_16QAM\_RB25#0




Date: 4.FEB.2021 20:45:20

### Band 2\_5 MHz\_High\_QPSK\_RB25#0




Date: 4.FEB.2021 18:14:03

### Band 2\_5 MHz\_High\_16QAM\_RB25#0




Date: 4.FEB.2021 20:44:31

### Band 2\_10 MHz\_Low\_QPSK\_RB50#0




Date: 1.JAN.2021 16:19:42

### Band 2\_10 MHz\_Low\_16QAM\_RB50#0




Date: 1.JAN.2021 16:19:59

### Band 2\_10 MHz\_High\_QPSK\_RB50#0



Date: 1.JAN.2021 16:20:20


### Band 2\_10 MHz\_High\_16QAM\_RB50#0



Date: 1.JAN.2021 16:20:36




### Band 2\_15 MHz\_Low\_QPSK\_RB75#0




Date: 1.JAN.2021 16:20:58

### Band 2\_15 MHz\_Low\_16QAM\_RB75#0




Date: 1.JAN.2021 16:21:17

### Band 2\_15 MHz\_High\_QPSK\_RB75#0




Date: 4.FEB.2021 20:42:05

### Band 2\_15 MHz\_High\_16QAM\_RB75#0




Date: 1.JAN.2021 16:21:56

### Band 2\_20 MHz\_Low\_QPSK\_RB100#0




Date: 1.JAN.2021 16:22:21

### Band 2\_20 MHz\_Low\_16QAM\_RB100#0




Date: 1.JAN.2021 16:22:43

### Band 2\_20 MHz\_High\_QPSK\_RB100#0




Date: 1.JAN.2021 16:23:03

### Band 2\_20 MHz\_High\_16QAM\_RB100#0




Date: 1.JAN.2021 16:23:22

### Band 4\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 1.JAN.2021 16:23:43

### Band 4\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 1.JAN.2021 16:24:02

### Band 4\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 4.FEB.2021 17:52:14

### Band 4\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 4.FEB.2021 17:52:48

### Band 4\_3 MHz\_Low\_QPSK\_RB15#0




Date: 1.JAN.2021 16:24:52

### Band 4\_3 MHz\_Low\_16QAM\_RB15#0




Date: 1.JAN.2021 16:25:11

### Band 4\_3 MHz\_High\_QPSK\_RB15#0



Date: 1.JAN.2021 16:25:27


### Band 4\_3 MHz\_High\_16QAM\_RB15#0



Date: 1.JAN.2021 16:25:46




### Band 4\_5 MHz\_Low\_QPSK\_RB25#0




Date: 4.FEB.2021 17:56:00

### Band 4\_5 MHz\_Low\_16QAM\_RB25#0




Date: 4.FEB.2021 17:56:29

### Band 4\_5 MHz\_High\_QPSK\_RB25#0




Date: 4.FEB.2021 17:57:06

### Band 4\_5 MHz\_High\_16QAM\_RB25#0




Date: 4.FEB.2021 17:57:38

### Band 4\_10 MHz\_Low\_QPSK\_RB50#0




Date: 1.JAN.2021 16:27:21

### Band 4\_10 MHz\_Low\_16QAM\_RB50#0




Date: 1.JAN.2021 16:27:38

### Band 4\_10 MHz\_High\_QPSK\_RB50#0




Date: 1.JAN.2021 16:27:55

### Band 4\_10 MHz\_High\_16QAM\_RB50#0




Date: 1.JAN.2021 16:28:12

### Band 4\_15 MHz\_Low\_QPSK\_RB75#0




Date: 4.FEB.2021 18:07:53

### Band 4\_15 MHz\_Low\_16QAM\_RB75#0




Date: 1.JAN.2021 16:28:53

### Band 4\_15 MHz\_High\_QPSK\_RB75#0




Date: 4.FEB.2021 18:09:32

### Band 4\_15 MHz\_High\_16QAM\_RB75#0




Date: 1.JAN.2021 16:29:32

### Band 4\_20 MHz\_Low\_QPSK\_RB100#0




Date: 1.JAN.2021 16:29:54

### Band 4\_20 MHz\_Low\_16QAM\_RB100#0




Date: 1.JAN.2021 16:30:13

### Band 4\_20 MHz\_High\_QPSK\_RB100#0



Date: 1.JAN.2021 16:30:32


### Band 4\_20 MHz\_High\_16QAM\_RB100#0



Date: 1.JAN.2021 16:30:51




### Band 5\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 25.JAN.2021 18:57:59

### Band 5\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 25.JAN.2021 18:58:21

### Band 5\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 25.JAN.2021 18:58:56

### Band 5\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 25.JAN.2021 18:59:25

### Band 5\_3 MHz\_Low\_QPSK\_RB15#0




Date: 1.JAN.2021 16:32:26

### Band 5\_3 MHz\_Low\_16QAM\_RB15#0




Date: 1.JAN.2021 16:32:41

### Band 5\_3 MHz\_High\_QPSK\_RB15#0




Date: 1.JAN.2021 16:33:01

### Band 5\_3 MHz\_High\_16QAM\_RB15#0




Date: 1.JAN.2021 16:33:16

### Band 5\_5 MHz\_Low\_QPSK\_RB25#0




Date: 25.JAN.2021 19:01:50

### Band 5\_5 MHz\_Low\_16QAM\_RB25#0




Date: 4.FEB.2021 17:31:26

### Band 5\_5 MHz\_High\_QPSK\_RB25#0




Date: 4.FEB.2021 17:32:57

### Band 5\_5 MHz\_High\_16QAM\_RB25#0




Date: 4.FEB.2021 17:47:15

### Band 5\_10 MHz\_Low\_QPSK\_RB50#0




Date: 1.JAN.2021 16:34:45

### Band 5\_10 MHz\_Low\_16QAM\_RB50#0




Date: 1.JAN.2021 16:35:05

### Band 5\_10 MHz\_High\_QPSK\_RB50#0



Date: 1.JAN.2021 16:35:23


### Band 5\_10 MHz\_High\_16QAM\_RB50#0



Date: 1.JAN.2021 16:35:43




### Band 7\_5 MHz\_Low\_QPSK\_RB25#0




Date: 4.FEB.2021 20:35:59

### Band 7\_5 MHz\_Low\_16QAM\_RB25#0




Date: 25.JAN.2021 19:06:31

### Band 7\_5 MHz\_High\_QPSK\_RB25#0




Date: 25.JAN.2021 19:07:02

### Band 7\_5 MHz\_High\_16QAM\_RB25#0




Date: 25.JAN.2021 19:07:25

### Band 7\_10 MHz\_Low\_QPSK\_RB50#0




Date: 20.JAN.2021 09:41:00

### Band 7\_10 MHz\_Low\_16QAM\_RB50#0




Date: 20.JAN.2021 09:41:16

### Band 7\_10 MHz\_High\_QPSK\_RB50#0




Date: 20.JAN.2021 09:41:34

### Band 7\_10 MHz\_High\_16QAM\_RB50#0




Date: 20.JAN.2021 09:41:50

### Band 7\_15 MHz\_Low\_QPSK\_RB75#0




Date: 25.JAN.2021 19:10:08

### Band 7\_15 MHz\_Low\_16QAM\_RB75#0




Date: 25.JAN.2021 19:10:37

### Band 7\_15 MHz\_High\_QPSK\_RB75#0




Date: 25.JAN.2021 19:11:17

### Band 7\_15 MHz\_High\_16QAM\_RB75#0




Date: 25.JAN.2021 19:11:46

### Band 7\_20 MHz\_Low\_QPSK\_RB100#0




Date: 25.JAN.2021 19:12:27

### Band 7\_20 MHz\_Low\_16QAM\_RB100#0




Date: 25.JAN.2021 19:12:56

### Band 7\_20 MHz\_High\_QPSK\_RB100#0



Date: 25.JAN.2021 19:13:37


### Band 7\_20 MHz\_High\_16QAM\_RB100#0



Date: 25.JAN.2021 19:14:06




### Band 17\_5 MHz\_Low\_QPSK\_RB25#0




Date: 4.FEB.2021 17:26:36

### Band 17\_5 MHz\_Low\_16QAM\_RB25#0




Date: 4.FEB.2021 17:27:34

### Band 17\_5 MHz\_High\_QPSK\_RB25#0




Date: 25.JAN.2021 19:16:49

### Band 17\_5 MHz\_High\_16QAM\_RB25#0




Date: 25.JAN.2021 19:17:11

### Band 17\_10 MHz\_Low\_QPSK\_RB50#0




Date: 1.JAN.2021 16:37:15

### Band 17\_10 MHz\_Low\_16QAM\_RB50#0




Date: 1.JAN.2021 16:37:31

### Band 17\_10 MHz\_High\_QPSK\_RB50#0



Date: 1.JAN.2021 16:37:49

### Band 17\_10 MHz\_High\_16QAM\_RB50#0



Date: 1.JAN.2021 16:38:05