

Linksys USA, Inc.

12045 E. Waterfront Drive, USA

Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

Attention: Application Examiner / Review Engineer

Subject: Request to change in identification per section 2.933 of FCC rules

Date: 2021-06-10

Reference: FCC ID: 2AYRA-03580

To The Commission:

This Change of Identification request applies for a new FCC ID: 2AYRA-03580 as established in 47CFR 2.933(b) for a currently approved device. This application by Linksys USA, Inc. will establish a new FCC ID under our own new grantee code (2AYRA) for purpose of marketing. The original grant issued to Belkin International, Inc. under FCC ID: K7S-03580 will remain in effect.

An authorization letter by (Belkin International, Inc) is attached.

Per 2.933(b)

1. The original identification is FCC ID: K7S-03580
2. The original grant date is 2.4G+5G B1, B4 cert. date: 07/23/2020; 5G B2, B3 cert. date: 02/01/2021
3. The equipment is electrically identical. Only the FCC ID number is different.
4. The original test results are applicable and representative of this changed device.
5. Exterior photographs are included in this application.
6. the device and will not alter or offer any capabilities that will modify DFS settings

The following files are electronically submitted as attachments:

Cover Letter

External Photos

FCC ID label format and location

Sincerely yours,

Po-Wen
Cheng

Digitally signed
by Po-Wen Cheng
Date: 2021.06.10
14:06:45 -07'00'

Po-Wen Cheng / Manager, Regulatory Compliance

Linksys USA, Inc.

Tel: +1 949 238-4518

E-mail: po-wen.cheng@linksys.com