

Page : 1 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

# **RADIO TEST REPORT**

**Product**: Wireless Headset

Model Name : HS2404

**FCC ID** : 2AYYS-HS2404

**Test Regulation**: FCC 47 CFR Part 15 Subpart C (Section 15.247)

**Received Date** : 2023/7/18

**Test Date** : 2023/7/25 ~ 2023/7/27

**Issued Date** : 2023/8/11

**Applicant**: Luxshare Precision Industry Co., Ltd.

Floor 2,Block A,Sanyo New Industrial Area, West Haoyi Community,Shajing Subdistrict Office, Bao an District

Shenzhen, P. R. China

**Issued By** : Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd.,

Zhudong Township, Hsinchu County, Taiwan





The results reported herein have been performed in accordance with the laboratory's terms of accreditation. This report shall not be reproduced except in full without the written approval of the Laboratory. The results in this report are responsible of the test sample(s) provided by the client only and are not to be used to indicate applicability to other similar products.

#### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 2 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

# **REVISION HISTORY**

Original Test Report No.: 4790729227-US-R0-V0

Revision	Test report No. 4790729227-US-R0-V0	Date	Page revised	Contents
Original	4790729227-US-R0-V0	2023/8/11	-	Initial issue
	-			

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 3 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

# **Table of Contents**

1. A	ttestation of Test Results	4
2. Su	ummary of Test Results	5
3. To	est Methodology and Reference Procedures	6
4. Fa	acilities and Accreditation	6
5. M	leasurement Uncertainty	7
6. E	quipment under Test	8
6.1.	Description of EUT	
6.2.	Channel List	
6.3.	Test Condition	
6.4.	Description of Available Antennas	
6.5.	Test Mode Applicability and Tested Channel Detail	
6.6.	Duty cycle	13
7. To	est Equipment	14
8. D	escription of Test Setup	16
9. To	est Results	18
9.1.	Channel Bandwidth	18
9.2.	Conducted Output Power	21
9.3.	Hopping Channel Separation	23
9.4.	Number of Hopping Frequency Used	
9.5.	Dwell Time on Each Channel	
9.6.	Conducted Out of Band Emission	
9.7.	Radiated Spurious Emission	
9.8.	AC Power Line Conducted Emission	56

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 4 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

#### 1. Attestation of Test Results

**APPLICANT:** Luxshare Precision Industry Co., Ltd.

Floor 2, Block A, Sanyo New Industrial Area, West Haoyi

Community, Shajing Subdistrict Office, Bao an District Shenzhen, P.

R. China

**MANUFACTURER:** Luxshare Precision Industry Co., Ltd.

Floor 2, Block A, Sanyo New Industrial Area, West Haoyi

Community, Shajing Subdistrict Office, Bao an District Shenzhen, P.

R. China

**EUT DESCRIPTION:** Wireless Headset

**BRAND:** DELL

MODEL: HS2404

**SAMPLE STAGE:** Engineering Verification Test sample

**DATE of TESTED:** 2023/7/25 ~ 2023/7/27

#### APPLICABLE STANDARDS

**STANDARD** 

**Test Results** 

FCC 47 CFR PART 15 Subpart C (Section 15.247)

**PASS** 

Underwriters Laboratories Taiwan Co., Ltd. tested the above equipment in accordance with the requirements set forth in the above standards. All indications of Pass/Fail in this report are opinions expressed by Underwriters Laboratories Taiwan Co., Ltd. based on interpretations and/or observations of test results. The test results show that the equipment tested is capable of demonstrating compliance with the requirements as documented in this report.

**Note:** The results documented in this report apply only to the tested sample, under the conditions and modes of operation as described herein. This document may not be altered or revised in any way unless done so by Underwriters Laboratories Taiwan Co., Ltd. and all revisions are duly noted in the revisions section. Any alteration of this document not carried out by Underwriters Laboratories Taiwan Co., Ltd. will constitute fraud and shall nullify the document. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, any agency of the Federal Government, or any agency of any government.

Prepared By: Approved and Authorized By:

Cindy Hsin Date: 2023/8/11 Eric Lee Date: 2023/8/11

Project Handler Senior Laboratory Engineer

#### Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 5 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

# 2. Summary of Test Results

Summary of Test Results						
FCC Clause	FCC Clause Test Items					
15.247(a)(1) (iii)	Number of Hopping Frequency Used	PASS				
15.247(a)(1) (iii)	Dwell Time on Each Channel	PASS				
15.247(a)(1)	1. Hopping Channel Separation     2. Spectrum Bandwidth of a Frequency     Hopping Sequence Spread Spectrum System	PASS				
15.247(b)	Conducted Output Power	PASS				
15.247(d)	Antenna Port Emission	PASS				
15.205 / 15.209 / 15.247(d)						
15.207	.207 AC Power Conducted Emission					
15.203	Antenna Requirement	PASS				

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 6 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

# 3. Test Methodology and Reference Procedures

The tests documented in this report were performed in accordance with 47 CFR FCC Part 2, KDB558074 D01 Meas Guidance v05r02, KDB414788 D01 Radiated Test Site v01r01, ANSI C63.10-2013.

# 4. Facilities and Accreditation

Test Location	Underwriters Laboratories Taiwan Co., Ltd.
Address  Building B and Building E, No. 372-7, Sec. 4, Zhong Rd., Zhudong Township, Hsinchu County, Taiwan	
Accreditation Certificate	Underwriters Laboratories Taiwan Co., Ltd. is accredited by TAF, Laboratory Code 3398.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 7 of 61
Issued date : 2023/8/11
FCC ID : 2AYYS-HS2404

# 5. Measurement Uncertainty

For statement of conformity, Simple acceptance (Section 4.3.4 of ISO Guide 115) was applied as decision rule for measurement in this test report.

The following uncertainties have been calculated to provide a confidence level of 95 % using a coverage factor k=2.

Determining compliance based on the results of the compliance measurement, not considering measurement instrumentation uncertainty.

Measurement	Frequency	Uncertainty
Conducted disturbance at mains terminals ports	150kHz ~ 30MHz	±3.1 dB
RF Conducted	9 kHz - 40GHz	±2.3 dB
Radiated disturbance below 30MHz	9 kHz - 30 MHz	±3.2 dB
Radiated disturbance below 1 GHz	30MHz ~ 1GHz	±6.1 dB
Radiated disturbance above 1 GHz	1GHz ~ 40GHz	±5.1 dB

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 8 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

# 6. Equipment under Test

# **6.1. Description of EUT**

Product	Wireless Headset
Brand Name	DELL
Model Name	HS2404
Operating Frequency	2402MHz ~ 2480MHz
Modulation	GFSK, π/4-DQPSK and 8DPSK
Transfer Rate Up to 3 Mbps	
Number of Channel	79
Maximum Output Power	10.69 dBm
Normal Voltage	5Vdc from host 3.7Vdc from battery
Sample ID	Conducted Test: 6284801 Radiated Test: 6284801

#### Note:

1. The EUT contains following accessory devices:

==== = = = = = ===== = ==== = = = = = =								
Product	Brand	Model	Description					
Charging cable	LUXSHARE	P0551	1.5 m					
USB-C adapter	DELL	UD2403	N/A					

2. The EUT could be supplied with rechargeable battery as the following table:

Brand Name	Model	Description	
Hangzhou Future Power	FT573439P	3.7Vdc, 750 mAh	

3. The above EUT information is declared by manufacturer and for more detailed features description, please refer the manufacturer's or user's manual, the laboratory shall not be held responsible.

#### Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 9 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

# **6.2. Channel List**

79 channels are provided for BT-EDR mode:

Channel	Frequency (MHz)						
0	2402	20	2422	40	2442	60	2462
1	2403	21	2423	41	2443	61	2463
2	2404	22	2424	42	2444	62	2464
3	2405	23	2425	43	2445	63	2465
4	2406	24	2426	44	2446	64	2466
5	2407	25	2427	45	2447	65	2467
6	2408	26	2428	46	2448	66	2468
7	2409	27	2429	47	2449	67	2469
8	2410	28	2430	48	2450	68	2470
9	2411	29	2431	49	2451	69	2471
10	2412	30	2432	50	2452	70	2472
11	2413	31	2433	51	2453	71	2473
12	2414	32	2434	52	2454	72	2474
13	2415	33	2435	53	2455	73	2475
14	2416	34	2436	54	2456	74	2476
15	2417	35	2437	55	2457	75	2477
16	2418	36	2438	56	2458	76	2478
17	2419	37	2439	57	2459	77	2479
18	2420	38	2440	58	2460	78	2480
19	2421	39	2441	59	2461	-	-

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 10 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

#### 6.3. Test Condition

Test Item	Test Site No.	Environmental Condition	Input Power	Test Date	Tested by
Antenna Port Conducted Measurement	SR4	23~26°C/ 63~66%RH	5Vdc form host	2023/07/25~ 2023/07/25	Jubo Shen
Radiated Spurious Emission	966-2	22~24°C/ 62~64%RH	5Vdc form host	2023/07/26~ 2023/07/27	Jubo Shen
AC power Line Conducted Emission	SR1	23~26°C/ 59~63%RH	5Vdc form host	2023/07/27~ 2023/07/27	Jubo Shen

FCC Test Firm Registration Number: 498077

#### **Sample Calculation:**

#### **Antenna Port Conducted Measurement:**

- Where relevant, the follow sample calculation is provided:

Result Value (dBm) = Reading Value (dBm) + Attenuator Factor (dB) + Cable Loss (dB).

Example: Result Value (10dBm) = Reading Value (-2dBm) +Attenuator Factor (10dB) + Cable Loss(2dB).

\*Test plot only shown the "Result Value".

#### Radiated Spurious Emission:

- Where relevant, the follow sample calculation is provided:

Result Value (dBuV/m) = Reading Value (dBuV) + Correction Factor (dB/m).

 $Correction\ Factor\ (dB/m) = Antenna\ Factor\ (dB/m) + Cable\ Loss\ (dB)\ -\ Preamp\ Factor\ (dB).$ 

Example: Result Value (34.5dBuV/m) = Reading Value (40.1dBuV) + Antenna Factor (18.7dB/m)

+ Cable Loss (4.2dB) - Preamp Factor (28.5dB).

#### AC power Line Conducted Emission:

- Where relevant, the follow sample calculation is provided:

Result Value (dBuV) = Reading Value (dBuV) + Correction Factor (dB).

Correction Factor (dB) = Insertion loss(dB) + Cable loss(dB).

Example: Result Value (53.7 dBuV) = Reading Value (35.1 dBuV) + Insertion loss(18.1 dB) + Cable loss(0.5 dB).

#### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 11 of 61
Issued date : 2023/8/11
FCC ID : 2AYYS-HS2404

# 6.4. Description of Available Antennas

Ant. No.	Transmitter Circuit	Brand Name	Model Name	Ant. Type	Maximum Gain (dBi)
1	Chain (0)	Top-link	240000945	Monopole Antenna	1.95

Note: The above antenna information was provided from customer and for more detailed features description, please refer the manufacturer's specification or user's manual, the laboratory shall not be held responsible.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 12 of 61
Issued date : 2023/8/11
FCC ID : 2AYYS-HS2404

# 6.5. Test Mode Applicability and Tested Channel Detail

- The fundamental of the EUT was investigated in three orthogonal axes X-Y/Y-Z/X-Z, it was determined that Y-Z plane was worst-case. Therefore, all final radiated testing was performed with the EUT in Y-Z plane.

- The EUT with three power source types: 3.7Vdc from the battery, 5Vdc from the host, and 5Vdc from the adapter, above three types were pre-tested, and the worst case was found in the 5Vdc from the host. Therefore only the test data of the 5Vdc from the host was recorded in this report.
- The Packet Type for DH1, DH3, and DH5 have all been pre-tested, the fundamental worst case of the Packet Type was found in the DH5. Therefore, only DH5 Packet Type is recorded in the report. (Except Dwell Time).
- The modulation and bandwidth are similar for  $\pi/4$ -DQPSK mode and 8DPSK mode, therefore investigated 8DPSK mode to representative mode in test report.
- For Antenna Port Conducted Measurement, this item includes all test value of each mode, but only includes spectrum plot of worst value of each mode.
- For below 30MHz testing, investigation was done on three antenna orientations (parallel, perpendicular, and ground-parallel), parallel and perpendicular are the worst orientations, therefore testing was performed on these two orientations only.
- For below 1 GHz radiated emission and AC power line conducted emission have performed all modes of operation were investigated and the worst-case emissions are reported.
- Pre-Scan has been conducted to determine the worst-case mode from all possible combinations between available modulations, data rates and antenna ports (if EUT with antenna diversity architecture).
- Since the DUT is a Bluetooth device, the AFH mode and non-AFH mode follow the Bluetooth timing protocol, and the same timing level has the same time interval, but the non-AFH mode has worse results, therefore only the test data of this type were recorded in this report.
- For charging mode, only the radiated emission below 1GHz, and AC power line conducted emission was evaluated.

Test Item	Modulation Type	Available Channel	Test Channel	Packet Type
Radiated Emissions	GFSK	0 to 78	0,39,78	DH5
(Above 1GHz)	8DPSK	0 to 78	0,39,78	3DH5
Radiated Emissions (Below 1GHz)	8DPSK	0 to 78	39	3DH5
AC Power Line Conducted Emission	8DPSK	0 to 78	39	3DH5
	GFSK	0 to 78	0,39,78	DH1*,DH3*,DH5
Antenna Port Conducted Measurement	8DPSK	0 to 78	0,39,78	3DH1*,3DH3*, 3DH5

<sup>\*</sup> Only for Dwell Time on Each Channel test

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 13 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

# 6.6. Duty cycle

Mode	On Time (ms)	On+Off Time (ms)	<b>Duty Cycle</b>	Duty Factor (dB)	VBW Set (above 1GHz)
GFSK(DH5)	2.850	3.745	0.7610	1.19	510Hz
8DPSK(3DH5)	2.885	3.760	0.7673	1.15	510Hz



Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 14 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

# 7. Test Equipment

	Test Equipment List						
Equipment	Manufacturer	Model No.	Serial No.	Cal. Date	Expired date		
Radiated Spurious Emission							
Spectrum Analyzer	Keysight	N9010A	MY56070827	2023/4/7	2024/4/6		
EMI Test Receiver	Rohde & Schwarz	ESR7	101754	2022/12/13	2023/12/12		
Loop Antenna	ETS lindgren	6502	00213440	2023/1/4	2024/1/3		
Trilog- Broadband Antenna with 5dB Attenuator	Schwarzbeck & EMCI	VULB 9168 & N-6-05	774 & AT- N0538	2023/2/13	2024/2/12		
Horn Antenna (1-18 GHz)	Schwarzbeck	BBHA 9120 D	01690	2022/12/21	2023/12/20		
Horn Antenna (18-40 GHz)	Schwarzbeck	BBHA 9170	781	2022/12/30	2023/12/29		
Preamplifier (30-1000 MHz)	EMCI	EMC330E	980405	2023/6/7	2024/6/6		
Preamplifier (1-18 GHz)	EMCI	EMC051835BE	980406	2023/2/17	2024/2/16		
Preamplifier (18-40GHz)	EMCI	EMC184040SEE	980426	2023/5/9	2024/5/8		
Cables	Hanyitek	K1K50-UP0264- K1K50-2500	170214-4 & 170425-2	2022/12/1	2023/11/30		
Cables	Hanyitek	K1K50-UP0264- K1K50-2500	170214-1 & 170214-2	2022/12/1	2023/11/30		

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 15 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

Test Equipment List						
Equipment	Manufacturer	Model No.	Serial No.	Cal. Date	Expired date	
Antenna Port Conducted Measurement						
Spectrum Analyzer	Rohde & Schwarz	FSV40	101490	2022/9/12	2023/9/11	
Attenuator	EMCI	EMC- 40ATK2W10	17002	2022/12/9	2023/12/8	
Pulse Power Sensor	Anritsu	MA2411B	1531202	2023/1/4	2024/1/3	
Power Meter	Anritsu	ML2495A	1645002	2023/1/4	2024/1/3	
	AC po	wer Line Con	ducted Emission			
EMI Test Receiver	Rohde & Schwarz	ESR7	101753	2022/11/10	2023/11/9	
Two-Line V- Network	Rohde & Schwarz	ENV216	102136	2023/5/24	2024/5/23	
Impuls-Begrenzer Pulse Limiter	Rohde & Schwarz	ESH3-Z2	102219-Qt	2022/8/30	2023/8/29	
Cables	TITAN	CFD200	T0732ACFD200 20A300-2	2023/5/23	2024/5/22	

UL Software					
Description Name Version					
Radiated measurement	e3	6.191211 (V6)			
Conducted measurement	RF-Conducted-FCC 15247	ver 1.0			
AC power Line Conducted Emission	EZ_EMC	UL-3A1.2			

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 16 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

# 8. Description of Test Setup

# **Support Equipment**

ID	Equipment	<b>Brand Name</b>	Model Name	S/N	Remark
Α	Laptop	DELL	Latitude E5470	CXSKWF2	Provide by Lab

## **I/O Cables**

ID	Equipment	Brand Name	Model Name	Length (m)	Remark
1	Charging Cable	LUXSHARE	P0551	1.5	Supplied by client

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948




Page : 17 of 61
Issued date : 2023/8/11
FCC ID : 2AYYS-HS2404

## **Test Setup**

Controlled using a bespoke application (Airoha Tool Kit – V3.4.4) on a test Notebook. The application was used to enable a continuous transmission mode and to select the test channels, data rates, modulation schemes and power setting as required.

## **Setup Diagram for Test**



Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 18 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

# 9. Test Results

#### 9.1. Channel Bandwidth

#### **Requirements**

For frequency hopping system operating in the 2400-2483.5MHz, If the 20dB bandwidth of hopping channel is greater than 25kHz, two-thirds 20dBbandwidth of hopping channel shall be a minimum limit for the hopping channel separation.

#### **Test procedure**

- a. Check the calibration of the measuring instrument using either an internal calibrator or a known signal from an external generator.
- b. Turn on the EUT and connect it to measurement instrument. Then set it to any one convenient frequency within its operating range. Set a reference level on the measuring instrument equal to the highest peak value.
- c. Measure the frequency difference of two frequencies that were attenuated 20dB from the reference level. Record the frequency difference as the emission bandwidth.
- d. Repeat above procedures until all frequencies measured were complete.

#### **Test Setup**



The loss between RF output port of the EUT and the input port of the Spectrum Analyzer has been taken into consideration.

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 19 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

# **Test Data**


Mode	СН	Freq (MHz)	20dB BW (MHz)	Limit (MHz)	Result
GFSK(DH5)	0	2402	0.957	N/A	Pass
GFSK(DH5)	39	2441	0.956	N/A	Pass
GFSK(DH5)	78	2480	0.957	N/A	Pass
8DPSK(3DH5)	0	2402	1.274	N/A	Pass
8DPSK(3DH5)	39	2441	1.276	N/A	Pass
8DPSK(3DH5)	78	2480	1.275	N/A	Pass

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 20 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404



#### Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 21 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

# 9.2. Conducted Output Power


## **Requirements**

The Maximum Output Power Measurement is 125mW.

## **Test Procedure**

A peak power sensor was used on the output port of the EUT. A power meter was used to read the response of the peak power sensor. Record the power level.

# **Test Setup**



The loss between RF output port of the EUT and the input port of the Power Meter has been taken into consideration.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 22 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

# **Test Data**

#### **Peak Power**

#### **BT GFSK**

Channel	Frequency (MHz)	Peak Power (mW)	Peak Power (dBm)	Limit (dBm)	Pass/Fail
0	2402	6.792	8.32	20.97	PASS
39	2441	6.982	8.44	20.97	PASS
78	2480	6.934	8.41	20.97	PASS

#### **BT 8DPSK**

Channel	Frequency (MHz)	Peak Power (mW)	Peak Power (dBm)	Limit (dBm)	Pass/Fail
0	2402	11.429	10.58	20.97	PASS
39	2441	11.722	10.69	20.97	PASS
78	2480	11.324	10.54	20.97	PASS

# **Average Power (Reference Only)**

## **BT GFSK**

Channel	Frequency (MHz)	Average Power (mW)	Average Power (dBm)
0	2402	6.501	8.13
39	2441	6.683	8.25
78	2480	6.653	8.23

#### **BT 8DPSK**

Channel	Frequency (MHz)	Average Power (mW)	Average Power (dBm)
0	2402	6.966	8.43
39	2441	7.079	8.50
78	2480	6.95	8.42

# Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 23 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

# 9.3. Hopping Channel Separation


## **Requirements**

At least 25kHz or two-third of 20dB hopping channel bandwidth (whichever is greater).

## **Test procedure**

- a. Check the calibration of the measuring instrument using either an internal calibrator or a known signal from an external generator.
- b. Turn on the EUT and connect it to measurement instrument. Then set it to any one convenient frequency within its operating range.
- c. By using the MaxHold function record the separation of two adjacent channels.
- d. Measure the frequency difference of these two adjacent channels by SA MARK function. And then plot the result on SA screen.

#### **Test Setup**



The loss between RF output port of the EUT and the input port of the Spectrum Analyzer has been taken into consideration.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 24 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

# **Test Data**


Mode	СН	Freq (MHz)	Channel Separation (MHz)	> Limit (MHz)
GFSK(DH5)	0	2402	0.997	0.638
GFSK(DH5)	39	2441	1.006	0.637
GFSK(DH5)	78	2480	1	0.638
8DPSK(3DH5)	0	2402	1	0.849
8DPSK(3DH5)	39	2441	0.999	0.851
8DPSK(3DH5)	78	2480	1.003	0.85

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 25 of 61
Issued date : 2023/8/11
FCC ID : 2AYYS-HS2404



#### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 26 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

# 9.4. Number of Hopping Frequency Used

#### **Requirements**

At least 15 channels frequencies, and should be equally spaced.

#### Test procedure

- a. Check the calibration of the measuring instrument (SA) using either an internal calibrator or a known signal from an external generator.
- b. Turn on the EUT and connect its antenna terminal to measurement via a low loss cable. Then set it to any one measured frequency within its operating range and make sure the instrument is operated in its linear range.
- c. Set the SA on MaxHold Mode, and then keep the EUT in hopping mode. Record all the signals from each channel until each one has been recorded.
- d. Set the SA on View mode and then plot the result on SA screen.
- e. Repeat above procedures until all frequencies measured were complete.

#### **Test Setup**



The loss between RF output port of the EUT and the input port of the Spectrum Analyzer has been taken into consideration.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 27 of 61
Issued date : 2023/8/11
FCC ID : 2AYYS-HS2404

## **Test Data**

There are 79 hopping frequencies in the hopping mode. On the plots, it shows that the hopping frequencies are equally spaced.



Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 28 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

#### 9.5. Dwell Time on Each Channel

#### **Requirements**

The average time of occupancy on any channel shall not be greater than 0.4 seconds within a period of 0.4 seconds multiplied by the number of hopping channels employed.

## **Test procedure**

- a. Check the calibration of the measuring instrument (SA) using either an internal calibrator or a known signal from an external generator.
- b. Turn on the EUT and connect its antenna terminal to measurement via a low loss cable. Then set it to any one measured frequency within its operating range and make sure the instrument is operated in its linear range.
- c. Adjust the center frequency of SA on any frequency be measured and set SA to zero span mode. And then, set RBW and VBW of spectrum analyzer to proper value.
- d. Measure the time duration of one transmission on the measured frequency. And then plot the result with time difference of this time duration.
- e. Repeat above procedures until all different time-slot modes have been completed.
- f. Measure the maximum time duration of one single pulse.

A Period Time = (channel number)\*0.4

For normal mode:

DH1 Time Slot: Reading \* (1600/2)\*31.6/(channel number)

DH3 Time Slot: Reading \* (1600/4)\*31.6/(channel number)

DH5 Time Slot: Reading \* (1600/6)\*31.6/(channel number)

For AFH mode:

DH1 Time Slot: Reading \* (800/2)\*31.6/(channel number)

DH3 Time Slot: Reading \* (800/4)\*31.6/(channel number)

DH5 Time Slot: Reading \* (800/6)\*31.6/(channel number)

#### **Test Setup**



The loss between RF output port of the EUT and the input port of the Spectrum Analyzer has been taken into consideration.

#### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 29 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

# **Test Data**


Mode	Freq (MHz)	Length of transmission time (ms)	Dwell Time (ms)	Limit (ms)	Result
GFSK(DH1)	2441	0.365	116.800	400	PASS
GFSK(DH3)	2441	1.620	259.200	400	PASS
GFSK(DH5)	2441	2.875	306.667	400	PASS
8DPSK(3DH1)	2441	0.375	120.000	400	PASS
8DPSK(3DH3)	2441	1.620	259.200	400	PASS
8DPSK(3DH5)	2441	2.870	306.133	400	PASS

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 30 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404



#### Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 31 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

#### 9.6. Conducted Out of Band Emission

#### **Requirements**

In any 100 kHz bandwidth outside the frequency band in which the spread spectrum or digitally modulated intentional radiator is operating, the radio frequency power that is produced by the intentional radiator shall be at least 20 dB below that in the 100 kHz bandwidth within the band that contains the highest level of the desired power, based on either an RF conducted or a radiated measurement, provided the transmitter demonstrates compliance with the peak conducted power limits. If the transmitter complies with the conducted power limits based on the use of RMS averaging over a time interval, as permitted under paragraph (b) (3) of this section, the attenuation required under this paragraph shall be 30 dB instead of 20 dB. Attenuation below the general limits specified in §15.209 (a) is not required.

#### Test procedure

The transmitter output was connected to the spectrum analyzer via a low lose cable. Set both RBW and VBW of spectrum analyzer to 100 kHz and 300 kHz with suitable frequency span including 100 MHz bandwidth from band edge. The band edges was measured and recorded.

# **Test Setup**



The loss between RF output port of the EUT and the input port of the Spectrum Analyzer has been taken into consideration.


Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 32 of 61
Issued date : 2023/8/11
FCC ID : 2AYYS-HS2404

#### **Test Data**




#### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 33 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404




#### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 34 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404




#### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 35 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404



#### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 36 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

# 9.7. Radiated Spurious Emission

# **Requirements**

Radiated emissions which fall in the restricted bands must comply with the radiated emission limits specified as below table. Other emissions shall be at least 20dB below the highest level of the desired power:

Frequency (MHz)	Field strength (microvolts/meter)	Measurement distance (meters)	
0.009-0.490	2400/F(kHz)	300	
0.490-1.705	24000/F(kHz)	30	
1.705-30.0	30	30	
30-88	100	3	
88-216	150	3	
216-960	200	3	
Above 960	500	3	

#### NOTE:

- 1. The lower limit shall apply at the transition frequencies.
- 2. Emission level  $(dBuV/m) = 20 \log Emission level (uV/m)$ .
- 3. For frequencies above 1000MHz, the field strength limits are based on average detector, however, the peak field strength of any emission shall not exceed the maximum permitted average limits, specified above by more than 20dB under any condition of modulation.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 37 of 61
Issued date : 2023/8/11
FCC ID : 2AYYS-HS2404

### **Test Procedures**

[For  $9 \text{ kHz} \sim 30 \text{ MHz}$ ]

- a. The EUT was placed on the top of a rotating table 0.8 meters above the ground at a 3 meter chamber room. The table was rotated 360 degrees to determine the position of the highest radiation
- b. The EUT was set 3 meters away from the interference-receiving antenna, which was mounted on the top of a variable-height antenna tower.
- c. Parallel, perpendicular, and ground-parallel orientations of the antenna are set to make the measurement.
- d. For each suspected emission, the EUT was arranged to its worst case and the rotatable table was turned from 0 degrees to 360 degrees to find the maximum reading.
- e. For measurement below 30MHz, the initial step in collecting conducted emission data is a spectrum analyzer peak detector mode pre-scanning the measurement frequency range. Significant peaks are then marked and then Quasi Peak detector mode re-measured. If the emission level of the EUT measured by the peak detector is lower than the applicable limit, the peak emission level will be reported. Otherwise, the emission measurement will be repeated using the quasi-peak detector and reported.

#### NOTE:

1. The resolution bandwidth and video bandwidth of test receiver/spectrum analyzer is 9kHz at frequency below 30MHz.

#### [For above 30 MHz]

- a. The EUT was placed on the top of a rotating table 0.8 meters (for 30MHz ~ 1GHz) / 1.5 meters (for above 1GHz) above the ground at 3 meter chamber room for test. The table was rotated 360 degrees to determine the position of the highest radiation.
- b. The EUT was set 3 meters away from the interference-receiving antenna, which was mounted on the top of a variable-height antenna tower.
- c. The height of antenna is varied from one meter to four meters above the ground to determine the maximum value of the field strength. Both horizontal and vertical polarizations of the antenna are set to make the measurement.
- d. For each suspected emission, the EUT was arranged to its worst case and then the antenna was tuned to heights from 1 meter to 4 meters and the rotatable table was turned from 0 degrees to 360 degrees to find the maximum reading.
- e. For measurement below 1GHz, the initial step in collecting conducted emission data is a spectrum analyzer peak detector mode pre-scanning the measurement frequency range. Significant peaks are then marked and then Quasi Peak detector mode re-measured. If the emission level of the EUT measured by the peak detector is lower than the applicable limit, the peak emission level will be reported. Otherwise, the emission measurement will be repeated using the quasi-peak detector and reported.
- f. The test-receiver system was set to peak and average detects function and specified bandwidth with maximum hold mode when the test frequency is above 1 GHz. If the peak reading value also meets average limit, measurement with the average detector is unnecessary.

#### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 38 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

#### Note:

1. The resolution bandwidth and video bandwidth of test receiver/spectrum analyzer is 120kHz for Quasi-peak detection (QP) at frequency below 1GHz.

- 2. The resolution bandwidth of test receiver/spectrum analyzer is 1 MHz and the video bandwidth is 3 MHz for Peak detection (PK) at frequency above 1GHz.
- 3. The resolution bandwidth of test receiver/spectrum analyzer is 1MHz and the video bandwidth is ≥ 1/T (Duty cycle < 98%) or 10Hz (Duty cycle ≥ 98%) for Average detection (AV) at frequency above 1GHz.

Carfiannation	Average				
Configuration	RBW	VBW			
Bluetooth	1MHz	Refer to section 6.6 for duty cycle.			

- 4. All modes of operation were investigated (includes all external accessories) and the worst-case emissions are reported, the other emission levels were low against the limit.
- 5. Test data of Result value (dBuV/m) = Reading value (dBuV/m) + Correction Factor (dB/m).
- 6. Test data of Margin(dB) = Result value (dBuV/m) Limit value (dBuV/m).
- 7. Test data of Correction Factor (dB/m) = Antenna Factor (dB/m) + Cable Loss (dB) Preamp Factor (dB).
- 8. Test data of Notation "@" = Fundamental Frequency
- 9. Test data of Notation " \* " = The peak result under 20 dB above and complies with AVG limit, AVG result is deemed to comply with AVG limit.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948




Page : 39 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

## **Test Setup**

<Frequency Range 9 kHz ~ 30 MHz>



<Frequency Range 30 MHz ~ 1 GHz >



## Underwriters Laboratories Taiwan Co., Ltd.


Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 40 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

## <Frequency Range above 1 GHz>



For the actual test configuration, please refer to the Setup Configurations.

## Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 41 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

# **Test Data**

## **Above 1 GHz**

Mode GFSK	Channel	0
-----------	---------	---


Dalawiastian	Notation	Frequency	Reading	Correct	Result	Limit	Margin	Damanlı
Polarization	Notation	(MHz)	(dBuV)	(dB/m)	(dBuV/m)	(dBuV/m)	(dB)	Remark
		2330.33	42.12	11.96	54.08	74	-19.92	PK
		2336.41	30.77	11.96	42.73	54	-11.27	AVG
Horizontal	@	2402	93.43	11.85	105.28	N/A	N/A	PK
	@	2402	93.3	11.85	105.15	N/A	N/A	AVG
	*	4804	43.91	2.14	46.05	74	-27.95	PK
		2364.15	41.66	11.91	53.57	74	-20.43	PK
		2382.58	31.25	11.88	43.13	54	-10.87	AVG
Vertical	@	2402	91.42	11.85	103.27	N/A	N/A	PK
	@	2402	91.29	11.85	103.14	N/A	N/A	AVG
	*	4804	43.37	2.14	45.51	74	-28.49	PK

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 42 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404



Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 43 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

Mode GFSK Channel 39


D.1	Madadian	Frequency	Reading	Correct	Result	Limit	Margin	D 1
Polarization	Notation	(MHz)	(dBuV)	(dB/m)	(dBuV/m)	(dBuV/m)	(dB)	Remark
		2333.18	41.96	11.95	53.91	74	-20.09	PK
		2354.46	30.6	11.94	42.54	54	-11.46	AVG
	@	2441	89.61	11.99	101.6	N/A	N/A	PK
Horizontal	@	2441	89.31	11.99	101.3	N/A	N/A	AVG
Horizoniai		2485.37	40.89	11.8	52.69	74	-21.31	PK
		2498.67	30.75	11.72	42.47	54	-11.53	AVG
	*	4882	40.38	2.21	42.59	74	-31.41	PK
	*	7323	33.31	10.26	43.57	74	-30.43	PK
		2321.21	30.75	11.96	42.71	54	-11.29	AVG
		2327.29	41.62	11.96	53.58	74	-20.42	PK
	@	2441	91.53	11.99	103.52	N/A	N/A	PK
Vertical	@	2441	91.35	11.99	103.34	N/A	N/A	AVG
verticai		2492.21	30.79	11.76	42.55	54	-11.45	AVG
		2493.54	41.53	11.75	53.28	74	-20.72	PK
	*	4882	39.46	2.21	41.67	74	-32.33	PK
	*	7323	33.25	10.26	43.51	74	-30.49	PK

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 44 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404



Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 45 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

Mode GFSK Channel 78


Dolomization	Matation	Frequency	Reading	Correct	Result	Limit	Margin	Damadr
Polarization	Notation	(MHz)	(dBuV)	(dB/m)	(dBuV/m)	(dBuV/m)	(dB)	Remark
	@	2480	89.11	11.83	100.94	N/A	N/A	PK
	@	2480	88.75	11.83	100.58	N/A	N/A	AVG
Horizontal		2484.8	30.79	11.8	42.59	54	-11.41	AVG
Поптенна		2498.86	40.29	11.72	52.01	74	-21.99	PK
	*	4960	36.62	2.3	38.92	74	-35.08	PK
	*	7440	33.65	10.69	44.34	74	-29.66	PK
	@	2480	88.02	11.83	99.85	N/A	N/A	PK
	@	2480	87.92	11.83	99.75	N/A	N/A	AVG
Vertical		2488.03	30.58	11.79	42.37	54	-11.63	AVG
vertical		2496.01	41.36	11.73	53.09	74	-20.91	PK
	*	4960	39.02	2.3	41.32	74	-32.68	PK
	*	7440	32.58	10.69	43.27	74	-30.73	PK

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 46 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404



## Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 47 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

Mode 8DPSK	Channel	0
------------	---------	---


Dolomization	Notation	Frequency	Reading	Correct	Result	Limit	Margin	Damanla
Polarization	Notation	(MHz)	(dBuV)	(dB/m)	(dBuV/m)	(dBuV/m)	(dB)	Remark
		2384.48	41.5	11.87	53.37	74	-20.63	PK
		2389.61	31.86	11.86	43.72	54	-10.28	AVG
Horizontal	@	2402	92.74	11.85	104.59	N/A	N/A	AVG
	@	2402	93.03	11.85	104.88	N/A	N/A	PK
	*	4804	42.57	2.14	44.71	74	-29.29	PK
		2364.72	41.62	11.91	53.53	74	-20.47	PK
		2366.05	30.69	11.92	42.61	54	-11.39	AVG
Vertical	@	2402	90.59	11.85	102.44	N/A	N/A	PK
	@	2402	90.33	11.85	102.18	N/A	N/A	AVG
	*	4804	39.54	2.14	41.68	74	-32.32	PK

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 48 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404



Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 49 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

Mode 8DPSK	Channel 39	
------------	------------	--


Dolomization	Notation	Frequency	Reading	Correct	Result	Limit	Margin	Damadr
Polarization	Notation	(MHz)	(dBuV)	(dB/m)	(dBuV/m)	(dBuV/m)	(dB)	Remark
		2338.5	41.76	11.95	53.71	74	-20.29	PK
		2349.9	30.9	11.95	42.85	54	-11.15	AVG
	@	2441	88.76	11.99	100.75	N/A	N/A	PK
Horizontal	@	2441	88.15	11.99	100.14	N/A	N/A	AVG
Horizoniai		2489.17	30.6	11.78	42.38	54	-11.62	AVG
		2491.83	42.11	11.76	53.87	74	-20.13	PK
	*	4882	38.78	2.21	40.99	74	-33.01	PK
	*	7323	33.01	10.26	43.27	74	-30.73	PK
		2359.4	41.31	11.93	53.24	74	-20.76	PK
		2370.23	30.9	11.9	42.8	54	-11.2	AVG
	@	2441	90.7	11.99	102.69	N/A	N/A	PK
Vertical	@	2441	88.62	11.99	100.61	N/A	N/A	AVG
verticai		2485.75	40.88	11.79	52.67	74	-21.33	PK
		2496.2	30.66	11.73	42.39	54	-11.61	AVG
	*	4882	36.94	2.21	39.15	74	-34.85	PK
	*	7323	33.77	10.26	44.03	74	-29.97	PK

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 50 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404



Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 51 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

Mode 8DPSK	Channel	78
------------	---------	----


Dolomization	Matation	Frequency	Reading	Correct	Result	Limit	Margin	Damanla
Polarization	Notation	(MHz)	(dBuV)	(dB/m)	(dBuV/m)	(dBuV/m)	(dB)	Remark
	@	2480	88.26	11.83	100.09	N/A	N/A	AVG
	@	2480	88.47	11.83	100.3	N/A	N/A	PK
Horizontal		2483.66	45.92	11.81	57.73	74	-16.27	PK
Horizoniai		2483.66	34.02	11.81	45.83	54	-8.17	AVG
	*	4960	37.62	2.3	39.92	74	-34.08	PK
	*	7440	32.54	10.69	43.23	74	-30.77	PK
	@	2480	87.75	11.83	99.58	N/A	N/A	PK
	@	2480	86.83	11.83	98.66	N/A	N/A	AVG
Vertical		2483.66	33.17	11.81	44.98	54	-9.02	AVG
vertical		2483.85	43.46	11.81	55.27	74	-18.73	PK
	*	4960	39.19	2.3	41.49	74	-32.51	PK
	*	7440	32.79	10.69	43.48	74	-30.52	PK

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 52 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404



Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 53 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

## **Below 1 GHz**

Polarization	Notation	Frequency	Reading	Correct	Result	Limit	Margin	Remark
Polarization	Notation	(MHz)	(dBuV)	(dB/m)	(dBuV/m)	(dBuV/m)	(dB)	Kemark
		33.88	38.09	-14.78	23.31	40	-16.69	PK
		98.87	45.44	-16.76	28.68	43.5	-14.82	PK
Horizontal		144.46	40.37	-12.26	28.11	43.5	-15.39	PK
Horizontai		175.5	42.01	-12.42	29.59	43.5	-13.91	PK
		241.46	46.4	-12.7	33.7	46	-12.3	PK
		349.13	36.49	-9.34	27.15	46	-18.85	PK
		30.97	47.28	-14.53	32.75	40	-7.25	PK
		94.99	45.75	-17.53	28.22	43.5	-15.28	PK
Vertical		181.32	40.77	-13.23	27.54	43.5	-15.96	PK
vertical		230.79	38.91	-13.75	25.16	46	-20.84	PK
		309.36	36.59	-10.4	26.19	46	-19.81	PK
		364.65	37.26	-8.96	28.3	46	-17.7	PK



Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948




Page : 54 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

# **Charging mode**

## **Below 1 GHz**

Mode Charging Mode	Channel	N/A
--------------------	---------	-----

Dolomization	Notation	Frequency	Reading	Correct	Result	Limit	Margin	Damanlı
Polarization	@	(MHz)	(dBuV)	(dB/m)	(dBuV/m)	(dBuV/m)	(dB)	Remark
		96.93	40.83	-17.04	23.79	43.5	-19.71	PK
		176.47	40.2	-12.51	27.69	43.5	-15.81	PK
Horizontal		230.79	41.05	-13.75	27.3	46	-18.7	PK
Horizontai		323.91	34.73	-9.75	24.98	46	-21.02	PK
		600.36	31.05	-2.38	28.67	46	-17.33	PK
		756.53	31.58	0.69	32.27	46	-13.73	PK
		53.28	39.4	-11.72	27.68	40	-12.32	PK
		62.01	38.31	-12.49	25.82	40	-14.18	PK
Vantical		323.91	35.31	-9.75	25.56	46	-20.44	PK
Vertical		652.74	31.29	-1.6	29.69	46	-16.31	PK
		847.71	31.54	1.8	33.34	46	-12.66	PK
		928.22	30.98	3.02	34	46	-12	PK



Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 55 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

#### 9 kHz ~ 30 MHz Data:

For 9 kHz to 30 MHz radiated emission have performed all modes of operation were investigated. The amplitude of spurious emissions attenuated more than 20 dB below the permissible value is not required to be report.

No non-compliance noted:

#### KDB 414788 D01 OATS and Chamber Correlation Justification

- Base on FCC 15.31 (f) (2): measurements may be performed at a distance closer than that specified in the regulations; however, an attempt should be made to avoid making measurements in the near field.
- OATs and chamber correlation testing had been performed and chamber measured test results is the worst case test result.

Although these tests were performed other than open area test site, adequate comparison measurements were confirmed against 30m open area test site. Therefore sufficient tests were made to demonstrate that the alternative site produces results that correlate with the ones of tests made in an open field based on KDB 414788.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 56 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

## 9.8. AC Power Line Conducted Emission

## **Requirements**

Fraguency (MUz)	Conducted limit (dBµV)				
Frequency (MHz)	Quasi-peak	Average			
0.15 - 0.5	66 - 56	56 - 46			
0.50 - 5.0	56	46			
5.0 - 30	60	50			

#### Note:

- 1. The lower limit shall apply at the transition frequencies.
- 2. The limit decreases in line with the logarithm of the frequency in the range of 0.15 to 0.50MHz.

### **Test Procedures**

- a. The EUT was placed 0.4 meters from the conducting wall of the shielded room with EUT being connected to the power mains through a line impedance stabilization network (LISN). Other support units were connected to the power mains through another LISN. The two LISNs provide 50 ohm/ 50uH of coupling impedance for the measuring instrument.
- b. Both lines of the power mains connected to the EUT were checked for maximum conducted interference.
- c. The frequency range from 150kHz to 30MHz was searched. Emission levels under (Limit 20dB) was not recorded.

#### NOTE:

- 1. The resolution bandwidth and video bandwidth of test receiver is 9kHz for quasi-peak detection (QP) and average detection (AV) at frequency 0.15MHz-30MHz.
- 2. All modes of operation were investigated (includes all external accessories) and the worst-case emissions are reported, the other emission levels were low against the limit.
- 3. Test data of Result value (dBuV) = Reading value (dBuV) + Correction Factor (dB).
- 4. Test data of Margin(dB) = Result value (dBuV) Limit value (dBuV).
- 5. Test data of Correction Factor (dB) = Insertion loss(dB) + Cable loss(dB).


Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 57 of 61
Issued date : 2023/8/11
FCC ID : 2AYYS-HS2404

## **Test Setup**



Note: 1.Support units were connected to second LISN.

For the actual test configuration, please refer to the Setup Configurations.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 58 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

## **Test Data**





No.	Frequency	Reading	Correct	Result	Limit	Margin	Remark
NO.	(MHz)	(dBuV)	(dB)	(dBuV)	(dBuV)	(dB)	Remark
1	0.1490	9.88	0.08	9.96	66.06	-56.10	QP
2	0.1490	6.10	0.08	6.18	56.06	-49.88	AVG
3	0.4576	34.48	0.07	34.55	56.74	-22.19	QP
4	0.4576	28.69	0.07	28.76	46.74	-17.98	AVG
5	1.5778	22.09	0.09	22.18	56.00	-33.82	QP
6	1.5778	15.20	0.09	15.29	46.00	-30.71	AVG
7	1.9177	23.48	0.10	23.58	56.00	-32.42	QP
8	1.9177	17.21	0.10	17.31	46.00	-28.69	AVG
9	2.2843	25.56	0.10	25.66	56.00	-30.34	QP
10	2.2843	19.20	0.10	19.30	46.00	-26.70	AVG
11	4.2800	21.95	0.13	22.08	56.00	-33.92	QP
12	4.2800	16.46	0.13	16.59	46.00	-29.41	AVG


Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 59 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

Mode	3DH5_TX	Channel	39
------	---------	---------	----



No.	Frequency	Reading	Correct	Result	Limit	Margin	Domonis
	(MHz)	(dBuV)	(dB)	(dBuV)	(dBuV)	(dB)	Remark
1	0.4775	34.47	0.06	34.53	56.38	-21.85	QP
2	0.4775	27.07	0.06	27.13	46.38	-19.25	AVG
3	0.6574	19.86	0.06	19.92	56.00	-36.08	QP
4	0.6574	12.65	0.06	12.71	46.00	-33.29	AVG
5	1.0021	24.56	0.07	24.63	56.00	-31.37	QP
6	1.0021	18.02	0.07	18.09	46.00	-27.91	AVG
7	1.9360	25.33	0.09	25.42	56.00	-30.58	QP
8	1.9360	19.49	0.09	19.58	46.00	-26.42	AVG
9	2.7091	24.15	0.10	24.25	56.00	-31.75	QP
10	2.7091	17.66	0.10	17.76	46.00	-28.24	AVG
11	4.8007	22.53	0.14	22.67	56.00	-33.33	QP
12	4.8007	17.08	0.14	17.22	46.00	-28.78	AVG

## Underwriters Laboratories Taiwan Co., Ltd.


Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 60 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

# **Charging mode**





No.	Frequency	Reading	Correct	Result	Limit	Margin	Remark
	(MHz)	(dBuV)	(dB)	(dBuV)	(dBuV)	(dB)	Remark
1	0.1505	36.20	0.08	36.28	65.97	-29.69	QP
2	0.1505	23.84	0.08	23.92	55.97	-32.05	AVG
3	0.4621	35.94	0.07	36.01	56.65	-20.64	QP
4	0.4621	29.02	0.07	29.09	46.65	-17.56	AVG
5	0.7570	20.77	0.08	20.85	56.00	-35.15	QP
6	0.7570	11.56	0.08	11.64	46.00	-34.36	AVG
7	1.3809	24.11	0.09	24.20	56.00	-31.80	QP
8	1.3809	16.86	0.09	16.95	46.00	-29.05	AVG
9	2.5956	27.76	0.11	27.87	56.00	-28.13	QP
10	2.5956	21.21	0.11	21.32	46.00	-24.68	AVG
11	4.2498	22.29	0.12	22.41	56.00	-33.59	QP
12	4.2498	16.73	0.12	16.85	46.00	-29.15	AVG


Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948



Page : 61 of 61 Issued date : 2023/8/11 FCC ID : 2AYYS-HS2404

Mode Charging Mode Channel N/A



N.	Frequency	Reading	Correct	Result	Limit	Margin	Damada
No.	(MHz)	(dBuV)	(dB)	(dBuV)	(dBuV)	(dB)	Remark
1	0.1675	33.17	0.07	33.24	65.08	-31.84	QP
2	0.1675	22.35	0.07	22.42	55.08	-32.66	AVG
3	0.4652	34.58	0.06	34.64	56.60	-21.96	QP
4	0.4652	29.07	0.06	29.13	46.60	-17.47	AVG
5	0.9271	22.99	0.07	23.06	56.00	-32.94	QP
6	0.9271	14.95	0.07	15.02	46.00	-30.98	AVG
7	1.5770	24.86	0.08	24.94	56.00	-31.06	QP
8	1.5770	18.96	0.08	19.04	46.00	-26.96	AVG
9	2.6450	25.59	0.10	25.69	56.00	-30.31	QP
10	2.6450	18.86	0.10	18.96	46.00	-27.04	AVG
11	4.9510	22.68	0.14	22.82	56.00	-33.18	QP
12	4.9510	17.50	0.14	17.64	46.00	-28.36	AVG

## **END OF REPORT**

## Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX ) :+886-3-583-7948