






Report No.: AAEMT/RF/231110-04-03





Report No.: AAEMT/RF/231110-04-03




Report No.: AAEMT/RF/231110-04-03




Report No.: AAEMT/RF/231110-04-03





Report No.: AAEMT/RF/231110-04-03






Report No.: AAEMT/RF/231110-04-03





Report No.: AAEMT/RF/231110-04-03

ax80 5.775 GHz




Report No.: AAEMT/RF/231110-04-03



Antenna 2:



a20 5.240 GHz



n20 5.180 GHz









Report No.: AAEMT/RF/231110-04-03





Report No.: AAEMT/RF/231110-04-03

ac20 5.180 GHz




Report No.: AAEMT/RF/231110-04-03

ac20 5.240 GHz



Report No.: AAEMT/RF/231110-04-03





Report No.: AAEMT/RF/231110-04-03



Report No.: AAEMT/RF/231110-04-03

ac80 5.210 GHz



Report No.: AAEMT/RF/231110-04-03






Report No.: AAEMT/RF/231110-04-03



Report No.: AAEMT/RF/231110-04-03



Report No.: AAEMT/RF/231110-04-03








Report No.: AAEMT/RF/231110-04-03





Report No.: AAEMT/RF/231110-04-03








Report No.: AAEMT/RF/231110-04-03




Report No.: AAEMT/RF/231110-04-03




Report No.: AAEMT/RF/231110-04-03




Report No.: AAEMT/RF/231110-04-03






Report No.: AAEMT/RF/231110-04-03











Report No.: AAEMT/RF/231110-04-03







Antenna 3:



a20 5.240 GHz



Report No.: AAEMT/RF/231110-04-03



Report No.: AAEMT/RF/231110-04-03



Report No.: AAEMT/RF/231110-04-03



Report No.: AAEMT/RF/231110-04-03



Report No.: AAEMT/RF/231110-04-03



Report No.: AAEMT/RF/231110-04-03

