







Report No.: AAEMT/RF/231110-04-03





Report No.: AAEMT/RF/231110-04-03





Report No.: AAEMT/RF/231110-04-03






Report No.: AAEMT/RF/231110-04-03




Report No.: AAEMT/RF/231110-04-03






Report No.: AAEMT/RF/231110-04-03

### Antenna 5:



## a20 5.240 GHz










Report No.: AAEMT/RF/231110-04-03







Report No.: AAEMT/RF/231110-04-03




Report No.: AAEMT/RF/231110-04-03




Report No.: AAEMT/RF/231110-04-03







Report No.: AAEMT/RF/231110-04-03






## ax40 5.190 GHz




Report No.: AAEMT/RF/231110-04-03





Report No.: AAEMT/RF/231110-04-03






Report No.: AAEMT/RF/231110-04-03








Report No.: AAEMT/RF/231110-04-03














Report No.: AAEMT/RF/231110-04-03



Report No.: AAEMT/RF/231110-04-03




Report No.: AAEMT/RF/231110-04-03




Report No.: AAEMT/RF/231110-04-03




Report No.: AAEMT/RF/231110-04-03





Report No.: AAEMT/RF/231110-04-03






Report No.: AAEMT/RF/231110-04-03





Report No.: AAEMT/RF/231110-04-03







Report No.: AAEMT/RF/231110-04-03

### Antenna 6:



## a2o 5.240 GHz





Report No.: AAEMT/RF/231110-04-03




Report No.: AAEMT/RF/231110-04-03


n20 5.240 GHz



Report No.: AAEMT/RF/231110-04-03



Report No.: AAEMT/RF/231110-04-03



Report No.: AAEMT/RF/231110-04-03




Report No.: AAEMT/RF/231110-04-03




Report No.: AAEMT/RF/231110-04-03



Report No.: AAEMT/RF/231110-04-03



Report No.: AAEMT/RF/231110-04-03



Report No.: AAEMT/RF/231110-04-03

